

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 16 Q1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
15/16 Annual Advance \$5,199,499.00						
Communities	Lemon Cove	Repair potholes with Road Patcher	Avenue 324 from Highway 198 to Road 248	9/3/2015	9/9/2015	\$ 535.16
	Lindcove	Repair potholes with Road Patcher	Avenue 320 from Road 220 to Avenue 320	9/9/2015	9/9/2015	
	Lindcove	Repair potholes with Road Patcher	Road 220 from Avenue 304 to Avenue 320	9/9/2015	9/9/2015	
	Lindcove	Repair potholes with Road Patcher	Road 220 from Avenue 304 to Avenue 320	9/10/2015	9/10/2015	\$ 642.19
	Plainview	Repair potholes with Road Patcher	Road 208 from Avenue 192 to Avenue 204	7/15/2015	7/15/2015	
	Plainview	Repair potholes with Road Patcher	Road 188 at Avenue 200	7/21/2015	7/22/2015	
	Plainview	Repair potholes with Road Patcher	Road 204 from Avenue 192 to Avenue 196	7/21/2015	7/21/2015	
	Plainview	Repair potholes with Road Patcher	Road 192 from Avenue 208 to Avenue 216	7/22/2015	7/22/2015	
	Plainview	Repair potholes with Road Patcher	Road 196 at Avenue 195	9/17/2015	9/17/2015	
	Plainview	Repair potholes with Road Patcher	Avenue 256 from Road 200 to Road 204	9/17/2015	9/17/2015	\$ 963.27
	Strathmore	Repair potholes with Road Patcher	Avenue 204 at Diagonal 228	6/30/2015	7/15/2015	
	Strathmore	Repair potholes with Road Patcher	Avenue 184 from Road 236 to Road 238	7/28/2015	7/28/2015	
	Strathmore	Repair potholes with Road Patcher	Road 238 from Diagonal 238 to Avenue 184	7/28/2015	7/28/2015	\$ 430.05
	Tonyville	Repair potholes with Road Patcher	Road 212 from Avenue 247 to Avenue 256	7/23/2015	7/23/2015	
	Tonyville	Repair potholes with Road Patcher	Avenue 240 from Road 204 to Road 216	7/27/2015	7/27/2015	
	Tonyville	Repair potholes with Road Patcher	Road 212 from Avenue 240 to Avenue 245	7/27/2015	7/27/2015	
	Tonyville	Repair potholes with Road Patcher	Road 212 from Avenue 245 to Avenue 256	7/28/2015	7/28/2015	
	Tonyville	Repair potholes with Road Patcher	Road 224 from Avenue 238 to Avenue 248	8/26/2015	8/26/2015	
	Tonyville	Repair potholes with Road Patcher	Avenue 250 from Road 216 to Road 224	8/26/2015	8/26/2015	
	Tonyville	Repair potholes with Road Patcher	Avenue 250 at Road 216	8/31/2015	8/31/2015	
	Tonyville	Repair potholes with Road Patcher	Avenue 256 from Road 204 to Road 212	9/3/2015	9/3/2015	
	Tonyville	Repair potholes with Road Patcher	Road 216 from Avenue 256 to Avenue 264	9/10/2015	9/10/2015	
	Tonyville	Repair potholes with Road Patcher	Road 214 from Avenue 240 to Avenue 245	9/14/2015	9/14/2015	
	Tonyville	Repair potholes with Road Patcher	Avenue 240 from Road 214 to Road 216	9/15/2015	9/15/2015	
	Tonyville	Repair potholes with Road Patcher	Road 214 south of Avenue 240	9/15/2015	9/15/2015	
	Tonyville	Repair potholes with Road Patcher	Road 212 from Avenue 247 to Avenue 256	9/15/2015	9/15/2015	
	Tonyville	Repair potholes with Road Patcher	Road 212 from Avenue 247 to Avenue 256	9/16/2015	ongoing	\$ 3,217.03
	West Exeter	Repair potholes with Road Patcher	Road 188 from Avenue 264 to Avenue 268	9/16/2015	9/16/2015	
	West Exeter	Repair potholes with Road Patcher	Road 192 from Avenue 256 to Avenue 269	9/16/2015	9/16/2015	\$ 214.06

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 16 Q1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads	Rural Roads	Repair potholes with Road Patcher	Road 228 from Avenue 228 to Avenue 234	6/29/2015	6/29/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 216 from Diagonal 242 to Road 228	6/29/2015	6/29/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 216 from Diagonal 216 to Road 220	6/29/2015	6/29/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 444 from Road 120 to State Highway 63	7/6/2015	7/6/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 452 at Road 124	7/6/2015	7/6/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 124 from Avenue 460 to Avenue 472	7/8/2015	7/8/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 124 at Avenue 448	7/13/2015	7/13/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 124 from Avenue 460 to Avenue 472	7/13/2015	7/13/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 404 from Road 96 to Road 104	7/14/2015	7/14/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 368 West of Road 76	7/14/2015	7/14/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 8 from Avenue 384 to Avenue 392	7/14/2015	7/14/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 205 from Avenue 220 to Avenue 224	7/15/2015	7/15/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 272 at Diagonal 211	7/15/2015	7/15/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 184 from Road 152 to Road 168	7/16/2015	7/20/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 164 from Avenue 200 to Avenue 208	7/20/2015	7/20/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 200 from Road 164 to Road 172	7/20/2015	7/20/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 200 from Road 172 to Road 188	7/21/2015	7/21/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 216 from Road 180 to Road 188	7/22/2015	7/22/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 16 from Avenue 392 to Avenue 384	7/23/2015	7/23/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 24 North of Avenue 396	7/23/2015	7/23/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 8 from Avenue 388 to County Line	7/23/2015	7/23/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 224 from Road 180 to Road 196	7/23/2015	7/23/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 144 from Avenue 416 to Avenue 432	7/27/2015	7/27/2015	
	Rural Roads	Repair potholes with Road Patcher	TRACT 213 (DISTRICT 5)	7/29/2015	7/29/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 208 from Avenue 152 to Avenue 144	7/29/2015	7/29/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 216 from Avenue 152 to Avenue 136	7/29/2015	7/29/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 44 from Avenue 360 to Avenue 368	8/3/2015	8/3/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 392 at Road 12	8/3/2015	8/3/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 388 from Road 8 to County Line	8/3/2015	8/3/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 8 North of Avenue 384	8/3/2015	8/3/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 20 at Avenue 392	8/3/2015	8/3/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 396 East of Road 20	8/4/2015	8/4/2015	
	Rural Roads	Repair potholes with Road Patcher	D15 from Avenue 392 to Avenue 396	8/4/2015	8/4/2015	
	Rural Roads	Repair potholes with Road Patcher	Monson Drive from Avenue 388 to Avenue 384	8/6/2015	8/6/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 388 from Road 8 to Bethel	8/6/2015	8/6/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 336 West of Road 156	8/6/2015	8/6/2015	
	Rural Roads	Repair potholes with Road Patcher	Charter Oak at Road 188	8/6/2015	8/6/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 188 from Avenue 256 to Avenue 264	8/26/2015	8/26/2015	
	Rural Roads	Repair potholes with Road Patcher	Mountain Road 161 from Highway 190 to Mountain Road 164	8/31/2015	8/31/2015	
	Rural Roads	Repair potholes with Road Patcher	Mountain Road 164 from Mountain Road 161 to Mountain Road 159	8/31/2015	8/31/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 224 at Road 236	8/31/2015	8/31/2015	
	Rural Roads	Repair potholes with Road Patcher	Diagonal 236 from Friant Kern Canal to Road 236	8/31/2015	8/31/2015	
	Rural Roads	Fill Oil Tank	Cain Trucking, 23004 Road 140	9/9/2015	9/9/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 188 from Avenue 242 to Avenue 256	9/10/2015	9/10/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 208 from Avenue 160 to Avenue 164	9/16/2015	9/16/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 208 from Avenue 196 to Avenue 208	9/16/2015	9/16/2015	
	Mountain Roads	Repair potholes with Road Patcher	Mountain Road 296 from Milepost 21 to Mountain Road 239	6/30/2015	6/30/2015	
	Mountain Roads	Repair potholes with Road Patcher	Mountain Road 296 from Highway 198 to Road 228	7/15/2015	7/15/2015	
Rural Roads					TOTAL	\$ 12,774.22

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 16 Q1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720) AC Overlays MR (AB720)	AC Overlay	Construction Engineering/ Design	Avenue 256 from Road 180 to Road 188	5/14/2014	ongoing	\$ 1,167.22
		Construction Engineering/ Design	Avenue 56 from State Route 43 to Road 96	5/14/2014	ongoing	\$ 798,005.58
		Construction Engineering/ Design	Diagonal 238 from Avenue 124 to TPD	5/14/2014	ongoing	\$ 318,815.42
		Preliminary Engineering/ Design	Community Road Surfacing	5/14/2014	ongoing	\$ 3,172.96
		Construction Engineering/ Design	Road 148 Avenue 280 Visalia Road to Avenue 288 Marinette Avenue	7/18/2014	ongoing	\$ 1,411.84
		Construction Engineering/ Design	Road 184 from Avenue 136 to Avenue 144	7/18/2014	ongoing	\$ 1,336.33
		Construction Engineering/ Design	Road 200 from Avenue 0 to Avenue 8	7/18/2014	ongoing	\$ 1,307.79
		Construction Engineering/ Design	Avenue 432 Floral Avenue Road 128 to State Highway 63 to Road 136	7/18/2014	ongoing	\$ 1,268.67
		Construction Engineering/ Design	Diagonal 208B Avenue 160 from Henderson to Road 208	7/18/2014	ongoing	\$ 1,236.03
		Construction Engineering/ Design	Diagonal 108A Avenue 384 to Road 104	11/19/2014	ongoing	\$ 811.08
		Construction Engineering/ Design	Success Drive from Park to Connor	11/19/2014	ongoing	\$ 409,776.74
		Construction Engineering/ Design	Rural Road Surface Maintainance	1/15/2015	ongoing	\$ 76,438.67
		Preliminary Engineering/ Design	Community Road Surface Maintainance	1/15/2015	ongoing	\$ 21,811.34
					TOTAL	\$ 1,655,335.65

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 2

**Local Programs**

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
15/16 Annual Advance \$5,199,499.00						
Communities	Doyle Colony	Repair road surface by hand patching	27531 Avenue 146	12/8/2015	12/8/2015	
	Doyle Colony	Repair road surface by hand patching	Doyle south of Crabtree	12/8/2015	12/8/2015	
	Doyle Colony	Repair road surface by hand patching	Bennett from Avenue 146 to Richard	12/8/2015	12/8/2015	\$ 73.40
	East Orosi	Repair road surface by hand patching	Avenue 416 East of Road 152	11/30/2015	11/30/2015	\$ 32.14
	London	Repair road surface by hand patching	Avenue 377 West of Road 57	12/7/2015	12/7/2015	\$ 69.45
	Orosi	Repair road surface by hand patching	Avenue 424 from Road 109 to Road 126	11/30/2015	11/30/2015	
	Orosi	Repair road surface by hand patching	Avenue 432 East of Road 120	11/30/2015	11/30/2015	\$ 202.10
	Plainview	Repair potholes with Road Patcher	Road 208 from Avenue 204 to Avenue 208	11/17/2015	11/17/2015	\$ 71.35
	Seville	Repair road surface by hand patching	Road 156 from Avenue 384 to Avenue 362	12/7/2015	12/7/2015	\$ 93.85
	Springville	Large area Patching with grader "Blade Patch"	Cramer from State Highway 190 to End	10/26/2015	10/27/2015	
	Springville	Repair potholes with Road Patcher	Ward at Lenard	11/10/2015	11/10/2015	
	Springville	Repair road surface by hand patching	Ward at Lenard	11/13/2015	11/13/2015	
	Springville	Repair road surface by hand patching	Pine east of Highway 190	12/8/2015	12/8/2015	\$ 8,095.78
	Strathmore	Repair road surface by hand patching	Avenue 182 from Road 224 to Road 232	11/10/2015	11/10/2015	
	Strathmore	Repair road surface by hand patching	Avenue 200 at Road 228	11/16/2015	11/16/2015	
	Strathmore	Repair road surface by hand patching	Avenue 228 at Road 228	11/16/2015	11/16/2015	
	Strathmore	Repair potholes with Road Patcher	Road 228 from Avenue 192 to Avenue 194	11/17/2015	11/17/2015	
	Strathmore	Repair potholes with Road Patcher	Avenue 192 from Road 228 to Road 242	11/17/2015	11/17/2015	
	Strathmore	Repair potholes with Road Patcher	Avenue 184 from Diagonal 242 to Road 236	11/19/2015	11/19/2015	
	Strathmore	Repair potholes with Road Patcher	Road 216 from Avenue 192 to Avenue 196	12/4/2015	12/15/2015	
	Strathmore	Repair potholes with Road Patcher	Avenue 188 at Road 224	12/8/2015	12/8/2015	
	Strathmore	Repair road surface by hand patching	Avenue 192 from Road 216 to Road 220	12/8/2015	12/8/2015	
	Strathmore	Repair potholes with Road Patcher	Avenue 176 from Road 192 to Road 208	12/15/2015	12/15/2015	
	Strathmore	Repair road surface by hand patching	Avenue 198 at Diagonal 242	12/16/2015	12/16/2015	
	Strathmore	Repair road surface by hand patching	Avenue 197 at Road 231	12/16/2015	12/16/2015	
	Strathmore	Repair road surface by hand patching	Road 236 from Avenue 200 to Avenue 204	12/16/2015	12/16/2015	\$ 2,589.97
	Three Rivers	Repair road surface by hand patching	M 368 from Mile Post 0 to Mile Post 2	12/16/2015	12/16/2015	
	Three Rivers	Repair road surface by hand patching	RM 357 form Mile Post 0 to Mile Post 2	12/16/2015	12/16/2015	\$ 351.01
	Tipton	Skin Patch	Graham from Jayne to Klinders	12/10/2015	12/10/2015	\$ 2,254.18
	Tonyville	Repair potholes with Road Patcher	Road 212 from Avenue 247 to Avenue 256	9/21/2015	9/21/2015	
	Tonyville	Repair potholes with Road Patcher	Diagonal 227 from Road 248 to End	10/29/2015	10/29/2015	
	Tonyville	Repair potholes with Road Patcher	Road 224 from Avenue 238 to Avenue 250	10/29/2015	10/29/2015	
	Tonyville	Repair potholes with Road Patcher	Avenue 256 west of Road 212	11/4/2015	11/4/2015	
	Tonyville	Repair potholes with Road Patcher	Diagonal 208 from Avenue 244 to Avenue 245	11/12/2015	11/12/2015	
	Tonyville	Repair road surface by hand patching	Road 212 west of Avenue 256	11/16/2015	11/16/2015	
	Tonyville	Repair potholes with Road Patcher	Avenue 256 from Road 204 to Road 212	12/3/2015	12/3/2015	
	Tonyville	Repair potholes with Road Patcher	Road 212 from Avenue 245 to Avenue 247	12/3/2015	12/3/2015	\$ 1,382.85
	Traver	Repair road surface by hand patching	Road 60 South of Avenue 352	11/5/2015	11/5/2015	\$ 27.53
	West Exeter	Repair road surface by hand patching	Road 188 from Avenue 272 to Exeter City Limits	11/10/2015	11/10/2015	
	West Exeter	Repair road surface by hand patching	Avenue 256 at Road 26	12/15/2015	12/15/2015	
	West Exeter	Repair road surface by hand patching	Avenue 264 at Road 180	12/15/2015	12/15/2015	
	West Exeter	Repair road surface by hand patching	Avenue 188 from Road 242 to Road 256	12/15/2015	12/15/2015	\$ 201.52
	Yokohl	Repair potholes with Road Patcher	Road 212 at Avenue 300	11/4/2015	11/12/2015	
	Yokohl	Repair potholes with Road Patcher	Road 212 at Avenue 304	11/12/2015	11/12/2015	
	Yokohl	Repair potholes with Road Patcher	Avenue 304 from Road 204 to Road 212	11/12/2015	11/12/2015	\$ 499.48

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 2

**Local Programs**

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads	Rural Roads	Repair potholes with Road Patcher	Road 224 from Avenue 188 to Avenue 192	9/22/2015	9/22/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 174 from Road 232 to Highway 65	10/13/2015	10/13/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 212 from Avenue 188 to Avenue 192	10/13/2015	10/13/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 216 from Avenue 184 to Avenue 188	10/13/2015	10/14/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 192 from Road 216 to Road 220	10/14/2015	10/14/2015	
	Rural Roads	Moved Steel Roller	Road 220 at Avenue 132	10/22/2015	10/22/2015	
	Rural Roads	Large area Patching with grader "Blade Patch"	Haul for District 2	10/23/2015	10/23/2015	
	Rural Roads	Large area Patching with grader "Blade Patch"	Colony, Road 124 to Road126	10/23/2015	10/27/2015	
	Rural Roads	Large area Patching with grader "Blade Patch"	Road 124, State Highway 132 North to End	10/23/2015	10/27/2015	
	Rural Roads	Large area Patching with grader "Blade Patch"	Colony from Road 124 to Road 126	10/23/2015	10/23/2015	
	Rural Roads	Repair potholes with Road Patcher	Diagonal 211 from Road 216 to Avenue 176	11/4/2015	11/4/2015	
	Rural Roads	Repair road surface by hand patching	Haul Patch material from Plant to various rock pits	11/4/2015	11/4/2015	
	Rural Roads	Hauling Planting Mix	Several Locations	11/4/2015	11/5/2015	
	Rural Roads	Hauled patch material	From Porterville Asphalt to Ave 376 at Pierda	11/4/2015	11/4/2015	
	Rural Roads	Haul Materials	Porterville Asphalt to Yard 1 and Porterville Asphalt to Ave 112 Pit	11/4/2015	11/4/2015	
	Rural Roads	Repair road surface by hand patching	Haul Patch material from Plant to various rock pits	11/5/2015	11/5/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 84 Road 96	11/5/2015	11/5/2015	
	Rural Roads	Hauled patch material	From Porterville Asphalt to Ave 368 Pit, Yard 2, Rankin Pit	11/5/2015	11/5/2015	
	Rural Roads	Haul Materials	Porterville Asphalt to District 4 368 Pit and District 2 Rankin Pit	11/5/2015	11/5/2015	
	Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 208 to Highway 137	11/10/2015	11/10/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 224 east of Road 180	11/10/2015	11/10/2015	
	Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 272 to Exeter City Limits	11/10/2015	11/10/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 248, Road 164 to Road 140	11/12/2015	11/12/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 144, State Highway 99 to State Highway 43	11/13/2015	11/13/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 184 to Road 176	11/13/2015	11/13/2015	
	Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 120 to Avenue 128	11/13/2015	11/13/2015	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 128 to Avenue 124	11/13/2015	11/13/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 240 east of Cedar	11/16/2015	11/16/2015	
	Rural Roads	Repair road surface by hand patching	Road 224 from Avenue 200 to Avenue 224	11/16/2015	11/16/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 200 at Road 228	11/16/2015	11/16/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 144, Road 112 to Road 104	11/16/2015	11/16/2015	
	Rural Roads	Repair road surface by hand patching	Road 96, from Addie Street to Avenue 184	11/16/2015	11/16/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 412 East of Road 104	11/16/2015	11/16/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 95 from Road 236 to Road 264	11/16/2015	11/16/2015	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 176 to Avenue 124	11/16/2015	11/17/2015	
	Rural Roads	Repair potholes with Road Patcher	Road 228 from Avenue 192 to Avenue 194	11/17/2015	11/17/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 192 from Road 228 to Diagonal 242	11/17/2015	11/17/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 208 from Road 216 to Diagonal 220B	11/17/2015	11/17/2015	
	Rural Roads	Repair road surface by hand patching	Road 96, Avenue 160 to Avenue 176	11/17/2015	11/17/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	11/17/2015	11/17/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 408 at Road 120	11/17/2015	11/17/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 408 West of Road 120	11/17/2015	11/17/2015	
	Rural Roads	Repair road surface by hand patching	Road 172 West of Avenue 352	11/17/2015	11/17/2015	
	Rural Roads	Repair road surface by hand patching	Diagonal 208 from Road 208 to Avenue 160	11/17/2015	11/17/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 160 from Diagonal 208 to Avenue 152	11/18/2015	11/18/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 160 from Road 208 to Porterville City Limits	11/19/2015	11/19/2015	
	Rural Roads	Repair potholes with Road Patcher	Avenue 184 from Road 236 to Road 238	11/19/2015	11/19/2015	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 80 to Avenue 56	11/19/2015	12/7/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 184 from Diagonal 242 to Road 248	11/20/2015	11/20/2015	
	Rural Roads	Repair road surface by hand patching	Road 220 from Diagonal 242 to Avenue 224	11/20/2015	11/20/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 220 at Road 252	11/20/2015	11/20/2015	

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 2

**Local Programs**

Rural Roads	Repair road surface by hand patching	Avenue 181 at Road 236	11/20/2015	11/20/2015
Rural Roads	Repair road surface by hand patching	Road 220 at Avenue 220	11/20/2015	11/20/2015
Rural Roads	Repair road surface by hand patching	Avenue 220 from Road 244 to Road 254	11/20/2015	11/20/2015
Rural Roads	Repair road surface by hand patching	Avenue 188 at Road 244	11/20/2015	11/20/2015
Rural Roads	Repair road surface by hand patching	Avenue 196, I Street to Road 96	11/20/2015	11/20/2015
Rural Roads	Repair road surface by hand patching	I Street, Avenue 192 Tulare City Limits	11/20/2015	11/20/2015
Rural Roads	Repair road surface by hand patching	Avenue 144 from Road 112 TO Road 72	11/20/2015	11/20/2015
Rural Roads	Repair road surface by hand patching	Road 220 from Avenue 208 to End	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	Avenue 228 east of Avenue 196	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	Avenue 164 from Road 252 to Lime	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 256 to Avenue 280	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	K Road from Road 132 to Road 128	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	Road 100 from Avenue 264 to Visalia City Limits	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	Avenue 264 from State Highway 99 to Road 108	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	Avenue 144 from Road 72 to State Highway 43	11/23/2015	11/23/2015
Rural Roads	Repair road surface by hand patching	Avenue 244 from Avenue 169 to Lime	11/24/2015	11/24/2015
Rural Roads	Repair road surface by hand patching	Avenue 208 from Road 244 to Road 245	11/24/2015	11/24/2015
Rural Roads	Repair road surface by hand patching	Road 196 from Highway 198 to Avenue 312	11/24/2015	11/24/2015
Rural Roads	Repair road surface by hand patching	Avenue 304 at Avenue 312	11/24/2015	11/24/2015
Rural Roads	Repair road surface by hand patching	Road 172 North of Avenue 352	11/30/2015	11/30/2015
Rural Roads	Repair road surface by hand patching	Avenue 416 between Road 130 to Road 168	12/1/2015	12/1/2015
Rural Roads	Repair road surface by hand patching	Road 124 North of Avenue 424	12/1/2015	12/1/2015
Rural Roads	Repair road surface by hand patching	Magnolia from Aster to Iris	12/1/2015	12/1/2015
Rural Roads	Repair road surface by hand patching	Cedar from Avenue 152 to Aster	12/1/2015	12/1/2015
Rural Roads	Repair road surface by hand patching	Avenue 216 Diagonal 242 to Road 228	12/2/2015	12/2/2015
Rural Roads	Repair road surface by hand patching	Road 124 between Avenue 424 and Avenue 432	12/2/2015	12/2/2015
Rural Roads	Repair road surface by hand patching	Avenue 432 between Road 124 and Road 128	12/2/2015	12/2/2015
Rural Roads	Repair road surface by hand patching	Road 84 between Avenue 384 and Avenue 368	12/2/2015	12/2/2015
Rural Roads	Repair road surface by hand patching	Crestview from Worth to Warzee	12/2/2015	12/3/2015
Rural Roads	Large area Patching with grader "Blade Patch"	Mountain 137 at Mile Post 1.5	12/2/2015	12/3/2015
Rural Roads	Repair potholes with Road Patcher	Road 168 from Avenue 196 to Avenue 200	12/3/2015	12/3/2015
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 240 to Road 248	12/3/2015	12/3/2015
Rural Roads	Repair road surface by hand patching	Avenue 120, Road 124 to State Highway 43	12/3/2015	12/3/2015
Rural Roads	Repair road surface by hand patching	Road 76 South of Ave 368	12/3/2015	12/3/2015
Rural Roads	Repair road surface by hand patching	Avenue 360 West of Road 76	12/3/2015	12/3/2015
Rural Roads	Repair potholes with Road Patcher	Road 168 from Avenue 196 to Avenue 200	12/4/2015	12/4/2015
Rural Roads	Repair potholes with Road Patcher	Avenue 184 at Road 208	12/4/2015	12/4/2015
Rural Roads	Repair road surface by hand patching	Ralph at City Limits	12/4/2015	12/4/2015
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 144 to Road 145	12/4/2015	12/4/2015
Rural Roads	Repair road surface by hand patching	Mountain 137 from Mile Post 1.5 to Mile Post 7	12/4/2015	12/4/2015
Rural Roads	Repair road surface by hand patching	Avenue 384 from Road 80 to Road 88	12/7/2015	12/7/2015
Rural Roads	Repair road surface by hand patching	load patch material at Yard 1	12/8/2015	12/8/2015
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 80 to Avenue 0	12/8/2015	12/8/2015
Rural Roads	Large area Patching with grader "Blade Patch"	Avenue 272 from Road 100 to Road 92	12/9/2015	12/9/2015
Rural Roads	Repair road surface by hand patching	Avenue 315 from Road 168 to Charter Oak	12/9/2015	12/9/2015
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 315 to Charter Oak	12/9/2015	12/9/2015
Rural Roads	Repair road surface by hand patching	Road 166 from Avenue 325 to Avenue 328	12/9/2015	12/9/2015
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 320 to Avenue 325	12/9/2015	12/9/2015
Rural Roads	Repair road surface by hand patching	Avenue 352 West of Road 180	12/9/2015	12/9/2015
Rural Roads	Repair road surface by hand patching	Road 216 from Avenue 192 to Avenue 196	12/10/2015	12/10/2015
Rural Roads	Repair road surface by hand patching	Avenue 352 East of Road 180	12/10/2015	12/10/2015
Rural Roads	Repair road surface by hand patching	Road 196 from State Route 198 to Avenue 324	12/15/2015	12/15/2015
Rural Roads	Repair potholes with Road Patcher	Road 216 from Avenue 192 to Avenue 176	12/15/2015	12/15/2015
Rural Roads	Repair potholes with Road Patcher	Avenue 176 from Road 192 to Road 208	12/15/2015	12/17/2015

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 2

Local Programs

Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 400 to Avenue 392	12/16/2015	12/16/2015	
Rural Roads	Repair potholes with Road Patcher	Avenue 176 from Diagonal 184 to Road 192	12/17/2015	12/18/2015	
Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 96 to Road 88	12/17/2015	12/17/2015	
Rural Roads	Repair road surface by hand patching	Avenue 388 from Road 88 to Road 84	12/17/2015	12/17/2015	
Rural Roads	Repair road surface by hand patching	Avenue 388 from Road 84 to Road 88	12/18/2015	12/18/2015	
Rural Roads	Repair road surface by hand patching	Lawrence from Road 56 to Road 57	12/18/2015	12/18/2015	
Rural Roads	Repair road surface by hand patching	Avenue 408 at Road 116	12/18/2015	12/18/2015	
Rural Roads	Repair potholes with Road Patcher	Diagonal 184 from Avenue 176 to Avenue 178	12/21/2015	12/21/2015	
Rural Roads	Repair road surface by hand patching	Road 48 from Ave 400 to Avenue 416	12/23/2015	12/23/2015	
Mountain Roads	Repair potholes with Road Patcher	Mountain Road 172 from Highway 190 to Highway 190	9/22/2015	9/22/2015	
Mountain Roads	Repair potholes with Road Patcher	Mountain Road 296 at Milepost 3	11/4/2015	11/4/2015	
Mountain Roads	Repair potholes with Road Patcher	Mountain Road 296 from Highway 198 to Road 284	11/4/2015	11/4/2015	
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Highway 198 to Milepost 12	12/2/2015	12/2/2015	
Mountain Roads	Repair road surface by hand patching	Mountain Road 231 from Milepost 1 to Milepost 2	12/4/2015	12/4/2015	
Mountain Roads	Repair road surface by hand patching	Avenue 176 at Mountain Road 176	12/4/2015	12/4/2015	
Mountain Roads	Repair road surface by hand patching	Mountain Road 231 from Mountain Road 239 to Milepost 1	12/7/2015	12/7/2015	
Mountain Roads	Repair road surface by hand patching	Mountain Road 231 from Mountain Road 239 to Milepost .5	12/8/2015	12/8/2015	
Mountain Roads	Repair road surface by hand patching	Mountain Road 208 at Milepost 0.5	12/16/2015	12/16/2015	
Rural Roads				TOTAL	\$ 94,356.27

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 2

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720) AC Overlays MR (AB720)	AC Overlay	Construction/Design	Avenue 256 from Road 180 to Road 188	5/14/2014	ongoing	\$ 22,153.94
		Construction/Design	Avenue 56 from State Route 43 to Road 96	5/14/2014	ongoing	\$ 335,730.02
		Construction/Design	Diagonal 238 from Avenue 124 to TPD	5/14/2014	ongoing	\$ 3,723.72
		Preliminary Engineering/ Design	Community Road Surfacing	5/14/2014	ongoing	\$ 1,581.10
		Construction/Design	Road 148 Avenue 280 Visalia Road to Avenue 288 Marinette Avenue	7/18/2014	ongoing	\$ 173,282.62
		Construction/Design	Road 184 from Avenue 136 to Avenue 144	7/18/2014	ongoing	\$ 11,602.40
		Construction/Design	Road 200 from Avenue 0 to Avenue 8	7/18/2014	ongoing	\$ 3,205.65
		Construction/Design	Avenue 432 Floral Avenue Road 128 to State Highway 63 to Road 136	7/18/2014	ongoing	\$ 212,941.27
		Construction/Design	Diagonal 208B Avenue 160 from Henderson to Road 208	7/18/2014	ongoing	\$ 101,532.63
		Construction/Design	Diagonal 108A Avenue 384 to Road 104	11/19/2014	ongoing	\$ 2,479.07
		Construction/Design	Success Drive from Park to Connor	11/19/2014	ongoing	\$ 22,761.64
		Construction/Design	Rural Road Surface Maintainance	1/15/2015	ongoing	\$ 1,719,987.60
		Preliminary Engineering/ Design	Community Road Surface Maintainance	1/15/2015	ongoing	\$ 5,483.52
					TOTAL	\$ 2,726,766.06



**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency:

Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
15/16 Annual Advance						
\$5,199,499.00						
<b>Communities</b>						
	Allensworth	Repair road surface by hand patching	Avenue 24 from State Highway 43 to Road 84	3/9/2016	3/9/2016	
	Allensworth	Repair road surface by hand patching	Road 84 from Avenue 24 to Avenue 39	3/9/2016	3/9/2016	\$ 373.98
	Alpaugh	Repair road surface by hand patching	Church, Tule-Knox	1/26/2016	1/26/2016	
	Alpaugh	Repair road surface by hand patching	Knox South of Avenue 54	1/26/2016	1/26/2016	
	Alpaugh	Repair road surface by hand patching	Olive, Church to Avenue 54	1/26/2016	1/26/2016	
	Alpaugh	Repair road surface by hand patching	Road 42 from Avenue 54 to the End	2/22/2016	2/22/2016	
	Alpaugh	Repair road surface by hand patching	Avenue 62 from Road 42 to Road 46	2/22/2016	2/22/2016	
	Alpaugh	Repair road surface by hand patching	Avenue 50 at Road 46	2/22/2016	2/22/2016	
	Alpaugh	Repair road surface by hand patching	Avenue 56 at State Highway 43	2/22/2016	2/22/2016	\$ 1,135.43
	Cutler/Orosi	Repair road surface by hand patching	Avenue 413 from Road 124 to Road 127	1/12/2016	1/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 404 East of Road 120	2/2/2016	2/2/2016	
	Cutler/Orosi	Repair road surface by hand patching	Second from Orosi to Cutler Avenue	2/4/2016	2/4/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 432 from Road 144 to Road 140	2/4/2016	2/4/2016	
	Cutler/Orosi	Repair road surface by hand patching	Cutler from Railroad to First Street	2/12/2016	2/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	First Street from Santa Fe to Orosi	2/12/2016	2/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Orosi from First Street to Second	2/16/2016	2/16/2016	
	Cutler/Orosi	Repair road surface by hand patching	First Drive from Cutler Drive to Orosi Drive	3/17/2016	3/17/2016	\$ 968.16
	Doyle Colony	Repair road surface by hot patching	LR270 from LA146A to LA147D	1/4/2016	1/4/2016	
	Doyle Colony	Repair road surface by hot patching	Crabtree south of Tulsa	1/12/2016	1/12/2016	
	Doyle Colony	Repair road surface by hot patching	Rocky Hill from Crabtree to Roby	1/15/2016	1/15/2016	
	Doyle Colony	Repair road surface by hot patching	Roby at Holcomb	1/15/2016	1/15/2016	
	Doyle Colony	Repair road surface by hot patching	Mountain Road 146 at Avenue 146	1/25/2016	1/25/2016	
	Doyle Colony	Repair road surface by hot patching	Avenue 146 at Road 272	1/25/2016	1/25/2016	
	Doyle Colony	Repair road surface by hot patching	LR269B from Avenue 148 to Avenue 150	1/25/2016	1/25/2016	
	Doyle Colony	Repair road surface by hot patching	Crabtree at Rocky Hill	2/10/2016	2/10/2016	
	Doyle Colony	Repair road surface by hot patching	Roby east of Rocky Hill	2/10/2016	2/10/2016	
	Doyle Colony	Repair potholes with Road Patcher	River at Leggett	2/11/2016	2/11/2016	
	Doyle Colony	Repair road surface by hot patching	Avenue 146 at Mountain Road 246	2/22/2016	2/22/2016	
	Doyle Colony	Repair road surface by hot patching	Ruth at Roby	2/22/2016	2/22/2016	
	Doyle Colony	Repair road surface by hot patching	Orange at Ruth	2/22/2016	2/22/2016	
	Doyle Colony	Repair road surface by hot patching	River from Leggett to Ruth	2/22/2016	2/23/2016	
	Doyle Colony	Repair road surface by hot patching	Conner at Roby	2/22/2016	2/23/2016	
	Doyle Colony	Repair road surface by hot patching	Richard at Bennett	2/23/2016	2/23/2016	
	Doyle Colony	Repair road surface by hot patching	Alta Vista at Crabtree	2/23/2016	2/23/2016	
	Doyle Colony	Repair road surface by hot patching	Conner at Roby	2/23/2016	2/23/2016	
	Doyle Colony	Repair road surface by hot patching	Crabtree from Holcomb to Tulsa	2/23/2016	2/23/2016	
	Doyle Colony	Repair road surface by hot patching	River from Leggett to Ruth	2/23/2016	2/23/2016	
	Doyle Colony	Repair potholes with Road Patcher	South "W" from Roby to End	3/14/2016	3/14/2016	
	Doyle Colony	Repair potholes with Road Patcher	Roby at South "W"	3/14/2016	3/14/2016	
	Doyle Colony	Repair road surface by hot patching	Park from Success to Corona	3/22/2016	3/22/2016	
	Doyle Colony	Repair road surface by hot patching	Alta Vista from Crabtree to Roby	3/25/2016	3/25/2016	
	Doyle Colony	Repair road surface by hot patching	Avenue 146 at 27378	3/29/2016	3/29/2016	
	Doyle Colony	Repair road surface by hot patching	Crabtree from Holcomb to Rocky Hill	3/31/2016	3/31/2016	
	Doyle Colony	Repair road surface by hot patching	Roby at Ruth	3/31/2016	3/31/2016	\$ 2,927.61

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Earlimart	Repair road surface by hand patching	Avenue 56 Overpass at State Highway 99	1/21/2016	1/21/2016	\$ 973.29
Earlimart	Repair road surface by hand patching	Tulare Avenue from Elm Street to Church Street	2/8/2016	2/8/2016	
Earlimart	Repair road surface by hand patching	Avenue 56 Overpass at State Highway 99	2/11/2016	2/11/2016	
Earlimart	Repair road surface by hand patching	Church, Armstrong to Washington	2/18/2016	2/18/2016	
Earlimart	Repair road surface by hand patching	Market from Avenue 48 to Kelly	2/18/2016	2/18/2016	
Earlimart	Repair road surface by hand patching	Market from Franklin to Avenue 48	2/19/2016	2/19/2016	
Earlimart	Repair road surface by hand patching	Clay from Market to Front	2/19/2016	2/19/2016	
Earlimart	Repair road surface by hand patching	Front North of Clay	2/19/2016	2/19/2016	
East Oroquieta	Repair road surface by hand patching	Road 144 at Avenue 416	2/8/2016	2/8/2016	\$ 1,977.47
East Oroquieta	Repair road surface by hand patching	Road 144 from Avenue 424 to Avenue 428	2/8/2016	2/8/2016	
East Oroquieta	Repair road surface by hand patching	Holister from Avenue 418 to Avenue 419	2/16/2016	2/16/2016	
East Oroquieta	Repair road surface by hand patching	Ione at Avenue 418	2/16/2016	2/16/2016	
East Oroquieta	Repair road surface by hand patching	Hollister Road from Avenue 418 to Idaho	2/17/2016	2/17/2016	
East Oroquieta	Repair road surface by hand patching	Road 139 from Avenue 418 to Avenue 417	2/17/2016	2/17/2016	
East Oroquieta	Repair road surface by hand patching	Avenue 416 West of Fruitvale	2/18/2016	2/18/2016	
East Oroquieta	Repair road surface by hand patching	Road 136 at Avenue 416	3/17/2016	3/17/2016	
East Oroquieta	Repair road surface by hand patching	Avenue 422 from State Highway 63 to Road 136	3/18/2016	3/18/2016	
East Oroquieta	Repair road surface by hand patching	Avenue 416 from State Highway 63 to Road 168	3/18/2016	3/18/2016	
Goshen	Repair road surface by hand patching	Betty Drive at Overpass	1/20/2016	1/20/2016	\$ 2,833.55
Goshen	Repair road surface by hand patching	Road 68 at Avenue 304	1/21/2016	1/21/2016	
Goshen	Repair road surface by hand patching	Avenue 308 from Road 64 to Road 62	1/22/2016	1/22/2016	
Goshen	Repair road surface by hand patching	Avenue 304 at Road 68	1/22/2016	1/22/2016	
Goshen	Repair road surface by hand patching	Route 64 South of Avenue 308	1/22/2016	1/22/2016	
Goshen	Repair road surface by hand patching	Road 52 from Avenue 304 to Avenue 308	2/9/2016	2/9/2016	
Goshen	Repair road surface by hand patching	Diagonal 69 from Avenue 304 to Avenue 305	2/9/2016	2/9/2016	
Goshen	Repair road surface by hand patching	Road 88 from Avenue 304 to the End	2/11/2016	2/11/2016	
Goshen	Repair road surface by hand patching	Road 76 from Avenue 304 to Avenue 308	2/11/2016	2/11/2016	
Goshen	Repair road surface by hand patching	Road 60 From Avenue 308 to Avenue 320	2/16/2016	2/16/2016	
Goshen	Repair road surface by hand patching	Avenue 308 West of Road 64	2/16/2016	2/16/2016	
Goshen	Repair road surface by hand patching	Road 76 from Avenue 304 to Avenue 308	2/19/2016	2/19/2016	
Goshen	Repair road surface by hand patching	Betty Drive 500 feet East of State Highway 99	2/23/2016	2/23/2016	
Goshen	Repair road surface by hand patching	Avenue 304 from Road 44 to Road 68	2/29/2016	2/29/2016	
Goshen	Repair road surface by hand patching	Road 64 from Avenue 304 to Avenue 308	3/1/2016	3/1/2016	
Goshen	Repair road surface by hand patching	Road 64 from Avenue 304 to Avenue 298	3/1/2016	3/1/2016	
Goshen	Repair road surface by hand patching	Road 68 from Avenue 304 to Avenue 306	3/17/2016	3/17/2016	
Goshen	Repair road surface by hand patching	Road 68 at Avenue 304	3/17/2016	3/17/2016	
Goshen	Repair road surface by hand patching	Road 70 at Avenue 310	3/18/2016	3/18/2016	
Ivanhoe	Repair road surface by hand patching	Depot Avenue from Road 159 to Road 160	1/12/2016	1/12/2016	\$ 399.54
Ivanhoe	Repair road surface by hand patching	Azalea Avenue from Road 159 to Road 16	1/29/2016	1/29/2016	
Ivanhoe	Repair road surface by hand patching	Road 158 from Aspen to Beechwood	2/18/2016	2/18/2016	
Ivanhoe	Repair road surface by hand patching	Fuschia East of Road 158	2/18/2016	2/18/2016	
Ivanhoe	Repair road surface by hand patching	Manzeita from Fuschia to Avenue 328	2/18/2016	2/18/2016	
Ivanhoe	Repair road surface by hand patching	Road 159 at Azalea	2/24/2016	2/24/2016	
Lindcove	Repair road surface by hot patching	Road 224 at Avenue 312	1/28/2016	1/28/2016	\$ 1,726.99
Lindcove	Repair road surface by hot patching	Road 226 at Avenue 312	1/28/2016	1/28/2016	
Lindcove	Repair road surface by hot patching	Avenue 312 at Road 220	1/28/2016	1/28/2016	
Lindcove	Repair road surface by hot patching	Road 226 from Avenue 314 to Avenue 315	1/29/2016	1/29/2016	
Lindcove	Repair road surface by hot patching	Road 236 south of Avenue 234	3/10/2016	3/10/2016	
Lindcove	Repair road surface by hot patching	Road 248 north of Avenue 334	3/10/2016	3/10/2016	\$ 1,726.99

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

Local Programs

London	Repair road surface by hand patching	Kate from Avenue 376 to Avenue 378	1/20/2016	1/20/2016	
London	Repair road surface by hand patching	Avenue 378 from Road 58 to Road 60	1/20/2016	1/20/2016	
London	Repair road surface by hand patching	Kate from Denver Avenue to Avenue 378	1/21/2016	1/21/2016	
London	Repair road surface by hand patching	Road 60 at Denver Ave	2/11/2016	2/11/2016	\$ 279.74
Monson	Repair road surface by hand patching	Monson Drive from Avenue 384 to Avenue 388	1/22/2016	1/22/2016	
Monson	Repair road surface by hand patching	Avenue 388 at Monson Drive	2/8/2016	2/8/2016	
Monson	Repair road surface by hand patching	Monson Drive West of Avenue 388	2/16/2016	2/16/2016	
Monson	Repair road surface by hand patching	Road 104 North of Avenue 388	2/16/2016	2/16/2016	
Monson	Repair road surface by hand patching	Monson Drive from Road 104 to Avenue 384	3/24/2016	3/24/2016	\$ 510.79
Orosi	Repair road surface by hand patching	Ralph North of Avenue 416	1/22/2016	1/22/2016	
Orosi	Repair road surface by hand patching	Miller Avenue from Road 126 to State Highway 63	1/29/2016	1/29/2016	
Orosi	Repair road surface by hand patching	Road 130 at Avenue 414	1/29/2016	1/29/2016	
Orosi	Repair road surface by hand patching	Avenue 414 West of Road 130	1/29/2016	1/29/2016	
Orosi	Repair road surface by hand patching	Ella from Road 128 to Road 130	2/2/2016	2/2/2016	
Orosi	Repair road surface by hand patching	Road 130 from Avenue 419 to Miller	2/2/2016	2/2/2016	
Orosi	Repair road surface by hand patching	Avenue 412 from St 63 to Road 152`	2/3/2016	2/3/2016	
Orosi	Repair road surface by hand patching	Road 130 from Avenue 416 to Avenue 419	3/17/2016	3/17/2016	
Orosi	Repair road surface by hand patching	Avenue 415 at State Highway 63	3/17/2016	3/17/2016	
Orosi	Repair road surface by hand patching	Road 126 from Ella to Avenue 414	3/17/2016	3/17/2016	
Orosi	Repair road surface by hand patching	Avenue 413 from Road 124 to State Highway 63	3/29/2016	3/29/2016	\$ 814.28
Pixley	Large area Patching with grader "Blade Patch"	Haul Material Avenue 96 from Cedar to Road 120	3/23/2016	3/23/2016	
Pixley	Repair road surface by hand patching	Market at Davis	2/25/2016	2/25/2016	
Pixley	Repair road surface by hand patching	Court from Pine to School	2/25/2016	2/25/2016	
Pixley	Repair road surface by hand patching	Bradbury to Market	2/25/2016	2/25/2016	
Pixley	Repair road surface by hand patching	Center from Bradbury to Market	2/25/2016	2/25/2016	
Pixley	Repair road surface by hand patching	Franklin at Center	2/25/2016	2/25/2016	
Pixley	Repair road surface by hand patching	Elm from Howard to Court	2/25/2016	2/25/2016	
Pixley	Repair road surface by hand patching	Ash from Court to Bradbury	2/26/2016	2/26/2016	
Pixley	Repair road surface by hand patching	Compton from Road 120 to Market	2/26/2016	2/26/2016	
Pixley	Repair road surface by hand patching	Ellsworth from Ash to Market	2/26/2016	2/26/2016	
Pixley	Repair road surface by hand patching	Davis from Ash to Market	2/26/2016	2/26/2016	
Pixley	Repair road surface by hand patching	Road 120 from Compton to Market	2/26/2016	2/26/2016	
Pixley	Repair road surface by hand patching	Avenue 96 from Airport to Main	2/26/2016	2/26/2016	
Pixley	Repair road surface by hand patching	Davis from Pine to Maple	2/26/2016	2/26/2016	
Pixley	Repair road surface by hand patching	Main from Compton to Center	2/29/2016	2/29/2016	
Pixley	Repair road surface by hand patching	Road 128 from Avenue 96 to State Highway 99	2/29/2016	2/29/2016	
Pixley	Repair road surface by hand patching	Road 120 from Avenue 96 to Avenue 80	3/9/2016	3/9/2016	
Pixley	Repair road surface by hand patching	Road 120 from Avenue 96 to Avenue 120	3/10/2016	3/10/2016	
Pixley	Repair road surface by hand patching	691 Joanne	3/10/2016	3/10/2016	
Pixley	Large area Patching with grader "Blade Patch"	Avenue 96 from Road 120 to Ash	3/23/2016	3/25/2016	
Pixley	Large area Patching with grader "Blade Patch"	Road 120 from Avenue 96 to Compton	3/23/2016	3/25/2016	
Pixley	Large area patching with grader "Blade Patch"	Haul material for District 2	3/23/2016	3/23/2016	\$ 37,840.66
Plainview	Repair potholes with Road Patcher	Avenue 208 west of Road 196	2/9/2016	2/9/2016	
Plainview	Repair potholes with Road Patcher	Road 228 at Avenue 184	2/29/2016	2/29/2016	
Plainview	Repair potholes with Road Patcher	Road 204 from Avenue 200 to Avenue 204	2/29/2016	2/29/2016	
Plainview	Repair potholes with Road Patcher	Road 204 from Avenue 204 to Avenue 208	2/29/2016	3/3/2016	\$ 901.12

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Porterville	Repair road surface by hot patching	Road 254 at Mulberry	1/12/2016	1/12/2016	
Porterville	Repair road surface by hot patching	Diagonal 242 from Avenue 169 to Avenue 170	1/14/2016	1/14/2016	
Porterville	Repair road surface by hot patching	Avenue 170 at Friant Kern Canal	1/14/2016	1/14/2016	
Porterville	Repair road surface by hot patching	Jaye from Westfield to Mulberry	2/22/2016	2/22/2016	
Porterville	Repair road surface by hot patching	G Street from Porterville City Limits to Mulberry	3/11/2016	3/11/2016	
Porterville	Repair road surface by hot patching	Roby from Newcomb to Cobb	3/14/2016	3/14/2016	
Porterville	Repair road surface by hot patching	Cobb from Olive to Roby	3/15/2016	3/15/2016	
Porterville	Repair road surface by hot patching	Mulberry from G Street to Jaye	3/16/2016	3/16/2016	
Porterville	Repair road surface by hot patching	Roby from Cobb to Slaughter	3/18/2016	3/18/2016	\$ 1,689.81
Strathmore	Repair road surface by hot patching	LR213A (Richardson) from Avenue 196 to Avenue 194	1/14/2016	1/14/2016	
Strathmore	Repair road surface by hot patching	Road 248 from Avenue 204 to Avenue 208	1/14/2016	1/14/2016	
Strathmore	Repair road surface by hot patching	Avenue 208 west of Road 248	1/14/2016	1/14/2016	
Strathmore	Repair road surface by hot patching	Avenue 231 at Lawson	1/15/2016	1/15/2016	
Strathmore	Repair road surface by hot patching	Avenue 231 from Diagonal 242 to Road 230	1/15/2016	1/15/2016	
Strathmore	Repair road surface by hot patching	Avenue 195 at Road 230	1/15/2016	1/15/2016	
Strathmore	Repair road surface by hot patching	Avenue 195 west of Road 234	1/15/2016	1/15/2016	
Strathmore	Repair road surface by hot patching	Rea Road at Avenue 194	1/15/2016	1/15/2016	
Strathmore	Repair road surface by hot patching	Road 224 from Avenue 196 to Avenue 200	1/15/2016	1/15/2016	
Strathmore	Repair road surface by hot patching	Avenue 200 at Road 228	1/27/2016	1/27/2016	
Strathmore	Repair road surface by hot patching	Road 232 at Avenue 196	2/2/2016	2/2/2016	
Strathmore	Repair road surface by hot patching	Avenue 196 at Friant Kern Canal	2/2/2016	2/2/2016	
Strathmore	Repair road surface by hot patching	Avenue 200 west of Diagonal 242	2/17/2016	2/22/2016	
Strathmore	Repair road surface by hot patching	Road 228 at Avenue 200	2/17/2016	2/17/2016	
Strathmore	Repair road surface by hot patching	Road 236 from Avenue 196 to Avenue 200	2/29/2016	2/29/2016	
Strathmore	Repair road surface by hot patching	Road 232 from Avenue 192 to Avenue 194	2/29/2016	2/29/2016	
Strathmore	Repair road surface by hot patching	Avenue 196 from Road 232 to Road 234	2/29/2016	2/29/2016	
Strathmore	Repair road surface by hot patching	Lawson at Strathmore Post Office	3/2/2016	3/2/2016	
Strathmore	Repair road surface by hot patching	Avenue 204 at Road 222	3/3/2016	3/3/2016	
Strathmore	Repair road surface by hot patching	Avenue 184 at Diagonal 242	3/11/2016	3/11/2016	
Strathmore	Repair potholes with Road Patcher	Avenue 216 from Diagonal 242 to Road 228	3/14/2016	3/14/2016	
Strathmore	Repair potholes with Road Patcher	Avenue 208 from Road 228 to Road 236	3/14/2016	3/14/2016	
Strathmore	Repair road surface by hot patching	Avenue 208 from Diagonal 242 to Road 256	3/16/2016	3/16/2016	\$ 3,580.12
Sultana	Repair road surface by hand patching	Avenue 416 West of Perkins	1/22/2016	1/22/2016	\$ 35.52
Teviston	Repair road surface by hand patching	Avenue 76 from Road 126 to Road 130	2/29/2016	2/29/2016	
Teviston	Repair road surface by hand patching	Avenue 72 from Road 136 to Road 128	3/15/2016	3/15/2016	
Teviston	Repair road surface by hand patching	Avenue 76 from Road 136 to Road 128	3/15/2016	3/15/2016	
Teviston	Repair road surface by hand patching	Avenue 80 from Road 128 to Road 136	3/15/2016	3/15/2016	
Teviston	Repair road surface by hand patching	Road 134 From Avenue 80 to the End	3/15/2016	3/15/2016	\$ 659.11
Three Rivers	Repair road surface by hand patching	Mountain Road 348 from Mile Post 8 to Mile Post 9	3/1/2016	3/1/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 348 from Mile Post 7.5 to Mile Post 8	3/2/2016	3/2/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 375 from Mile Post 1 to Mile Post 3 at Hammond	3/15/2016	3/15/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 375 from Mile Post 3 to Mile Post 6	3/16/2016	3/16/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 375 from Mile Post 5 to Mile Post 8	3/17/2016	3/17/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 375 from Mile Post 5 to Mile Post 7	3/17/2016	3/17/2016	
Three Rivers	Repair road surface by hand patching	Cherokee Oak from Skyline to End	3/18/2016	3/18/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 357 from Mile Post 0 to Mile Post 3	3/18/2016	3/18/2016	
Three Rivers	Repair road surface by hand patching	Cherokee Oak at Grouse	3/18/2016	3/18/2016	\$ 3,514.36
Tipton	Repair road surface by hand patching	Callison Road from Avenue 144 to Avenue 152	2/10/2016	2/10/2016	
Tipton	Repair road surface by hand patching	Burnett Road from Avenue 152 to Avenue 144	2/10/2016	2/10/2016	
Tipton	Repair road surface by hand patching	West Woods East of Burnett Road	2/10/2016	2/10/2016	
Tipton	Repair road surface by hand patching	Thompson Road From Olive Avenue to Klindera Avenue	3/23/2016	3/23/2016	
Tipton	Repair road surface by hand patching	Jayne Road from Evans Avenue to Thompson Road	3/23/2016	3/23/2016	\$ 639.72

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Tonyville	Repair road surface by hot patching	Road 212 south of Avenue 256	1/29/2016	2/10/2016	
Tonyville	Repair road surface by hot patching	Road 216 south of Avenue 264	1/29/2016	1/29/2016	
Tonyville	Repair road surface by hot patching	Road 212 north of Avenue 256	2/11/2016	2/11/2016	
Tonyville	Repair road surface by hot patching	Road 204 at Friant Kern Canal	2/18/2016	2/26/2016	
Tonyville	Large area patching with grader "Blade Patch"	Road 204 at Friant Kern Canal	2/29/2016	3/4/2016	
Tonyville	Repair road surface by hot patching	Avenue 256 at Road 204	3/3/2016	3/3/2016	
Tonyville	Moving Equipment	Road 204 at Friant Kern Canal to Yard 1	3/9/2016	3/9/2016	
Tonyville	Large area patching with grader "Blade Patch"	Avenue 268 west of Friant Kern Canal	3/11/2016	4/1/2016	
Tonyville	Repair potholes with Road Patcher	Road 208 at Avenue 256	3/15/2016	3/15/2016	
Tonyville	Repair potholes with Road Patcher	Avenue 256 from Road 208 to Road 212	3/15/2016	3/15/2016	
Tonyville	Repair road surface by hot patching	Avenue 244 at Road 204	4/1/2016	4/1/2016	\$ 21,248.82
Tooleville	Repair road surface by hot patching	Road 204 at (LA274C) Alfred	1/28/2016	1/28/2016	
Tooleville	Repair potholes with Road Patcher	Avenue 276 from Exeter City Limits to Road 204	2/10/2016	2/10/2016	
Tooleville	Repair potholes with Road Patcher	Road 208 from Avenue 200 to Avenue 204	2/22/2016	3/3/2016	
Tooleville	Repair potholes with Road Patcher	Avenue 264 from Road 204 to Road 212	3/15/2016	3/15/2016	
Tooleville	Repair potholes with Road Patcher	Avenue 288 from Road 196 to Road 204	3/16/2016	3/16/2016	
Tooleville	Large area patching with grader "Blade Patch"	Road 204 at Friant Kern Canal (completed 4/7/16)	3/25/2016	4/1/2016	\$ 6,015.87
Traver	Repair road surface by hand patching	Zantz Drive at Merritt Drive	1/15/2016	1/15/2016	
Traver	Repair road surface by hand patching	Merritt at State 99 Overpass	1/20/2016	1/20/2016	
Traver	Repair road surface by hand patching	Merritt at Burke	2/4/2016	2/4/2016	
Traver	Repair road surface by hand patching	Burke South of Merritt Drive	2/11/2016	2/11/2016	
Traver	Repair road surface by hand patching	Burke from Merritt to Ave 360	3/23/2016	3/23/2016	
Traver	Repair road surface by hand patching	Avenue 360 at Burke	3/24/2016	3/24/2016	\$ 1,826.82
Waukena	Repair road surface by hand patching	Road 28 From Avenue 199 to Avenue 196	3/4/2016	3/4/2016	\$ 261.78
West Exeter	Repair road surface by hot patching	Road 188 from Avenue 256 to Avenue 269	1/12/2016	1/12/2016	
West Exeter	Large area patching with grader "Blade Patch"	Road 188 south of Avenue 288	1/13/2016	1/15/2016	
West Exeter	Repair road surface by hot patching	Avenue 268 at Road 200	1/15/2016	1/15/2016	
West Exeter	Repair road surface by hot patching	Avenue 264 from Road 176 to Road 180	1/28/2016	1/28/2016	
West Exeter	Repair potholes with Road Patcher	Avenue 269 from Road 188 to Road 192	1/29/2016	2/10/2016	
West Exeter	Repair road surface by hot patching	Avenue 312 east of Lort Drive	2/10/2016	2/11/2016	
West Exeter	Repair road surface by hot patching	Road 212 north of Avenue 256	2/11/2016	2/11/2016	
West Exeter	Repair road surface by hot patching	Avenue 264 from Road 180 to Road 192	2/12/2016	2/12/2016	
West Exeter	Repair road surface by hot patching	Avenue 264 at Road 180	2/12/2016	2/12/2016	
West Exeter	Repair road surface by hot patching	Avenue 272 from Road 192 to Exeter City Limits	3/2/2016	3/2/2016	\$ 3,134.21

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
<b>Rural Roads</b>	Rural Roads	Repair road surface by hand patching	Road 204 at Friant Kern Canal	12/29/2015	2/2/2016	
	Rural Roads	Repair road surface by hand patching	Mountain Road 453 from Diagonal 243 to Mile Post 3	12/30/2015	12/30/2015	
	Rural Roads	Repair road surface by hand patching	Diagonal 243 from Mile Post 1 to State Highway 245	12/30/2015	12/30/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 178 from Road 180 to Diagonal 184B	12/30/2015	12/30/2015	
	Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 178 to Avenue 184	12/30/2015	12/30/2015	
	Rural Roads	Repair road surface by hand patching	View Drive from Road 136 to Road 140	12/31/2015	12/31/2015	
	Rural Roads	Repair road surface by hand patching	Avenue 188 from Diagonal 229 to Road 232	12/31/2015	12/31/2015	
	Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 160 to Avenue 164	12/31/2015	12/31/2015	
	Rural Roads	Repair road surface by hand patching	Road 208 north of Avenue 176	12/31/2015	12/31/2015	
	Rural Roads	Repair road surface by hand patching	Road 156 North of Avenue 288	1/4/2016	1/4/2016	
	Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 280 to Avenue 256	1/4/2016	1/4/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 140 to Road 164	1/4/2016	1/4/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 264 from Road 100 to State Highway 99	1/4/2016	1/4/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 256 at Road 92	1/4/2016	1/4/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 240 from Road 140 to Road 168	1/4/2016	1/4/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 216 at Road 228	1/4/2016	1/4/2016	
	Rural Roads	Repair road surface by hand patching	Road 108 at Avenue 328	1/12/2016	1/12/2016	
	Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 416 to Avenue 432	1/12/2016	1/12/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 426 from Road 62 to Road 64	1/12/2016	1/12/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 160 at Road 208	1/12/2016	1/12/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 300 from Road 196 at Road 204	1/12/2016	1/12/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 430 at Road 68	1/13/2016	1/13/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 448 from Road 120 to Road 124	1/13/2016	1/13/2016	
	Rural Roads	Repair road surface by hand patching	Road 248 at Avenue 212	1/14/2016	1/14/2016	
	Rural Roads	Repair road surface by hand patching	Road 232 from Avenue 216 to Avenue 220	1/14/2016	1/14/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 220 west of Road 232	1/14/2016	1/14/2016	
	Rural Roads	Repair road surface by hand patching	Road 180 at Avenue 200	1/14/2016	1/14/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 304 at Lort Drive	1/15/2016	1/15/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 220 to Road 224	1/15/2016	1/15/2016	
	Rural Roads	Haul Material	Porterville Asphalt to 368 Pit and Rankin Pit	1/19/2016	1/19/2016	
	Rural Roads	Haul Patching Material	From Porterville to Avenue 368 Pit	1/19/2016	1/19/2016	
	Rural Roads	HAUL PLANT RUN FOR MEASURE R WORK	Porterville Rock to Avenue 368 Pit	1/19/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Haul Patch Material	1/19/2016	1/19/2016	
	Rural Roads	Haul Material	Mitch Brown to 112 Pit and Yard 1	1/20/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Road 8 from Avenue 384 to Avenue 392	1/20/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Road 108 from Avenue 328 to Avenue 320	1/20/2016	1/20/2016	
	Rural Roads	Haul Patching Material	From Road 289 to Road 112	1/20/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Road 92 from Gail Street to Avenue 248	1/20/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 240 West of Road 92	1/20/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 92 to Road 80	1/20/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Haul Patch Material	1/20/2016	1/20/2016	
	Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 50 to End	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 376 from State Highway 245 to Road 204	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 320	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 360 to Avenue 368	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Road 108 from Avenue 320 to Avenue 328	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 384 at State 99 Overpass	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Road 84 from Avenue 384 to Avenue 368	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 96 from Main Street to Road 120	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Road 120 North of Avenue 96	1/21/2016	1/21/2016	
	Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 216 to State Highway 99	1/21/2016	1/21/2016	

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair road surface by hand patching	Road 112 North of Avenue 184	1/21/2016	1/21/2016
Rural Roads	Repair potholes with Road Patcher	Road 204 from Avenue 188 to Avenue 192	1/21/2016	1/21/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 108 to Road 100	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 112 to Road 120	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 152	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Road 136 from Avenue 320 to Avenue 428	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 322 at Road 136	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 184 West of Road 96	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Road 56 from State Highway 43 to the West	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Road 138 at Avenue 54	1/22/2016	1/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 95 from Road 236 to Road 238	1/25/2016	1/25/2016
Rural Roads	Repair road surface by hand patching	Road 244 from Avenue 80 to Avenue 76	1/25/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 224 to Tule River Bridge	1/25/2016	1/25/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 200 from Road 180 to Road 192	1/25/2016	1/26/2016
Rural Roads	Repair potholes with Road Patcher	Road 224 from Avenue 188 to Avenue 192	1/25/2016	1/26/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 212 from Road 226 to Road 232	1/25/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Avenue 80 from Road 228 to Road 232	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Road 228 from Avenue 80 to Avenue 88	1/26/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Road 72 from Avenue 428 to Avenue 428	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Road 64 North of Avenue 478	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 376 at Road 204	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Road 204 from Avenue 376 to Avenue 380	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 376 East of Road 204	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Road 172 at Cottonwood Creek	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 200 to Avenue 208	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 174 at Friant Kern Canal	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 174 from Highway 65 to Road 232	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Road 204 from Avenue 256 to Avenue 264	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 188 at Road 224	1/26/2016	1/26/2016
Rural Roads	Repair road surface by hand patching	Road 192 from Avenue 168 to Avenue 8	1/27/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Road 232 from Avenue 80 to Avenue 88	1/27/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Road 72 from Avenue 430 to Avenue 424	1/27/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Avenue 426 from Road 64 to Road 62	1/27/2016	1/27/2016
Rural Roads	HAUL PLANT RUN FOR MEASURE R WORK	Rankin Pit to Pixley Road Yard 2	1/27/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Avenue 288 East of Road 156	1/27/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Avenue 280 at Road 156	1/27/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Avenue 144 from Road 112 to Road 72	1/27/2016	1/27/2016
Rural Roads	Repair potholes with Road Patcher	Road 228 from Avenue 196 to Avenue 200	1/27/2016	1/27/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 200 to Road 228	1/27/2016	1/27/2016
Rural Roads	Repair road surface by hand patching	Road 192 from Avenue 8 to Avenue 112	1/28/2016	1/28/2016
Rural Roads	Repair road surface by hand patching	Avenue 288 West of Road 180	1/28/2016	1/28/2016
Rural Roads	Repair road surface by hand patching	Road 158 from Avenue 296 to State Highway 216	1/28/2016	1/28/2016
Rural Roads	Repair road surface by hand patching	Mountain 137 at Mile Post 7.5	1/29/2016	1/29/2016
Rural Roads	Repair road surface by hand patching	Road 144 North of Saint Johns	1/29/2016	1/29/2016
Rural Roads	Repair road surface by hand patching	Road 156 South of Avenue 376	1/29/2016	1/29/2016
Rural Roads	Repair road surface by hand patching	Avenue 264 at Road 100	1/29/2016	1/29/2016
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 272 to Avenue 276	1/29/2016	1/29/2016
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 312 to Avenue 320	1/29/2016	1/29/2016
Rural Roads	Repair road surface by hand patching	Road 256 south of Lynch	1/29/2016	1/29/2016
Rural Roads	Repair potholes with Road Patcher	Road 188 south of Avenue 216	1/29/2016	1/29/2016
Rural Roads	Repair potholes with Road Patcher	Road 188 south of Avenue 232	1/29/2016	1/29/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 264 to Avenue 280	2/1/2016	2/1/2016
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 280 to Avenue 272	2/1/2016	2/1/2016
Rural Roads	Repair road surface by hand patching	Beacon from Road 96 to Luton Street	2/1/2016	2/1/2016

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 200 to Avenue 208	2/1/2016	2/1/2016
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 108 to Road 80	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 424 at Road 108	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 128 from Road 136 to Road 144	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 280 at Road 156	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 288 at Road 156	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 192 to Avenue 200	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 320 West of Road 100	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 144 East of State Highway 43	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Road 96 South of Avenue 120	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 256 to Farmersville City Limits	2/2/2016	2/2/2016
Rural Roads	Repair road surface by hand patching	Diagonal 205 from Avenue 8 to Avenue 0	2/3/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 360 to Avenue 364	2/3/2016	2/3/2016
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 140 to Road 156	2/3/2016	2/3/2016
Rural Roads	Repair road surface by hand patching	Road 100 at Avenue 272	2/3/2016	2/3/2016
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 96 to Road 24	2/3/2016	2/3/2016
Rural Roads	Repair road surface by hand patching	Avenue 264 from Road 100 to State Highway 99	2/3/2016	2/3/2016
Rural Roads	Repair road surface by hand patching	Road 212 from Avenue 256 to Avenue 245	2/3/2016	2/3/2016
Rural Roads	Repair road surface by hand patching	Diagonal 205 from Avenue 8 to Avenue 16	2/4/2016	2/5/2016
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 236 to Clemens	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Avenue 384 at Road 120	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Avenue 340 from Avenue 220 to Avenue 228	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Road 220 at 34172	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 328 to Avenue 320	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Avenue 144 from Burnett to State Highway 43	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 104 to Avenue 96	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Avenue 200 from Spacer Drive to State Highway 99	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Avenue 178 at Road 232	2/4/2016	2/4/2016
Rural Roads	Repair road surface by hand patching	Mountain 137 from Mile Post 4 to Mile Post 8	2/5/2016	2/5/2016
Rural Roads	Repair road surface by hand patching	Avenue 344 at Road 156	2/5/2016	2/5/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 344 to Avenue 352	2/5/2016	2/5/2016
Rural Roads	Repair road surface by hand patching	Road 156 North of Avenue 288	2/5/2016	2/5/2016
Rural Roads	Repair road surface by hand patching	Road 100 from Avenue 264 to Avenue 272	2/5/2016	2/5/2016
Rural Roads	Repair road surface by hand patching	Avenue 304 from Effie Drive to Road 68	2/5/2016	2/5/2016
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 152 to Avenue 160	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Road 224 from Avenue 0 to Avenue 8	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Road 234 at 9568 Road 234	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 56 east of Road 208	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 56 from Road 236 to Road 240	2/8/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 92 at Road 264	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 80 from Road 192 to Road 205	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Road 8 from Avenue 388 to Avenue 392	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 96 to Avenue 92	2/8/2016	2/8/2016
Rural Roads	Repair potholes with Road Patcher	Road 188 from Avenue 256 to Avenue 264	2/8/2016	2/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 80 from Road 192 to Road 208	2/9/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 56 to Avenue 88	2/9/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Road 197 from Avenue 368 to Avenue Avenue 360	2/9/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 188 to Road 196	2/9/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 340 from Road 222 to Road 228	2/9/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 328 to Avenue 336	2/9/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 128 to Road 140	2/9/2016	2/9/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 208 west of Road 196	2/9/2016	2/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 80 from Road 184 to Road 208	2/10/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Road 200 from Avenue 144 to Avenue 152	2/10/2016	2/10/2016



**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair road surface by hand patching	Avenue 64 from Road 144 to Road 152	2/10/2016	2/10/2016
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 128 to Road 156	2/10/2016	2/10/2016
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 74 to Road 68	2/10/2016	2/10/2016
Rural Roads	Repair road surface by hand patching	Road 76 South of Avenue 216	2/10/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Avenue 224 west of Diagonal 242	2/10/2016	2/10/2016
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 32 to Road 28	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Road 48 from Ave 432 to Ave 416	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Road 24 from Avenue 424 to Avenue 416	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Avenue 428 from Road 48 to Road 44	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Road 74 from Avenue 384 to Avenue 400	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Avenue West of Road 80	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Avenue 16 West of Road 128	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 96 to Avenue 72	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Road 128 North of Avenue 72	2/11/2016	2/11/2016
Rural Roads	HAUL PLANT RUN FOR MEASURE R WORK	Rankin Pit to Pixley Road Yard	2/11/2016	2/11/2016
Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to End	2/12/2016	3/23/2016
Rural Roads	Repair road surface by hand patching	Avenue 64 from Road 144 to Road 168	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Avenue 64 from Road 224 to Road 232	2/12/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 136 at Avenue 400	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 324 to Avenue 332	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 80 to Road 64	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 160 to Avenue 176	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 48 to Road 46	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Road 46 from Avenue 228 to Avenue 230	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 228 to Avenue 232	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 60 to Road 52	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 240 to Avenue 264	2/12/2016	2/12/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 184 east of Road 152	2/12/2016	2/12/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 188 from Road 152 to Road 168	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Harvard at Diagonal 242	2/12/2016	2/12/2016
Rural Roads	Repair road surface by hand patching	Road 234 from Avenue 80 to Avenue 88	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Road 232 from Avenue 80 to Avenue 64	2/16/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 96 to Avenue 8	2/16/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Drive 118 from Avenue 400 to Road 120	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 388 West of Road 120	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 388 to Avenue 392	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 228 to Avenue 232	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 192 to Avenue 164	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Road 126 North of Avenue 232	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 232 to Avenue 280	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 280 from Road 140 to Farmersville City Limits	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 288 from Road 148 to Farmersville City Limits	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	K Road from Road 128 to Road 132	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 264 from State Highway 99 to Visalia City Limits	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Road 100 from Avenue 264 to Visalia City Limits	2/16/2016	2/16/2016
Rural Roads	Repair potholes with Road Patcher	Road 204 from Avenue 200 to Avenue 204	2/16/2016	2/16/2016
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 50 to MP22.5	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Road 168 at El Rio	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 84 to Road 52	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Road 60 at Avenue 308	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 60 to Road 52	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 320 to Avenue 310	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 88 to Avenue 120	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 96 to Road 80	2/17/2016	2/17/2016

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair road surface by hand patching	Road 120 North of Avenue 96	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Road 224 south of Avenue 188	2/17/2016	2/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 56 from Road 256 to Road 272	2/18/2016	2/18/2016
Rural Roads	Repair road surface by hand patching	Road 144 at Saint John	2/18/2016	2/18/2016
Rural Roads	Repair road surface by hand patching	Road 168 at Avenue 315	2/18/2016	2/18/2016
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 96 to Avenue 54	2/18/2016	2/18/2016
Rural Roads	Repair potholes with road patcher	Avenue 224 from Road 140 to Road 132	2/18/2016	2/18/2016
Rural Roads	Repair potholes with road patcher	Road 128 from Avenue 192 to Avenue 160	2/18/2016	2/18/2016
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 400	2/19/2016	2/19/2016
Rural Roads	Repair road surface by hand patching	Avenue 376 at Road 204	2/19/2016	2/19/2016
Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 336 to Charter Oak	2/19/2016	2/19/2016
Rural Roads	Repair road surface by hand patching	Charter Oak from Road 188 to Road 180	2/19/2016	2/19/2016
Rural Roads	Repair road surface by hand patching	Road 180 at Fisher	2/19/2016	2/19/2016
Rural Roads	Repair road surface by hand patching	Avenue 320 West of Road 196	2/19/2016	2/19/2016
Rural Roads	Repair road surface by hand patching	Avenue 344 at Road 172	2/19/2016	2/19/2016
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 36 from Road 52	2/22/2016	2/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 216 West of Road 84	2/22/2016	2/22/2016
Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 216 to Avenue 228	2/22/2016	2/22/2016
Rural Roads	RE-LAY WITH PLANT RUN MATERIAL	K Road from Road 128 to Road 132	2/22/2016	2/25/2016
Rural Roads	Haul Material	Vulcan to K Road for District 2	2/23/2016	2/23/2016
Rural Roads	Haul Patching Material	From K Road to Loverslane	2/23/2016	2/23/2016
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 184 to Avenue 160	2/23/2016	2/23/2016
Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 216 to Avenue 192	2/23/2016	2/23/2016
Rural Roads	Repair road surface by hand patching	Avenue 192 at the End of Road 68	2/23/2016	2/23/2016
Rural Roads	Moving Equipment	District 2 K Street to Santa Fe	2/23/2016	2/24/2016
Rural Roads	Repair road surface by hand patching	Road 112 at Avenue 360	2/24/2016	2/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 390 from Road 34 to Road 36	2/24/2016	2/24/2016
Rural Roads	Repair road surface by hand patching	Road 180 South of Fisher	2/24/2016	2/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 176 From Road 80 to Road 28	2/24/2016	2/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 238 to Road 96	2/24/2016	2/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 95 from Road 236 to Road 248	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Road 248 from Avenue 95 to Avenue 96	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 432 From Road 128 to Road 136	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 206 to Pine	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 336 to State Highway 216	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 28 to Road 20	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Road 54 at Avenue 224	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Road 84 from Pleasant to Avenue 248	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 184 at Road 180	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 208 west of Road 208	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 181 from Road 238 to Diagonal 242	2/25/2016	2/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 88 from Road 236 to Avenue 240	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Road 240 from Avenue 86 to Avenue 88	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 4 to Avenue 8	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 8 to Avenue 80	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Saint Johns at Riverside	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Riverside from Saint Johns to WCL	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 400 from Road 136 to Road 144	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Road 84 from Avenue 256 to Avenue 248	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 280 from Road 60 to Road 68	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 304 from Road 64 to 30672	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 264 east of Road 204	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 178 east of Road 232	2/26/2016	2/26/2016
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 184 to Road 192	2/29/2016	3/1/2016

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair road surface by hand patching	Avenue 40 from Road 140 to Road 160	2/29/2016	2/29/2016
Rural Roads	Repair road surface by hand patching	Road 224 at Avenue 128	2/29/2016	2/29/2016
Rural Roads	Repair road surface by hand patching	Road 28 from Avenue 208 to Avenue 216	2/29/2016	2/29/2016
Rural Roads	Repair road surface by hand patching	Road 28 from Avenue 216 TO 22121	2/29/2016	2/29/2016
Rural Roads	Repair road surface by hand patching	Avenue 194 at Road 180	2/29/2016	2/29/2016
Rural Roads	Repair road surface by hand patching	Avenue 136 from Road 192 to Road 224	3/1/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Avenue 40 from Road 144 to Road 160	3/1/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 256 to Visalia City Limits	3/1/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 256 to Visalia City Limits	3/1/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 256 to Farmersville City Limits	3/1/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 152 from Visalia City Limits to State Highway 216	3/1/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 148 From Avenue 264 to Avenue 224	3/1/2016	3/1/2016
Rural Roads	Repair road surface by hand patching	Road 261 from Avenue 104 to End	3/2/2016	3/2/2016
Rural Roads	Repair road surface by hand patching	Road 232 from Avenue 80 to A88	3/2/2016	3/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 128 from Road 96 to Road 80	3/2/2016	3/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 112 at Road 128	3/2/2016	3/2/2016
Rural Roads	Repair road surface by hand patching	Avenue 168 at Road 136	3/2/2016	3/2/2016
Rural Roads	Repair road surface by hand patching	Road 261 from Avenue 104 to End	3/2/2016	3/2/2016
Rural Roads	Repair road surface by hand patching	Road 232 from Avenue 80 to Avenue 88	3/2/2016	3/2/2016
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 144 to Avenue 152	3/3/2016	3/3/2016
Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 0 to Avenue 56	3/3/2016	3/3/2016
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 92 to Road 124	3/3/2016	3/3/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 368 to Avenue 352	3/3/2016	3/3/2016
Rural Roads	Repair road surface by hand patching	Avenue 56 from Road 120 to Road 96	3/3/2016	3/3/2016
Rural Roads	Repair road surface by hand patching	Avenue 56 from State Highway 43 to Road 54	3/3/2016	3/3/2016
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 160 to Avenue 168	3/3/2016	3/3/2016
Rural Roads	Repair potholes with Road Patcher	Road 188 from Avenue 242 to Avenue 256	3/3/2016	3/3/2016
Rural Roads	Repair road surface by hand patching	Road 112 South of Avenue 352	3/4/2016	3/4/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 352 to Avenue 344	3/4/2016	3/4/2016
Rural Roads	Repair road surface by hand patching	Road 112 at Avenue 328	3/4/2016	3/4/2016
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 152 West of Road 150	3/4/2016	3/4/2016
Rural Roads	Repair potholes with road patcher	Avenue 272 from Road 140 to Road 128	3/4/2016	3/4/2016
Rural Roads	Repair potholes with road patcher	Avenue 256 from Road 156 to road 164	3/4/2016	3/4/2016
Rural Roads	Repair road surface by hand patching	Avenue 176 from Road 112 to Road 120	3/4/2016	3/4/2016
Rural Roads	Repair road surface by hand patching	Road 132 North of Avenue 352	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Road 60 from Avenue 328 to Avenue 360	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 128 West of Road 96	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Road 88 North of Avenue 128	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 152 from State Highway 99 to Road 96	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Road 96 at Avenue 120	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 272 from Road 140 to Road 128	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 229 from Road 48 to Road 46	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Avenue 230 from Road 48 to Road 46	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Road 204 from Avenue 232 to Avenue 237	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Road 232 from Avenue 220 to Avenue 216	3/8/2016	3/8/2016
Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 24 to Avenue 56	3/9/2016	3/9/2016
Rural Roads	Repair road surface by hand patching	Road 46 From Avenue 228 to Avenue 230	3/9/2016	3/9/2016
Rural Roads	Repair potholes with road patcher	Avenue 184 from State Highway 99 to Road 128	3/9/2016	3/9/2016
Rural Roads	Repair potholes with road patcher	Road 112 North of Avenue 184	3/9/2016	3/9/2016
Rural Roads	Repair potholes with road patcher	Road 128 from Avenue 184 to Avenue 176	3/9/2016	3/9/2016
Rural Roads	Repair potholes with road patcher	Avenue 184 from State Highway 99 to Road 96	3/9/2016	3/9/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 188 from Road 216 to Road 220	3/9/2016	3/9/2016
Rural Roads	Repair potholes with Road Patcher	Road 212 from Avenue 188 to Avenue 192	3/9/2016	3/9/2016
Rural Roads	Repair potholes with Road Patcher	Road 212 from Avenue 192 to Avenue 196	3/9/2016	3/9/2016

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair potholes with Road Patcher	Road 212 from Avenue 196 to Avenue 208	3/9/2016	3/9/2016
Rural Roads	Repair potholes with Road Patcher	Road 208 from Avenue 160 to Avenue 164	3/9/2016	3/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 184 from Diagonal 242 to Road 248	3/9/2016	3/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 192 from Road 196 to Road 152	3/9/2016	3/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 224 from Diagonal 242 to Road 220	3/9/2016	3/9/2016
Rural Roads	Repair road surface by hand patching	Avenue 88 from Road 168 to Road 192	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Avenue 48 from Road 152 to Road 192	3/10/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Mountain 109 at MP5.5	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 136 to Road 144	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 72 at Avenue 424	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 60 from Avenue 360 to Avenue 328	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Avenue 337 from Avenue 220 to Avenue 222	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 46 from Avenue 228 to Avenue 230	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 228 to Avenue 230	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 200 to Avenue 212	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 212 to Address of 21426	3/10/2016	3/10/2016
Rural Roads	Repair potholes with road patcher	Avenue 184 from State Highway 99 to Road 96	3/10/2016	3/10/2016
Rural Roads	Repair potholes with road patcher	Avenue 184 from Road 96 to Road 64	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 96 to State Highway 99	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Avenue 319 at State Highway 243	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 228 at Avenue 232	3/10/2016	3/10/2016
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 0 to Avenue 48	3/11/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 272 from Road 140 to Address of 12747	3/11/2016	3/11/2016
Rural Roads	Repair road surface by hand patching	Santa Fe from Avenue 272 to Visalia City Limits	3/11/2016	3/11/2016
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 56 to Avenue 24	3/11/2016	3/11/2016
Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 0 to Avenue 56	3/14/2016	4/1/2016
Rural Roads	Repair road surface by hand patching	Sand Creek at Mile Post 1.5	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Road 40 from Avenue 400 to Avenue 392	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 West of Road 108	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Avenue 272 from Road 140 to Visalia City Limits	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Avenue 288 from 15115 to Farmersville City Limits	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Road 158 from Avenue 296 to State Highway 216	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Road 204 at Friant Kern Canal	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Road 248 north of Avenue 200	3/14/2016	3/14/2016
Rural Roads	Repair road surface by hand patching	Road 224 from Avenue 112 to Avenue 128	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 108 to Road 100	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Road 36 West of Avenue 352	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 108 to Road 92	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 328 at Road 108	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Road 152 From Avenue 232 to State Highway 137	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 228 from Road 140 to 1000 feet South of Road 132	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Road 96 at Avenue 198	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Road 96 at Avenue 204	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 56 East of Road 30	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 40 to Avenue 0	3/15/2016	3/15/2016
Rural Roads	Repair potholes with Road Patcher	Diagonal 211 from Road 216 to Avenue 272	3/15/2016	3/15/2016
Rural Roads	Large area patching with Grader "Blade Patch"	Road 232 from Avenue 212 to Avenue 220	3/15/2016	3/15/2016
Rural Roads	Repair road surface by hand patching	Avenue 136 from Road 208 to West Street	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 128 from Road 224 to Road 232	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 128 from West St to Road 208	3/16/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 320 to Avenue 312	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Road 76 at Avenue 320	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 80 to Road 68	3/16/2016	3/16/2016

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 12 to Road 8	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 452 to Avenue 456	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 456 to Avenue 450	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 452 from Filer Road to Road 136	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 120 from State Highway 43 to East of 1st Bridge	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 92 to Road 68	3/16/2016	3/16/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 272 from Diagonal 211 to Road 228	3/16/2016	3/16/2016
Rural Roads	Repair potholes with Road Patcher	Avenue 300 from Road 196 at Road 204	3/16/2016	3/16/2016
Rural Roads	Repair road surface by hand patching	Avenue 112 from Road 208 to Road 224	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 104 at Road 192	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 56 to Avenue 152	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 434	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 304 at State Highway 99 Offramp	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 304 at Road 68	3/17/2016	3/17/2016
Rural Roads	Repair potholes with road patcher	Avenue 184 from Road 64 to Road 28	3/17/2016	3/17/2016
Rural Roads	Repair potholes with road patcher	Road 96 from Avenue 184 to Avenue 196	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 96 to Avenue 88	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 112 to Road 80	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Park at Avenue 96	3/17/2016	3/17/2016
Rural Roads	Repair road surface by hand patching	Diagonal 205 from Avenue 56 to Avenue 32	3/18/2016	3/18/2016
Rural Roads	Repair road surface by hand patching	Avenue 340 from State Highway 216 to Road 222	3/18/2016	3/18/2016
Rural Roads	Repair road surface by hand patching	Avenue 364 from Road 140 to Road 144	3/18/2016	3/18/2016
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 96 to Road 92	3/18/2016	3/18/2016
Rural Roads	Repair road surface by hand patching	Avenue 220 from Road 232 to Friant Kern Canal	3/18/2016	3/18/2016
Rural Roads	Repair road surface by hand patching	Road 256 from Avenue 196 to Lynch	3/18/2016	3/18/2016
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 104 to Avenue 96	3/21/2016	3/21/2016
Rural Roads	Repair road surface by hand patching	Capinero Oaks from M56 to End	3/21/2016	3/21/2016
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 40 to Avenue 0	3/21/2016	3/21/2016
Rural Roads	Repair road surface by hand patching	Avenue 16 from Road 128 to Road 112	3/21/2016	3/21/2016
Rural Roads	Repair potholes with road patcher	Avenue 152 from Road 152 to Road 120	3/21/2016	3/21/2016
Rural Roads	Repair potholes with road patcher	Road 140 from Avenue 224 to Avenue 200	3/21/2016	3/21/2016
Rural Roads	Repair potholes with road patcher	Avenue 200 from Road 140 to Rankin Pit Entrance	3/21/2016	3/21/2016
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 152 to Avenue 160	3/21/2016	3/21/2016
Rural Roads	Repair road surface by hand patching	Diagonal 116 from Avenue 160 to Avenue 152	3/21/2016	3/21/2016
Rural Roads	Repair road surface by hand patching	Avenue 280 at State Highway 99 offramp	3/21/2016	3/21/2016
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 109 to Mile Post 15.5	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Road 206 from Avenue 352 to State Highway 245	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 340 from Road 222 to Road 226	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 337 at Road 220	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 348 from Road 204 to Millwood	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Newcomb at Avenue 178	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Road 248 at Avenue 224	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Road 216 from Avenue 256 to Avenue 264	3/22/2016	3/22/2016
Rural Roads	Repair road surface by hand patching	Avenue 12 from Road 224 to State Route 65	3/23/2016	3/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 76	3/23/2016	3/23/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 at Road 76	3/23/2016	3/23/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 West of Road 76	3/23/2016	3/23/2016
Rural Roads	Repair road surface by hand patching	Avenue 384 East of Road 80	3/23/2016	3/23/2016
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 296 to Avenue 304	3/23/2016	3/23/2016
Rural Roads	Repair road surface by hand patching	Avenue 0 at Diagonal 205	3/24/2016	3/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 360 East of Road 52	3/24/2016	3/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 424 West of Road 96	3/24/2016	3/24/2016
Rural Roads	Repair road surface by hand patching	Avenue 412 East of Road 104	3/24/2016	3/24/2016
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 200 to Spacer Drive	3/24/2016	3/25/2016

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

**Local Programs**

Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 256 to Road	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 264 to R268	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Road 196 at Avenue 336	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 336 West of Road 196	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 336 to Drive 194	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Road 188 North of Avenue 344	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 144 East of State Highway 43	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Avenue 174 at Friant Kern Canal	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Road 204 from Avenue 256 to Diagonal 205	3/25/2016	3/25/2016
Rural Roads	Repair road surface by hand patching	Road 48 at Avenue 408	3/28/2016	3/28/2016
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 376 to Avenue 352	3/28/2016	3/28/2016
Rural Roads	Repair road surface by hand patching	Avenue 408 from City Limit to Road 144	3/28/2016	3/28/2016
Rural Roads	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	3/28/2016	3/28/2016
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 200 to Avenue 192	3/28/2016	3/28/2016
Rural Roads	Repair road surface by hand patching	Avenue 192 at Road 128	3/28/2016	3/28/2016
Rural Roads	Repair road surface by hand patching	Road 108 from Avenue 328 to Avenue 320	3/29/2016	3/29/2016
Rural Roads	Repair road surface by hand patching	Avenue 364 at Road 140	3/29/2016	3/29/2016
Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 364	3/29/2016	3/29/2016
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 364 to Avenue 376	3/29/2016	3/29/2016
Rural Roads	Repair road surface by hand patching	Road 144 South of Avenue 408	3/29/2016	3/29/2016
Rural Roads	Repair road surface by hand patching	Avenue 410 East of Road 144	3/29/2016	3/29/2016
Rural Roads	Repair road surface by hand patching	Avenue 192 from Road 124 to Spacer Drive	3/29/2016	3/29/2016
Rural Roads	Repair road surface by hand patching	Road 100 from Avenue 264 to Visalia City Limits	3/29/2016	3/29/2016
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 152 to State Highway 99	3/29/2016	3/31/2016
Rural Roads	Repair road surface by hand patching	North 465 from Mountain Road 469 to Mile Post 6	3/30/2016	3/30/2016
Rural Roads	Repair road surface by hand patching	Drive 254 from Mountain Road 465 to FCL	3/30/2016	3/30/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 132 to Road 140	3/30/2016	3/30/2016
Rural Roads	Repair road surface by hand patching	Road 100 from Avenue 276 to Avenue 268	3/30/2016	3/30/2016
Rural Roads	Repair road surface by hand patching	Avenue 240 from Road 68 to Road 48	3/30/2016	3/30/2016
Rural Roads	Repair road surface by hand patching	Road 114 North of Avenue 424	3/31/2016	3/31/2016
Rural Roads	Repair road surface by hand patching	Avenue 432 from State Highway 63 to Road 136	3/31/2016	3/31/2016
Rural Roads	Repair potholes with road patcher	Franklin at Elm	3/31/2016	3/31/2016
Rural Roads	Repair road surface by hand patching	Avenue 184 at Road 236	3/31/2016	3/31/2016
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 128 to Road 136	4/1/2016	4/1/2016
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 432 to Avenue 428	4/1/2016	4/1/2016
Rural Roads	Repair road surface by hand patching	Road 48 at Avenue 408	4/1/2016	4/1/2016
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 80 to Road 60	4/1/2016	4/1/2016
Rural Roads	Repair potholes with road patcher	Avenue 216 from Road 68 to Road 84	4/1/2016	4/1/2016
Rural Roads	HAUL MATERIAL FOR BLADE PATCH	Avenue 112 from Road 104 to Road 96	4/1/2016	4/1/2016
Rural Roads	HAUL MATERIAL FOR BLADE PATCH	Avenue 160 from Diagonal 116B to Road 120	4/1/2016	4/1/2016
Rural Roads	Repair road surface by hand patching	Santa Fe North of Avenue 272	4/1/2016	4/1/2016
Mountain Roads	Repair road surface by hot patching	Meadow from Pleasant Oak to End	12/28/2015	12/28/2015
Mountain Roads	Repair road surface by hot patching	Maverick at Mustang	12/28/2015	12/28/2015
Mountain Roads	Repair road surface by hot patching	Mountain Road 161 from Mountain Road 172A to Mountain Road 172A	12/29/2015	12/29/2015
Mountain Roads	Repair road surface by hot patching	Mountain Road 172A from Mountain Road 161 to Highway 190	12/29/2015	12/29/2015
Mountain Roads	Repair road surface by hot patching	Mountain Road 296 north of Avenue 280	1/28/2016	1/28/2016
Mountain Roads	Repair road surface by hot patching	Mountain Road 161 Wardlaw to Cattle	3/8/2016	3/8/2016
Mountain Roads	Repair potholes with Road Patcher	Mountain Road 296 at Milepost 4	3/16/2016	3/16/2016
Mountain Roads	Repair road surface by hot patching	Mountain Road 208 from Highway 190 to End	3/21/2016	3/21/2016
Mountain Roads	Repair road surface by hot patching	Mountain Road 296 from Milepost 25 to Mountain Road 276	3/21/2016	3/21/2016
Mountain Roads	Repair road surface by hot patching	Mountain Road 239 from Mountain Road 296 to Mountain Road 276	3/29/2016	3/29/2016
Mountain Roads	Repair road surface by hot patching	Mountain Road 296 from Mountain Road 239 to Milepost 12.5	3/29/2016	3/29/2016

**Rural Roads** TOTAL \$ 224,098.87

Tulare County Association Of Goverments  
Quarterly Reporting  
Measure R Programs

Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 3

## Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter	
AC Sidewalk MR (AB 720) AC Overlays MR (AB720)	AC Overlay	Construction/Design	Avenue 256 from Road 180 to Road 188	5/14/2014	ongoing	\$ 29.36	
		Construction/Design	Avenue 56 from State Route 43 to Road 96	5/14/2014	ongoing	\$ 54.19	
		Preliminary Engineering/ Design	Community Road Surfacing	5/14/2014	ongoing	\$ 1,623.41	
		Construction/Design	Road 148 Avenue 280 Visalia Road to Avenue 288 Marinette Avenue	7/18/2014	ongoing	\$ 321.31	
		Construction/Design	Road 184 from Avenue 136 to Avenue 144	7/18/2014	ongoing	\$ 192,789.65	
		Construction/Design	Road 200 from Avenue 0 to Avenue 8	7/18/2014	ongoing	\$ 5,774.58	
		Construction/Design	Avenue 432 Floral Avenue Road 128 to State Highway 63 to Road 136	7/18/2014	ongoing	\$ 598.56	
		Construction/Design	Diagonal 208B Avenue 160 from Henderson to Road 208	7/18/2014	ongoing	\$ 6,582.97	
		Construction/Design	Success Drive from Park to Connor	11/19/2014	ongoing	\$ 146.22	
		Construction/Design	Rural Road Surface Maintainance	1/15/2015	ongoing	\$ 1,139.08	
		Preliminary Engineering/ Design	Community Road Surface Maintainance	1/15/2015	ongoing	\$ 4,633.33	
		Preliminary Engineering/ Design	Rural Road Surface Maintainance	6/2/2015	ongoing	\$ 398.96	
		Preliminary Engineering/ Design	Woodville Elementary and Road 168	3/2/2016	ongoing	\$ 11.23	
		Preliminary Engineering/ Design	Sunnyside Elementary and Avenue 196	3/2/2016	ongoing	\$ 11.23	
		Preliminary Engineering/ Design	Sequoia Union Elementary and Avenue 324	3/2/2016	ongoing	\$ 11.23	
		Preliminary Engineering/ Design	Ducor Elementary School and Avenue 56	3/2/2016	ongoing	\$ 11.23	
		Preliminary Engineering/ Design	Road 256 South of Avenue 104	3/2/2016	ongoing	\$ 11.23	
		Preliminary Engineering/ Design	EI Monte West of Road 124	3/2/2016	ongoing	\$ 122.54	

**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

**Local Programs**

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
15/16 Annual Advance \$5,199,499.00 Communities	Alpaugh	Repair road surface by hand patching	Avenue 54 From State Highway 63 To Road 38	4/21/2016	4/21/2016	
	Alpaugh	Repair road surface by hand patching	Road 38 From Avenue 54 To Avenue 56	5/17/2016	5/17/2016	\$ 672.68
	Alpine Village	Repair road surface by hand patching	Mountain Road 276 From Highway 190 To Mountain Road 215	5/24/2016	5/24/2016	\$ 585.08
	Camp Nelson	Repair road surface by hand patching	Mountain Road 193A From Mountain Road 192A To Mountain Road 200A	5/23/2016	5/23/2016	\$ 885.69
	Cutler/Orosi	Repair road surface by hand patching	Second At Santa Fe	4/20/2016	4/20/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 404 From State Highway 63 To Mueller Road	4/25/2016	4/25/2016	\$ 685.16
	Doyle Colony	Repair road surface by hand patching	Lr258A (Ruth) At Diagonal 261(Date)	4/19/2016	4/19/2016	
	Doyle Colony	Repair road surface by hand patching	Road 272 At Avenue 146	4/19/2016	4/19/2016	\$ 22.41
	Earlimart	Repair road surface by hand patching	Washington West Of Railroad Tracks	4/12/2016	4/12/2016	
	Earlimart	Repair road surface by hand patching	Washington At Front	4/12/2016	4/12/2016	
	Earlimart	Repair road surface by hand patching	Washington At Elm	4/12/2016	4/12/2016	
	Earlimart	Repair road surface by hand patching	Washington At Ash	4/12/2016	4/12/2016	
	Earlimart	Repair road surface by hand patching	Avenue 56 At State Highway 99 Bridge	4/20/2016	4/20/2016	
	Earlimart	Repair road surface by hand patching	State Highway 99 Off-Ramp	4/28/2016	4/28/2016	
	Earlimart	Repair road surface by hand patching	Armstrong At Elm	5/3/2016	5/3/2016	
	Earlimart	Repair road surface by hand patching	Spring At Sutter	5/3/2016	5/3/2016	
	Earlimart	Repair road surface by hand patching	Spring At Bent Ranch	5/3/2016	5/3/2016	
	Earlimart	Repair road surface by hand patching	State Street From Spruce To Armstrong	5/3/2016	5/3/2016	
	Earlimart	Repair road surface by hand patching	Olive From Armstrong To Spruce	5/3/2016	5/3/2016	
	Earlimart	Repair road surface by hand patching	Church From Armstrong To Cable	5/3/2016	5/3/2016	
	Earlimart	Repair road surface by hand patching	Center At Church	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	Sutter From Front To Market	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	Avenue 56 From Front To State	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	State From Washington To Armstrong	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	Church From Armstrong To Cable	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	Spruce From Church To State	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	Front From Armstrong To Washington	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	Tulare From State To Church	5/4/2016	5/4/2016	
	Earlimart	Repair road surface by hand patching	Center From Church To State	5/5/2016	5/5/2016	\$ 2,088.29
	Goshen	Repair road surface by hand patching	Betty Drive From Road 67 To State Highway 99	4/7/2016	4/7/2016	
	Goshen	Repair road surface by hand patching	Avenue 304 From Road 68 To Road 44	4/18/2016	4/18/2016	
	Goshen	Repair road surface by hand patching	Road 68 From Avenue 304 To Diagonal 68	4/18/2016	4/18/2016	
	Goshen	Repair road surface by hand patching	Road 67 At 30676	4/18/2016	4/18/2016	
	Goshen	Repair road surface by hand patching	Road 64 From Avenue 304 To State Highway 198	4/18/2016	4/19/2016	
	Goshen	Repair road surface by hand patching	Road 92 From Avenue 312 To Avenue 320	4/19/2016	4/19/2016	
	Goshen	Repair road surface by hand patching	Commercial Road From Avenue 308 To Avenue 310	4/26/2016	4/26/2016	
	Goshen	Repair road surface by hand patching	Road 76 From Avenue 308 To Robinson	4/26/2016	4/26/2016	
	Goshen	Repair road surface by hand patching	Avenue 305 At Camp Drive	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Road 71 From Avenue 305 To Avenue 306	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Farr Road From Avenue 305 To Avenue 306	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Commercial Drive From Wills Avenue To Avenue 305	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Road 70 At Avenue 308	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Robinson From Avenue 308 To Camp Drive	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Elder From Camp Drive To Road 69	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Avenue 308 At Road 76	4/27/2016	4/27/2016	
	Goshen	Repair road surface by hand patching	Betty Drive East Of State Highway 99	5/12/2016	5/12/2016	
	Goshen	Large area Patching with grader "Blade Patch"	Betty Drive East Of State Highway 99	5/18/2016	5/18/2016	



**Tulare County Association Of Governments**  
**Quarterly Reporting**  
**Measure R Programs**

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

**Local Programs**

Goshen	Large area Patching with grader "Blade Patch"	Diagonal 69 From Avenue 304 To Avenue 308	5/18/2016	5/18/2016	
Goshen	Large area Patching with grader "Blade Patch"	Effie Drive From Avenue 304 To Avenue 306	5/18/2016	5/18/2016	
Goshen	Striping	Betty Drive from Nutmeg to the Highway 99	5/18/2016	5/18/2016	
Goshen	Repair road surface by hand patching	Betty Drive West Of State Highway 99 Bridge	6/2/2016	6/2/2016	
Goshen	Repair road surface by hand patching	Road 76 From Avenue 304 To Avenue 308	6/2/2016	6/2/2016	
Goshen	Repair road surface by hand patching	Avenue 304 At Road 64	6/2/2016	6/2/2016	
Goshen	Repair road surface by hand patching	Road 64 From Avenue 308 To State Highway 198	6/2/2016	6/2/2016	\$ 9,391.08
Ivanhoe	Repair road surface by hand patching	Road 159 At Azalea	5/19/2016	5/19/2016	\$ 95.61
London	Repair road surface by hand patching	Avenue 378 East Of Road 60	4/12/2016	4/12/2016	
London	Repair road surface by hand patching	Avenue 377 At Road 57	4/12/2016	4/12/2016	\$ 222.61
Matheny Tract	Repair road surface by hand patching	Various Road And Avenues	4/6/2016	4/6/2016	
Matheny Tract	Repair road surface by hand patching	Beacon Avenue From Road 96 To I Street	4/7/2016	4/7/2016	
Matheny Tract	Repair road surface by hand patching	Wade Avenue From Road 96 To Canal Street	4/7/2016	4/7/2016	\$ 1,056.67
Monson	Repair road surface by hand patching	Monson From Avenue 384 To Avenue 388	4/27/2016	4/27/2016	
Monson	Repair road surface by hand patching	Monson From Road 104 To Avenue 384	6/8/2016	6/8/2016	\$ 144.15
Oakranch	Repair road surface by hand patching	Oak Ranch At Appaloosa	5/19/2016	5/19/2016	\$ 95.61
Patterson Tract	Repair road surface by hand patching	Forrester At Floral	5/19/2016	5/19/2016	
Patterson Tract	Repair road surface by hand patching	Frontage At Friden	5/19/2016	5/19/2016	\$ 191.23
Pixley	Repair road surface by hand patching	Avenue 96 From Elm To Market	5/12/2016	5/12/2016	
Pixley	Repair road surface by hand patching	Elm Street From Avenue 96 To Court Street	5/12/2016	5/12/2016	
Pixley	Repair road surface by hand patching	2827 Elm Street	5/17/2016	5/17/2016	\$ 1,325.92
Pixley	Repair road surface by hand patching	Ash From Avenue 96 To Elm Street	5/17/2016	5/17/2016	
Ponderosa	Repair road surface by hand patching	Fox From Mountain Road 107 To Peppermint	6/9/2016	6/9/2016	
Ponderosa	Repair road surface by hand patching	Silver Tip From Fox To End	6/9/2016	6/9/2016	
Ponderosa	Repair road surface by hand patching	Pondrosa From Snowflake To Silver Tip	6/9/2016	6/9/2016	
Ponderosa	Repair road surface by hand patching	Summit Drive From Peppermint To Fawn	6/9/2016	6/9/2016	
Ponderosa	Repair road surface by hand patching	Mountain Road 107 At Ponderosa Lodge	6/9/2016	6/9/2016	
Ponderosa	Repair road surface by hand patching	Mountain Road 178B From Mountain Road 173B To Avenue 175* (End)	6/13/2016	6/13/2016	
Ponderosa	Large area Patching with grader "Blade Patch"	Sweep Ponderosa Streets For Future Blade Patches	6/13/2016	6/13/2016	\$ 3,268.41
Richgrove	Repair road surface by hand patching	Diagonal 205 From Avenue 0 To Avenue 16	4/6/2016	4/6/2016	
Richgrove	Repair road surface by hand patching	Avenue 95 East Of State Highway 65	4/12/2016	4/12/2016	\$ 509.81
Sequoia Crest	Repair road surface by hand patching	Hossack From Mountain Road 216 To Alder	5/24/2016	5/24/2016	\$ 361.64
Seville	Repair road surface by hand patching	Avenue 388 From Road 153 To Road 154	6/2/2016	6/2/2016	
Seville	Repair road surface by hand patching	Seville From Road 154 To Road 156	6/6/2016	6/6/2016	\$ 227.53
Strathmore	Repair road surface by hand patching	Road 228 From Avenue 196 To Avenue 228	4/14/2016	4/14/2016	
Strathmore	Repair potholes with Road Patcher	Avenue 184 From Road 216 To Road 224	4/18/2016	4/18/2016	
Strathmore	Repair road surface by hand patching	Avenue 194 From Road 228 To Diagonal 242	4/26/2016	4/26/2016	
Strathmore	Repair road surface by hand patching	Lr230D (Wallace) Avenue 195 To Avenue 196	5/4/2016	5/4/2016	
Strathmore	Repair road surface by hand patching	Road 224 North Of Avenue 188	6/16/2016	6/16/2016	\$ 1,875.48
Terra Bella	Repair road surface by hand patching	23777 Palm Avenue	5/16/2016	5/16/2016	\$ 75.42

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

Three Rivers	Repair road surface by hand patching	Mountain Road 357 From Mile Post 7 To Mile Post 7.5	4/15/2016	4/15/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 368 From Mile Post 1 To Mile Post 3	4/28/2016	4/28/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 357 From Mile Post 3 To Mile Post 7	4/28/2016	4/28/2016	
Three Rivers	Repair road surface by hand patching	South Fork East Of Blossom Trail	5/9/2016	5/9/2016	
Three Rivers	Repair road surface by hand patching	Mountain 375 From Mile Post O To Mile Post 4	5/16/2016	5/16/2016	
Three Rivers	Repair road surface by hand patching	Mountain Road 375 From Mile Post 3 To Mile Post 6.5	5/17/2016	5/17/2016	
Three Rivers	Repair road surface by hand patching	Groose At Ferndale	5/19/2016	5/19/2016	
Three Rivers	Repair road surface by hand patching	Kaweah From Mountain Road 357 To End	5/19/2016	5/19/2016	
Three Rivers	Repair road surface by hand patching	42148 South Fork Drive	5/19/2016	5/19/2016	
Three Rivers	Repair road surface by hand patching	South Fork From Blossom To Mile Post 2	5/24/2016	5/24/2016	
Three Rivers	Repair road surface by hand patching	Hammond From Oak Grove To Mineral King	5/24/2016	5/24/2016	\$ 3,670.87
Tipton	Repair potholes with Road Patcher	Hamlin South Of Avenue 152	5/10/2016	5/10/2016	
Tipton	Repair potholes with Road Patcher	Lafond From Spencer To Klindera	5/10/2016	5/10/2016	
Tipton	Repair potholes with Road Patcher	Thompson From Lipscomb To Avenue 152	5/10/2016	5/10/2016	
Tipton	Repair potholes with Road Patcher	Avenue 152 At Newman	5/10/2016	5/10/2016	
Tipton	Repair potholes with Road Patcher	Callison From Avenue 152 To Avenue 160	5/10/2016	5/10/2016	
Tipton	Repair potholes with Road Patcher	Road 172 From Avenue 160 To Diagonal 112	5/10/2016	5/10/2016	
Tipton	Repair potholes with Road Patcher	Thompson From Avenue 160 To Avenue 164	5/10/2016	5/10/2016	
Tipton	Repair road surface by hand patching	Woods From Burnett To Graham	6/1/2016	6/1/2016	
Tipton	Repair road surface by hand patching	Klindera From Burnett To Graham	6/1/2016	6/1/2016	
Tipton	Repair road surface by hand patching	Avenue 56 At State Highway 99	6/13/2016	6/13/2016	
Tipton	Repair road surface by hand patching	Church Street At Sutter Avenue	6/13/2016	6/13/2016	
Tipton	Repair road surface by hand patching	Berry Road From Avenue 152 To Klindera Avenue	6/13/2016	6/13/2016	\$ 1,652.68
Tonyville	Repair road surface by hand patching	Road 212 South Of Avenue 256	4/15/2016	4/15/2016	\$ 44.82
Tooleville	Large area Patching with grader "Blade Patch"	Road 204 (Spruce) From Avenue 273 To Avenue 276	5/16/2016	5/19/2016	
Tooleville	Repair road surface by hand patching	Road 204 From Avenue 273 To Avenue 278	5/16/2016	5/19/2016	
Tooleville	Repair road surface by hand patching	Road 204 At Avenue 268	4/14/2016	4/14/2016	
Tooleville	Repair road surface by hand patching	Avenue 262 From Road 204 To End	4/25/2016	4/25/2016	
Tooleville	Large area Patching with grader "Blade Patch"	Road 204 At Avenue 268	5/12/2016	5/19/2016	
Tooleville	Large area Patching with grader "Blade Patch"	Road 204 From Avenue 273 To Avenue 276	5/16/2016	5/31/2016	
Tooleville	Large area Patching with grader "Blade Patch"	Road 204 At Avenue 274	6/13/2016	6/13/2016	
Tooleville	Repair road surface by hand patching	Avenue 256 From Road 204 To Road 212	6/16/2016	6/16/2016	
Tooleville	Repair road surface by hand patching	Avenue 240 From Road 204 To Road 216	6/16/2016	6/16/2016	\$ 23,320.65
Traver	Repair road surface by hand patching	Merritt Drive From Burke To State Highway 99	5/26/2016	5/26/2016	
Traver	Repair road surface by hand patching	Burke North Of Merritt Drive	6/15/2016	6/15/2016	\$ 165.19
West Exeter	Repair road surface by hand patching	Avenue 288 East Of Road 188	4/6/2016	4/6/2016	\$ 44.82
Western Divide	Repair road surface by hand patching	Mountain Road 107 From Milepost 3 To Milepost 10	4/19/2016	4/19/2016	
Western Divide	Repair road surface by hand patching	Mountain Road 107 From Milepost 3 To Mountain Road 50	4/20/2016	4/20/2016	
Western Divide	Repair road surface by hand patching	Mountain Road 107 From Milepost 1 To Mountain Road 50	4/21/2016	4/21/2016	
Western Divide	Repair road surface by hand patching	Mountain Road 107 From Mountain Road 180B To Mountain Road 50	6/13/2016	6/13/2016	
Western Divide	Repair road surface by hand patching	Mountain Road 107 From Milepost 10 To Milepost 15	6/14/2016	6/14/2016	\$ 3,396.34
Woodeville	Repair road surface by hand patching	Road 168 From Avenue 164 To Avenue 168	4/13/2016	4/13/2016	\$ 52.35
Yokohl	Repair road surface by hand patching	Avenue 288 East Of Road 200	4/6/2016	4/6/2016	
Yokohl	Stripping	Road 204 from Avenue 288 Marinette to Highway 198	4/6/2016	4/6/2016	
Yokohl	Large area Patching with grader "Blade Patch"	Road 204 At Friant Kern Canal	4/4/2016	4/11/2016	\$ 42,852.94

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads		Repair road surface by hand patching	Road 140 From Avenue 432 To Avenue 420	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Avenue 432 From State Highway 65 To Road 140	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Avenue 200 From Road 52 To Road 60	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Road 44 From Avenue 216 To Avenue 192	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Avenue 264 From Road 140 To Road 156	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Road 156 From Avenue 256 To Avenue 280	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Road 164 From Avenue 256 To Farmersville Cl	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Road 148 From Avenue 232 To Avenue 224	4/4/2016	4/4/2016	
		Repair road surface by hand patching	Road 40 From Avenue 400 To Avenue 416	4/5/2016	4/5/2016	
		Repair road surface by hand patching	Avenue 328 From Road 80 To State Highway 99	4/5/2016	4/5/2016	
		Repair road surface by hand patching	Road 60 From Avenue 200 To Avenue 208	4/5/2016	4/5/2016	
		Repair road surface by hand patching	Road 136 From Avenue 192 To Avenue 180	4/5/2016	4/5/2016	
		Repair road surface by hand patching	Avenue 56 From Road 256 To Road 272	4/5/2016	4/5/2016	
		Repair road surface by hand patching	Road 256 From Avenue 56 To Avenue 72	4/5/2016	4/5/2016	
		Repair road surface by hand patching	Road 48 From Avenue 400 To Avenue 416	4/6/2016	4/6/2016	
		Repair road surface by hand patching	Road 136 From Avenue 400 To Avenue 392	4/6/2016	4/6/2016	
		PUSH UP MATERIAL	Rankin Pit	4/6/2016	4/6/2016	
		Repair road surface by hand patching	Road 256 From Avneue 72 To Avenue 56	4/6/2016	4/6/2016	
		Repair road surface by hand patching	Avenue 96 From Road 208 To Road 192	4/6/2016	4/6/2016	
		Repair road surface by hand patching	Road 136 From Avenue 160 To Avenue 180	4/6/2016	4/6/2016	
		Repair road surface by hand patching	Road 74 From Avenue 384 To Avenue 392	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Road 156 South Of Avenue 376	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Road 172 From Avenue 376 To Avenue 344	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Road 172 From Avenue 360 To Avenue 352	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Diagonal 205 South Of Avenue 24	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Avenue 96 From Road 192 To Road 152	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Road 192 From Avenue 56 To Avenue 152	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Avenue 95 From Road 236 To Road 256	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Avenue 112 From Road 126 To Road 192	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Avenue 160 From Road 136 To Diagonal 116B	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Diagonal 116B From Avenue 152 To Avenue 184	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Avenue 176 From Diagonal 116B To Road 128	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Diagonal 116B From Diagonal 112 To Avenue 152	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Road 60 North Of Avenue 208	4/7/2016	4/7/2016	
		Repair road surface by hand patching	Avenue 200 From Road 52 To Road 60	4/7/2016	4/8/2016	
		Repair road surface by hand patching	Avenue 226 At Road 242	4/7/2016	4/8/2016	
		Repair road surface by hand patching	Road 136 From Avenue 392 To Avenue 384	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Avenue 360 From Sentenial To Road 220	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Sentenial From Avenue 364 To Avenue 360	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Avenue 364 At Road 204	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Avenue 332 From Road 128 To Road 136	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Avenue 388 From Road 136 To Road 124	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Avenue 208 From Road 68 To Road 72	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Road 60 From Avenue 200 To Avenue 216	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Road 96 From Avenue 168 To Avenue 144	4/8/2016	4/8/2016	
		Repair road surface by hand patching	Avenue 437 West Pf Road 136	4/11/2016	4/11/2016	
		Repair road surface by hand patching	Johnson Drive From Drive 152 To Road 142	4/11/2016	4/11/2016	
		Repair road surface by hand patching	Avenue 120 From Road 96 To Road 88	4/11/2016	4/11/2016	
		Repair road surface by hand patching	Road 142 From Avenue 416 To Avenue 432	4/12/2016	4/12/2016	
		Repair road surface by hand patching	Road 252 South Of Avenue 80	4/12/2016	4/12/2016	
		Repair road surface by hand patching	Avneue 128 From Road 238 To Road 268	4/12/2016	4/12/2016	

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

	Repair road surface by hand patching	Indiana Avenue From Road 120 To Hemlock Strt	4/12/2016	4/12/2016
	Repair road surface by hand patching	Road 176 From Avenue 104 To Avenue 136	4/12/2016	4/12/2016
	Repair road surface by hand patching	Rowland At Avenue 8	4/13/2016	4/13/2016
	Repair road surface by hand patching	Road 210 From Avenue 8 To Grove Drive	4/13/2016	4/13/2016
	Repair road surface by hand patching	Avenue 176 From Diagonal 112 To Road 128	4/13/2016	4/13/2016
	Repair road surface by hand patching	I Street From Avenue 200 To Tulare City Limits	4/13/2016	4/14/2016
	Repair road surface by hand patching	Road 176 From Avenue 104 To Avenue 136	4/13/2016	4/13/2016
	Repair road surface by hand patching	Road 168 From Avenue 164 To Avenue 168	4/13/2016	4/13/2016
	Repair road surface by hand patching	Road 188 From Avenue 344 To State Highway 216	4/14/2016	4/14/2016
	Repair road surface by hand patching	Avenue 336 East Of State Highway 216	4/14/2016	4/14/2016
	Repair road surface by hand patching	Road 132 From Avenue 352 To Avenue 384	4/14/2016	4/14/2016
	Repair road surface by hand patching	Avenue 392 From Road 84 To Road 88	4/14/2016	4/14/2016
	Repair road surface by hand patching	Road 96 From Avenue 416 To Avenue 432	4/14/2016	4/14/2016
	Repair road surface by hand patching	Diagonal 112 From Avenue 160 To Avenue 184	4/14/2016	4/14/2016
	Repair road surface by hand patching	Road 180 From Avenue 256 To Avenue 268	4/14/2016	4/14/2016
	Repair road surface by hand patching	Road 188 From Avenue 256 To Avenue 268	4/14/2016	4/14/2016
	Repair road surface by hand patching	Avenue 170 At Friant Kern Canal	4/14/2016	4/14/2016
	Repair road surface by hand patching	Avenue 256 At Road 196	4/14/2016	4/14/2016
	Repair road surface by hand patching	Avenue 384 From Road 80 To Road 88	4/15/2016	4/15/2016
	Repair road surface by hand patching	Road 84 From Avenue 400 To Avenue 384	4/15/2016	4/15/2016
	Repair road surface by hand patching	Avenue 424 From Road 88 To Road 96	4/15/2016	4/15/2016
	Repair road surface by hand patching	Road 40 From Avenue 384 To Avenue 390	4/18/2016	4/18/2016
	Repair road surface by hand patching	Avenue 368 West Of Road 108	4/18/2016	4/18/2016
	Repair road surface by hand patching	Avenue 368 West Of Road 80	4/18/2016	4/18/2016
	Repair road surface by hand patching	Road 168 From Millwood To Avenue 324	4/18/2016	4/18/2016
	Repair road surface by hand patching	Avenue 184 From State Highway 99 To Road 96	4/18/2016	4/18/2016
	Repair road surface by hand patching	Avenue 224 At Road 216	4/18/2016	4/18/2016
	Repair road surface by hand patching	Road 188 South Of Avenue 242	4/18/2016	4/18/2016
	Repair road surface by hand patching	Mountain 99 From Tulare County Line To Mountain 50	4/19/2016	4/21/2016
	Repair road surface by hand patching	Mountain 50 From Mountain 99 To Mountain 107	4/19/2016	4/21/2016
	Repair road surface by hand patching	Diagonal 246C (Fritz) South Of Diagonal 246B (Mehrten)	4/19/2016	4/19/2016
	Repair road surface by hand patching	Road 256 South Of Avenue 200	4/19/2016	4/19/2016
	Repair road surface by hand patching	Avenue 176 West Of Road 216	4/19/2016	4/19/2016
	Repair road surface by hand patching	Diagonal 252 (Lynch) East Of Road 252	4/19/2016	4/19/2016
	Repair road surface by hand patching	Mountain 137 At Mile Post 3.5	4/20/2016	4/20/2016
	Repair road surface by hand patching	Mountain 137 At Mile Post 7	4/20/2016	4/20/2016
	Repair road surface by hand patching	Road 64 From Avenue 426 To Avenue 420	4/20/2016	4/20/2016
	Repair road surface by hand patching	Road 92 From Avenue 328 To Avenue 312	4/20/2016	4/20/2016
	Repair road surface by hand patching	Road 168 From State Highway 216 To Saint John'S	4/20/2016	4/20/2016
	Repair road surface by hand patching	Avenue 432 From State Highway 63 To Road 136	4/20/2016	4/20/2016
	Repair road surface by hand patching	Road 140 North Of Avenue 432	4/20/2016	4/20/2016
	Repair road surface by hand patching	Avenue 56 From Road 120 To Borchardt Ave	4/20/2016	4/20/2016
	Repair road surface by hand patching	Avenue From Road 88 To Road 80	4/21/2016	4/21/2016
	Repair road surface by hand patching	Avenue 424 From Road 88 To Road 124	4/21/2016	4/21/2016
	Repair road surface by hand patching	Road 104 From Avenue 424 To Avenue 432	4/21/2016	4/21/2016
	Repair road surface by hand patching	Road 144 South Of Saint John'S	4/21/2016	4/21/2016
	Repair road surface by hand patching	Avenue 368 From Road 80 To Road 60	4/21/2016	4/21/2016
	Repair road surface by hand patching	Avenue 320 At Road 96	4/21/2016	4/21/2016
	Repair road surface by hand patching	Avenue 120 From Road 80 To State Hiway 63	4/21/2016	4/21/2016
	Repair road surface by hand patching	Avenue 120 From Road 80 To State Hiway 99	4/21/2016	4/21/2016
	Repair road surface by hand patching	Road 224 From Avenue 140 To Porterville City Limits	4/25/2016	4/25/2016
	Repair road surface by hand patching	Gibbons (Avenue 138) West Of Plano (Road 252)	4/25/2016	4/25/2016
	Repair road surface by hand patching	Mountain 109 From Avenue 96 To Avenue 56	4/25/2016	4/28/2016
	Repair road surface by hand patching	Mountain 56 From Mountain 50 To Pine Mountain Dr	4/25/2016	4/25/2016

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

	Repair road surface by hand patching	Avenue 248 From Road 36 To Road 44	4/25/2016	4/25/2016
	Repair road surface by hand patching	Avenue 176 From Road 64 To Road 80	4/25/2016	4/25/2016
	Repair road surface by hand patching	Road 80 From Avenue 184 To Avenue 176	4/25/2016	4/25/2016
	Repair road surface by hand patching	Avenue 428 East Of Road 136	4/26/2016	4/26/2016
	Repair road surface by hand patching	Road 240 From Avenue 56 To Avenue 92	4/26/2016	4/26/2016
	Repair road surface by hand patching	Avenue 432 From Road 128 To Road 136	4/26/2016	4/26/2016
	Repair road surface by hand patching	Road 148 From Avenue 280 To Avenue 288	4/26/2016	4/26/2016
	Repair road surface by hand patching	Road 136 From Avenue 432 To Avenue 428	4/26/2016	4/26/2016
	Repair road surface by hand patching	Avenue 368 West Of State Highway 63	4/26/2016	4/26/2016
	Repair road surface by hand patching	Avenue 404 From Road 74 To Road 64	4/26/2016	4/26/2016
	Repair potholes with Road Patcher	Avenue 216 From Road 84 To Road 36	4/26/2016	4/26/2016
	Repair road surface by hand patching	Road 200 At Spencer Drive	4/26/2016	4/26/2016
	Repair road surface by hand patching	Road 148 North Of Avenue 280	4/26/2016	4/26/2016
	Repair road surface by hand patching	Road 224 From Avenue 96 To Avenue 56	4/27/2016	4/27/2016
	Repair road surface by hand patching	Road 392 At Road 52	4/27/2016	4/27/2016
	Repair road surface by hand patching	Road 52 From Avenue 416 To Avenue 408	4/27/2016	4/27/2016
	Repair road surface by hand patching	Road 42 At Avenue 410	4/27/2016	4/27/2016
	Repair road surface by hand patching	Avenue 432 At Road 64	4/27/2016	4/27/2016
	Repair road surface by hand patching	Road 40 From Avenue 400 To Avenue 384	4/27/2016	4/27/2016
	Repair potholes with Road Patcher	Avenue 216 At Road 84	4/27/2016	4/27/2016
	Repair potholes with Road Patcher	Avenue 184 From Road 96 To Road 28	4/27/2016	4/27/2016
	Repair potholes with Road Patcher	Avenue 144 From State Highway 99 To Road 96	4/27/2016	4/27/2016
	Repair road surface by hand patching	Mountain 137 From Road 284 To End	4/28/2016	5/18/2016
	Repair road surface by hand patching	Mountain 160 From Mountain 137 To State Route 190	4/28/2016	4/28/2016
	Repair road surface by hand patching	Road 140 From Avenue 368 To South Of Avenue 352	4/28/2016	4/28/2016
	Repair potholes with Road Patcher	Avenue 144 From Road 112 To Road 96	4/28/2016	4/28/2016
	Repair road surface by hand patching	Avenue 312 From Road 92 To Road 84	4/28/2016	4/28/2016
	Repair road surface by hand patching	Avenue 120 From Road 124 To Road 112	4/28/2016	4/28/2016
	Repair road surface by hand patching	Avenue 280 From Road 52 North To End	4/28/2016	4/28/2016
	Repair road surface by hand patching	Road 192 At Avenue 344	5/2/2016	5/2/2016
	Haul Patching Material	Deer Creek	5/2/2016	5/2/2016
	Haul Patching Material	Avenue 216 @ Road 46	5/2/2016	5/2/2016
	Haul Patching Material	Avenue 216 @ Road 52	5/2/2016	5/2/2016
	Large area Patching with grader "Blade Patch"	Avenue 229 From Road 46 To Road 48	5/2/2016	5/2/2016
	Large area Patching with grader "Blade Patch"	Avenue 230 From Road 46 To Road 48	5/2/2016	5/2/2016
	Large area Patching with grader "Blade Patch"	Road 48 From Avenue 228 To Avenue 229	5/2/2016	5/2/2016
	Large area Patching with grader "Blade Patch"	Road 46 From Avenue 228 To Avenue 229	5/2/2016	5/2/2016
	Repair road surface by hand patching	Road 52 From Avenue 280 North To End	5/2/2016	5/2/2016
	Repair road surface by hand patching	Road 56 From Avenue 280 To State Highway 198	5/2/2016	5/2/2016
	Repair road surface by hand patching	Avenue 280 From Road 68 To Road 44	5/2/2016	5/2/2016
	Repair road surface by hand patching	Road 112 From Avenue 144 To Avenue 120	5/2/2016	5/2/2016
	Repair road surface by hand patching	Road 224 From Avenue 95 To Avenue 128	5/3/2016	5/3/2016
	Repair road surface by hand patching	Avenue 96 From Road 224 To Road 232	5/3/2016	5/3/2016
	Repair road surface by hand patching	Avenue 336 From Road 156 To Road 168	5/3/2016	5/3/2016
	Repair road surface by hand patching	Avenue 248 From Road 68 To Road 92	5/3/2016	5/3/2016
	Repair road surface by hand patching	Road 124 From Avenue 256 To Avenue 240	5/3/2016	5/3/2016
	Repair road surface by hand patching	Road 80 From Avenue 144 To Avenue 128	5/3/2016	5/3/2016
	Repair road surface by hand patching	Avenue 200 From Road 140 To Road 132	5/3/2016	5/3/2016
	Repair road surface by hand patching	Avenue 88 From Road 96 To Road 84	5/3/2016	5/3/2016
	Repair road surface by hand patching	Road 84 From Avenue 88 To Avenue 84	5/3/2016	5/3/2016
	Repair road surface by hand patching	Avenue 208 East Of Road 168	5/3/2016	5/3/2016
	Repair road surface by hand patching	Road 184 From Avenue 56 To Avenue 80	5/4/2016	5/4/2016
	Repair road surface by hand patching	Avenue 96 From Road 90 To Road 120	5/4/2016	5/4/2016
	Repair road surface by hand patching	Road 96 From Avenue 96 To Avenue 112	5/4/2016	5/4/2016

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

	Repair road surface by hand patching	Road 156 From Avenue 288 To Avenue 296	5/4/2016	5/4/2016
	Repair road surface by hand patching	Road 136 From Avenue 96 To Avenue 112	5/4/2016	5/4/2016
	Repair road surface by hand patching	Road 188 From Avenue 208 To Avenue 256	5/4/2016	5/4/2016
	Repair road surface by hand patching	Crestview From Avenue 128 To Avenue 140	5/5/2016	5/5/2016
	Repair road surface by hand patching	Avenue 128 From Road 224 To Road 232	5/5/2016	5/5/2016
	Repair road surface by hand patching	Avenue 32 From Road 140 To Road 192	5/5/2016	5/5/2016
	Repair road surface by hand patching	Avenue 388 From Road 80 To Road 84	5/5/2016	5/5/2016
	Repair road surface by hand patching	Road 40 At Avenue 408	5/5/2016	5/5/2016
	Repair road surface by hand patching	Diagonal 60 From Avenue 352 To Diagonal 56	5/5/2016	5/5/2016
	Repair road surface by hand patching	Road 96 From Avenue 112 To Avenue 144	5/5/2016	5/5/2016
	Repair road surface by hand patching	Road 80 From Avenue 128 To Avenue 120	5/5/2016	5/5/2016
	Repair road surface by hand patching	Avenue 32 From Road 144 To Road 192	5/9/2016	5/10/2016
	Repair road surface by hand patching	Avenue 95 From Road 232 To Road 256	5/9/2016	5/9/2016
	Repair road surface by hand patching	Avenue 0 From Road 176 To Road 192	5/9/2016	5/9/2016
	Repair road surface by hand patching	Avenue 16 From Road 168 To Road 176	5/9/2016	5/9/2016
	Repair road surface by hand patching	Avenue 24 From Diagonal 205 To Road 192	5/9/2016	5/10/2016
	Repair road surface by hand patching	Avenue 80 From Road 248 To Road 256	5/9/2016	5/9/2016
	Repair road surface by hand patching	Road 132 From Avenue 232 To Avenue 212	5/9/2016	5/9/2016
	Repair road surface by hand patching	Road 176 From Avenue 0 To Avenue 56	5/10/2016	5/16/2016
	Repair road surface by hand patching	Road 238 At Avenue 94	5/10/2016	5/10/2016
	Repair road surface by hand patching	A128 At West	5/10/2016	5/10/2016
	Repair road surface by hand patching	Avenue 320 From Road 128 To Road 132	5/10/2016	5/10/2016
	Repair road surface by hand patching	Avenue 320 From Road 132 To Road 140	5/10/2016	5/10/2016
	Repair road surface by hand patching	Road 160 From Avenue 344 To Avenue 352	5/10/2016	5/10/2016
	Repair road surface by hand patching	Avenue 96 From Road 152 To Road 208	5/11/2016	6/22/2016
	Repair road surface by hand patching	Road 152 From Avenue 96 To Avenue 104	5/11/2016	5/11/2016
	Repair road surface by hand patching	Avenue 88 From Road 236 To Road 256	5/11/2016	5/11/2016
	Repair road surface by hand patching	Avenue 344 At Millwood	5/11/2016	5/11/2016
	Repair road surface by hand patching	Road 132 From Avenue 352 To Avenue 368	5/11/2016	5/11/2016
	Repair road surface by hand patching	Road 156 At Cutler Road	5/11/2016	5/11/2016
	Repair road surface by hand patching	Avenue 364 At Road148	5/11/2016	5/11/2016
	Repair road surface by hand patching	Avenue 368 At Road 140	5/11/2016	5/11/2016
	Repair road surface by hand patching	Road 168 At Avenue 308	5/11/2016	5/10/2016
	Repair road surface by hand patching	Avenue 304 From Road 68 To Road 64	5/11/2016	5/11/2016
	Repair road surface by hand patching	Avenue 308 From Road 64 To Road 52	5/11/2016	5/11/2016
	Repair road surface by hand patching	Avenue 280 At State Highway 99 Overpass	5/11/2016	5/11/2016
	Repair road surface by hand patching	Road 60 At Avenue 308	5/11/2016	5/11/2016
	Repair road surface by hand patching	Road 112 From Avenue 56 To Avenue 54	5/11/2016	5/11/2016
	Repair road surface by hand patching	Road 42 From Avenue 54 To Avenue 56	5/11/2016	5/11/2016
	Repair potholes with Road Patcher	Avenue 144 From Road 104 To Road 88	5/11/2016	5/11/2016
	Repair road surface by hand patching	Avenue 128 At Road 176	5/12/2016	5/12/2016
	Repair road surface by hand patching	Avenue 136 From Road 192 To Road 236	5/12/2016	5/19/2016
	Repair road surface by hand patching	Road 196 From Avenue 364 To Avenue 368	5/12/2016	5/12/2016
	Repair road surface by hand patching	Road 197 South Of State Highway 201	5/12/2016	5/12/2016
	Repair road surface by hand patching	Road 197 North Of State Highway 201	5/12/2016	5/12/2016
	Repair road surface by hand patching	Road 200 North Of State Highway 201	5/12/2016	5/12/2016
	Repair road surface by hand patching	Avenue 380 From Road 200 To Road 204	5/12/2016	5/12/2016
	Repair road surface by hand patching	Avenue 336 From Avenue 216 To Road 180	5/12/2016	5/12/2016
	Repair road surface by hand patching	Diagonal 60 From Avenue 328 To Avenue 352	5/12/2016	5/12/2016
	Repair road surface by hand patching	Avenue 328 At 6329	5/12/2016	5/12/2016
	Repair road surface by hand patching	Avenue 360 From Road 44 To Road 76	5/12/2016	5/12/2016
	Repair road surface by hand patching	Avenue 368 At Cotton Creek	5/12/2016	5/12/2016
	Repair potholes with Road Patcher	Avenue 184 From Road 96 To Road 88	5/12/2016	5/12/2016
	Repair road surface by hand patching	Avenue 54 East Of Road 88	5/12/2016	5/12/2016

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

	Repair road surface by hand patching	Avenue 80 From Road 236 To Road 240	5/16/2016	5/16/2016
	Repair road surface by hand patching	Avenue 80 From Road 256 To Road 264	5/16/2016	5/17/2016
	Repair road surface by hand patching	Avenue 368 West Of Road 108	5/16/2016	5/16/2016
	Repair road surface by hand patching	Avenue 368 West Of Road 80	5/16/2016	5/16/2016
	Repair road surface by hand patching	Road 160 From Avenue 344 To Avenue 352	5/16/2016	5/16/2016
	Repair road surface by hand patching	Diagonal 243 From Mile Post 0 To Mile Post 19	5/16/2016	5/16/2016
	Repair road surface by hand patching	Mountain Road 469 From Mile Post 0 To Mile Post 3	5/16/2016	5/16/2016
	Repair road surface by hand patching	Mountain 393 From Mile Post 0 To Mile Post 3	5/16/2016	5/16/2016
	Repair road surface by hand patching	Elster Avenue West Of E Street	5/16/2016	5/16/2016
	Repair road surface by hand patching	Avenue 200 From Laspina To Spacer Drive	5/16/2016	5/16/2016
	Repair road surface by hand patching	Road 68 From Avenue 240 To Avenue 248	5/16/2016	5/16/2016
	Repair road surface by hand patching	Road 28 From Avenue 232 To Avenue 248	5/16/2016	5/16/2016
	Repair road surface by hand patching	Road 264 From Avenue 80 To Avenue 96	5/17/2016	5/19/2016
	Repair road surface by hand patching	Mountain Road 469 At Mountain Road 468	5/17/2016	5/17/2016
	Repair road surface by hand patching	Mountain Road 468 From Mile Post 0 To Mile Post .5	5/17/2016	5/17/2016
	Repair road surface by hand patching	Road 28 From Avenue 232 To Avenue 208	5/17/2016	5/17/2016
	Repair road surface by hand patching	Road 36 From Avenue 228 To Avenue 238	5/17/2016	5/17/2016
	Repair road surface by hand patching	Avenue 56 From Road 120 To Road 96	5/17/2016	5/17/2016
	Repair road surface by hand patching	Avenue 120 East Of State Highway 99	5/17/2016	5/17/2016
	Repair road surface by hand patching	Road 224 From Avenue 186 To Avenue 192	5/17/2016	5/17/2016
	Repair road surface by hand patching	Mountain Road 465 From State Highway 245 To Mountain Road 469	5/18/2016	5/18/2016
	Repair road surface by hand patching	Mountain Road 469 At Mountain Road 465	5/18/2016	5/18/2016
	Repair road surface by hand patching	Mountain Road 468 From Mile Post .5 To End	5/18/2016	5/18/2016
	Repair road surface by hand patching	Mountain Road 453 South Of Mountain Road 469	5/18/2016	5/18/2016
	Repair road surface by hand patching	Avenue 308 From Road 52 To Road 44	5/18/2016	5/18/2016
	Repair road surface by hand patching	Avenue 264 East Of Road 100	5/18/2016	5/18/2016
	Repair road surface by hand patching	Avenue 96 From Road 264 To R256	5/19/2016	5/19/2016
	Repair road surface by hand patching	Avenue 120 From Road 248 To Road 252	5/19/2016	5/19/2016
	Repair road surface by hand patching	Avenue 368 From Road 108 To Road 84	5/19/2016	5/19/2016
	Repair road surface by hand patching	Wilsonia	5/19/2016	5/19/2016
	Repair road surface by hand patching	Burnett From Jayne To Avenue 144	5/19/2016	5/19/2016
	Repair road surface by hand patching	Avenue 308 From Road 44 To Road 52	5/19/2016	5/19/2016
	Repair road surface by hand patching	Road 52 From Avenue 308 To Avenue 320	5/19/2016	5/19/2016
	Repair road surface by hand patching	Avenue 316 East Of Road 52	5/19/2016	5/19/2016
	Repair road surface by hand patching	Avenue 120 From Road 152 To State Highway 99	5/19/2016	5/19/2016
	Repair road surface by hand patching	Avenue 200 From Road 140 To Spacer Drive	5/19/2016	5/19/2016
	Repair road surface by hand patching	Road 168 From Avenue 8 To Avenue 56	5/23/2016	5/24/2016
	Repair road surface by hand patching	Wilsonia	5/23/2016	5/23/2016
	Repair road surface by hand patching	Avenue 120 From Road 128 To Road 152	5/23/2016	5/23/2016
	Repair road surface by hand patching	Road 248 From Avenue 96 To Avenue 100	5/24/2016	5/24/2016
	Repair road surface by hand patching	Avenue 396 East Of Road 136	5/24/2016	5/24/2016
	Repair road surface by hand patching	Avenue 228 East Of Road 196	5/24/2016	5/24/2016
	Repair road surface by hand patching	Avenue 328 From Road 80 To State Highway 99	5/25/2016	5/25/2016
	Repair road surface by hand patching	Wilsonia	5/25/2016	5/25/2016
	Repair road surface by hand patching	Road 112 North Of Avenue 184	5/25/2016	5/25/2016
	Repair road surface by hand patching	Road 188 North Of Highway 137	5/25/2016	5/25/2016
	Repair road surface by hand patching	Road 208 From Avenue 152 To Avenue 128	5/26/2016	5/26/2016
	Repair road surface by hand patching	Road 192 From Avenue 112 To Avenue 0	5/26/2016	5/26/2016
	Repair road surface by hand patching	Avenue 328 From Road 132 To Road 127	5/26/2016	5/26/2016
	Repair road surface by hand patching	Avenue 328 From Road 80 To State Highway 99	5/26/2016	5/26/2016
	Repair road surface by hand patching	Diagonal 60 From Avenue 328 To Avenue 360	5/26/2016	5/26/2016
	Repair road surface by hand patching	Avenue 352 West Of Road 36	5/26/2016	5/26/2016
	Repair road surface by hand patching	Avenue 424 From Road 124 To Road 88	5/26/2016	5/26/2016
	Repair road surface by hand patching	Road 68 From Avenue 216 To Avenue 192	5/26/2016	5/26/2016

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

	Repair road surface by hand patching	Road 64 From Avenue 192 To Avenue 184	5/26/2016	5/26/2016
	Repair road surface by hand patching	Avenue 264 From Road 100 To State Highway 99	5/31/2016	5/31/2016
	Repair road surface by hand patching	Elm Street From Avenue 96 To Avenue 84	5/31/2016	5/31/2016
	Repair road surface by hand patching	Diagonal 140 From Avenue 24 To Avenue 16	5/31/2016	5/31/2016
	Repair road surface by hand patching	Road 128 From Avenue 0 To Avenue 44	5/31/2016	5/31/2016
	Repair road surface by hand patching	Avenue 160 From Hager Pit To Road 208	5/31/2016	5/31/2016
	Repair road surface by hand patching	Road 208 From Avenue 160 To Avenue 184	5/31/2016	5/31/2016
	Repair road surface by hand patching	Avenue 168 From Road 224 To Road 216	5/31/2016	5/31/2016
	Repair road surface by hand patching	Road 264 From Avenue 96 To Avenue 108	6/1/2016	6/1/2016
	Repair road surface by hand patching	Avenue 396 From Road 24 To Kcl	6/1/2016	6/1/2016
	Repair road surface by hand patching	Road 132 At Avenue 336	6/1/2016	6/1/2016
	Repair road surface by hand patching	Avenue 313 From Road 144 To Road 148	6/1/2016	6/1/2016
	Repair road surface by hand patching	Avenue 440 From Road 120 To Road 128	6/1/2016	6/1/2016
	Repair road surface by hand patching	Road 28 From Avenue 232 To Avenue 216	6/1/2016	6/1/2016
	Repair road surface by hand patching	Avenue 216 East Of Road 28	6/1/2016	6/1/2016
	Repair road surface by hand patching	Road 128 From Avenue 184 To Avenue 160	6/1/2016	6/1/2016
	Repair road surface by hand patching	Road 96 North Of Avenue 196	6/1/2016	6/1/2016
	Repair road surface by hand patching	Avenue 430 From Road 56 To Road 64	6/2/2016	6/2/2016
	Repair road surface by hand patching	Road 156 From Avenue 280 To Avenue 256	6/2/2016	6/2/2016
	Repair road surface by hand patching	Road 32 East Of Jasper	6/4/2016	6/4/2016
	Repair road surface by hand patching	Road 148 From Avenue 328 To Avenue 336	6/6/2016	6/6/2016
	Repair road surface by hand patching	Road 28 From Avenue 216 To Avenue 232	6/6/2016	6/6/2016
	Repair road surface by hand patching	Avenue 216 From Road 28 To Road 84	6/6/2016	6/6/2016
	Repair road surface by hand patching	Road 168 From Avenue 296 To St Johns River	6/6/2016	6/6/2016
	Repair road surface by hand patching	Avenue 170 From Road 28 To State Highway 137	6/6/2016	6/6/2016
	Repair road surface by hand patching	Avenue 120 From Road 264 To Mountain 120	6/7/2016	6/7/2016
	Repair road surface by hand patching	Diagonal 152 From State Highway 245 To Johnson Drive	6/7/2016	6/7/2016
	Repair road surface by hand patching	Avenue 328 From Road 132 To State Highway 63	6/7/2016	6/7/2016
	Repair road surface by hand patching	Road 108 From Avenue 320 To Avenue 328	6/7/2016	6/7/2016
	Repair road surface by hand patching	Avenue 104 From Road 208 To Road 184	6/8/2016	6/8/2016
	Repair road surface by hand patching	Avenue 2 From State Route 65 To End	6/8/2016	6/8/2016
	Repair road surface by hand patching	Road 248 From Avenue 104 To Avenue 106	6/8/2016	6/8/2016
	Repair road surface by hand patching	Road 168 From Avenue 8 To Avenue 24	6/8/2016	6/8/2016
	Repair road surface by hand patching	Avenue 52 From Road 160 To Road 168	6/8/2016	6/15/2016
	Repair road surface by hand patching	Road 180 From Charter Oak To Avenue 312	6/8/2016	6/8/2016
	Repair road surface by hand patching	Fisher From Road 180 To Avenue 318	6/8/2016	6/8/2016
	Repair road surface by hand patching	Charter From Road 188 To Road 180	6/8/2016	6/8/2016
	Repair road surface by hand patching	Road 74 From Avenue 384 To Avenue 392	6/8/2016	6/8/2016
	Repair road surface by hand patching	Road 33 From Avenue 400 To Avenue 396	6/8/2016	6/8/2016
	Repair road surface by hand patching	Road 64 At Avenue 252	6/8/2016	6/8/2016
	Repair road surface by hand patching	Avenue 248 From Road 96 To Road 68	6/8/2016	6/8/2016
	Repair road surface by hand patching	Road 96 From Avenue 168 To Avenue 144	6/8/2016	6/8/2016
	Repair road surface by hand patching	Road 120 South Of Avenue 144	6/8/2016	6/8/2016
	Repair road surface by hand patching	Elm Street From Avenue 112 To Court Street	6/8/2016	6/8/2016
	Repair road surface by hand patching	Avenue 96 From State Highway 99 To Road 80	6/8/2016	6/8/2016
	Repair road surface by hand patching	Park Street From Avenue 120 To Court Street	6/8/2016	6/8/2016
	Repair road surface by hand patching	Avenue 2 From Road 224 To Road 240	6/9/2016	6/9/2016
	Repair road surface by hand patching	Hogback From Mile Post 1 To Mile Post 3	6/9/2016	6/9/2016
	Repair potholes with Road Patcher	Avenue 200 From Spacer Drive To Tulare City Limits	6/9/2016	6/9/2016
	Repair potholes with Road Patcher	Road 100 From Avenue 264 To Visalia City Limits	6/9/2016	6/9/2016
	Repair potholes with Road Patcher	Road 140 From Avenue 256 To Avenue 280	6/9/2016	6/9/2016
	Repair potholes with Road Patcher	Road 76 From Avenue 308 To Visalia City Limits	6/9/2016	6/9/2016
	Repair potholes with Road Patcher	I Street From Avenue 200 To Tulare City Limits	6/9/2016	6/9/2016
	Repair road surface by hand patching	Avenue 120 From State Highway 99 To State Highway 43	6/9/2016	6/9/2016



Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

	Repair road surface by hand patching	Road 120 From Avenue 56 To Avenue 54	6/9/2016	6/9/2016
	Repair road surface by hand patching	I Street From Avenue 200 To Tulare City Limits	6/13/2016	6/13/2016
	Repair road surface by hand patching	Road 96 From Avenue 168 To Avenue 144	6/14/2016	6/14/2016
	Large area Patching with grader "Blade Patch"	Hauling Material For Various Blade Patches From Plant To Avenue 112 Pit	6/14/2016	6/14/2016
	Repair road surface by hand patching	Avenue 312 East Of Road 196	6/14/2016	6/14/2016
	Repair road surface by hand patching	Road 248 From Avenue 106 To Avenue 108	6/15/2016	6/15/2016
	Repair road surface by hand patching	Road 96 From Avenue 144 To Avenue 168	6/15/2016	6/15/2016
	Repair road surface by hand patching	Road 52 From Avenue 252 To Avenue 264	6/15/2016	6/15/2016
	Repair road surface by hand patching	Diagonal 112 From Avenue 152 To Avenue 184	6/15/2016	6/15/2016
	Repair road surface by hand patching	Mountain 9 From Mountain 3 To End	6/16/2016	6/16/2016
	Repair road surface by hand patching	Road 92 At Avenue 260	6/16/2016	6/16/2016
	Repair road surface by hand patching	Betty Drive In Front Of Yamaha Shop	6/16/2016	6/16/2016
	Repair road surface by hand patching	Avenue 309 At Road 48	6/16/2016	6/16/2016
	Repair road surface by hand patching	Avenue 264 From Road 100 To Road 108	6/16/2016	6/16/2016
	Repair road surface by hand patching	Avenue 174 From Road 224 To Road 232	6/16/2016	6/16/2016
	Repair road surface by hand patching	Avenue 224 At Road 188	6/16/2016	6/16/2016
	Repair road surface by hand patching	Avenue 228 From Road 196 To Highway 65	6/16/2016	6/16/2016
	Repair road surface by hand patching	Avenue 384 At Road 12	6/20/2016	6/20/2016
	Repair road surface by hand patching	Clarkson At Avenue 12	6/20/2016	6/20/2016
	Repair road surface by hand patching	Avenue 392 At Road 12	6/20/2016	6/20/2016
	Repair road surface by hand patching	Avenue 328 West Of Road 80	6/20/2016	6/20/2016
	Repair road surface by hand patching	Road 8 From Avenue 388 To F.C.L.	6/20/2016	6/20/2016
	Repair road surface by hand patching	Rasmussen Avenue From Road 71 To Road 76	6/20/2016	6/20/2016
	Repair road surface by hand patching	Betty Drive In Front Of Yamaha Shop	6/20/2016	6/20/2016
	Repair road surface by hand patching	Road 76 From Rasmussen Avenue To Avenue 308	6/20/2016	6/20/2016
	Repair road surface by hand patching	Road 44 From State Highway 198 To Avenue 304	6/20/2016	6/20/2016
	Repair road surface by hand patching	Avenue 176 From Road 80 To Road 64	6/20/2016	6/20/2016
	Repair road surface by hand patching	Road 188 From Avenue 192 To Avenue 224	6/20/2016	6/20/2016
	Repair road surface by hand patching	Avenue 176 From Road 80 To Road 68	6/21/2016	6/21/2016
	Repair road surface by hand patching	Avenue 216 From Road 96 To Road 36	6/21/2016	6/21/2016
	Repair road surface by hand patching	I Street From Avenue 200 To Tulare City Limits	6/21/2016	6/21/2016
	Repair road surface by hand patching	Avenue 304 From Road 44 To Road 68	6/21/2016	6/21/2016
	Repair road surface by hand patching	Road 68 From Avenue 304 To Harley Shop	6/21/2016	6/21/2016
	Repair road surface by hand patching	Road 44 From State Highway 198 To Avenue 304	6/21/2016	6/21/2016
	Repair road surface by hand patching	Road 48 From Avenue 304 To State Highway 198	6/21/2016	6/21/2016
	Repair road surface by hand patching	Road 52 From Avenue 304 To State Highway 198	6/21/2016	6/21/2016
	Repair road surface by hand patching	Avenue 220 South Of Road 196	6/21/2016	6/21/2016
	Repair road surface by hand patching	Road 152 From Avenue 96 To Avenue 144	6/22/2016	6/22/2016
	Repair road surface by hand patching	Road 192 From Avenue 56 To Avenue 152	6/22/2016	6/23/2016
	Repair road surface by hand patching	Avenue 368 From Road 80 To Road 60	6/22/2016	6/22/2016
	Repair road surface by hand patching	Avenue 378 From Road 60 To Road 57	6/22/2016	6/22/2016
	Repair road surface by hand patching	Road 48 From Avenue 304 To State Highway 198	6/22/2016	6/22/2016
	Repair road surface by hand patching	Road 52 From Avenue 304 To State Highway 198	6/22/2016	6/22/2016
	Repair road surface by hand patching	Road 64 From Avenue 304 To State Highway 198	6/22/2016	6/22/2016
	Repair road surface by hand patching	Avenue 216 From Road 96 To Road 36	6/22/2016	6/22/2016
	Repair road surface by hand patching	Avenue 256 From West Street To Enterprise Avenue	6/22/2016	6/22/2016
	Repair road surface by hand patching	Gail Avenue At West Street	6/22/2016	6/22/2016
	Repair road surface by hand patching	Avenue 248 From West Street To Road 28	6/22/2016	6/22/2016
	Repair road surface by hand patching	Avenue 360 From Road 80 To Road 52	6/23/2016	6/23/2016
	Repair road surface by hand patching	Road 44 From Avenue 360 To Avenue 368	6/23/2016	6/23/2016
	Repair road surface by hand patching	Diagonal 60 From Avenue 352 To Avenue 328	6/23/2016	6/23/2016
	Repair road surface by hand patching	Road 144 From Avenue 328 To Avenue 320	6/23/2016	6/23/2016
	Repair road surface by hand patching	Avenue 120 From Road 152 1000' East	6/23/2016	6/23/2016
	Repair road surface by hand patching	Road 130 From Avenue 80 To Avenue 72	6/23/2016	6/23/2016

Tulare County Association Of Governments  
Quarterly Reporting  
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2016 Quarter 4

Local Programs

	Repair road surface by hand patching	Avenue 56 From Road 120 To State Highway 43	6/23/2016	6/23/2016	
	Repair road surface by hand patching	Road 104 At Avenue 144	6/23/2016	6/23/2016	
	Repair road surface by hand patching	Avenue 120 From State Highway 99 To Road 96	6/23/2016	6/23/2016	
	Repair road surface by hand patching	Avenue 208 West Of Road 168	6/23/2016	6/23/2016	
	Repair road surface by hand patching	Road 188 From Avenue 242 To Avenue 256	6/23/2016	6/23/2016	
	Repair road surface by hand patching	Road 196 From Highway 198 To Lort Drive	6/23/2016	6/23/2016	
Mountain Roads	Repair road surface by hand patching	Mountain Road 171A From Avenue 176 To End	4/15/2016	4/15/2016	
	Repair road surface by hand patching	Mountain Road 220 From Milepost 16 To Milepost 18	5/10/2016	5/10/2016	
	Repair road surface by hand patching	Mountain Road 196A At Mountain Road 193A	5/23/2016	5/23/2016	
	Repair road surface by hand patching	Mountain Road 200A From Mountain Road 193A To Avenue 198* (End)	5/23/2016	5/23/2016	
	Repair road surface by hand patching	Mountain Road 191A At Mountain Road 193A	5/23/2016	5/23/2016	
	Large area Patching with grader "Blade Patch"	Mountain Road 296 From Milepost 31.5 To Milepost 35	5/24/2016	5/26/2016	
	Repair road surface by hand patching	Mountain Road 296 At Milepost 19	6/14/2016	6/14/2016	
	Repair road surface by hand patching	Mountain Road 208 From Highway 190 To End	6/21/2016	6/21/2016	
	Repair road surface by hand patching	Mountain Road 208 At Milepost 1.5	6/22/2016	6/22/2016	
	Repair road surface by hand patching	Mountain Road 296 At Milepost 17	6/22/2016	6/22/2016	
	Repair road surface by hand patching	Mountain Road 276 At Milepost 4	6/22/2016	6/22/2016	
Rural Roads				Total	\$ 216,547.77

Tulare County Association Of Goverments  
Quarterly Reporting  
Measure R Programs

FY 2016 Quarter 4

## Local Programs

[illegible]