

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
16/17 Annual Advance \$4,199,499.00 Communities	Alpaugh	Repair road surface by hand patching	Lake Road from Avenue 54 to Park Street	7/13/16/	7/13/2016	\$ 164.55
	Belknap	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 188B to Avenue 197* (End)	8/22/2016	8/22/2016	\$ 953.71
	Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 188E to Mountain Road199A	7/21/2016	7/21/2016	
	Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 189C to Avenue 197* (End)	8/19/2016	8/19/2016	\$ 927.36
	Cutler/Orosi	Repair road surface by hand patching	Railroad Drive from Road 124 to Road 128	7/7/2016	7/7/2016	
	Cutler/Orosi	Repair road surface by hand patching	First Drive from Lincoln Road to Road 128	7/11/2016	7/11/2016	
	Cutler/Orosi	Repair road surface by hand patching	Orosi Drive from Road 128 to Railroad Drive	7/11/2016	7/11/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 406 at Road 127	7/11/2016	7/11/2016	
	Cutler/Orosi	Repair road surface by hand patching	George Road at Avenue 407	7/11/2016	7/11/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 406 from George Road to Lincoln Road	7/11/2016	7/11/2016	
	Cutler/Orosi	Repair road surface by hand patching	School Avenue from Road 128 to Mueller Road	7/11/2016	7/11/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 403 from Road 128 to Cannon Avenue	7/11/2016	7/11/2016	
	Cutler/Orosi	Repair road surface by hand patching	Road 126 at Ella Avenue	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	David Road at Avenue 414	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Luxor Avenue from David Road to Road 124	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Aceves Avenue from Road 124 to Road 120	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 West of Avenue 413	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Wilsonia Avenue at Sequoia Avenue	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Badger Avenue West of Road 124	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 South of Avenue 419	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Eddy Road from Avenue 416 to Miller Road	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 at Avenue 419	7/12/2016	7/12/2016	
	Cutler/Orosi	Repair road surface by hand patching	Orosi Drive from Railroad Drive to First Drive	7/13/2016	7/13/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 407 at Road 124	7/13/2016	7/13/2016	
	Cutler/Orosi	Repair road surface by hand patching	Short Avenue East of Road 124	7/13/2016	7/13/2016	\$ 1,404.95
	Earlimart	Kat Patcher	Avenue 48 from Road 144 to Front Street	8/16/2016	8/16/2016	
	Earlimart	Kat Patcher	Spruce from Church to Lane	8/16/2016	8/16/2016	
	Earlimart	Kat Patcher	Church from Spruce to Avenue 56	8/16/2016	8/16/2016	
	Earlimart	Kat Patcher	Washington from Front to Howard	8/16/2016	8/16/2016	
	Earlimart	Kat Patcher	Valente from Avenue 56 to Washington	8/16/2016	8/16/2016	
	Earlimart	Kat Patcher	Center at Valente	8/16/2016	8/16/2016	
	Earlimart	Kat Patcher	Front Street from Avenue 56 to State Highway 99	8/17/2016	8/17/2016	
	Earlimart	Kat Patcher	Front Street at Cedar Avenue	8/17/2016	8/17/2016	
	Earlimart	Kat Patcher	Wilson Avenue from Market Street to Front Street	8/17/2016	8/17/2016	\$ 1,381.31
	Goshen	Kat Patcher	Road 76 from Avenue 308 to Rasmussen	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Rasmussen from Road 76 to Road 72	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Farr Road from Woodbine Avenue to Avenue 310	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Commercial at Harvest	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Commercial from Avenue 310 to Avenue 308	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Avenue 308 from Road 76 to Camp Driver	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Road 69 at Avenue 310	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Avenue 310 east of Robinson Road	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Effie Road from Avenue 306 to road 68	7/27/2016	7/27/2016	
	Goshen	Kat Patcher	Road 68 at Harvest	7/27/2016	7/27/2016	
	Goshen	Repair road surface by hand patching	Betty Drive at State Highway 99	8/30/2016	8/30/2016	
	Goshen	Repair road surface by hand patching	Avenue 308 from Road 44 to Road 68	8/30/2016	8/30/2016	
	Goshen	Repair road surface by hand patching	Avenue 304 from Road 44 to Road 68	8/30/2016	8/30/2016	\$ 1,157.24

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

Ivanhoe	Repair road surface by hand patching	Road 157 from Avenue 327 to Rosaline Avenue	7/13/2016	7/13/2016	
Ivanhoe	Repair road surface by hand patching	Road 158 at Beechwood Avenue	7/13/2016	7/13/2016	
Ivanhoe	Repair road surface by hand patching	Road 159 at Avenue 327	7/13/2016	7/13/2016	
Ivanhoe	Repair road surface by hand patching	Fucshia Avenue at Road 157	7/13/2016	7/13/2016	
Ivanhoe	Repair road surface by hand patching	Avenue 332 from Road 159 to Hawthorne Road	7/22/2016	7/22/2016	
Ivanhoe	Repair road surface by hand patching	Road 159 North of Avenue 328	7/22/2016	7/22/2016	
Ivanhoe	Repair road surface by hand patching	Depot Drive from Road 158 to Road 160	7/22/2016	7/22/2016	
Ivanhoe	Repair road surface by hand patching	Live Oak Drive from Road 156 to Avenue 330	7/22/2016	7/22/2016	
Ivanhoe	Repair road surface by hand patching	Road 158 at Avenue 328	7/22/2016	7/22/2016	
Ivanhoe	Repair road surface by hand patching	Road 160 North Walter Avenue	7/22/2016	7/22/2016	
Ivanhoe	Repair road surface by hand patching	Road 140 from Avenue 344 to Avenue 352	7/22/2016	7/22/2016	
Ivanhoe	Repair road surface by hand patching	Road 160 North of Road 328	7/28/2016	7/28/2016	
Ivanhoe	Repair road surface by hand patching	Road 160 from Avenue 332 to Avenue 336	8/3/2016	8/3/2016	
Ivanhoe	Repair road surface by hand patching	Avenue 332 from Road 160 to Road 161	8/3/2016	8/3/2016	
Ivanhoe	Repair road surface by hand patching	Heather Avenue at Road 160	8/24/2016	8/24/2016	
Ivanhoe	Repair road surface by hand patching	Heather Avenue from Road 160 to Road 161	8/25/2016	8/25/2016	
Ivanhoe	Repair road surface by hand patching	Road 161 from Heather Avenue to Avenue 332	8/25/2016	8/25/2016	
Ivanhoe	Repair road surface by hand patching	Azalea Avenue from Hawthorne Road to Road 160	8/25/2016	8/25/2016	
Ivanhoe	Repair road surface by hand patching	Azalea Avenue at Road 158	8/25/2016	8/25/2016	
Ivanhoe	Repair road surface by hand patching	Avenue 327 at Road 158	8/25/2016	8/25/2016	
Ivanhoe	Repair road surface by hand patching	Jasmine Avenue at Road 160	8/25/2016	8/25/2016	
Ivanhoe	Repair road surface by hand patching	Avenue 330 West of Road 156	8/25/2016	8/25/2016	\$ 3,500.59
Lemon Cove	Repair road surface by hand patching	Avenue 324 from Highway 198 to Road 236	7/25/2016	7/26/2016	\$ 273.19
London	Repair road surface by hand patching	Avenue 378 from Road 60 to Road 58	8/26/2016	8/26/2016	\$ 199.52
Matheny Tract	Repair road surface by hand patching	Avenue 144 from State Highway 43 to Road 80	7/11/2016	7/11/2016	
Matheny Tract	Repair road surface by hand patching	Various roads in the Tract	7/21/2016	7/22/2016	\$ 748.71
Monson	Repair road surface by hand patching	Monson Drive from Road 104 to Avenue 384	9/16/2016	9/16/2016	\$ 137.51
Mulanax Tract	Grinding	Mulanax Drive at Avenue 264	7/25/2016	7/25/2016	
Mulanax Tract	Hauling oil	From Yard 4 to Mulanax Drive	7/26/2016	7/26/2016	
Mulanax Tract	Large area patching with grader "Blade Patch"	Diagonal 125F (Mulanax) from Avenue 264 to Avenue 264* (for District 2)	7/25/2016	8/1/2016	
Mulanax Tract	Reconstruction of Road	Mulanax Drive north of Avenue 264	7/21/2016	8/15/2016	
Mulanax Tract	Repair Road Surface by resurfacing	Mulanax Tract Helping District 2	7/25/2016	8/3/2016	\$ 83,538.62
Oak Ranch	Repair road surface by hand patching	Avenue 312 from Tower Road to End	7/22/2016	7/22/2016	
Oak Ranch	Repair road surface by hand patching	Avenue 313 from Tower Road to Ranchero Road	7/22/2016	7/22/2016	
Oak Ranch	Repair road surface by hand patching	Lipson Avenue from Tower Road to Ranchero Road	7/22/2016	7/22/2016	
Oak Ranch	Repair road surface by hand patching	Road 144 at VCL	7/22/2016	7/22/2016	\$ 797.35
Orosi	Repair road surface by hand patching	Road 130 from Avenue 416 to Avenue 412	7/7/2016	7/7/2016	
Orosi	Repair road surface by hand patching	Avenue 414 from Road 130 to Road 128	7/7/2016	7/7/2016	
Orosi	Repair road surface by hand patching	Avenue 412 at Road 130	7/7/2016	7/7/2016	
Orosi	Repair road surface by hand patching	Avenue 413 from Road 128 to Road 127	7/7/2016	7/7/2016	\$ 678.71
Patterson Tract	Repair road surface by hand patching	Lincoln Road from Avenue 328 to Avenue 326	7/6/2016	7/6/2016	
Patterson Tract	Repair road surface by hand patching	Lincoln Road from Avenue 328 to Avenue 324	7/28/2016	7/28/2016	
Patterson Tract	Repair road surface by hand patching	Road 127 from Avenue 328 to Avenue 324	7/28/2016	7/28/2016	
Patterson Tract	Repair road surface by hand patching	Avenue 328 from Road 127 to Road 132	7/28/2016	7/28/2016	\$ 487.20

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

Pixley	Kat Patcher	Road 120 west of Bradberry Road	7/13/2016	7/13/2016	
Pixley	Kat Patcher	Davis Road at Market Avenue	7/13/2016	7/13/2016	
Pixley	Kat Patcher	Road 96 from Ash to Center	7/13/2016	7/13/2016	
Pixley	Kat Patcher	Park Avenue from Road 96 to Court Street	7/13/2016	7/13/2016	
Pixley	Kat Patcher	Davis Road from Main Street to Maple Street	7/13/2016	7/13/2016	
Pixley	Kat Patcher	Maple Street at Joanne Avenue	7/13/2016	7/13/2016	
Pixley	Kat Patcher	Elm Street from Road 96 to Howard Road	7/13/2016	7/13/2016	
Pixley	Kat Patcher	School Street from Road 96 to Court Street	7/13/2016	7/13/2016	
Pixley	Kat Patcher	Elm Street from Avenue 96 to Avenue 80	7/25/2016	7/25/2016	\$ 1,111.65
Plainview	Repair road surface by hand patching	Avenue 192 at Road 200	7/6/2016	7/6/2016	
Plainview	Repair road surface by hand patching	Road 196 from Avenue 184 to Avenue 192	7/22/2016	7/22/2016	
Plainview	Repair road surface by hand patching	Avenue 208 east of Road 196	9/9/2016	9/9/2016	
Plainview	Repair road surface by hand patching	Road 196 south of Avenue 192	9/12/2016	9/12/2016	
Plainview	Repair road surface by hand patching	Road 204 from Avenue 184 to Avenue 188	9/16/2016	9/16/2016	\$ 1,423.94
Ponderosa	Repair road surface by hand patching	Mountain Road 168 at Mountain Road 107	8/19/2016	8/19/2016	
Ponderosa	Repair road surface by hand patching	Mountain Road 180B from Mountain Road 107 to Mountain Road 179B	8/19/2016	8/19/2016	\$ 932.52
Porterville	Repair road surface by hand patching	Avenue 169 from Road 250* Porterville CityLimits to Road 252	6/28/2016	6/28/2016	
Porterville	Repair road surface by hand patching	Avenue 169 from Road 252 to Road 248	6/30/2016	6/30/2016	\$ 482.41
Strathmore	Repair road surface by hand patching	Avenue 204 from Road 228 to Road 232	7/5/2016	7/5/2016	
Strathmore	Repair road surface by hand patching	Avenue 184 from Diagonal 242 to Road 248	7/13/2016	7/13/2016	
Strathmore	Repair road surface by hand patching	Avenue 188 from Road 236 to Road 244	8/12/2016	8/12/2016	
Strathmore	Repair road surface by hand patching	Avenue 192 at Road 200	8/23/2016	8/23/2016	
Strathmore	Repair road surface by hand patching	22081 Avenue 208	9/2/2016	9/2/2016	
Strathmore	Repair road surface by hand patching	Avenue 200 from Road 223 to Diagonal 242	9/9/2016	9/9/2016	\$ 1,572.41
Terra Bella	Repair road surface by hand patching	Terra Bella Streets	7/12/2016	7/12/2016	\$ 319.79
Three Rivers	Repair road surface by hand patching	Mountain 348 from Mile Post 6 to Mile Post 9	8/10/2016	8/10/2016	
Three Rivers	Repair road surface by hand patching	Mountain 348 from Mile Post 7 to Mile Post 5.5	8/11/2016	8/11/2016	
Three Rivers	Repair road surface by hand patching	Mountain 357 from Mile Post 0 to Mile Post 7	8/11/2016	8/11/2016	
Three Rivers	Repair road surface by hand patching	Mountain 346 from Mountain 345 to Highway 198	9/1/2016	9/1/2016	
Three Rivers	Repair road surface by hand patching	Mountain 375 from Mile Post 0 to Mile Post 2	9/1/2016	9/1/2016	
Three Rivers	Repair road surface by hand patching	Pierce Drive South of Highway 198	9/1/2016	9/1/2016	\$ 2,137.82
Tonyville	Repair road surface by hand patching	Diagonal 227 from Avenue 248 to Avenue 256	7/7/2016	7/7/2016	
Tonyville	Repair road surface by hand patching	Avenue 240 from Road 204 to Road 216	7/13/2016	7/13/2016	
Tonyville	Repair road surface by hand patching	Road 216 from Avenue 250 to Avenue 264	7/13/2016	7/13/2016	
Tonyville	Repair road surface by hand patching	Avenue 256 from Road 204 to Road 216	7/13/2016	7/13/2016	
Tonyville	Repair road surface by hand patching	Road 212 from Avenue 256 to Avenue 240	7/13/2016	7/13/2016	
Tonyville	Repair road surface by hand patching	Avenue 256 at Road 212	8/23/2016	8/24/2016	
Tonyville	Repair road surface by hand patching	Road 216 north of Avenue 264	9/2/2016	9/2/2016	\$ 1,657.33
Tooleville	Repair road surface by hand patching	Avenue 204 from Road 273 to Road 276	6/27/2016	6/27/2016	
Tooleville	Repair road surface by hand patching	Road 204 at Avenue 264	7/5/2016	7/5/2016	
Tooleville	Repair road surface by hand patching	Road 204 from Avenue 256 to Avenue 288	7/7/2016	7/7/2016	
Tooleville	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 256	7/13/2016	7/13/2016	
Tooleville	Repair road surface by hand patching	Road 188 from Avenue 256 to Avenue 288	7/25/2016	7/25/2016	
Tooleville	Repair road surface by hand patching	Avenue 268 from Diagonal 211 to Road 216	8/5/2016	8/5/2016	
Tooleville	Repair road surface by hand patching	Avenue 264 from Road 204 to Road 212	9/2/2016	9/2/2016	\$ 3,796.91
West Exeter	Repair road surface by hand patching	Road 188 from Highway 137 to Avenue 288	7/5/2016	7/5/2016	
West Exeter	Repair road surface by hand patching	Avenue 288 from Road 188 to Road 204	7/5/2016	7/5/2016	
West Exeter	Repair road surface by hand patching	Road 180 at Avenue 288	7/5/2016	7/5/2016	
West Exeter	Repair road surface by hand patching	Road 188 from Avenue 288 to Avenue 284* (Exeter City Limits)	7/6/2016	7/6/2016	
West Exeter	Repair road surface by hand patching	Avenue 256 from Road 204 to Road 216	7/25/2016	7/25/2016	
West Exeter	Repair road surface by hand patching	Road 188 from Avenue 254 to Avenue 264	9/3/2016	9/3/2016	
West Exeter	Repair road surface by hand patching	Road 188 from Avenue 248 to Exeter City Limits	9/7/2016	9/7/2016	
West Exeter	Repair road surface by hand patching	Avenue 264 at Road 188	9/16/2016	9/16/2016	
West Exeter	Repair road surface by hand patching	Road 188 from Avenue 256 to Exeter City Limits	9/16/2016	9/16/2016	\$ 2,449.13

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads		Repair road surface by hand patching	Avenue 220 from Road 236 to Road 242	6/27/2016	6/30/2016	
		Repair road surface by hand patching	Avenue 120 From Road 96 To State highway 43	6/27/2016	6/27/2016	
		Repair road surface by hand patching	Avenue 54 From State highway 43 To Road 42	6/27/2016	6/27/2016	
		Repair road surface by hand patching	Avenue 264 From State highway 99 To Avenue 108	6/27/2016	6/27/2016	
		Repair road surface by hand patching	Road 158 From Avenue 296 To State highway 216	6/27/2016	6/27/2016	
		Repair road surface by hand patching	Road 132 From Avenue 200 To Avenue 208	6/28/2016	6/28/2016	
		Repair road surface by hand patching	Road 100 From Avenue 264 To Visalia City Limits	6/28/2016	6/28/2016	
		Repair road surface by hand patching	Avenue 96 from Diagonal 216 to Road 224	6/28/2016	6/29/2016	
		Repair road surface by hand patching	Road 192 from Avenue 120 to Avenue 128	6/28/2016	6/29/2016	
		Repair road surface by hand patching	Avenue 120 From Road 96 To Road 80	6/29/2016	6/29/2016	
		Repair road surface by hand patching	Avenue 120 From Road 80 To Road 72	6/30/2016	6/30/2016	
		Repair road surface by hand patching	Road 192 from Avenue 120 to Avenue 144	6/30/2016	6/30/2016	
		Repair road surface by hand patching	Avenue 120 from Road 152 To Road 160	6/30/2016	6/30/2016	
		Kat Patcher	Road 124 From Avenue 232 To Avenue 224	7/5/2016	7/5/2016	
		Kat Patcher	Avenue 128 From Road 96 To Road 88	7/5/2016	7/5/2016	
		Kat Patcher	Munson Road From Avenue 224 To Avenue 226	7/5/2016	7/5/2016	
		Kat Patcher	Allen Road From Avenue 224 To Avenue 226	7/5/2016	7/5/2016	
		Kat Patcher	Avenue 226 From Allen Road To Road 132	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Avenue 328 East of Road 132	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Avenue 428 from Road 136 to Road 128	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Avenue 432 from Road 128 to Road 144	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Avenue 408 from Road 56 to DCL	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Road 64 from Avenue 408 to Avenue 404	7/5/2016	7/5/2016	
		Repair road surface by hand patching	A364 from R140 to R144	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Road 160 at Avenue 362	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Avenue 336 from Road 196 to Highway 216	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Avenue 352 from Road 156 to Road 152	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Road 160 from Avenue 64 to Avenue 80	7/5/2016	7/5/2016	
		Repair road surface by hand patching	Avenue 176 from Road 208 to Road 224	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Road 320 from Avenue 176 to M194G (End)	7/6/2016	7/6/2016	
		Kat Patcher	Avenue 224 From Road 152 To Tulare City Limits	7/6/2016	7/6/2016	
		Kat Patcher	Avenue 152 From State highway 99 To Road 96	7/6/2016	7/6/2016	
		Kat Patcher	Road 96 From Avenue 144 To Avenue 176	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 368 at Road 132	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 368 from Road 140 to Road 132	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Road 140 from Avenue 364 to Avenue 352	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 388 East of Road 120	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 360 from Road 76 to Road 52	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 400 East of Road 128	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 416 from Road 130 to Road 168	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 56 from Road 256 to Road 272	7/6/2016	7/6/2016	
		Repair road surface by hand patching	Avenue 172 from Road 224 to Road 231	7/7/2016	7/7/2016	
		Repair road surface by hand patching	Avenue 120 From Road 122 To 12996 (Address)	7/7/2016	7/7/2016	
		Kat Patcher	Road 96 From Avenue 176 To Avenue 144	7/7/2016	7/7/2016	
		Kat Patcher	Road 140 South Of Caldwell Avenue	7/7/2016	7/7/2016	
		Kat Patcher	Avenue 216 From Road 96 To Road 52	7/7/2016	7/7/2016	
		Repair road surface by hand patching	Sandcreek Drive at Mile Post 1.5	7/7/2016	7/7/2016	
		Repair road surface by hand patching	Avenue 460 from Road 128 to Road 132	7/7/2016	7/7/2016	
		Repair road surface by hand patching	Avenue 468 from Road 128 to Road 120	7/7/2016	7/7/2016	
		Repair road surface by hand patching	Avenue 472 from Road 120 to END	7/7/2016	7/7/2016	
		Repair road surface by hand patching	Road 128 from Avenue 460 to Avenue 472	7/7/2016	7/7/2016	
		Repair road surface by hand patching	Avenue 464 from Road 128 to Road 120	7/7/2016	7/7/2016	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

	Repair road surface by hand patching	Road 124 from Avenue 460 to Avenue 472	7/7/2016	7/7/2016
	Repair road surface by hand patching	Avenue 216 From Road 52 To Road 28	7/11/2016	7/11/2016
	Repair road surface by hand patching	Road 60 From Avenue 232 To Avenue 240	7/11/2016	7/11/2016
	Repair road surface by hand patching	Matheny Tract Roads	7/11/2016	7/11/2016
	Repair road surface by hand patching	Avenue 360 from Road 76 to Road 74	7/11/2016	7/11/2016
	Repair road surface by hand patching	Road 236 at Avenue 100	7/11/2016	7/11/2016
	Repair road surface by hand patching	Avenue 92 at Road 248	7/11/2016	7/11/2016
	Repair road surface by hand patching	Road 248 from Avenue 60 to Avenue 76	7/11/2016	7/12/2016
	Repair road surface by hand patching	Road 144 From Avenue 160 To Avenue 192	7/12/2016	7/12/2016
	Repair road surface by hand patching	Avenue 208 West Of Road 152	7/12/2016	7/12/2016
	Repair road surface by hand patching	Avenue 144 From Road 88 To Road 120	7/12/2016	7/12/2016
	Kat Patcher	Avenue 208 From Road 152 To Road 140	7/12/2016	7/12/2016
	Kat Patcher	Road 128 From Avenue 160 To Avenue 192	7/12/2016	7/12/2016
	Repair road surface by hand patching	Road 136 From Avenue 192 To Avenue 180	7/12/2016	7/12/2016
	Repair road surface by hand patching	Avenue 432 West of Road 136	7/12/2016	7/12/2016
	Repair road surface by hand patching	Road 136 From Avenue 180 To Avenue 168	7/13/2016	7/13/2016
	Repair road surface by hand patching	Spacer Drive At Elk Bayou	7/13/2016	7/13/2016
	Repair road surface by hand patching	Avenue 200 At The Address Of 11485	7/13/2016	7/13/2016
	Repair road surface by hand patching	Avenue 128 From Road 96 To Road 88	7/13/2016	7/13/2016
	Repair road surface by hand patching	Road 88 From Avenue 120 To Avenue 128	7/13/2016	7/13/2016
	Repair road surface by hand patching	Avenue 56 From Road 96 To Road 128	7/13/2016	7/13/2016
	Repair road surface by hand patching	Road 136 From Avenue 180 To Avenue 160	7/14/2016	7/14/2016
	Repair road surface by hand patching	Avenue 296 From Road 168 To The End	7/14/2016	7/14/2016
	Kat Patcher	Avenue 184 From Road 112 To Road 80	7/14/2016	7/14/2016
	Repair road surface by hand patching	Road 72 From Avenue 144 To Avenue 152	7/14/2016	7/14/2016
	Repair road surface by hand patching	Road 52 From Avenue 200 To Avenue 216	7/14/2016	7/14/2016
	Repair road surface by hand patching	Avenue 396 from Road 24 to KCL	7/14/2016	7/14/2016
	Repair road surface by hand patching	Road 320 from Avenue 396 to Avenue 392	7/14/2016	7/14/2016
	Repair road surface by hand patching	Road 48 From Avenue 272 To Avenue 264	7/15/2016	7/15/2016
	Repair road surface by hand patching	Road 58 South Of Avenue 264	7/15/2016	7/15/2016
	Repair road surface by hand patching	Avenue 128 From Road 80 To Road 88	7/15/2016	7/15/2016
	Repair road surface by hand patching	Road 96 From Avenue 88 To Avenue 120	7/15/2016	7/15/2016
	Repair road surface by hand patching	Avenue 88 From Road 96 To Road 84	7/15/2016	7/15/2016
	Repair road surface by hand patching	Avenue 380 from Road 206 to Road 208	7/15/2016	7/15/2016
	Repair road surface by hand patching	Road 206 from Avenue 380 to Avenue 384	7/15/2016	7/15/2016
	Repair road surface by hand patching	Avenue 384 from Road 206 to Road 204	7/15/2016	7/15/2016
	Repair road surface by hand patching	Road 204 from Avenue 384 to Avenue 376	7/15/2016	7/15/2016
	Repair road surface by hand patching	Avenue 388 from Road 128 to Road 120	7/15/2016	7/15/2016
	Repair road surface by hand patching	Road 132 at Avenue 384	7/15/2016	7/15/2016
	Repair road surface by hand patching	Road 96 From Avenue 112 To Avenue 188	7/18/2016	7/18/2016
	Repair road surface by hand patching	Avenue 144 From Road 80 To Road 72	7/18/2016	7/19/2016
	Repair road surface by hand patching	Road 140 from Avenue 420 to Avenue 428	7/18/2016	7/18/2016
	Repair road surface by hand patching	Ione Road from Avenue 416 to Avenue 420	7/18/2016	7/18/2016
	Repair road surface by hand patching	Road 136 from Avenue 416 to Avenue 428	7/18/2016	7/18/2016
	Repair road surface by hand patching	Avenue 320 At Akers Road	7/19/2016	7/19/2016
	Repair road surface by hand patching	Road 96 From Avenue 104 To Avenue 96	7/19/2016	7/19/2016
	Repair road surface by hand patching	Diagonal 96 At Avenue 304 On-Ramp	7/19/2016	7/19/2016
	Repair road surface by hand patching	Avenue 420 from Road 136 to Road 140	7/19/2016	7/19/2016
	Repair road surface by hand patching	Avenue 426 from Road 62 to Road 56	7/19/2016	7/19/2016
	Repair road surface by hand patching	Avenue 424 from Road 96 to Road 88	7/21/2016	7/21/2016
	Repair road surface by hand patching	Avenue 426 from Road 56 to Road 64	7/21/2016	7/21/2016
	Repair road surface by hand patching	Boyd Drive from Mile Post 0 to State Highway 245	7/21/2016	7/21/2016
	Repair road surface by hand patching	Avenue 272 from Road 228 to Diagonal 211	7/22/2016	7/22/2016
	Repair road surface by hand patching	I Street From Avenue 200 To Tulare City Limits	7/22/2016	7/22/2016
	Repair road surface by hand patching	Road 68 From Avenue 196 To Avenue 228	7/22/2016	7/22/2016

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

	Kat Patcher	Avenue 216 From Tulare City Limits To State Highway 137	7/25/2016	7/25/2016
	Repair road surface by hand patching	Avenue 352 from Road 140 to Road 156	7/26/2016	7/26/2016
	Repair road surface by hand patching	Road 140 from Avenue 344 to Avenue 352	7/26/2016	7/26/2016
	Repair road surface by hand patching	Avenue 360 at 7000	7/26/2016	7/28/2016
	Repair road surface by hand patching	Road 44 From Avenue 232 To Avenue 236	7/27/2016	7/27/2016
	Repair road surface by hand patching	Avenue 424 from Road 92 to Road 100	7/27/2016	7/27/2016
	Repair road surface by hand patching	Road 56 North of Lawrence Avenue	7/27/2016	7/27/2016
	Repair road surface by hand patching	Avenue 320 from Road 148 to Road 124	7/27/2016	7/27/2016
	Repair road surface by hand patching	Road 150 from Avenue 352 to Avenue 360	7/27/2016	7/27/2016
	Repair road surface by hand patching	Avenue 352 from Road 112 to Road 124	7/27/2016	7/28/2016
	Kat Patcher	Road 156 North Of Avenue 264	7/28/2016	7/28/2016
	Kat Patcher	Avenue 264 From Road 156 To Road 164	7/28/2016	7/28/2016
	Kat Patcher	Stanford Avenue From Road 136 To Park Street	7/28/2016	7/28/2016
	Repair road surface by hand patching	Avenue 248 From Road 92 To Road 64	7/28/2016	7/28/2016
	Repair road surface by hand patching	Avenue 120 From Road 16 To Road 24	7/28/2016	7/28/2016
	Repair road surface by hand patching	Avenue 352 from Road 112 to Road 124	7/28/2016	7/28/2016
	Repair road surface by hand patching	Avenue 336 from Road 160 to Road 168	7/28/2016	7/28/2016
	Repair road surface by hand patching	Road 44 from Avenue 368 to Avenue 360	7/28/2016	7/28/2016
	Kat Patcher	Avenue 104 From Road 112 To Road 64	7/29/2016	7/29/2016
	Repair road surface by hand patching	Avenue 360 from Road 76 to Road 52	7/29/2016	7/29/2016
	Repair road surface by hand patching	Avenue 368 from Road 80 to Road 60	7/29/2016	7/29/2016
	Repair road surface by hand patching	Avenue 260 From Road 148 East To The End	8/1/2016	8/1/2016
	Repair road surface by hand patching	Avenue 308 From Road 64 To The West	8/1/2016	8/1/2016
	Repair road surface by hand patching	Diagonal 69 From Avenue 304 To Avenue 306	8/1/2016	8/1/2016
	Repair road surface by hand patching	Road 60 From Avenue 308 To Avenue 320	8/1/2016	8/1/2016
	Repair road surface by hand patching	Road 72 North Of Avenue 184	8/1/2016	8/1/2016
	Kat Patcher	Diagonal 69 From Avenue 304 To Avenue 306	8/1/2016	8/1/2016
	Kat Patcher	Avenue 260 From Road 148 To The End	8/1/2016	8/1/2016
	Kat Patcher	Avenue 308 From Road 64 To The West	8/1/2016	8/1/2016
	Kat Patcher	Avenue 184 From Road 28 To Road 104	8/1/2016	8/1/2016
	Repair road surface by hand patching	Avenue 424 from Road 100 to Road 120	8/1/2016	8/1/2016
	Repair road surface by hand patching	Road 160 from Avenue 352 to Avenue 344	8/1/2016	8/1/2016
	Repair road surface by hand patching	Avenue 360 from Road 76 to Road 52	8/1/2016	8/1/2016
	Repair road surface by hand patching	Avenue 120 From State Highway 99 To Road 88	8/2/2016	8/2/2016
	Repair road surface by hand patching	Avenue 264 West Of Road 100	8/2/2016	8/2/2016
	Repair road surface by hand patching	Avenue 120 From Park To Road 152	8/2/2016	8/2/2016
	Repair road surface by hand patching	Avenue 388 from Monson Drive to Road 88	8/2/2016	8/2/2016
	Repair road surface by hand patching	Road 42 from Avenue 416 to Avenue 424	8/2/2016	8/2/2016
	Repair road surface by hand patching	Avenue 410 at Road 48	8/2/2016	8/2/2016
	Kat Patcher	Avenue 120 From Road 128 To Road 136	8/3/2016	8/3/2016
	Kat Patcher	Road 128 From Avenue 120 To Avenue 128	8/3/2016	8/3/2016
	Kat Patcher	Avenue 144 From Burnett To State Highway 43	8/3/2016	8/3/2016
	Repair road surface by hand patching	Avenue 336 from Road 172 to Road 144	8/3/2016	8/3/2016
	Repair road surface by hand patching	Road 172 from Avenue 352 to Avenue 356	8/3/2016	8/3/2016
	Repair road surface by hand patching	Road 48 from Avenue 410 to Avenue 416	8/3/2016	8/3/2016
	Repair road surface by hand patching	Road 156 from Avenue 376 to Avenue 362	8/3/2016	8/3/2016
	Repair road surface by hand patching	Avenue 260 From Road 52 To Road 60	8/4/2016	8/4/2016
	Kat Patcher	Road 112 From Avenue 152 To Avenue 184	8/4/2016	8/4/2016
	Kat Patcher	Diagonal 112 From Avenue 152 To Avenue 184	8/4/2016	8/4/2016
	Repair road surface by hand patching	Road 40 from Avenue 384 to Avenue 392	8/4/2016	8/4/2016
	Repair road surface by hand patching	Road 28 from Avenue 384 to Avenue 390	8/4/2016	8/4/2016
	Repair road surface by hand patching	Diagonal 60 from Avenue 360 to Avenue 328	8/4/2016	8/4/2016
	Repair road surface by hand patching	Avenue 368 from Road 20 to Road 36	8/4/2016	8/4/2016
	Repair road surface by hand patching	Avenue 320 from Road 196 to Road 190	8/4/2016	8/4/2016
	Repair road surface by hand patching	Avenue 160 at Friant Kern Canal	8/5/2016	8/5/2016

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

	Repair road surface by hand patching	Road 100 From Avenue 264 To Visalia City Limits	8/5/2016	8/5/2016
	Repair road surface by hand patching	Avenue 56 From Road 32 To Road 116	8/5/2016	8/5/2016
	Repair road surface by hand patching	Diagonal 152 from Road 152 To State Highway 245	8/5/2016	8/5/2016
	Kat Patcher	Road 148 From Avenue 240 To Avenue 248	8/8/2016	8/8/2016
	Kat Patcher	Avenue 240 From Road 12 To Road 168	8/8/2016	8/8/2016
	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 352	8/8/2016	8/8/2016
	Repair road surface by hand patching	Avenue 368 from Road 36 to Road 28	8/8/2016	8/8/2016
	Repair road surface by hand patching	Avenue 368 from Road 80 to Road 76	8/8/2016	8/8/2016
	Repair road surface by hand patching	Avenue 220 from Road 224 to Road 228	8/9/2016	8/9/2016
	Repair road surface by hand patching	Road 220 from Diagonal 242 to Avenue 220	8/9/2016	8/9/2016
	Kat Patcher	Road 148 From Avenue 248 To Avenue 256	8/9/2016	8/9/2016
	Kat Patcher	Avenue 200 From Road 136 To Road 140	8/9/2016	8/9/2016
	Repair road surface by hand patching	Road 136 From Avenue 0 To Avenue 16	8/10/2016	8/10/2016
	Kat Patcher	Road 168 From Avenue 296 North To The End	8/10/2016	8/10/2016
	Kat Patcher	Road 158 From Avenue 296 North To The End	8/10/2016	8/10/2016
	Kat Patcher	Road 152 From Avenue 296 To State Hiway 216	8/10/2016	8/10/2016
	Kat Patcher	Road 176 From Avenue 264 To Avenue 280	8/10/2016	8/10/2016
	Kat Patcher	Avenue 264 From Road 140 To Road 176	8/10/2016	8/10/2016
	Kat Patcher	I Street From Avenue 200 To Addie	8/10/2016	8/10/2016
	Repair road surface by hand patching	Road 136 From Avenue 16 To Avenue 24	8/11/2016	8/11/2016
	Repair road surface by hand patching	Avenue 239 at Road 204	8/12/2016	8/12/2016
	Repair road surface by hand patching	Avenue 241 from Road 200 to Road 204	8/12/2016	8/12/2016
	Repair road surface by hand patching	Road 244 from Avenue 196 to Avenue 224	8/12/2016	8/12/2016
	Repair road surface by hand patching	Burnett Road From Avenue 144 To Avenue 152	8/12/2016	8/12/2016
	Repair road surface by hand patching	Callison Road From Avenue 144 To Avenue 152	8/12/2016	8/12/2016
	Repair road surface by hand patching	Avenue 152 From State Highway 99 To Road 96	8/12/2016	8/12/2016
	Repair road surface by hand patching	Road 96 From Avenue 160 To Avenue 168	8/12/2016	8/12/2016
	Repair road surface by hand patching	Avenue 448 from Road 120 to Road 128	8/12/2016	8/12/2016
	Repair road surface by hand patching	Avenue 460 from Road 128 to Road 132	8/12/2016	8/12/2016
	Repair road surface by hand patching	Road 128 South of Avenue 472	8/12/2016	8/12/2016
	Repair road surface by hand patching	Road 68 From Avenue 192 To Avenue 216	8/16/2016	8/16/2016
	Repair road surface by hand patching	Avenue 120 From Road 72 To Road 80	8/16/2016	8/16/2016
	Repair road surface by hand patching	Road 48 from Avenue 416 to Avenue 410	8/16/2016	8/16/2016
	Repair road surface by hand patching	Road 172 from Avenue 384 to Avenue 344	8/16/2016	8/16/2016
	Repair road surface by hand patching	Avenue 336 from Road 188 to Road 158	8/16/2016	8/16/2016
	Repair road surface by hand patching	Road 48 at Avenue 408	8/16/2016	8/16/2016
	Repair road surface by hand patching	Charter Oak Drive from Road 188 to Road 168	8/16/2016	8/16/2016
	Kat Patcher	Road 120 From Avenue 80 To Avenue 96	8/17/2016	8/17/2016
	Repair road surface by hand patching	Avenue 120 From Road 72 To State Highway 43	8/17/2016	8/17/2016
	Repair road surface by hand patching	Road 92 North Of Avenue 260	8/17/2016	8/17/2016
	Repair road surface by hand patching	Avenue 392 East of Road 136	8/17/2016	8/17/2016
	Repair road surface by hand patching	Avenue 400 East of Road 128	8/17/2016	8/17/2016
	Repair road surface by hand patching	Road 62 at Avenue 422	8/17/2016	8/17/2016
	Repair road surface by hand patching	Road 84 from Avenue 400 to Avenue 368	8/17/2016	8/17/2016
	Repair road surface by hand patching	Avenue 120 From Road 88 To State Highway 43	8/18/2016	8/18/2016
	Repair road surface by hand patching	El Rio Drive from Road 168 to Highway 216	8/18/2016	8/18/2016
	Repair road surface by hand patching	Road 140 from Avenue 344 to Avenue 368	8/18/2016	8/18/2016
	Repair road surface by hand patching	Avenue 328 from Road 156 to Road 152	8/18/2016	8/18/2016
	Repair road surface by hand patching	Charter Oak Drive from Road 180 to Road 188	8/18/2016	8/23/2016
	Repair road surface by hand patching	Road 148 from Avenue 336 to Avenue 328	8/18/2016	8/23/2016
	Repair road surface by hand patching	Avenue 304 At Road 48	8/19/2016	8/19/2016
	Repair road surface by hand patching	Road 44 From State Highway 198 To Avenue 304	8/19/2016	8/19/2016
	Repair road surface by hand patching	Avenue 216 From Enterprise To Road 68	8/19/2016	8/19/2016
	Repair road surface by hand patching	Road 180 south of Avenue 216	8/23/2016	8/23/2016
	Repair road surface by hand patching	Road 220 at Diagonal 242	8/23/2016	8/23/2016

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

	Repair road surface by hand patching	Avenue 216 from Diagonal 242 to Road 244	8/23/2016	8/23/2016
	Repair road surface by hand patching	Avenue 304 from Road 182 to Road 180	8/23/2016	8/23/2016
	Repair road surface by hand patching	Avenue 312 at Road 204 (Highway 245)	8/23/2016	8/23/2016
	Repair road surface by hand patching	Avenue 304 at Road 182	8/23/2016	8/23/2016
	Kat Patcher	Avenue 240 From Tulare City Limit To Road 68	8/23/2016	8/23/2016
	Kat Patcher	Avenue 256 From Road 140 To Road 168	8/23/2016	8/23/2016
	Kat Patcher	Avenue 168 From Raod 140 To farmersville C.L.	8/23/2016	8/23/2016
	Kat Patcher	Road 68 From Avenue 240 To Avenue 248	8/23/2016	8/23/2016
	Repair road surface by hand patching	Avenue 180 From Raod 128 To Road 136	8/23/2016	8/23/2016
	Repair road surface by hand patching	Road 128 From Avenue 164 To Avenue 192	8/23/2016	8/23/2016
	Repair road surface by hand patching	Avenue 404 from Road 48 to Road 40	8/23/2016	8/23/2016
	Repair road surface by hand patching	Avenue 368 West of Road 140	8/23/2016	8/23/2016
	Repair road surface by hand patching	Avenue 315 from Road 168 to Charter Oak Drive	8/23/2016	8/23/2016
	Repair road surface by hand patching	Road 168 at Charter Oak Drive	8/23/2016	8/23/2016
	Repair road surface by hand patching	Road 184 from Avenue 312 to End	8/23/2016	8/23/2016
	Repair road surface by hand patching	Road 172 at Avenue 384	8/24/2016	8/24/2016
	Repair road surface by hand patching	Road 256 from Diagonal 252 to Avenue 196	8/25/2016	8/25/2016
	Repair road surface by hand patching	Road 128 From Avenue 164 To Avenue 192	8/25/2016	8/25/2016
	Repair road surface by hand patching	Avenue 56 From Road 96 To Road 120	8/25/2016	8/25/2016
	Repair road surface by hand patching	Road 28 From Avenue 208 To Avenue 232	8/25/2016	8/25/2016
	Repair road surface by hand patching	Reid Avenue from Lime Street to Porterville City Limits	8/26/2016	8/26/2016
	Repair road surface by hand patching	Road 80 From Avenue 144 To Avenue 160	8/26/2016	8/26/2016
	Repair road surface by hand patching	Avenue 392 from Road 144 to End	8/26/2016	8/26/2016
	Repair road surface by hand patching	Road 140 from Avenue 364 to Avenue 344	8/26/2016	8/26/2016
	Repair road surface by hand patching	Avenue 336 from Road 156 to Road 132	8/26/2016	8/26/2016
	Repair road surface by hand patching	Avenue 352 from Pine Road to Road 206	8/26/2016	8/26/2016
	Repair road surface by hand patching	Avenue 320 from Road 108 to Road 100	8/26/2016	8/26/2016
	Repair road surface by hand patching	Road 108 from Avenue 328 to Avenue 320	8/26/2016	8/26/2016
	Repair road surface by hand patching	Road 132 From Avenue 256 To Avenue 272	8/29/2016	8/29/2016
	Repair road surface by hand patching	Midvalley Avenue From Road 124 East To End	8/29/2016	8/29/2016
	Repair road surface by hand patching	Avenue 272 From Road 100 To Road 108	8/29/2016	8/29/2016
	Repair road surface by hand patching	Road 80 From Avenue 160 To Avenue 176	8/29/2016	8/29/2016
	Repair road surface by hand patching	Road 112 From Avenue 160 To Avenue 176	8/29/2016	8/29/2016
	Repair road surface by hand patching	Avenue 120 From Road 88 To Road 96	8/29/2016	8/29/2016
	Repair road surface by hand patching	Avenue 200 From Road 140 To Laspina Avenue	8/29/2016	8/29/2016
	Repair road surface by hand patching	Road 80 North of Avenue 328	8/29/2016	8/29/2016
	Repair road surface by hand patching	Avenue 424 from Road 100 to Road 96	8/29/2016	8/29/2016
	Repair road surface by hand patching	Fisher Drive from Road 180 to Avenue 320	8/30/2016	8/30/2016
	Repair road surface by hand patching	Avenue 328 from Road 80 to Highway 99	8/30/2016	8/30/2016
	Repair road surface by hand patching	Avenue 416 from Road 136 from Road 168	8/30/2016	8/30/2016
	Repair road surface by hand patching	Avenue 424 from Road 100 to Road 88	8/30/2016	8/30/2016
	Repair road surface by hand patching	Avenue 318 from Road 196 to Fisher Drive	8/30/2016	8/30/2016
	Repair road surface by hand patching	Road 52 From Avenue 216 To Avenue 228	8/31/2016	8/31/2016
	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 424	8/31/2016	8/31/2016
	Repair road surface by hand patching	Avenue 368 from Road 204 to State Highway 245	8/31/2016	8/31/2016
	Repair road surface by hand patching	Road 114 from Avenue 424 to Avenue 432	8/31/2016	8/31/2016
	Repair road surface by hand patching	Road 112- Sequoia Field Airport	8/31/2016	8/31/2016
	Repair road surface by hand patching	Road 132 from Avenue 352 to Avenue 360	9/1/2016	9/1/2016
	Repair road surface by hand patching	Avenue 352 from Road 140 to Road 156	9/1/2016	9/1/2016
	Repair road surface by hand patching	Avenue 424 from Road 96 to Road 100	9/1/2016	9/1/2016
	Repair road surface by hand patching	Avenue 424 from Road 72 to Road 64	9/1/2016	9/1/2016
	Repair road surface by hand patching	Avenue 224 from Diagonal 242 to Highway 65	9/2/2016	9/2/2016
	Repair road surface by hand patching	Avenue 224 from Road 196 to Road 204	9/2/2016	9/2/2016
	Repair road surface by hand patching	Avenue 280 west of Mountain Road 296	9/2/2016	9/2/2016
	Repair road surface by hand patching	Avenue 352 from Road 112 to Road 140	9/2/2016	9/2/2016

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

	Repair road surface by hand patching	Avenue 336 from Road 132 to Road 156	9/2/2016	9/2/2016	
	Repair road surface by hand patching	Avenue 328 from Road 127 to Road 132	9/2/2016	9/2/2016	
	Repair road surface by hand patching	Road 114 from Avenue 416 to Avenue 424	9/2/2016	9/2/2016	
	Repair road surface by hand patching	Road 144 from Avenue 328 to Avenue 320	9/6/2016	9/6/2016	
	Repair road surface by hand patching	Avenue 408 from Road 144 to Road 136	9/6/2016	9/6/2016	
	Repair road surface by hand patching	Avenue 192 at Road 152	9/7/2016	9/7/2016	
	Kat Patcher	Avenue 216 From Road 36 To Road 80	9/7/2016	9/7/2016	
	Kat Patcher	Avenue 144 From Burnett To State Highway 43	9/8/2016	9/8/2016	
	Kat Patcher	Road 80 South Of Avenue 144	9/8/2016	9/8/2016	
	Repair road surface by hand patching	Reid Avenue from Scenic Drive to Lime Street	9/9/2016	9/9/2016	
	Repair road surface by hand patching	Avenue 208 from Road 164 to Road 196	9/9/2016	9/9/2016	
	Repair road surface by hand patching	Avenue 2 from Road 232* State Highway 65 to Road 244* End	9/9/2016	9/9/2016	
	Kat Patcher	Avenue 264 From Road 108 To State Highway 99	9/9/2016	9/9/2016	
	Kat Patcher	Court Street From Park To School	9/9/2016	9/9/2016	
	Kat Patcher	Road 120 North Of Avenue 96	9/9/2016	9/9/2016	
	Repair road surface by hand patching	Avenue 208 at Road 164	9/12/2016	9/12/2016	
	Repair road surface by hand patching	Road 168 south of Avenue 208	9/12/2016	9/12/2016	
	Kat Patcher	Avenue 184 From Road 72 To State Highway 99	9/12/2016	9/12/2016	
	Repair road surface by hand patching	Road 196 from Avenue 184 to Avenue 192	9/13/2016	9/13/2016	
	Kat Patcher	Road 100 From Avenue 264 To Visalia City Limits	9/13/2016	9/13/2016	
	Kat Patcher	Avenue 200 From Road 140 To Road 132	9/13/2016	9/13/2016	
	Kat Patcher	Road 140 From Avenue 256 To Avenue 280	9/13/2016	9/13/2016	
	Repair road surface by hand patching	Road 116 at Avenue 408	9/13/2016	9/13/2016	
	Repair road surface by hand patching	Road 142 from Avenue 416 to Avenue 420	9/13/2016	9/13/2016	
	Repair road surface by hand patching	Road 136 from Avenue 428 to Avenue 432	9/13/2016	9/13/2016	
	Repair road surface by hand patching	Avenue 408 at Road 136	9/13/2016	9/13/2016	
	Repair road surface by hand patching	Road 136 from Avenue 432 to Avenue 428	9/13/2016	9/13/2016	
	Kat Patcher	Avenue 152 From Road 152 To State Highway 99	9/14/2016	9/14/2016	
	Kat Patcher	Avenue 184 From Road 96 To State Highway 99	9/14/2016	9/14/2016	
	Repair road surface by hand patching	Avenue 428 from Road 144 to Road 142	9/14/2016	9/14/2016	
	Repair road surface by hand patching	Road 140 from Avenue 428 to Avenue 432	9/14/2016	9/14/2016	
	Repair road surface by hand patching	Avenue 436 from Road 136 to Road 140	9/14/2016	9/14/2016	
	Kat Patcher	Avenue 152 From Diagonal 112 To State Highway 99	9/15/2016	9/15/2016	
	Kat Patcher	Road 148 South Of Avenue 256	9/15/2016	9/15/2016	
	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 250	9/16/2016	9/16/2016	
	Repair road surface by hand patching	Avenue 224 at Road 188	9/16/2016	9/16/2016	
	Repair road surface by hand patching	Avenue 184 from Road 236 to Road 247	9/16/2016	9/16/2016	
	Repair road surface by hand patching	Road 238 from Avenue 180*(Porterville City Limits north of Johns Drive) to Avenue	9/16/2016	9/16/2016	
	Repair road surface by hand patching	Avenue 181 from Diagonal 242 to Road 238	9/16/2016	9/16/2016	
	Kat Patcher	Avenue 152 From State Highway 99 To Road 96	9/16/2016	9/16/2016	
	Kat Patcher	Road 96 From Avenue 152 To Avenue 168	9/16/2016	9/16/2016	
	Repair road surface by hand patching	Avenue 408 from DCL to Road 56	9/16/2016	9/16/2016	
	Repair road surface by hand patching	Avenue 352 from Road 180 to Avenue 334	9/16/2016	9/16/2016	
	Repair road surface by hand patching	Avenue 344 at Road 158	9/16/2016	9/16/2016	
Mountain Roads	Repair road surface by hand patching	Mountain Road 171A from Avenue 171* (End) to Avenue 176	6/28/2016	6/28/2016	
	Repair road surface by hand patching	Mountain Road 220 at Milepost 3.5	6/29/2016	6/29/2016	
	Repair road surface by hand patching	Mountain Road 276 at Milepost 3.5	6/29/2016	6/29/2016	
	Repair road surface by hand patching	Mountain Road 276 from Mountain Road 239 to Milepost 31	6/29/2016	6/29/2016	
	Repair road surface by hand patching	Mountain Road 161 from Mountain Road 168A to Mountain Road 164	6/30/2016	6/30/2016	
	Repair road surface by hand patching	Mountain Road 172A from Avenue 172* (Highway 190) to Milepost 4.56 (Highway 1	6/30/2016	6/30/2016	
	Repair road surface by hand patching	Mountain Road 276 from Mountain Road 296 to Milepost 3.5	6/30/2016	6/30/2016	
	Repair road surface by hand patching	Mountain Road 296 from Milepost 0 (Highway 198) to Milepost 3	7/22/2016	7/22/2016	
	Repair road surface by hand patching	Mountain Road 173A from Road 320 to Mountain Road 170A	8/5/2016	8/5/2016	
	Repair road surface by hand patching	Mountain Road 172C from Mountain Road 173A to Road 316* (End)	8/5/2016	8/5/2016	\$ 94,369.49

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720) AC Overlays MR (AB720)		Preliminary Engineering	Avenue 280 County Line to State Route 99 Farm to Market	7/25/2016	ongoing	\$ 5,853.06
		Preliminary Engineering/ Design	Community Road Surfacing	5/14/2014	ongoing	\$ 105.79
		Construction/Design	Road 148 Avenue 280 Visalia Road to Avenue 288 Marinette Avenue	7/18/2014	ongoing	\$ 6,879.19
		Construction/Design	Road 200 from Avenue 0 to Avenue 8	7/18/2014	ongoing	\$ 119.93
		Construction/Design	Avenue 432 Floral Avenue Road 128 to State Highway 63 to Road 136	7/18/2014	ongoing	\$ 11,255.88
		Preliminary Engineering/ Design	Community Road Surface Maintenance	1/15/2015	ongoing	\$ 413.51
		Preliminary Engineering/ Design	Woodville Elementary and Road 168	3/2/2016	ongoing	\$ 4,810.00
		Preliminary Engineering/ Design	Sunnyside Elementary and Avenue 196	3/2/2016	ongoing	\$ 7,016.30
		Preliminary Engineering/ Design	Sequoia Union Elementary and Avenue 324	3/2/2016	ongoing	\$ 39,207.43
		Preliminary Engineering/ Design	School Street to Park Drive	3/2/2016	ongoing	\$ 4,692.60
		Preliminary Engineering/ Design	Terra Bella Avenue to Court Avenue	3/2/2016	ongoing	\$ 3,950.91
		Preliminary Engineering/ Design	Road 38 at Avenue 54 to 650 South of Intersection	3/2/2016	ongoing	\$ 5,269.18
		Preliminary Engineering/ Design	Avenue 306 to Effie Drive	3/2/2016	ongoing	\$ 8,286.56
		Preliminary Engineering/ Design	Avenue 368 East of Canal Drive	3/2/2016	ongoing	\$ 5,575.38
		Preliminary Engineering/ Design	Zante Drive and Baker Drive	3/2/2016	ongoing	\$ 3,057.96
		Preliminary Engineering/ Design	Ducor Elementary School and Avenue 56	3/2/2016	ongoing	\$ 5,244.44
		Preliminary Engineering/ Design	Road 256 South of Avenue 104	3/2/2016	ongoing	\$ 11,153.71
		Preliminary Engineering/ Design	Road 236 from Avenue 96 to Avenue 100	3/2/2016	ongoing	\$ 482.81
		Construction/Design	Strathmore Slurry Seal and Isolated Road Repair	3/2/2016	ongoing	\$ 1,493.72
		Preliminary Engineering/ Design	El Monte (Avenue 416) West of Road 124	3/2/2016	ongoing	\$ 18,000.00
		Preliminary Engineering/ Design	Golden Valley School and Road 127	3/2/2016	ongoing	\$ 3,041.74
						\$ 352,514.02

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
16/17 Annual Advance \$4,199,499.00 Communities	Camp Nelson	Repair road surface by hand patching	Mountain Road 198A at Mountain Road 193A	10/26/2016	10/26/2016	\$ 389.84
	Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from Road 124 to State Highway 63	11/4/2016	11/4/2016	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 from Avenue 412 to Avenue 416	12/14/2016	12/14/2016	\$ 230.26
	Doyle Colony	Repair road surface by hand patching	Avenue 150 east of Road 272	11/21/2016	11/21/2016	\$ 309.52
	East Orosi	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 144	10/25/2016	10/25/2016	\$ 91.00
	Elderwood	Repair road surface by hand patching	Avenue 364 from Road 197 to State Highway 245	10/24/2016	10/24/2016	\$ 134.22
	Goshen	Repair road surface by hand patching	Rasmussen Avenue from Road 72 to Road 76	12/23/16	12/23/16	
	Goshen	Repair road surface by hand patching	Avenue 308 from Road 44 to Road 68	12/23/16	12/23/16	\$ 657.74
	Lindcove	Repair road surface by hand patching	Road 226 at Avenue 314	10/13/2016	10/13/2016	\$ 71.68
	London	Large area patching with grader. "Blade Patch"	Avenue 378 from Road 57 to Road 60	10/3/2016	10/4/2016	
	London	Repair road surface by hand patching	Kate Road from Avenue 376 to Avenue 378	10/4/2016	10/4/2016	\$ 2,537.33
	Mulanax Tract	Hauling patching material	Mitch Brown Construction to Rankin Pit	10/24/2016	10/24/2016	
	Mulanax Tract	Measure R Reconstruction	Diagonal 125F (Mulanax) from Avenue 264 to Avenue 264* (for District 2)	10/24/2016	10/24/2016	
	Mulanax Tract	Sweep/clean up Mulanax	Avenue 264	10/13/16	10/13/16	
	Mulanax Tract	Large area patching with grader. "Blade Patch"	Avenue 264	10/25/16	10/26/16	\$ 7,879.86
	Oak Ranch	Repair road surface by hand patching	Oak Ranch Drive at Appaloosa Road	11/1/2016	11/1/2016	\$ 57.21
	Orosi	Repair road surface by hand patching	Road 124 from Avenue 413 to Avenue 414	12/14/2016	12/14/2016	\$ 156.77
	Patterson Tract	Repair road surface by hand patching	Avenue 328 from State Highway 63 to Avenue 368	10/19/2016	10/19/2016	\$ 94.02
	Pixley	Repair road surface by hand patching	Park Street from Court to Pixley Park	12/19/16	12/19/16	
	Pixley	Repair road surface by hand patching	Howard Road from Park Street to Elm Street	12/19/16	12/19/16	
	Pixley	Repair road surface by hand patching	Elm Street from Howard Road to Avenue 96	12/19/16	12/19/16	
	Pixley	Repair road surface by hand patching	School Street from Avenue 96 to Court	12/19/16	12/19/16	
	Pixley	Repair road surface by hand patching	Pine Street from Compton Road to Howard Road	12/19/16	12/19/16	
	Pixley	Repair road surface by hand patching	Park Street from Court to Avenue 96	12/19/16	12/19/16	
	Pixley	Repair road surface by hand patching	Avenue 96 at Main Street	12/19/16	12/19/16	
	Pixley	Repair road surface by hand patching	Elm Street from Avenue 84 to Avenue 96	11/16/16	11/16/16	\$ 1,206.01
	Plainview	Repair road surface by hand patching	Avenue 192 at Road 204	10/22/2016	10/22/2016	
	Plainview	Repair road surface by hand patching	Road 168 from Road 160 to Road 184	11/10/2016	11/10/2016	
	Plainview	Repair road surface by hand patching	Road 212 from Avenue 196 to Avenue 220	11/15/2016	11/15/2016	
	Plainview	Repair road surface by hand patching	Avenue 200 from Road 172 to Road 188	11/29/2016	11/29/2016	
	Plainview	Repair potholes with Road Patcher	Road 208 from Avenue 196 to Avenue 200	11/30/2016	11/30/2016	
	Plainview	Repair potholes with Road Patcher	Road 212 from Avenue 196 to Avenue 208	12/7/2016	12/7/2016	
	Plainview	Repair road surface by hand patching	Road 196 from Avenue 184 to Avenue 192	12/12/2016	12/12/2016	
	Plainview	Repair potholes with Road Patcher	Road 216 from Avenue 184 to Avenue 196	12/14/2016	12/14/2016	\$ 2,031.24
	Poplar/Cotton Center	Repair potholes with Road Patcher	Road 208 from Avenue 144 to Avenue 152	10/26/2016	10/28/2016	\$ 676.82
	Sequoia Crest	Repair road surface by hand patching	Mountain Road 214 from Avenue 216* to Mountain Road 215	10/17/2016	10/17/2016	
	Sequoia Crest	Repair road surface by hand patching	Mountain Road 215 from Mountain Road 214 to Mountain Road 216	10/17/2016	10/17/2016	\$ 622.15
	Springville	Repair potholes with Road Patcher	Mountain Road 178 from Road 330* to Road 336*	12/13/2016	12/14/2016	\$ 158.13

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

Strathmore	Repair road surface by hand patching	Avenue 208 at Road 236	10/4/2016	10/4/2016	
Strathmore	Repair road surface by hand patching	Road 224 south of Avenue 192	10/6/2016	10/6/2016	
Strathmore	Repair potholes with Road Patcher	Avenue 184 from Diagonal 242 to Road 238	10/27/2016	10/27/2016	
Strathmore	Repair potholes with Road Patcher	Avenue 184 from Diagonal 242 to Road 248	11/1/2016	11/1/2016	
Strathmore	Repair road surface by hand patching	Avenue 200 from Road 228 to Road 238	11/4/2016	11/4/2016	
Strathmore	Repair road surface by hand patching	Road 232 at Avenue 198	11/15/2016	11/15/2016	
Strathmore	Repair road surface by hand patching	Road 228 from Avenue 238 to Diagonal 242	11/15/2016	11/15/2016	
Strathmore	Repair road surface by hand patching	Road 228 from Diagonal 242 to Avenue 238	11/29/2016	11/29/2016	
Strathmore	Repair potholes with Road Patcher	Road 176 from Avenue 176 to Avenue 184	11/29/2016	11/29/2016	
Strathmore	Repair potholes with Road Patcher	Road 208 from Avenue 188 to Avenue 192	11/30/2016	11/30/2016	
Strathmore	Repair road surface by hand patching	Road 228 from Avenue 200 to Avenue 228	12/6/2016	12/6/2016	
Strathmore	Repair road surface by hand patching	Road 232 from Avenue 196 to Avenue 200	12/9/2016	12/9/2016	
Strathmore	Repair road surface by hand patching	Avenue 182 from Road 224 to Road 232	12/9/2016	12/9/2016	
Strathmore	Repair road surface by hand patching	Road 232 north of Avenue 192	12/12/2016	12/12/2016	\$ 2,579.74
Sultana	Repair road surface by hand patching	Avenue 416 at Perkins Road	10/31/2016	10/31/2016	\$ 42.23
Terra Bella	Repair road surface by hand patching	Avenue 95 from Road 256 to Road 236	10/21/2016	10/21/2016	\$ 336.19
Tonyville	Repair road surface by hand patching	Avenue 240 from Road 204 to Road 214	10/4/2016	10/4/2016	
Tonyville	Repair road surface by hand patching	Road 212 at Avenue 240	10/4/2016	10/4/2016	
Tonyville	Repair road surface by hand patching	Road 214 at Avenue 240	10/4/2016	10/4/2016	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 239 to Avenue 250	10/10/2016	10/10/2016	
Tonyville	Repair road surface by hand patching	Avenue 247 from Road 212 to Road 216	11/2/2016	11/2/2016	
Tonyville	Repair road surface by hand patching	Avenue 264 from Road 204 to Road 216	11/10/2016	11/10/2016	
Tonyville	Repair road surface by hand patching	Avenue 250 from Road 216 to Road 224	11/15/2016	11/15/2016	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 250	11/15/2016	11/15/2016	
Tonyville	Repair road surface by hand patching	Avenue 256 at Friant Kern Canal	11/16/2016	11/16/2016	
Tonyville	Repair road surface by hand patching	Avenue 256 from Road 204 to Road 216	11/17/2016	11/17/2016	
Tonyville	Repair road surface by hand patching	Avenue 247 from Road 216 to Road 218*	12/5/2016	12/5/2016	
Tonyville	Repair road surface by hand patching	Avenue 256 from Road 204 to Road 212	12/6/2016	12/6/2016	\$ 3,292.58
Tooleville	Repair road surface by hand patching	Avenue 280 from Road 204 to Mountain Road 296	10/7/2016	10/7/2016	
Tooleville	Repair road surface by hand patching	Avenue 264 from Road 204 to Road 200*	11/18/2016	11/18/2016	\$ 619.26
Traver	Repair road surface by hand patching	Merritt Drive at Zante Drive	9/30/2016	9/30/2016	
Traver	Repair road surface by hand patching	Avenue 368 from Burke Drive to Canal Drive	10/4/2016	10/4/2016	
Traver	Repair road surface by hand patching	Baker Drive from Merritt Drive to Jacobs Drive	10/4/2016	10/4/2016	
Traver	Repair road surface by hand patching	Road 36 North of Merritt Drive	10/4/2016	10/4/2016	
Traver	Repair road surface by hand patching	Burke Drive South of Merritt Drive	11/18/2016	11/18/2016	\$ 302.06
West Exeter	Repair road surface by hand patching	Road 180 north of Avenue 288	9/26/2016	9/26/2016	
West Exeter	Repair road surface by hand patching	Road 188 from Avenue 256 to Avenue 264	10/5/2016	10/5/2016	
West Exeter	Repair road surface by hand patching	Road 188 north of Exeter City Limits	10/12/2016	10/12/2016	
West Exeter	Repair road surface by hand patching	Road 192 from Avenue 256 to Avenue 272	10/13/2016	10/13/2016	\$ 580.58

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads		Repair road surface by hand patching	Road 96 from Avenue 152 to Avenue 168	9/19/16	9/19/16	
		Repair road surface by hand patching	Avenue 432 West of Road 80	9/21/2016	9/21/2016	
		Repair road surface by hand patching	Road 64 from Avenue 426 to Avenue 430	9/21/2016	9/21/2016	
		Repair road surface by hand patching	Avenue 432 East of Road 88	9/21/2016	9/21/2016	
		Repair road surface by hand patching	Avenue 436 East of Road 136	9/22/2016	9/22/2016	
		Repair road surface by hand patching	Avenue 432 West of Road 104	9/22/2016	9/22/2016	
		Repair road surface by hand patching	Avenue 428 from State Highway 63 to Road 144	9/22/2016	9/22/2016	
		Repair road surface by hand patching	Road 140 at Avenue 436	9/22/2016	9/22/2016	
		Repair road surface by hand patching	Road 96 North of Avenue 424	9/22/2016	9/22/2016	
		Repair road surface by hand patching	Diagonal 60 from Road 36 to Avenue 328	9/23/2016	9/23/2016	
		Repair road surface by hand patching	Road 20 from Avenue 368 to Avenue 376	9/23/2016	9/23/2016	
		Repair road surface by hand patching	Avenue 328 from State Highway 99 to Road 80	9/23/2016	9/23/2016	
		Repair road surface by hand patching	Avenue 336 East of Road 156	9/26/2016	9/26/2016	
		Repair road surface by hand patching	Road 160 from Avenue 340 to Avenue 336	9/26/2016	9/26/2016	
		Repair road surface by hand patching	Road 160 from Avenue 340 to Avenue 344	9/26/2016	9/26/2016	
		Repair road surface by hand patching	Avenue 208 east of Road 164	9/26/2016	9/26/2016	
		Repair road surface by hand patching	Avenue 336 from Highway 216 to Road 188	9/29/2016	9/29/2016	
		Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	9/30/2016	9/30/2016	
		Repair road surface by hand patching	Avenue 428 at Road 144	9/30/2016	9/30/2016	
		Repair road surface by hand patching	Avenue 408 from Road 32 to Road 24	9/30/2016	9/30/2016	
		Repair road surface by hand patching	Avenue 352 from Road 112 to Road 140	9/30/2016	9/30/2016	
		Repair road surface by hand patching	Avenue 412 East of Road 136	9/30/2016	9/30/2016	
		Repair road surface by hand patching	Avenue 120 from Road 152 to State Highway 99	10/3/16	10/3/16	
		Fill with oil at Cain Oil	Cain Oil, Tulare	10/3/2016	10/3/2016	
		Repair road surface by hand patching	Road 44 from Avenue 360 to Avenue 368	10/4/2016	10/4/2016	
		Repair road surface by hand patching	Road 36 from Avenue 368 to Avenue 384	10/4/2016	10/4/2016	
		Repair road surface by hand patching	Road 32 from Avenue 376 to Avenue 384	10/4/2016	10/4/2016	
		Repair road surface by hand patching	Road 40 from Avenue 368 to Avenue 384	10/4/2016	10/4/2016	
		Repair road surface by hand patching	Avenue 352 from Kingsburg City Limit to State Highway 99	10/4/2016	10/4/2016	
		Repair road surface by hand patching	Road 156 from Avenue 256 to Avenue 280	10/4/16	10/4/16	
		Repair road surface by hand patching	Road 140 from Avenue 256 to Avenue 280	10/4/16	10/4/16	
		Repair road surface by hand patching	Avenue 200 west of Road 140	10/4/16	10/4/16	
		Repair road surface by hand patching	Avenue 228 east of Road 204	10/4/2016	10/4/2016	
		Repair potholes with Road Patcher	Road 208 from Highway 190 to Avenue 152	10/4/2016	10/4/2016	
		Repair road surface by hand patching	Road 74 from Avenue 384 to Avenue 400	10/5/2016	10/5/2016	
		Repair road surface by hand patching	Road 156 from Avenue 280 to Avenue 296	10/5/16	10/5/16	
		Repair road surface by hand patching	Avenue 288 from Farmersville to Visalia city limits	10/5/16	10/5/16	
		Repair road surface by hand patching	Road 128 from Avenue 56 to White River Bridge	10/5/16	10/5/16	
		Repair road surface by hand patching	Avenue 228 from Road 228 to Road 242	10/5/2016	10/5/2016	
		Repair road surface by hand patching	Road 180 from Avenue 208 to Avenue 216	10/6/2016	10/6/2016	
		Repair road surface by hand patching	Avenue 216 from Road 216 to Road 236	10/6/2016	10/6/2016	
		Repair road surface by hand patching	Road 144 from Avenue 416 to Avenue 432	10/7/2016	10/7/2016	
		Repair road surface by hand patching	Avenue 416 from State Highway 63 to Road 168	10/7/2016	10/7/2016	
		Repair road surface by hand patching	Avenue 432 from State Highway 63 to Road 144	10/7/2016	10/7/2016	
		Repair road surface by hand patching	Avenue 174 from Road 224 to Highway 65	10/7/2016	10/7/2016	
		Repair road surface by hand patching	Avenue 224 from Road 236 to Road 244	10/10/2016	10/10/2016	
		Repair road surface by hand patching	Avenue 228 from Road 228 to Road 236	10/10/2016	10/10/2016	
		Repair road surface by hand patching	Road 64 from Avenue 426 to Avenue 430	10/12/2016	10/12/2016	
		Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limit	10/12/2016	10/12/2016	
		Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	10/12/2016	10/12/2016	
		Repair road surface by hand patching	Avenue 328 from Road 132 to State Highway 63	10/12/2016	10/12/2016	
		Repair road surface by hand patching	Road 158 from State Highway 216 to Mineral King Avenue	10/12/2016	10/12/2016	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

	Repair road surface by hand patching	Road 156 from Avenue 362 to Avenue 376	10/12/2016	10/12/2016
	Repair road surface by hand patching	Avenue 160 at Porterville City Limits	10/12/2016	10/12/2016
	Repair road surface by hand patching	Avenue 340 at Road 112	10/13/2016	10/13/2016
	Repair road surface by hand patching	Avenue 328 at Road 108	10/13/2016	10/13/2016
	Repair road surface by hand patching	Road 108 from Avenue 320 to Avenue 328	10/13/2016	10/13/2016
	Repair road surface by hand patching	Avenue 332 from Road 108 to Road 112	10/13/2016	10/13/2016
	Repair road surface by hand patching	Road 132 North of Avenue 336	10/13/2016	10/13/2016
	Repair road surface by hand patching	Road 140 from State Highway 137 to Avenue 280	10/13/16	10/13/16
	Repair road surface by hand patching	Road 100 from Avenue 264 to Visalia City Limits	10/13/16	10/13/16
	Repair road surface by hand patching	Avenue 264 from Road 108 to State Highway 99	10/13/16	10/13/16
	Repair road surface by hand patching	Road 144 at Avenue 404	10/17/2016	10/17/2016
	Repair road surface by hand patching	Avenue 404 East of Road 136	10/17/2016	10/17/2016
	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 122	10/17/2016	10/17/2016
	Repair road surface by hand patching	Road 96 from Avenue 424 to Avenue 432	10/17/2016	10/17/2016
	Repair road surface by hand patching	Road 40 from Avenue 368 to Avenue 384	10/17/2016	10/17/2016
	Repair road surface by hand patching	Avenue 376 from Road 36 to Road 40	10/17/2016	10/17/2016
	Repair road surface by hand patching	Road 74 South of Avenue 376	10/17/2016	10/17/2016
	Repair road surface by hand patching	Road 124 from Avenue 424 to Avenue 440	10/18/2016	10/18/2016
	Repair road surface by hand patching	Avenue 440 from Road 120 to State Highway 63	10/18/2016	10/18/2016
	Repair road surface by hand patching	Avenue 424 East of Road 52	10/18/2016	10/18/2016
	Repair road surface by hand patching	Avenue 428 from Road 44 to Road 56	10/18/2016	10/18/2016
	Repair road surface by hand patching	Avenue 424 from State Highway 63 to Dinuba City Limit	10/18/2016	10/18/2016
	Repair road surface by hand patching	Road 140 from Avenue 328 to Avenue 368	10/18/2016	10/18/2016
	Repair road surface by hand patching	Avenue 368 from State Highway 63 to Road 132	10/19/2016	10/19/2016
	Repair road surface by hand patching	Road 140 from Avenue 328 to Avenue 368	10/19/2016	10/19/2016
	Repair road surface by hand patching	Avenue 328 fro State Highway 63 to Road 132	10/19/2016	10/19/2016
	Repair road surface by hand patching	Road 132 from Avenue 352 to Avenue 368	10/19/2016	10/19/2016
	Repair road surface by hand patching	Road 76 from Avenue 360 to Avenue 376	10/20/2016	10/20/2016
	Repair road surface by hand patching	Avenue 368 from Road 76 to Road 80	10/20/2016	10/20/2016
	Repair road surface by hand patching	Avenue 422 from State Highway 63 to Road 136	10/20/2016	10/20/2016
	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 424	10/20/2016	10/20/2016
	Repair road surface by hand patching	Road 44 from Avenue 424 to Avenue 428	10/20/2016	10/20/2016
	Repair road surface by hand patching	Road 42 from Avenue 416 to Avenue 424	10/20/2016	10/20/2016
	Repair road surface by hand patching	Road 196 South of Avenue 336	10/21/2016	10/21/2016
	Repair road surface by hand patching	Road 160 at Avenue 344	10/21/2016	10/21/2016
	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 416	10/21/2016	10/21/2016
	Repair road surface by hand patching	Avenue 336 from Road 132 to Road 140	10/21/2016	10/21/2016
	Repair road surface by hand patching	Avenue 352 West of Road 172	10/21/2016	10/21/2016
	Repair road surface by hand patching	Avenue 216 from Enterprise Road to Road 76	10/21/16	10/21/16
	Repair road surface by hand patching	Road256 from Avenue 56 to Avenue 95	10/21/2016	10/21/2016
	Repair road surface by hand patching	Road 172 at Avenue 384	10/24/2016	10/24/2016
	Repair road surface by hand patching	Avenue 376 from Road 204 to State Highway 245	10/24/2016	10/24/2016
	Repair road surface by hand patching	Road 32 North of Avenue 400	10/24/2016	10/24/2016
	Repair road surface by hand patching	Road 140 from Avenue 384 to Avenue 392	10/24/2016	10/24/2016
	Repair road surface by hand patching	Avenue 240 from Road 204 to LR207	10/24/2016	10/24/2016
	Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limit	10/25/2016	10/25/2016
	Repair road surface by hand patching	Diagonal 56 from Diagonal 60 to Avenue 360	10/25/2016	10/25/2016
	Repair road surface by hand patching	Road 112 from Avenue 328 to Avenue 340	10/25/2016	10/25/2016
	Repair road surface by hand patching	Avenue 424 from Road 92 to Road 96	10/26/2016	10/26/2016
	Repair road surface by hand patching	Avenue 408 from Jasper Drive to Avenue 400	10/26/2016	10/26/2016
	Repair road surface by hand patching	Road 32 from Jasper Drive to Avenue 400	10/26/2016	10/26/2016
	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 76	10/26/2016	10/26/2016
	Repair road surface by hand patching	Avenue 328 from Road 92 to Road 156	10/26/2016	10/26/2016
	Repair road surface by hand patching	Avenue 104 from Road 168 to Road 176	10/26/2016	10/26/2016
	Repair potholes with Road Patcher	Avenue 104 from Road 176 to Road 192	10/26/2016	10/26/2016

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

	Repair road surface by hand patching	Road 188 from Avenue 336 to Charter Oak Drive	10/27/2016	10/27/2016
	Repair road surface by hand patching	Charter Oak Drive from Road 168 to Road 188	10/27/2016	10/27/2016
	Repair road surface by hand patching	Diagonal 243 from Mile post 1 to Mile post 5.5	10/27/2016	10/27/2016
	Repair road surface by hand patching	Road 164 South of Avenue 376	10/27/2016	10/27/2016
	Repair road surface by hand patching	Road 144 South of Avenue 376	10/27/2016	10/27/2016
	Repair road surface by hand patching	Avenue 392 from Road 136 to Road 144	10/27/2016	10/27/2016
	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 360	10/27/2016	10/27/2016
	Repair road surface by hand patching	Avenue 336 from Road 200 to Road 204	10/28/2016	10/28/2016
	Repair road surface by hand patching	Road 204 North of Avenue 376	10/31/2016	10/31/2016
	Repair road surface by hand patching	Road 162 at Avenue 416	10/31/2016	10/31/2016
	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 168	10/31/2016	10/31/2016
	Repair road surface by hand patching	Road 132 from Avenue 384 to St. Johns River	10/31/2016	10/31/2016
	Repair road surface by hand patching	Avenue 328 from State Highway 63 to Road 132	10/31/2016	10/31/2016
	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	10/31/2016	10/31/2016
	Repair road surface by hand patching	Road 140 from State Highway 137 to Avenue 280	10/31/16	10/31/16
	Repair road surface by hand patching	Avenue 152 from Road 128 to Road 144	10/31/16	10/31/16
	Repair road surface by hand patching	Avenue 328 West of Diagonal 56	11/1/2016	11/1/2016
	Repair road surface by hand patching	Avenue 390 East of Road 28	11/1/2016	11/1/2016
	Repair road surface by hand patching	Road 8 from Avenue 384 to Avenue 392	11/1/2016	11/1/2016
	Repair road surface by hand patching	Road 132 from Avenue 432 to Avenue 440	11/1/2016	11/1/2016
	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	11/1/2016	11/1/2016
	Repair road surface by hand patching	Avenue 152 from Road 136 to Road 152	11/1/16	11/1/16
	Repair road surface by hand patching	Avenue 144 from Burnett to Road 104	11/1/16	11/1/16
	Repair potholes with Road Patcher	Road 208 from Avenue 160 to Avenue 164	11/1/2016	11/1/2016
	Repair road surface by hand patching	Road 100 from Avenue 416 to Avenue 424	11/2/2016	11/2/2016
	Repair road surface by hand patching	Avenue 328 from State Highway 99 to Road 80	11/2/2016	11/2/2016
	Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limit	11/3/2016	11/3/2016
	Repair road surface by hand patching	Road 52 from Avenue 408 to Avenue 416	11/3/2016	11/3/2016
	Repair road surface by hand patching	Avenue 344 at Road 156	11/3/2016	11/3/2016
	Repair road surface by hand patching	Avenue 340 from Road 152 to Road 156	11/3/2016	11/3/2016
	Repair road surface by hand patching	Avenue 320 from Road 190 to Road 196	11/3/2016	11/3/2016
	Repair road surface by hand patching	Avenue 336 East of Road 152	11/3/2016	11/3/2016
	Repair road surface by hand patching	Road 66 from Avenue 404 to Avenue 408	11/4/2016	11/4/2016
	Repair road surface by hand patching	Road 40 from Avenue 384 to Avenue 400	11/4/2016	11/4/2016
	Repair road surface by hand patching	Road 33 from Avenue 396 to Avenue 400	11/4/2016	11/4/2016
	Repair road surface by hand patching	Avenue 328 West of Road 132	11/7/2016	11/7/2016
	Repair road surface by hand patching	Road 156 from Avenue 360 to Avenue 384	11/7/2016	11/7/2016
	Repair road surface by hand patching	Road 164 South of Avenue 376	11/7/2016	11/7/2016
	Repair road surface by hand patching	Avenue 368 West of Road 80	11/7/2016	11/7/2016
	Repair road surface by hand patching	Avenue 360 West of Road 80	11/7/2016	11/7/2016
	Repair road surface by hand patching	Avenue 120 from Road 144 to Road 152	11/7/2016	11/7/2016
	Repair road surface by hand patching	Road 160 from Avenue 128 to Avenue 140	11/7/2016	11/7/2016
	Repair road surface by hand patching	Road 168 from Avenue 128 to Avenue 140	11/7/2016	11/7/2016
	Repair road surface by hand patching	Avenue 128 west of Road 152	11/7/2016	11/7/2016
	Repair road surface by hand patching	Road 84 from Avenue 368 to Avenue 384	11/8/2016	11/8/2016
	Repair road surface by hand patching	Monson Drive from Road 104 to Avenue 384	11/8/2016	11/8/2016
	Repair road surface by hand patching	Avenue 408 from Road 96 to Road 104	11/8/2016	11/8/2016
	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 76	11/8/2016	11/8/2016
	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 128	11/9/2016	11/9/2016
	Repair road surface by hand patching	Avenue 416 from Road 92 to Road 168	11/9/2016	11/9/2016
	Repair road surface by hand patching	Road 52 from Avenue 360 to Avenue 368	11/9/2016	11/9/2016
	Repair road surface by hand patching	Avenue 320 from Road 52 to Road 60	11/9/2016	11/9/2016
	Repair road surface by hand patching	Avenue 169 from Road 244 to Road 252	11/10/2016	11/10/2016
	Repair road surface by hand patching	Diagonal 242 at Road 178	11/10/2016	11/10/2016
	Repair road surface by hand patching	Road 256 from Avenue 169 to Diagonal 252	11/10/2016	11/10/2016

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

	Repair road surface by hand patching	Mounain Road 375 from Mile post 2 to Mile post 3	11/15/2016	11/15/2016
	Repair road surface by hand patching	Road 136 at Avenue 416	11/15/2016	11/15/2016
	Repair road surface by hand patching	Avenue 428 East of State Highway 63	11/15/2016	11/15/2016
	Repair road surface by hand patching	Road 196 from Avenue 336 to St. Johns River	11/16/2016	11/16/2016
	Repair road surface by hand patching	Road 136 South of Avenue 392	11/16/2016	11/16/2016
	Repair road surface by hand patching	Avenue 440 from Road 120 to Road 124	11/16/2016	11/16/2016
	Repair road surface by hand patching	Road 132 from Avenue 432 to Avenue 440	11/16/2016	11/16/2016
	Repair road surface by hand patching	Road 196 from Avenue 296 to Avenue 328*	11/16/2016	11/16/2016
	Repair road surface by hand patching	Avenue 268 west of Road 216	11/16/2016	11/16/2016
	Repair road surface by hand patching	Road 224 north of Avenue 184	11/16/2016	11/16/2016
	Repair road surface by hand patching	Road 24 from Avenue 400 to Avenue 404	11/17/2016	11/17/2016
	Repair road surface by hand patching	Avenue 416 from Road 144 to Road 168	11/17/2016	11/17/2016
	Repair road surface by hand patching	Avenue 336 from Road 188 to Road 196	11/17/2016	11/17/2016
	Repair road surface by hand patching	Road 36 at Avenue 390	11/17/2016	11/17/2016
	Repair road surface by hand patching	Boyd Drive from Mile post 0 to Mile post 1	11/17/2016	11/17/2016
	Repair road surface by hand patching	Avenue 396 from Road 16 to Road 18	11/18/2016	11/18/2016
	Repair road surface by hand patching	Road 76 South of Avenue 384	11/18/2016	11/18/2016
	Repair road surface by hand patching	Avenue 224 at Road 196	11/18/2016	11/18/2016
	Repair road surface by hand patching	Avenue 384 at State Highway 99	11/22/2016	11/22/2016
	Repair road surface by hand patching	Avenue 392 from Road 8 to Road 12	11/22/2016	11/22/2016
	Repair road surface by hand patching	Road 112 from Avenue 400 to Avenue 408	11/22/2016	11/22/2016
	Repair road surface by hand patching	Road 112 from Avenue 408 to Avenue 416	11/22/2016	11/22/2016
	Repair road surface by hand patching	Avenue 424 from Road 92 to Road 96	11/22/2016	11/22/2016
	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 92	11/22/2016	11/22/2016
	Repair road surface by hand patching	Road 64 from Avenue 400 to Avenue 408	11/22/2016	11/22/2016
	Repair road surface by hand patching	Road 254 from Avenue 208 to Avenue 216	11/29/2016	11/29/2016
	Repair road surface by hand patching	Avenue 169 from Road 244 to Road 248	11/29/2016	11/29/2016
	Repair road surface by hand patching	Avenue 169 from Road 250* to Road 252	11/29/2016	11/29/2016
	Repair road surface by hand patching	Road 252 from Avenue 169 to Diagonal 252	11/29/2016	11/29/2016
	Repair potholes with Road Patcher	Avenue 160 from Road 208 to Road 221*	11/29/2016	11/29/2016
	Repair road surface by hand patching	Avenue 352 from Diagonal 60 to Tulare County Limit	11/30/2016	11/30/2016
	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Road 60	11/30/2016	11/30/2016
	Repair road surface by hand patching	Avenue 360 from Road 74 to Road 80	11/30/2016	11/30/2016
	Repair road surface by hand patching	Road 172 at Avenue 384	11/30/2016	11/30/2016
	Repair road surface by hand patching	Avenue 404 from Road 66 to Road 74	11/30/2016	12/1/2016
	Repair road surface by hand patching	Road 176 from Avenue 264 to Avenue 280	11/30/16	11/30/16
	Repair road surface by hand patching	Road 168 from Avenue 296 to St Johns River Bridge	11/30/16	11/30/16
	Repair road surface by hand patching	Road 156 west of Avenue 296	11/30/16	11/30/16
	Repair road surface by hand patching	Avenue 352 from Road 206 to Pine Street	12/1/2016	12/1/2016
	Repair potholes with Road Patcher	Avenue 212 from Road 232 to Road 242	12/1/2016	12/1/2016
	Repair road surface by hand patching	Road 180 from Avenue 336 to Avenue 344	12/2/2016	12/2/2016
	Repair road surface by hand patching	Avenue 144 from Burnett to Road 72	12/5/16	12/5/16
	Repair road surface by hand patching	Avenue 240 from Road 204 to Road 212	12/6/2016	12/6/2016
	Repair road surface by hand patching	Avenue 416 from Road 136 to Road 142	12/9/2016	12/9/2016
	Repair road surface by hand patching	Avenue 432 from Road 136 to Road 144	12/9/2016	12/9/2016
	Repair road surface by hand patching	Road 236 north of Avenue 200	12/9/2016	12/9/2016
	Repair road surface by hand patching	Road 254 at Avenue 216	12/12/2016	12/12/2016
	Repair road surface by hand patching	Avenue 220 from Road 252 to Road 254	12/12/2016	12/12/2016
	Repair road surface by hand patching	Avenue 248 from Road 28 to Road 92	12/13/16	12/13/16
	Repair road surface by hand patching	Road 164 at Avenue 352	12/14/2016	12/14/2016
	Repair road surface by hand patching	Avenue 336 from Road 160 to State Highway 216	12/14/2016	12/14/2016
	Repair road surface by hand patching	Road 168 from Avenue 296 to St Johns River Bridge	12/15/16	12/15/16
	Repair road surface by hand patching	Road 112 from Avenue 160 to Avenue 184	12/20/16	12/20/16
	Haul material- SC 800 Mix	From Avenue 112 pit to Yard 1- Porterville	12/21/2016	12/21/2016
	Belly Dump Truck	from Deer Creek Asphalt to Yard #5, haul patching material	12/21/16	12/22/16

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

	Repair road surface by hand patching	Avenue 88 from Road 140 to Road 164	12/21/2016	12/21/2016
	Repair road surface by hand patching	Road 176 from Avenue 96 to Avenue 104	12/21/2016	12/21/2016
	Haul Material for Hand Patching	Deer Creek to Avenue 112 Pit Terra Bella	12/21/2016	12/21/2016
	Haul Material for Hand Patching	Deer Creek to Road District 1	12/21/2016	12/21/2016
	Haul Measure R Material for Stockpile	Various locations for Districts 1, 2, 4 & 5	12/21/2016	12/22/2016
	Repair potholes with Road Patcher	Road 220 from Diagonal 242 to Avenue 224	12/21/2016	12/21/2016
	Repair potholes with Road Patcher	Avenue 220 from Road 228 to Road 224	12/21/2016	12/21/2016
	Haul material- SC 800 Mix	From Rankin Pit to Avenue 368 Pit	12/22/2016	12/22/2016
	Repair road surface by hand patching	Mountain 109 from Avenue 56 to Mountain 12	12/22/2016	12/22/2016
	Haul Material for Hand Patching	Deer Creek to Rankin Pit	12/22/2016	12/22/2016
	Haul Material for Hand Patching	Deer Creek to 368 Pit	12/22/2016	12/22/2016
	Repair road surface by hand patching	Road 33 from Avenue 396 too Avenue 400	12/23/2016	12/23/2016
	Repair road surface by hand patching	Road 28 from Avenue 384 to Avenue 390	12/23/2016	12/23/2016
	Repair road surface by hand patching	Road 160 from Avenue 88 to Avenue 64	12/23/2016	12/23/2016
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 from Mountain Road 239 to Milepost 7	9/23/2016	9/23/2016
	Repair road surface by hand patching	Mountain Road 296 at Mountain Road 239	9/23/2016	9/23/2016
	Repair road surface by hand patching	Mountain Road 296 from Milepost 6 to Milepost 20	9/30/2016	9/30/2016
	Repair road surface by hand patching	Mountain Road 296 from Milepost 8 to Mountain Road 239	10/7/2016	10/7/2016
	Repair road surface by hand patching	43250 Balch Park Road	10/18/2016	10/18/2016
	Repair road surface by hand patching	Mountain Road 276 from Milepost 7.5 to Milepost 8.5	11/17/2016	11/17/2016
	Repair road surface by hand patching	Mountain Road 161 from Highway 190 to Mountain Road 172A	11/18/2016	11/18/2016
	Repair road surface by hand patching	Mountain Road 276 at Milepost 0.5	11/18/2016	11/18/2016
	Repair road surface by hand patching	Mountain Road 276 from Mountain Road 296 to Milepost 2	11/22/2016	11/22/2016
	Repair road surface by hand patching	Mountain Road 296 from Milepost 3 to Milepost 7	11/22/2016	11/22/2016

\$ 64,739.96

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 2

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720)		Preliminary Engineering	Avenue 280 County Line to State Route 99 Farm to Market	7/25/2016	ongoing	\$ 20,590.19
		Construction/Design	Road 148 Avenue 280 Visalia Road to Avenue 288 Marinette Avenue	7/18/2014	ongoing	\$ 7,020.38
		Construction/Design	Road 184 from Avenue 136 to Avenue 144	7/18/2014	ongoing	\$ 4,070.50
		Construction/Design	Road 200 from Avenue 0 to Avenue 8	7/18/2014	ongoing	\$ 2,644.73
		Construction/Design	Avenue 432 Floral Avenue Road 128 to State Highway 63 to Road 136	7/18/2014	ongoing	\$ 8,264.96
		Construction/Design	Diagonal 208B Avenue 160 from Henderson to Road 208	7/18/2014	ongoing	\$ 1,062.50
		Preliminary Engineering/ Design	Community Road Surface Maintainance	1/15/2015	ongoing	\$ 142.58
		Preliminary Engineering/ Design	Rural Road Surface Maintainance	6/2/2015	ongoing	\$ 1,031.13
		Preliminary Engineering/ Design	Community Road Surface Maintainance	6/2/2015	ongoing	\$ 1,080.23
		Preliminary Engineering/ Design	Sequoia Union Elementary and Avenue 324	3/2/2016	ongoing	\$ 95.69
		Preliminary Engineering/ Design	School Street to Park Drive	3/2/2016	ongoing	\$ 3,519.99
		Preliminary Engineering/ Design	Terra Bella Avenue to Court Avenue	3/2/2016	ongoing	\$ 2,834.38
		Preliminary Engineering/ Design	Road 38 at Avenue 54 to 650 South of Intersection	3/2/2016	ongoing	\$ 2,033.55
		Preliminary Engineering/ Design	Avenue 306 to Effie Drive	3/2/2016	ongoing	\$ 2,541.42
		Preliminary Engineering/ Design	Avenue 368 East of Canal Drive	3/2/2016	ongoing	\$ 2,523.48
		Preliminary Engineering/ Design	Zante Drive and Baker Drive	3/2/2016	ongoing	\$ 1,471.36
		Preliminary Engineering/ Design	Avenue 378	3/2/2016	ongoing	\$ 36,374.78
		Preliminary Engineering/ Design	Road 256 South of Avenue 104	3/2/2016	ongoing	\$ 1,842.33
		Preliminary Engineering/ Design	Road 236 from Avenue 96 to Avenue 100	3/2/2016	ongoing	\$ 6,192.51
		Construction/Design	Strathmore Slurry Seal and Isolated Road Repair	3/2/2016	ongoing	\$ 1,650.44
		Preliminary Engineering/ Design	ADA Ramp Improvements	3/2/2016	ongoing	\$ 281.45
						\$ 197,064.98

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
16/17 Annual Advance \$4,199,499.00 Communities	Allensworth	Repair road surface by hand patching	Road 84 from Avenue 32 to Avenue 24	3/10/2017	3/10/2017	\$ 92.50
	Alpaugh	Repair road surface by hand patching	Wilbur Street from Avenue 54 to Avenue 52	3/2/2017	3/2/2017	
	Alpaugh	Repair road surface by hand patching	Avenue 54 from Road 38 to Borchardt	3/2/2017	3/2/2017	
	Alpaugh	Repair road surface by hand patching	Avenue 54 from Road 38 to Borchardt	3/3/2017	3/3/2017	
	Alpaugh	Repair road surface by hand patching	Road 38 from Avenue 54 to Avenue 38	3/10/2017	3/10/2017	
	Alpaugh	Repair road surface by hand patching	Road 50 and Avenue 50	3/10/2017	3/10/2017	
	Alpaugh	Repair road surface by hand patching	Road 50 at Avenue 46	3/10/2017	3/10/2017	\$ 1,948.18
	Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 192A to Mountain Road 189C	3/1/2017	3/1/2017	\$ 352.23
	Cutler/Orosi	Repair road surface by hand patching	Road 124 at Avenue 414	12/30/2016	12/30/2016	
	Cutler/Orosi	Repair road surface by hand patching	Lee Road at Avenue 408	12/30/2016	12/30/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 415 at State Highway 63	12/30/2016	12/30/2016	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 at Avenue 412	12/30/2016	12/30/2016	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 404 from State Highway 63 to Road 130	1/24/2017	1/24/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 408 at Road 120	1/24/2017	1/24/2017	
	Cutler/Orosi	Repair road surface by hand patching	Ralph Road from Avenue 403 to Avenue 403	1/30/2017	1/31/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 408 East of Road 136	1/30/2017	1/30/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 312 at State Highway 63	1/30/2017	1/30/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 136 from Avenue 412 to Avenue 416	1/30/2017	1/30/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 422 from State Highway 63 to Road 136	1/30/2017	1/30/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 at Avenue 404	1/31/2017	1/31/2017	
	Cutler/Orosi	Repair road surface by hand patching	Ralph Road at Avenue 403	1/31/2017	1/31/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 403 East of State Highway 63	1/31/2017	1/31/2017	
	Cutler/Orosi	Repair road surface by hand patching	Railroad Drive from Road 124 to State Highway 63	2/8/2017	2/8/2017	
	Cutler/Orosi	Repair road surface by hand patching	Second Drive West of Santa Fe Drive	2/14/2017	2/14/2017	
	Cutler/Orosi	Repair road surface by hand patching	Second Drive from Cutler Drive to Orosi Drive	2/14/2017	2/14/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 404 from Mueller Road to Road 140	2/22/2017	2/22/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 127 at Amethyst Avenue	3/7/2017	3/7/2017	
	Cutler/Orosi	Repair road surface by hand patching	Railroad Drive from Topeka Road to State Highway 63	3/15/2017	3/15/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 from Amethyst Avenue to Short Avenue	3/17/2017	3/17/2017	\$ 1,999.29
	Doyle Colony	Repair road surface by hand patching	Avenue 148 at Road 256	12/31/2016	12/31/2016	
	Doyle Colony	Repair road surface by hand patching	Baxley at Crabtree	2/22/2017	2/22/2017	
	Doyle Colony	Repair road surface by hand patching	Road 284 at Mountain Road 146	3/6/2017	3/8/2017	
	Doyle Colony	Repair road surface by hand patching	883 Randy	3/8/2017	3/8/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 147 from Road 254 to LR258A	3/17/2017	3/17/2017	
	Doyle Colony	Repair road surface by hand patching	Road 270 at LA147D	3/17/2017	3/17/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 150 from Road 264 to Road 272	3/17/2017	3/17/2017	\$ 1,307.66
	Earlimart	Repair road surface by hand patching	Avenue 48 from Road 144 to Front St	2/23/2017	2/23/2017	
	Earlimart	Repair road surface by hand patching	Avenue 56 from Front Street to Church St	2/23/2017	2/23/2017	
	Earlimart	Repair road surface by hand patching	Avenue 48 from Road 144 to Front Street	2/23/2017	2/24/2017	
	Earlimart	Repair road surface by hand patching	Avenue 56 from Front Street to Church	2/23/2017	2/24/2017	
	Earlimart	Repair road surface by hand patching	Tulare St from Elm to Church	2/24/2017	3/1/2017	
	Earlimart	Repair road surface by hand patching	Church from Armstrong (Road 144) to Cable	3/2/2017	3/2/2017	
	Earlimart	Repair road surface by hand patching	State from Armstrong (Road 144) to Tulare St	3/2/2017	3/2/2017	
	Earlimart	Repair road surface by hand patching	Avenue 56 off-ramp at State Highway 99	3/16/2017	3/16/2017	\$ 3,306.96
	East Kingsburg	Repair road surface by hand patching	Avenue 392 from Road 8 to Road 12	2/6/2017	2/6/2017	\$ 94.02

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

East Orosi	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 168	1/26/2017	1/26/2017	
East Orosi	Repair road surface by hand patching	Avenue 416 East of Road 130	2/6/2017	2/6/2017	
East Orosi	Repair road surface by hand patching	Road 124 North of Avenue 424	2/6/2017	2/6/2017	
East Orosi	Repair road surface by hand patching	Avenue 424 East of Road 124	2/6/2017	2/6/2017	
East Orosi	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 168	2/9/2017	2/9/2017	
East Orosi	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 168	2/15/2017	2/15/2017	
East Orosi	Repair road surface by hand patching	Avenue 428 East of Road 128	2/15/2017	2/15/2017	
East Orosi	Repair road surface by hand patching	Road 140 South of Avenue 432	2/15/2017	2/15/2017	\$ 1,101.80
Goshen	Repair road surface by hand patching	Avenue 310 at Farr Road	1/18/2017	1/18/2017	
Goshen	Repair road surface by hand patching	Road 68 from Avenue 296 to Avenue 308	1/18/2017	1/18/2017	
Goshen	Repair road surface by hand patching	Diagonal 69 from Avenue 304 to Avenue 306	1/19/2017	1/19/2017	
Goshen	Repair road surface by hand patching	Betty Drive at State Highway 99 overpass	1/20/2017	1/20/2017	
Goshen	Repair road surface by hand patching	Road 60 from Avenue 308 to Avenue 312	1/25/2017	1/25/2017	
Goshen	Repair road surface by hand patching	Road 64 east of Avenue 308	1/25/2017	1/25/2017	
Goshen	Repair road surface by hand patching	Road 68 east of Avenue 304	1/25/2017	1/25/2017	
Goshen	Repair road surface by hand patching	Betty Drive at State Highway 99 overpass	2/22/2017	2/22/2017	
Goshen	Repair road surface by hand patching	Avenue 304 at Road 68	2/22/2017	2/22/2017	
Goshen	Repair road surface by hand patching	Road 68 from Avenue 304 to Avenue 308	2/22/2017	2/22/2017	
Goshen	Repair road surface by hand patching	Diagonal 69 from Avenue 304 to Avenue 305	2/22/2017	2/22/2017	
Goshen	Repair road surface by hand patching	Road 68 from Diagonal 69 to Avenue 306	2/22/2017	2/22/2017	
Goshen	Repair road surface by hand patching	Road 76 from Avenue 304 to Avenue 308	2/22/2017	2/22/2017	
Goshen	Repair road surface by hand patching	Avenue 308 from Road 48 to Road 64	2/23/2017	2/23/2017	
Goshen	Repair road surface by hand patching	Road 64 from State Highway 198 to Avenue 304	2/23/2017	2/23/2017	
Goshen	Repair road surface by hand patching	Avenue 308 from Road 44 to Road 64	2/24/2017	2/24/2017	
Goshen	Repair road surface by hand patching	Avenue 308 from Road 44 to Road 60	3/1/2017	3/1/2017	
Goshen	Repair road surface by hand patching	Road 52 from Avenue 308 to Avenue 309	3/1/2017	3/1/2017	
Goshen	Repair road surface by hand patching	Road 52 from Avenue 304 to Avenue 308	3/1/2017	3/1/2017	
Goshen	Repair road surface by hand patching	Road 60 from Avenue 308 to Avenue 320	3/1/2017	3/1/2017	
Goshen	Repair road surface by hand patching	Road 64 from Avenue 304 to Avenue 308	3/2/2017	3/2/2017	
Goshen	Repair road surface by hand patching	Avenue 304 from Road 60 to Road 68	3/2/2017	3/2/2017	
Goshen	Repair road surface by hand patching	Markham Road at Avenue 308	3/2/2017	3/2/2017	
Goshen	Repair road surface by hand patching	Road 44 from Avenue 304 to State Highway 198	3/3/2017	3/3/2017	
Goshen	Repair road surface by hand patching	Avenue 304 from Road 44 to Road 48	3/3/2017	3/3/2017	
Goshen	Repair road surface by hand patching	Road 60 from Avenue 308 to Avenue 320	3/3/2017	3/3/2017	
Goshen	Repair road surface by hand patching	Markham Road from Avenue 304 to Avenue 308	3/3/2017	3/3/2017	
Goshen	Repair road surface by hand patching	Avenue 308 from Road 72 to Road 76	3/8/2017	3/8/2017	
Goshen	Repair road surface by hand patching	Road 60 from State Highway 198 to Avenue 304	3/9/2017	3/9/2017	
Goshen	Repair road surface by hand patching	Road 52 from State Highway 198 to Avenue 304	3/9/2017	3/9/2017	
Goshen	Repair road surface by hand patching	Road 48 from State Highway 198 to Avenue 304	3/9/2017	3/9/2017	
Goshen	Repair road surface by hand patching	Commercial Road from Avenue 305 to Avenue 310	3/10/2017	3/10/2017	
Goshen	Repair road surface by hand patching	Commercial Road at Woodbine Avenue	3/10/2017	3/10/2017	
Goshen	Repair road surface by hand patching	Diagonal 69 from Avenue 304 to Road 70	3/10/2017	3/10/2017	
Goshen	Repair road surface by hand patching	Avenue 310 at Farr Road	3/10/2017	3/10/2017	
Goshen	Repair road surface by hand patching	Road 44 from Avenue 304 to State Highway 198	3/10/2017	3/10/2017	
Goshen	Repair road surface by hand patching	Road 72 at Riggins Avenue	3/10/2017	3/10/2017	
Goshen	Repair road surface by hand patching	Diagonal 60 South of Avenue 320	3/15/2017	3/16/2017	\$ 10,459.16

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Ivanhoe	Repair road surface by hand patching	Avenue 332 from Hawthorne Road to Road 159	12/29/2016	12/29/2016	
Ivanhoe	Repair road surface by hand patching	Road 164 from Avenue 320 to Avenue 325	12/29/2016	12/29/2016	
Ivanhoe	Repair road surface by hand patching	Road 164 North of Avenue 344	12/29/2016	12/29/2016	
Ivanhoe	Repair road surface by hand patching	Avenue 332 from Buckeye Road to Road 158	2/7/2017	2/7/2017	
Ivanhoe	Repair road surface by hand patching	Avenue 332 from Road 158 to Road 161	2/16/2017	2/16/2017	
Ivanhoe	Repair road surface by hand patching	Road 160 from Avenue 332 to Avenue 336	2/16/2017	2/16/2017	\$ 529.49
Lemon Cove	Repair road surface by hand patching	Road 236 at Avenue 324	2/23/2017	2/23/2017	
Lemon Cove	Repair road surface by hand patching	Avenue 334 from Road 248 to Highway 198	2/28/2017	2/28/2017	
Lemon Cove	Repair road surface by hand patching	Road 248 from Avenue 330 to Avenue 334	2/28/2017	2/28/2017	
Lemon Cove	Repair road surface by hand patching	Avenue 324 from Road 248 to Highway 198	2/28/2017	2/28/2017	
Lemon Cove	Repair road surface by hand patching	Avenue 328 from Highway 198 to Road 248	2/28/2017	2/28/2017	
Lemon Cove	Repair road surface by hand patching	Road 248 from Avenue 324 to Avenue 324	2/28/2017	2/28/2017	\$ 544.01
Lindcove	Repair road surface by hand patching	Avenue 320 at Road 228	2/23/2017	2/23/2017	\$ 29.27
London	Repair road surface by hand patching	Avenue 377 West of Road 57	3/7/2017	3/7/2017	
London	Repair road surface by hand patching	Kate Road from Avenue 376 to Avenue 378	3/13/2017	3/14/2017	\$ 211.64
Monson	Repair road surface by hand patching	Avenue 384 at Diagonal 108	12/29/2016	12/29/2016	
Monson	Repair road surface by hand patching	Monson Drive from Road 104 to Avenue 384	1/30/2017	1/30/2017	\$ 173.53
Oak Ranch	Repair road surface by hand patching	Tower Road at Rancheria Road	3/3/2017	3/3/2017	\$ 147.08
Orosi	Repair road surface by hand patching	Avenue 413 from David Road to State Highway 63	1/19/2017	1/19/2017	\$ 95.62
Pixley	Repair potholes with Road Patcher	Road 120 north of Avenue 96	1/11/2017	1/11/2017	
Pixley	Repair road surface by hand patching	Pixley Main Street off-ramp to SH99	1/19/2017	1/19/2017	
Pixley	Repair road surface by hand patching	Avenue 96 from Market St. to Road 128	1/19/2017	1/19/2017	
Pixley	Repair road surface by hand patching	Avenue 324 east of Road 236	2/23/2017	2/23/2017	
Pixley	Repair road surface by hand patching	Avenue 96 from School St to Road 112	3/9/2017	3/10/2017	
Pixley	Repair road surface by hand patching	Road 128 from Avenue 72 to Avenue 96	3/10/2017	3/10/2017	\$ 2,450.52
Plainview	Repair road surface by hand patching	Avenue 196 north of Road 192	1/26/2017	1/26/2017	
Plainview	Repair road surface by hand patching	Avenue 192 from Road 196 to Road 208	2/16/2017	2/16/2017	
Plainview	Repair road surface by hand patching	Road 208 from Avenue 192 to Avenue 208	3/3/2017	3/3/2017	
Plainview	Repair road surface by hand patching	Road 192 from Avenue 188 to Avenue 208	3/3/2017	3/3/2017	
Plainview	Repair road surface by hand patching	Road 204 from Avenue 184 to Avenue 192	3/3/2017	3/3/2017	\$ 1,206.12
Porterville	Repair road surface by hand patching	LR235G at Avenue 151	2/1/2017	2/1/2017	
Porterville	Repair road surface by hand patching	Avenue 151 at LR235G	2/1/2017	2/1/2017	
Porterville	Repair road surface by hand patching	1075 W. Roby	2/15/2017	2/15/2017	
Porterville	Repair road surface by hand patching	Cobb from Roby to Olive	2/15/2017	2/15/2017	\$ 367.18
Richgrove	Repair road surface by hand patching	Dooley at Vineyard Drive	2/15/2017	2/15/2017	
Richgrove	Repair road surface by hand patching	Changey Drive at Richgrove Drive	2/15/2017	2/15/2017	\$ 234.65
Seville	Repair road surface by hand patching	Road 156 South of Avenue 376	2/9/2017	2/9/2017	\$ 92.50
Springville	Repair road surface by hand patching	Mountain Road 172A from Highway 190 to Highway 190	1/5/2017	1/5/2017	
Springville	Repair road surface by hand patching	33251 La Colina Drive	1/6/2017	1/6/2017	
Springville	Repair road surface by hand patching	Mountain Road 161 at Mountain Road 172	1/6/2017	1/6/2017	
Springville	Repair road surface by hand patching	Mountain Road 163 at Mountain Road 161	1/6/2017	1/6/2017	
Springville	Repair road surface by hand patching	Mountain Road 172A at Pleasant Oak	1/13/2017	1/13/2017	\$ 1,454.83

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Strathmore	Repair road surface by hand patching	Road 236 south of Avenue 200	12/28/2016	12/28/2016	
Strathmore	Repair road surface by hand patching	Avenue 208 from Diagonal 242 to Road 228	12/28/2016	12/28/2016	
Strathmore	Repair road surface by hand patching	Avenue 196 east of Road 232	12/29/2016	12/29/2016	
Strathmore	Repair road surface by hand patching	Road 232 north of Avenue 196	1/13/2017	1/13/2017	
Strathmore	Repair road surface by hand patching	Road 230 north of Avenue 196	1/18/2017	1/18/2017	
Strathmore	Repair road surface by hand patching	Road 232 from Avenue 196 to Avenue 200	1/27/2017	1/27/2017	
Strathmore	Repair road surface by hand patching	Avenue 200 at Road 232	2/15/2017	2/15/2017	
Strathmore	Repair road surface by hand patching	Road 232 from Avenue 192 to Avenue 200	2/22/2017	2/22/2017	
Strathmore	Repair road surface by hand patching	Avenue 208 from Road 228 to Road 236	2/27/2017	2/27/2017	
Strathmore	Repair road surface by hand patching	Avenue 200 at Friant Kern Canal	3/1/2017	3/1/2017	
Strathmore	Repair road surface by hand patching	Road 224 north of Avenue 192	3/3/2017	3/3/2017	
Strathmore	Repair road surface by hand patching	Meredith at Avenue 198	3/3/2017	3/3/2017	
Strathmore	Repair road surface by hand patching	Road 216 from Avenue 192 to Avenue 196	3/7/2017	3/7/2017	
Strathmore	Repair road surface by hand patching	Avenue 192 from Road 216 to Road 220	3/7/2017	3/7/2017	
Strathmore	Repair potholes with Road Patcher	Road 228 from Avenue 184 to Avenue 188	3/7/2017	3/7/2017	
Strathmore	Repair road surface by hand patching	Road 236 at Avenue 196	3/8/2017	3/8/2017	
Strathmore	Repair road surface by hand patching	Avenue 208 from Road 228 to Road 244	3/8/2017	3/8/2017	
Strathmore	Repair road surface by hand patching	Avenue 200 at Road 228	3/9/2017	3/9/2017	
Strathmore	Repair road surface by hand patching	Avenue 194 from Road 232 to Diagonal 242	3/9/2017	3/9/2017	
Strathmore	Repair road surface by hand patching	Road 232 from Avenue 192 to Avenue 194	3/9/2017	3/9/2017	
Strathmore	Repair road surface by hand patching	Road 234 from Avenue 192 to Avenue 194	3/9/2017	3/9/2017	
Strathmore	Repair road surface by hand patching	Road 228 at Avenue 200	3/9/2017	3/9/2017	
Strathmore	Repair road surface by hand patching	Avenue 196 from Diagonal 242 to Highway 65	3/10/2017	3/10/2017	
Strathmore	Repair road surface by hand patching	Avenue 208 from Road 244 to Road 254	3/10/2017	3/10/2017	\$ 5,500.63
Three Rivers	Repair road surface by hand patching	North Fork Drive from State Highway 198 to Mile Post 3	1/31/2017	1/31/2017	
Three Rivers	Repair road surface by hand patching	Cherokee Oaks Drive from State Highway 198 to Elk Drive	3/13/2017	3/13/2017	
Three Rivers	Repair road surface by hand patching	Grouse Drive from Cherokee Oaks Drive to End	3/13/2017	3/13/2017	
Three Rivers	Repair road surface by hand patching	Oak Ridge Drive from End to End	3/13/2017	3/13/2017	
Three Rivers	Repair road surface by hand patching	Ferndale Drive from Grouse Drive to End	3/13/2017	3/13/2017	
Three Rivers	Repair road surface by hand patching	North Fork Drive from State Highway 198 to Mile Post 6.5	3/14/2017	3/14/2017	
Three Rivers	Repair road surface by hand patching	Kaweah Drive North of North Fork Drive	3/14/2017	3/14/2017	\$ 1,214.95
Tipton	Repair road surface by hand patching	Road 120 from Avenue 144 to Avenue 152	2/23/2017	2/24/2017	
Tipton	Repair road surface by hand patching	Diagonal 116 from Avenue 148 to Avenue 152	2/23/2017	2/23/2017	
Tipton	Repair road surface by hand patching	Diagonal 116B from Avenue 148 to Avenue 148	2/24/2017	2/24/2017	
Tipton	Repair road surface by hand patching	Diagonal 115A from Avenue 144 to Avenue 152	2/24/2017	2/24/2017	
Tipton	Repair road surface by hand patching	Avenue 144 from Highway 99 to Road 104	3/1/2017	3/1/2017	
Tipton	Repair road surface by hand patching	Avenue 144 from Highway 99 to Road 96	3/2/2017	3/2/2017	
Tipton	Repair road surface by hand patching	Avenue 144 from Road 80 to Road 104	3/3/2017	3/3/2017	
Tipton	Repair road surface by hand patching	Avenue 144 from Road 68 to Road 80	3/8/2017	3/8/2017	
Tipton	Repair road surface by hand patching	Avenue 144 from Road 64 to Road 72	3/9/2017	3/9/2017	
Tipton	Repair road surface by hand patching	Avenue 144 from Road 72 to Highway 43	3/10/2017	3/10/2017	
Tipton	Repair road surface by hand patching	Avenue 144 from Highway 43 to Road 80	3/17/2017	3/17/2017	\$ 7,029.78

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Tonyville	Repair road surface by hand patching	Road 204 from Avenue 244 to Avenue 296	1/25/2017	1/25/2017	
Tonyville	Repair road surface by hand patching	Avenue 256 west of Road 204	1/25/2017	1/25/2017	
Tonyville	Repair road surface by hand patching	Avenue 245 at Diagonal 208D	1/25/2017	1/25/2017	
Tonyville	Repair road surface by hand patching	Road 216 at Avenue 245	1/25/2017	1/25/2017	
Tonyville	Repair road surface by hand patching	Road 212 from Avenue 240 to Avenue 256	1/27/2017	1/27/2017	
Tonyville	Repair road surface by hand patching	Road 212 from Avenue 240 to Avenue 247	3/7/2017	3/7/2017	
Tonyville	Repair road surface by hand patching	Road 212 at Avenue 256	3/16/2017	3/16/2017	
Tonyville	Repair road surface by hand patching	Avenue 240 from Road 212 to Road 214	3/16/2017	3/16/2017	\$ 1,337.78
Tooleville	Repair road surface by hand patching	Road 204 north of Avenue 264	1/5/2017	1/5/2017	
Tooleville	Repair road surface by hand patching	Road 204 at Avenue 268	1/19/2017	1/19/2017	
Tooleville	Repair road surface by hand patching	Road 204 from Avenue 264 to Avenue 268	1/24/2017	1/25/2017	
Tooleville	Repair road surface by hand patching	Avenue 244 from Road 196 to Road 204	1/25/2017	1/25/2017	
Tooleville	Repair road surface by hand patching	Avenue 268 east of LR206	1/26/2017	1/26/2017	
Tooleville	Repair road surface by hand patching	Avenue 268 east of Friant Kern Canal	2/27/2017	2/27/2017	\$ 731.31
Traver	Repair road surface by hand patching	Merritt Drive at State Highway 99	12/29/2016	12/29/2016	
Traver	Repair road surface by hand patching	Merritt Drive at Burke Drive	1/19/2017	1/19/2017	
Traver	Repair road surface by hand patching	Burke Drive at Merritt Drive	2/9/2017	2/9/2017	
Traver	Repair road surface by hand patching	Merritt Drive at Burke Drive	2/27/2017	2/27/2017	\$ 242.83
West Exeter	Repair road surface by hand patching	Road 180 from Avenue 256 to Avenue 296	12/28/2016	12/28/2016	
West Exeter	Repair road surface by hand patching	Road 188 at Avenue 288	2/8/2017	2/8/2017	
West Exeter	Repair road surface by hand patching	Road 180 from Avenue 280 to Avenue 295	2/14/2017	2/14/2017	
West Exeter	Repair road surface by hand patching	Road 180 at Avenue 264	2/14/2017	2/14/2017	
West Exeter	Repair road surface by hand patching	Road 188 from Exeter City Limits to Avenue 288	2/22/2017	2/22/2017	
West Exeter	Repair road surface by hand patching	Avenue 277 from Road 180 to Road 188	2/22/2017	2/22/2017	
West Exeter	Repair road surface by hand patching	Road 180 south of Avenue 288	2/23/2017	2/23/2017	
West Exeter	Repair road surface by hand patching	Road 188 south of Avenue 288	2/23/2017	2/27/2017	\$ 1,052.68
Yokohl	Repair road surface by hand patching	Mountain Road 296 from Avenue 296 to Highway 198	1/11/2017	1/12/2017	
Yokohl	Repair road surface by hand patching	Mountain Road 296 from Road 228 to Avenue 294	1/13/2017	1/13/2017	
Yokohl	Repair road surface by hand patching	Road 217 at Avenue 296	1/25/2017	1/25/2017	
Yokohl	Repair road surface by hand patching	Avenue 296 from Mountain Road 296 to Road 226	2/13/2017	2/13/2017	\$ 1,399.82

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads	Rural Roads	Repair road surface by hand patching	Avenue 300 east of Road 200	12/27/2016	12/27/2016	
	Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 80 to Avenue 64	12/28/2016	12/28/2016	
	Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 24 to Avenue 56	12/28/2016	12/29/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 112 from Road 208 to Road 192	12/28/2016	12/29/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 368 West of Road 108	12/28/2016	12/28/2016	
	Rural Roads	Repair road surface by hand patching	Negro Creek Road at Mile Post 14.5	12/28/2016	12/28/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 224 from Highway 65 to Diagonal 242	12/28/2016	12/28/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 192 to Road 208	12/29/2016	12/29/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 388 from End to Road 28	12/29/2016	12/29/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 390 from Road 28 to Road 40	12/29/2016	12/29/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 352 at Road 164	12/29/2016	12/29/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 144 to Road 148	12/30/2016	12/30/2016	
	Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 320 to Avenue 328	12/30/2016	12/30/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 384 at State Highway 99	12/30/2016	12/30/2016	
	Rural Roads	Repair road surface by hand patching	Road 76 at Avenue 430	12/30/2016	12/30/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 72 to Road 88	12/30/2016	12/30/2016	
	Rural Roads	Repair road surface by hand patching	Avenue 95 from Road 238 to Road 256	1/3/2017	1/3/2017	
	Rural Roads	Repair road surface by hand patching	Road 248 from Avenue 95 to Avenue 88	1/3/2017	1/3/2017	
	Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 128 to Avenue 152	1/3/2017	1/3/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 70 from Avenue 256 to Road 267	1/3/2017	1/3/2017	
	Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 352 to Avenue 376	1/6/2017	1/6/2017	
	Rural Roads	Repair road surface by hand patching	Road 76 from Avenue 376 to Avenue 384	1/6/2017	1/6/2017	
	Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to End	1/9/2017	1/9/2017	
	Rural Roads	Repair road surface by hand patching	Mountain 3 from Mile Post 5 to Mile Post 5.5	1/10/2017	1/10/2017	
	Rural Roads	Repair road surface by hand patching	Mountain 9 at Mile Post 4	1/10/2017	1/10/2017	
	Rural Roads	Repair road surface by hand patching	Road 216 from Avenue 128 to Avenue 136	1/11/2017	1/11/2017	
	Rural Roads	Repair road surface by hand patching	Mountain 137 from Mile Post 1.5 to Mile Post 8.5	1/13/2017	1/13/2017	
	Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 216 to Avenue 228	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 56 from Church Street to Road 96	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 296 to St. Johns River Bridge	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 164 from Mountain 109 to Avenue 120	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 104 from Road 236 to State Highway 65	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 216 from Avenue 144 to Avenue 152	1/17/2017	3/6/2017	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 104 to Avenue 112	1/17/2017	3/7/2017	
	Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 320 to Avenue 336	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Charter Oak Drive from Road 168 to Road 188	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 144 from St. Johns River to Avenue 328	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 124 to Road 140	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 108 at Avenue 328	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 172 fro Avenue 352 to Avenue 360	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 368 at Road 100	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 84 at Avenue 384	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Road 178 at Avenue 224	1/17/2017	1/17/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 140 to Road 148	1/18/2017	1/18/2017	
	Rural Roads	Repair road surface by hand patching	Road 108 at Pratt Avenue	1/18/2017	1/18/2017	
	Rural Roads	Repair road surface by hand patching	Road 158 from Avenue 216 to Avenue 296	1/18/2017	1/18/2017	
	Rural Roads	Repair road surface by hand patching	Diagonal 205 from Avenue 0 to Avenue 24	1/18/2017	1/18/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 230 from Road 240 to Road 242	1/18/2017	1/18/2017	
	Rural Roads	Repair road surface by hand patching	Road 156 at Avenue 228	1/19/2017	1/19/2017	
	Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 88 to Avenue 96	1/19/2017	1/19/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 132 to Road 140	1/19/2017	1/19/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 237 to Road 238	1/19/2017	1/19/2017	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Road 105 North of Avenue 416	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 at Road 120	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 400	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Road 120 North of Avenue 392	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 East of Road 88	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 West of Monson Drive	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 320 to Avenue 328	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 12 to Road 16	1/19/2017	1/19/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 344 to Avenue 384	1/20/2017	1/20/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 West of Road 120	1/22/2017	1/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 West of Road 108	1/22/2017	1/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 West of Road 108	1/22/2017	1/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 264 from State Highway 99 to Road 108	1/24/2017	1/24/2017
Rural Roads	Repair road surface by hand patching	Road 60 from Avenue 240 to Avenue 248	1/24/2017	1/24/2017
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 200 to Avenue 208	1/24/2017	1/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 264 from State Highway 99 to Road 1001/25/17	1/25/2017	1/25/2017
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 208 to Avenue 212	1/25/2017	1/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 68 to Road 84	1/25/2017	1/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 112 to Road 120	1/25/2017	1/25/2017
Rural Roads	Repair road surface by hand patching	Road 172 at Avenue 384	1/25/2017	1/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 100 to Road 108	1/25/2017	1/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 238 from Road 228 to Bellah	1/25/2017	1/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 224 at Road 196	1/26/2017	1/26/2017
Rural Roads	Repair road surface by hand patching	Avenue 196 from Mountain 176 to Road 320	1/26/2017	1/26/2017
Rural Roads	Repair road surface by hand patching	Road 196 at Lord Drive	1/27/2017	1/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 112 to Road 120	1/27/2017	1/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limits	1/27/2017	1/27/2017
Rural Roads	Repair road surface by hand patching	Road 28 at Avenue 400	1/27/2017	1/27/2017
Rural Roads	Repair road surface by hand patching	Lort Drive East of Road 196	1/27/2017	1/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 12 to Road 28	1/27/2017	1/27/2017
Rural Roads	Repair road surface by hand patching	Road 116 from Avenue 392 to Avenue 400	1/30/2017	1/30/2017
Rural Roads	Repair road surface by hand patching	Avenue 388 at Road 96	1/30/2017	1/30/2017
Rural Roads	Repair road surface by hand patching	Avenue 388 from Road 120 to State Highway 63	1/30/2017	1/30/2017
Rural Roads	Repair road surface by hand patching	Road 136 South of Avenue 388	1/30/2017	1/30/2017
Rural Roads	Repair road surface by hand patching	Road 212 from Avenue 248 to Avenue 256	1/31/2017	1/31/2017
Rural Roads	Repair road surface by hand patching	Dry Creek Drive from Mile Post 8 to Mile Post 14.5	1/31/2017	1/31/2017
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 208 to Road 192	2/1/2017	2/1/2017
Rural Roads	Repair road surface by hand patching	Road 208 at Avenue 96	2/1/2017	2/1/2017
Rural Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 6.5 to Mile Post 10	2/1/2017	2/1/2017
Rural Roads	Repair road surface by hand patching	Road 224 from Fir to Avenue 250	2/1/2017	2/1/2017
Rural Roads	Repair road surface by hand patching	Road 223 from Avenue 250 to Avenue 252	2/1/2017	2/1/2017
Rural Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 5.5 to Mile Post 6.5	2/2/2017	2/2/2017
Rural Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 4 to Mile Post 5.6	2/3/2017	2/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 96	2/3/2017	2/3/2017
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 424	2/3/2017	2/3/2017
Rural Roads	Repair road surface by hand patching	Road 108 South of Avenue 328	2/6/2017	2/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 West of Road 108	2/6/2017	2/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 East of State Highway 63	2/6/2017	2/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 360 West of Road 112	2/6/2017	2/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 West of Road 108	2/6/2017	2/6/2017
Rural Roads	Repair road surface by hand patching	Road 144 at St. Johns River	2/7/2017	2/7/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 132 to Road 144	2/7/2017	2/7/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 160 to Road 172	2/7/2017	2/7/2017
Rural Roads	Repair road surface by hand patching	Avenue 326 East of Road 168	2/7/2017	2/7/2017
Rural Roads	Repair road surface by hand patching	Road 124 at Avenue 432	2/8/2017	2/8/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 428 to Avenue 432	2/8/2017	2/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 412 at Road 150	2/8/2017	2/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	2/8/2017	2/8/2017
Rural Roads	Repair road surface by hand patching	Mountain 137 from Avenue 296 to End	2/9/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 West of Road 196	2/9/2017	2/9/2017
Rural Roads	Repair road surface by hand patching	Riverside Drive East of State Highway 245	2/9/2017	2/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 East of Road 88	2/9/2017	2/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 344 West of Road 180	2/9/2017	2/9/2017
Rural Roads	Repair road surface by hand patching	Road 196 from Highway 198 to Avenue 234	2/9/2017	2/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 95 east of Highway 65	2/13/2017	2/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 88 at Road 238	2/13/2017	2/13/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 128 to Highway 190	2/13/2017	2/13/2017
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 408 to Avenue 416	2/13/2017	2/13/2017
Rural Roads	Repair road surface by hand patching	Road 64 from Avenue 400 to Avenue 404	2/13/2017	2/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 132 to Road 144	2/13/2017	2/13/2017
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 332 to Avenue 336	2/13/2017	2/13/2017
Rural Roads	Repair road surface by hand patching	Road 20 North of Avenue 376	2/13/2017	2/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 152 to Road 112	2/14/2017	2/14/2017
Rural Roads	Repair road surface by hand patching	Road 112 south of Avenue 152	2/14/2017	2/14/2017
Rural Roads	Haul Material	Jaxon Baker to Avenue 112 Pit	2/14/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 92 to Road 108	2/14/2017	2/14/2017
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 400	2/14/2017	2/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 East of Road 120	2/14/2017	2/14/2017
Rural Roads	Haul measure R material	Jaxon Enterprises to Avenue 112 Pit	2/14/2017	2/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 152 at road 96	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Road 56 from Avenue 280 to State Highway 198	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Road 52 north of Avenue 308	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 261 at Tammy	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Mountain 137 from Mile Post 7 to End	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Road 210 south of Guerrero	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 80 from Road 232 to Road 228	2/15/2017	2/16/2017
Rural Roads	Repair road surface by hand patching	Mills Drive West of State Highway 216	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 408	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 West of Road 120	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Dry Creek Drive from Mile Post 4 to Mile Post 5	2/15/2017	2/15/2017
Rural Roads	Repair road surface by hand patching	Road 228 from Avenue 80 to Avenue 88	2/16/2017	2/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 24 from Road 160 to Road 176	2/16/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 160 to Avenue 192	2/16/2017	2/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 192 from Road 208 to Road 216	2/16/2017	2/16/2017
Rural Roads	Repair road surface by hand patching	Road 36 from Avenue 228 to Avenue 232	2/17/2017	2/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 at Road 80	2/17/2017	2/17/2017
Rural Roads	Repair road surface by hand patching	Road 80 north of Avenue 152	2/17/2017	2/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 248 from West Street to Road 80	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 112 to Road 104	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 152 to Road 140	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 148 to Road 132	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Avenue 248 west of Road 140	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 158 from Avenue 296 to State Highway 216	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 296 to St. Johns River Bridge	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 156 at Avenue 288	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 112 south of Avenue 184	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 112 to Road 104	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 96 to Avenue 90	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 408	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 28 from Avenue 384 to Avenue 388	2/21/2017	2/21/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 33 to Road 34	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 34 from Avenue 393 to Aavenue 396	2/21/2017	2/21/2017
Rural Roads	Get Oil for Repair potholes with Road Patcher	Yard 1 to Cain Oil, Visalia	2/21/2017	2/21/2017
Rural Roads	Repair road surface by hand patching	Road 100 from Aveneue 264 to VCL	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 264 from Road 108 to State Highway 99	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 140 to Road 132	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Diagonal 205 from Avenue 0 to Avenue 16	2/22/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 452 from Road 128 to Road 132	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 456 from Road 128 to Filer Road	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Road 28 North of Avenue 384	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Reid from Porterville City Limits to Lime	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 256 to Highway 137	2/22/2017	2/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 280 from Road 140 to Farmersville city limits	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Santa Fe Street from Avenue 272 to VCL	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 280 to Avenue 256	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 271 from Road 122 to Santa Fe St	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 272 from Road 122 to Santa Fe St	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 238 to Road 236	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Road 240 from Avenue 92 to Avenue 80	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to Mile Post 8	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Johnson Drive from Road 144 to Road 152	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Road 72 from Avenue 424 to Avenue 430	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 426 from Road 62 to Road 64	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 88 to Road 96	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 256 at Road 188	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 220 from Road 228 to Road 236	2/23/2017	2/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 68 to Road 86	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Road 132 south of Avenue 224	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 32 to Road 62	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 144 west of Road 72	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 80 to Avenue 64	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 92 to Road 96	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Road 84 from Avenue 376 to Avenue 384	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 392 to Avenue 396	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 at Road 108	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 8 to Road 12	2/24/2017	2/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 80 to State Hiway 99	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 84 to Road 52	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Road 36 from Avenue 228 to Avenue 232	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 288 at Road 156	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Noble Avenue west of Road 152	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 288 east of Road 168	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Diagonal 205 from Avenue 16 to Avenue 8	2/27/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Mountain 51 at Mile Post 1.25	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 50 to Mile Post 18	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 360 to Avenue 384	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 West of Road 108	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Road 108 North of Avenue 368	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 220 from Road 232 to Road 240	2/27/2017	2/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 248 1/2 mile east of Road 84	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 52 to Road 36	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 148 south of Avenue 256	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 96 to Road 64	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 192 from Road 44 to Road 48	2/28/2017	2/28/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 176 east of State Highway 137	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 24 to Avenue 32	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 240 from Avenue 92 to Avenue 88	2/28/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 20 to Road 36	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 36 North of Avenue 352	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 456 from Road 120 to Road 124	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Dry Creek Drive from Mile post 5 to Stage Coach Drive	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 344 at Road 180	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 352 to Avenue 360	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 164 North of Avenue 352	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 east of Road 152	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 168 west of Road 224	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 192 to Avenue 232	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 208 to Avenue 232	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 192 to Avenue 208	2/28/2017	2/28/2017
Rural Roads	Repair road surface by hand patching	Hauled patch material to Avenue 368 Pit	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Hauled patch material to Rankin Pit	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Hauled patch material to Pixley Yard	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 176 from Road 28 to S.R. 137	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 80 to Road 64	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 56 to Road 36	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Road 152 North of Avenue 16	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Road 196 south of Avenue 232	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 170 west of Friant Kern Canal	3/1/2017	3/1/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 192 to Avenue 200	3/1/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Diagonal 205 south of Avenue 56	3/2/2017	3/2/2017
Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 120 to Avenue 168	3/2/2017	3/2/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 144 to Avenue 128	3/2/2017	3/2/2017
Rural Roads	Repair road surface by hand patching	Avenue 88 from Road 192 to Road 184	3/2/2017	3/2/2017
Rural Roads	Repair road surface by hand patching	Mountain 99 from Tulare County Line to Mountain 50	3/2/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 56 from Front Street to Road 16	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 72 to Road 104	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 at Road 112	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 144 to Avenue 152	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Road 96 at Avenue 128	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 120 from S.R. 43 to Road 44	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 56 from Front St to Road 96	3/3/2017	3/3/2017
Rural Roads	Large area Patching with grader "Blade Patch"	Avenue 48 at Road 170	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Visalia City Limits to Avenue 328	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 336 to Lort Drive	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Road 126 from Avenue 422 to Avenue 424	3/3/2017	3/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 144 west of Road 72	3/4/2017	3/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 178 at Road 232	3/5/2017	3/5/2017
Rural Roads	Repair road surface by hand patching	Road 68 north of Avenue 228	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Road 28 from Avenue 228 to Avenue 232	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Road 192 from Avenue 96 to Avenue 144	3/6/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 184 to Road 176	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Road 248 from Avenue 95 to Avenue 100	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Road 216 from State Highway 190 to Avenue 152	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 at Road 100	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Road 44 North of Avenue 410	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 344	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 312 from Road 180 to Road 196	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Road 180 north of Avenue 312	3/6/2017	3/6/2017
Rural Roads	Repair road surface by hand patching	Road 28 from Avenue 228 to Avenue 216	3/7/2017	3/7/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 288 east of Road 148	3/7/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	Road 261 from Avenue 104 to End	3/7/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 352 to St. Johns Bridge	3/7/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 424 to Avenue 432	3/7/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	Road 64 from Avenue 424 to Avenue 430	3/7/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	Road 144 North of Avenue 376	3/7/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 340 to Avenue 352	3/7/2017	3/7/2017
Rural Roads	Repair potholes with Road Patcher	Avenue 238 at Hillcrest	3/7/2017	3/7/2017
Rural Roads	Repair potholes with Road Patcher	Avenue 174 from Road 232 to Highway 65	3/7/2017	3/7/2017
Rural Roads	Repair road surface by hand patching	R156 and State Highway 198 on overpass	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 288 to State Highway 198	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 288 1/2 mile west of Road 156	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 24 from Diagonal 205 to Road 208	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 112 from Road 208 to Road 224	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 362 to Avenue 384	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Road 156 at Avenue 344	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Road 172 North of Avenue 344	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 West of Road 148	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 344 to Avenue 360	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 170 at Friant Kern Canal	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 224 to Road 228	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 216 to End	3/8/2017	3/8/2017
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 232 to Avenue 280	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Road 38 from Avenue 38 to Avenue 56	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 96 to Compton	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 56 from State Highway 43 to Borchardt	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 72	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 54 from Road 36 to Road 24	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Road 120 100 feet north of Compton	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 24 to Ave 8	3/9/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 240 to Road 244	3/9/2017	3/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 212 from Road 236 to Road 244	3/9/2017	3/9/2017
Rural Roads	Repair potholes with Road Patcher	Road 204 at Avenue 168	3/9/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 56 from Borchardt to State Highway 43	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 96 to State Highway 99	3/10/2017	3/10/2017
Rural Roads	Repair potholes with Road Patcher	Road 132 from Avenue 208 to Avenue 224	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 54 from Road 36 to Road 16	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 152 from State Highway 99 to Road 96	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 80 from Road 192 to R208	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 212 to Road 220	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Sentinel Drive at Avenue 364	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 376 from State Highway 245 to Road 204	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 388 at Road 104	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 280 at State Highway 99	3/10/2017	3/10/2017
Rural Roads	Large area Patching with grader "Blade Patch"	Road 20 at Avenue 376	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Road 254 at Avenue 208	3/10/2017	3/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 152 to Road 192	3/13/2017	3/13/2017
Rural Roads	Repair road surface by hand patching	Road 192 from Avenue 56 to Avenue 144	3/13/2017	3/13/2017
Rural Roads	Large area Patching with grader "Blade Patch"	Mountain 56 at Capinero Road	3/13/2017	3/13/2017
Rural Roads	Repair road surface by hand patching	Road 74 from Avenue 384 to Avenue 400	3/13/2017	3/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 from State Highway 63 to Road 156	3/13/2017	3/13/2017
Rural Roads	Repair road surface by hand patching	Road 192 at Avenue 344	3/13/2017	3/13/2017
Rural Roads	Repair road surface by hand patching	Road 248 from Avenue 169 to Avenue 171	3/13/2017	3/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 171 from Road 244 to Road 248	3/13/2017	3/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 80 to Road 88	3/14/2017	3/14/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Rural Roads	Repair potholes with Road Patcher	Road 132 from Avenue 208 to Avenue 216	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 192 from Road 20 to Road 28	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 0 to Avenue 26	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Road 224 from Avenue 112 to Avenue 128	3/14/2017	3/22/2017
Rural Roads	Large area Patching with grader "Blade Patch"	Road 212 south of Avenue 256	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 388 East of Road 16	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 437 from Road 80 to Road 88	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Road 96 North of Avenue 416	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Road 16 North of Avenue 388	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 300 from Road 196 to Road 200	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 168 from Road 216 to Road 224	3/14/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 238 at Road 224	3/14/2017	3/14/2017
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 272 to Avenue 280	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 288 from Visalia to Farmersville	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 296 to Avenue 256	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 108 from Avenue 368 to Avenue 384	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 East of Road 108	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 384	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 408	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 108 from St. Johns River bridge to Visalia City Limits	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 from R92 to Road 108	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 432	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Avenue 432 East of Road 88	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Diagonal 252 from Road 252 to Road 256	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 252 from Diagonal 252 to Avenue 169	3/15/2017	3/15/2017
Rural Roads	Repair road surface by hand patching	Road 126 at State Highway 137	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 200 from Spacer to Hosfield	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 136 from West St to Friant Kern Canal	3/16/2017	3/20/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 8 to Avenue 32	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Road 168 at El Rio Drive	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 328 to State Highway 216	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 324 to Avenue 336	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 190 to Road 196	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Road 190 from Avenue 318 to Avenue 320	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 318 from Road 190 to Fisher Drive	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Road 168 South of State Highway 216	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 West of Road 120	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 at Railroad tracks	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 196 from Road 96 to Road 112	3/17/2017	3/17/2017
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 96 to Avenue 88	3/17/2017	3/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 264 from Road 108 to State Highway 99	3/17/2017	3/17/2017
Rural Roads	Repair road surface by hand patching	Road 64 from Avenue 252 to Avenue 260	3/17/2017	3/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 280 from Visalia County Line to State Highway 99	3/17/2017	3/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 264 at Road 100	3/17/2017	3/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 398 from State Highway 245 to End	3/17/2017	3/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	3/17/2017	3/17/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Mountain Roads	Mountain Roads	Repair road surface by hand patching	Mountain Road 296 east of Mountain Road 239	1/6/2017	1/6/2017	\$ 223,766.93
	Mountain Roads	Repair road surface by hand patching	Mountain Road 296 at Milepost 32	1/6/2017	1/6/2017	
	Mountain Roads	Repair road surface by hand patching	Mountain Road 220 at Mountain Road 239	1/18/2017	1/18/2017	
	Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Mountain Road 239 to Mountain Road 276	1/26/2017	1/26/2017	
	Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Highway 198 to Road 228	2/13/2017	2/13/2017	
	Mountain Roads	Repair road surface by hand patching	Mountain Road 208 at Milepost 0.5	2/15/2017	2/15/2017	
	Mountain Roads	Repair road surface by hand patching	Mountain Road 276 from Milepost 4 to Milepost 6	2/16/2017	2/16/2017	
	Mountain Roads	Repair road surface by hand patching	m220 mp2.5 mp4	2/24/2017	2/24/2017	
	Mountain Roads	Repair road surface by hand patching	Pleasant Oak from Highway 190 to Road 332*	3/7/2017	3/7/2017	
	Mountain Roads	Repair road surface by hand patching	Tule Oak from Globe Drive to End	3/7/2017	3/7/2017	
	Mountain Roads	Repair road surface by hand patching	Globe Drive from Pleasant Oak to Highway 190	3/7/2017	3/7/2017	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 3

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720)		Preliminary Engineering	Avenue 280 County Line to State Route 99 Farm to Market	7/25/2016	ongoing	\$ 32,485.16
		Construction/Design	Road 148 Avenue 280 Visalia Road to Avenue 288 Marinette Avenue	7/18/2014	ongoing	\$ 2,818.73
		Construction/Design	Road 200 from Avenue 0 to Avenue 8	7/18/2014	ongoing	\$ 43.90
		Construction/Design	Avenue 432 Floral Avenue Road 128 to State Highway 63 to Road 136	7/18/2014	ongoing	\$ 3,811.75
		Construction/Design	Rural Road Surface Maintainance	1/15/2015	ongoing	\$ 98.21
		Preliminary Engineering/ Design	Community Road Surface Maintainance	1/15/2015	ongoing	\$ 294.62
		Preliminary Engineering/ Design	School Street to Park Drive	3/2/2016	ongoing	\$ 1,556.73
		Preliminary Engineering/ Design	Terra Bella Avenue to Court Avenue	3/2/2016	ongoing	\$ 1,164.93
		Preliminary Engineering/ Design	Road 38 at Avenue 54 to 650 South of Intersection	3/2/2016	ongoing	\$ 1,442.12
		Preliminary Engineering/ Design	Avenue 306 to Effie Drive	3/2/2016	ongoing	\$ 911.00
		Preliminary Engineering/ Design	Avenue 368 East of Canal Drive	3/2/2016	ongoing	\$ 775.97
		Preliminary Engineering/ Design	Zante Drive and Baker Drive	3/2/2016	ongoing	\$ 640.93
		Preliminary Engineering/ Design	Road 236 from Avenue 96 to Avenue 100	3/2/2016	ongoing	\$ 4,432.72
		Construction/Design	Strathmore Slurry Seal and Isolated Road Repair	3/2/2016	ongoing	\$ 556.29
		Preliminary Engineering/ Design	Sundale Union High School	2/21/2017	ongoing	\$ 74.91
		Preliminary Engineering/ Design	Pleasant View West	2/21/2017	ongoing	\$ 93.64
		Preliminary Engineering/ Design	Saucelito Elementary School	2/21/2017	ongoing	\$ 56.19
		Preliminary Engineering/ Design	Waukena Union Elementary	2/21/2017	ongoing	\$ 56.19
		Preliminary Engineering/ Design	Stone Corral Elementary	2/21/2017	ongoing	\$ 56.19
		Preliminary Engineering/ Design	Monson-Sultana School District	2/21/2017	ongoing	\$ 37.46
		Preliminary Engineering/ Design	Alta Vista Elementary School	2/21/2017	ongoing	\$ 37.46
		Preliminary Engineering/ Design	Outside Creek Elementary	2/21/2017	ongoing	\$ 37.46
		Preliminary Engineering/ Design	Columbine Elementary School	2/21/2017	ongoing	\$ 37.46
		Preliminary Engineering/ Design	West Goshen Avenue 308	2/21/2017	ongoing	\$ 723.42
		Preliminary Engineering/ Design	Poplar Crossing Road 192 and Avenue 146	2/21/2017	ongoing	\$ 2,144.48
		Preliminary Engineering/ Design	Strathmore Avenue 196 and Road 228 Intersection	2/21/2017	ongoing	\$ 2,167.37
		Preliminary Engineering/ Design	Terra Bella Road 243 at Avenue 95 and Avenue 92	2/21/2017	ongoing	\$ 218.96
		Preliminary Engineering/ Design	Diagonal 205 Rehabilitation	2/21/2017	ongoing	\$ 5,305.08
						\$ 332,554.28

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
16/17 Annual Advance \$4,199,499.00 Communities	Cameron Creek	Repair road surface by hand patching	Avenue 296 from Road 168 to Road 176	4/13/2017	4/13/2017	\$ 693.15
	Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 195A to Highway 190	4/17/2017	4/17/2017	\$ 528.12
	Cutler/Orosi	Repair road surface by hand patching	George Road from Amethyst Avenue to Avenue 406	3/20/2017	3/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 413 from David Road to State Highway 63	3/20/2017	3/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	David Road East of State Highway 63	3/20/2017	3/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 at Avenue 416	3/20/2017	3/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 at Avenue 417	3/20/2017	3/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 407 at Road 124	3/20/2017	3/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	School Avenue from State Highway 63 to Mueller Road	3/20/2017	3/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	Railroad Drive from Road 124 to Topeka Drive	3/20/2017	3/20/2017	
	Cutler/Orosi	Large area patching with Grader- "Blade Patch"	Topeka Drive from Railroad Drive to First Drive	6/19/2017	6/19/2017	
	Cutler/Orosi	Large area patching with Grader- "Blade Patch"	Cutler Drive from Railroad Drive to First Drive	6/19/2017	6/22/2017	
	Cutler/Orosi	Large area patching with Grader- "Blade Patch"	Second Drive from Cutler Drive to Orosi Drive	6/19/2017	6/20/2017	
	Cutler/Orosi	Repair road surface by hand patching	Orosi Drive North of First Drive	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Orosi Drive from Road 128 to Second Drive	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	School Avenue from Road 120 to Mueller Road	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Mueller Road from School Avenue to Avenue 404	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Cannon Avenue from Avenue 403 to Road 130	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Sierra Avenue from Avenue 403 to Road 130	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Robert Road South of Cannon Avenue	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 415 East of Road 128	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 414 from Bienhom Road to Road 127	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 413 from David Road to Road 127	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 from Albert Avenue to Avenue 412	6/19/2017	6/19/2017	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 at Avenue 412	6/19/2017	6/19/2017	
	Cutler/Orosi	Large area patching with Grader- "Blade Patch"	Avenue 404 from State Highway 63 to Mueller Road	6/20/2017	6/20/2017	
	Cutler/Orosi	Haul material to location for blade patch	Avenue 404 from State Highway 63 to Mueller Road	6/20/2017	6/20/2017	
	Cutler/Orosi	Haul material to location for blade patch	Second Drive from Cutler Drive to Orosi Drive	6/20/2017	6/20/2017	
	Cutler/Orosi	Haul material to location for blade patch	Ella Avenue from Ralph Road to Road 130	6/21/2017	6/21/2017	
	Cutler/Orosi	Large area patching with Grader- "Blade Patch"	Ella Avenue from Ralph Road to Road 130	6/21/2017	6/21/2017	
	Cutler/Orosi	Repair road by hand patching	Road 130 at Ella Avenue	6/21/2017	6/21/2017	
	Cutler-Orosi	Large area Patching with grader "Blade Patch"	Topeka Drive from Railroad Drive to First Drive	6/19/2017	6/19/2017	
	Cutler-Orosi	Large area Patching with grader "Blade Patch"	Cutler Drive from Railroad Drive to First Drive	6/19/2017	6/19/2017	
	Cutler-Orosi	Large area Patching with grader "Blade Patch"	Second Drive from Orosi Drive to Cutler Drive	6/19/2017	6/20/2017	
	Cutler-Orosi	Large area Patching with grader "Blade Patch"	Avenue 404 from Road 128 to Mueller Road	6/20/2017	6/20/2017	
	Cutler-Orosi	Large area Patching with grader "Blade Patch"	Elle Avenue from Ralph Road to Road 130	6/21/2017	6/21/2017	\$ 14,302.35
	Doyle Colony	Repair potholes with Road Patcher	Avenue 146 west of Road 284	4/13/2017	4/13/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 146 from Road 272 to Road 284	4/13/2017	4/13/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 148 at Road 267	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Road 262 from Avenue 146 to LA148B	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 148 from Road 264 to Road 264	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 148 from Road 272 to Road 266	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Road 272 from Avenue 146 to Avenue 150	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Road 270 from Avenue 146 to Avenue 148	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Road 264 at Avenue 150	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 148 at Road 266	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Road 269 from Avenue 146 to Avenue 150	4/25/2017	4/25/2017	
	Doyle Colony	Repair road surface by hand patching	Avenue 150 at Road 262	4/27/2017	4/27/2017	
	Doyle Colony	Repair road surface by hand patching	Road 262 at Avenue 150	4/27/2017	4/27/2017	\$ 1,640.32

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

East Kingsburg	Repair road surface by hand patching	Road 16 from Avenue 384 to Avenue 392	6/16/2017	6/16/2017	
East Kingsburg	Repair road surface by hand patching	Avenue 392 from Road 8 to Road 16	6/16/2017	6/16/2017	
East Kingsburg	Repair road surface by hand patching	Road 40 from Avenue 400 to Avenue 408	6/20/2017	6/20/2017	
East Kingsburg	Repair road surface by hand patching	Road 40 from Avenue 400 to Avenue 416	6/21/2017	6/21/2017	
East Kingsburg	Repair road surface by hand patching	Road 40 from Avenue 384 to Avenue 400	6/21/2017	6/21/2017	
East Kingsburg	Repair road surface by hand patching	Avenue 392 East of Road 40	6/21/2017	6/21/2017	
East Kingsburg	Repair road surface by hand patching	Diagonal 27 at Avenue 384	6/22/2017	6/22/2017	\$ 4,059.54
East Orosi	Repair road surface by hand patching	Hollister Road from Avenue 418 to Avenue 419	4/6/2017	4/6/2017	
East Orosi	Repair road surface by hand patching	Avenue 419 from Lone Road to Road 139	4/10/2017	4/10/2017	
East Orosi	Repair road surface by hand patching	Road 139 from Avenue 419 to Idaho Avenue	4/10/2017	4/10/2017	
East Orosi	Repair road surface by hand patching	Road 139 at Avenue 417	4/10/2017	4/10/2017	
East Orosi	Repair road surface by hand patching	Avenue 417 from Road 139 to Fruitvale Road	4/10/2017	4/13/2017	\$ 1,147.35
Ivanhoe	Repair road surface by hand patching	Road 156 from Avenue 320 to Avenue 328	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Avenue 324 West of Road 156	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Jasmine Avenue West of Road 160	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Road 157 at Rosaline Avenue	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Road 158 from Aspen Avenue to Beechwood Avenue	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Road 156 North of Avenue 328	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Live Oak Drive from Road 156 to Avenue 330	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Avenue 329 from Road 157 to Road 158	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Fuschia Avenue from Road 158 to Manzanita Road	5/15/2017	5/15/2017	
Ivanhoe	Repair road surface by hand patching	Azalea Avenue from Road 159 to Road 160	5/15/2017	5/15/2017	\$ 4,688.09
Lindcove	Large area Patching with grader "Blade Patch"	LA316 from Road 220 to LR224	3/29/2017	4/6/2017	
Lindcove	Large area Patching with grader "Blade Patch"	LR224 from Avenue 312 to LA313	3/29/2017	4/6/2017	
Lindcove	Repair road surface by hand patching	Avenue 300 at Road 220	3/31/2017	3/31/2017	
Lindcove	Large area Patching with grader "Blade Patch"	LR226B from LA313 to Avenue 315	4/6/2017	4/6/2017	
Lindcove	Repair road surface by hand patching	Avenue 304 at Road 220	4/10/2017	4/10/2017	
Lindcove	Repair road surface by hand patching	Avenue 310 at Road 228	4/11/2017	4/11/2017	
Lindcove	Repair road surface by hand patching	Diagonal 211 from Road 272 to Avenue 268	4/11/2017	4/11/2017	
Lindcove	Repair road surface by hand patching	Diagonal 246B from Highway 198 to Avenue 307	5/1/2017	5/1/2017	\$ 58,990.91
Monson	Repair road by hand patching	Road 108 from Avenue 384 to Avenue 388	5/24/2017	5/24/2017	\$ 82.93
Oak Ranch	Repair road surface by hand patching	Avenue 312 from Tower Road to Hacienda Road	3/28/2017	3/28/2017	
Oak Ranch	Repair road surface by hand patching	Lipson Avenue from Tower Road to End of Road	4/27/2017	4/27/2017	\$ 209.84
Orosi	Repair road surface by hand patching	Miller Road from Road 125 to Road 126	3/24/2017	3/24/2017	
Orosi	Repair road surface by hand patching	Miller Road from Road 126 to Road 128	3/24/2017	3/24/2017	
Orosi	Repair road surface by hand patching	Ella Avenue from Road 130 to Mueller Road	4/4/2017	4/4/2017	
Orosi	Repair road surface by hand patching	Avenue 414 from State Highway 63 to Road 130	4/5/2017	4/5/2017	
Orosi	Repair road surface by hand patching	Road 130 South of Avenue 414	4/5/2017	4/5/2017	
Orosi	Repair road surface by hand patching	Ella Avenue from Mueller Road to Ralph Road	4/5/2017	4/5/2017	
Orosi	Repair road surface by hand patching	Road 130 at Ella Avenue	4/5/2017	4/5/2017	
Orosi	Repair road surface by hand patching	Road 130 from Avenue 416 to Tactacan Avenue	4/5/2017	4/5/2017	
Orosi	Repair road surface by hand patching	Clyde Avenue at Road 130	4/5/2017	4/5/2017	
Orosi	Repair road surface by hand patching	Avenue 413 from Road 124 to State Highway 63	4/6/2017	4/6/2017	
Orosi	Repair road surface by hand patching	Bienhorn Road from Ella Avenue to Avenue 414	4/6/2017	4/6/2017	\$ 2,009.24
Patterson Tract	Repair road surface by hand patching	Avenue 328 East of Road 127	4/26/2017	4/26/2017	
Patterson Tract	Repair road surface by hand patching	Road 127 from Avenue 328 to End of Road	4/26/2017	4/26/2017	
Patterson Tract	Repair road surface by hand patching	Lincoln Road North of Avenue 324	5/4/2017	5/4/2017	
Patterson Tract	Repair road surface by hand patching	Lincoln Road from Avenue 324 to Avenue 328	6/16/2017	6/16/2017	
Patterson Tract	Repair road surface by hand patching	Avenue 416 from State Highway 63 to Road 152	6/22/2017	6/22/2017	\$ 1,075.09

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Location	Activity	Project Description	Start Date	End Date	Amount
Plainview	Repair road surface by hand patching	Road 196 from Avenue 184 to Avenue 192	4/3/2017	4/3/2017	
Plainview	Repair road surface by hand patching	Road 200 from Avenue 184 to Avenue 192	4/3/2017	4/3/2017	
Plainview	Repair road surface by hand patching	Road 204 from Avenue 184 to Avenue 192	4/3/2017	4/3/2017	
Plainview	Repair potholes with Road Patcher	Road 184 east of Avenue 152	4/10/2017	4/10/2017	
Plainview	Repair potholes with Road Patcher	Road 212 from Avenue 188 to Avenue 196	4/17/2017	4/17/2017	
Plainview	Repair road surface by hand patching	LR195 at Avenue 195	4/27/2017	4/27/2017	
Plainview	Repair road surface by hand patching	Avenue 192 east of Road 188	4/27/2017	4/27/2017	\$ 844.45
Sequoia Crest	Repair road surface by hand patching	Mountain Road 218 from Mountain Road 216 to Mountain Road 217	4/17/2017	4/17/2017	\$ 376.21
Seville	Repair road surface by hand patching	Road 155 from Inyo Avenue to Seville Avenue	3/24/2017	3/24/2017	
Seville	Repair road surface by hand patching	Visalia Avenue from Road 154 to Road 155	3/24/2017	3/24/2017	
Seville	Repair road surface by hand patching	Visalia Avenue East of Road 155	4/4/2017	4/4/2017	
Seville	Repair road surface by hand patching	Inyo Avenue from Road 153 to Road 156	4/4/2017	4/4/2017	
Seville	Repair road surface by hand patching	Road 153 from Inyo Avenue to Avenue 384	4/4/2017	4/4/2017	
Seville	Repair road surface by hand patching	Avenue 383 from Road 153 to Road 154	4/4/2017	4/4/2017	
Seville	Repair road surface by hand patching	Seville Avenue from Road 153 to Road 156	4/4/2017	4/4/2017	
Seville	Repair road surface by hand patching	Visalia Avenue from Road 153 to Road 154	4/4/2017	4/4/2017	
Seville	Repair road surface by hand patching	Road 154 from Inyo Avenue to Avenue 384	4/4/2017	4/4/2017	
Seville	Repair road surface by hand patching	Kern Road from Avenue 384 to Seville Avenue	4/4/2017	4/4/2017	\$ 931.70
Strathmore	Repair potholes with Road Patcher	Avenue 204 from Road 228 to Road 232	3/24/2017	3/24/2017	
Strathmore	Repair road surface by hand patching	Avenue 204 from Road 228 to Road 232	3/24/2017	3/24/2017	
Strathmore	Repair road surface by hand patching	Avenue 188 at Road 188	3/27/2017	3/27/2017	
Strathmore	Repair road surface by hand patching	Avenue 188 at Diagonal 242	3/29/2017	3/29/2017	
Strathmore	Repair road surface by hand patching	Avenue 192 at Road 228	3/29/2017	3/29/2017	
Strathmore	Repair road surface by hand patching	Road 228 from Avenue 192 to Avenue 196	3/29/2017	3/29/2017	
Strathmore	Repair potholes with Road Patcher	Road 228 from Avenue 196 to Avenue 220	3/30/2017	3/30/2017	
Strathmore	Repair road surface by hand patching	Road 228 at Avenue 184	3/30/2017	3/30/2017	
Strathmore	Repair road surface by hand patching	Road 228 from Avenue 196 to Avenue 220	3/30/2017	3/30/2017	
Strathmore	Repair potholes with Road Patcher	Avenue 200 at Friant Kern Canal	4/3/2017	4/3/2017	
Strathmore	Repair potholes with Road Patcher	Avenue 204 from Road 228 to Road 232	4/3/2017	4/3/2017	
Strathmore	Repair road surface by hand patching	Avenue 200 at Friant Kern Canal	4/3/2017	4/3/2017	
Strathmore	Repair road surface by hand patching	Avenue 204 from Road 228 to Road 232	4/3/2017	4/3/2017	
Strathmore	Repair road surface by hand patching	Road 244 from Avenue 188 to Avenue 244	4/3/2017	4/3/2017	
Strathmore	Repair road surface by hand patching	Road 220 from Avenue 184 to Avenue 192	4/3/2017	4/3/2017	
Strathmore	Repair potholes with Road Patcher	Avenue 204 from Road 232 to Road 236	4/5/2017	4/5/2017	
Strathmore	Repair potholes with Road Patcher	Avenue 188 from Road 224 to Road 228	4/6/2017	4/6/2017	
Strathmore	Repair potholes with Road Patcher	Road 216 from Avenue 184 to Avenue 196	4/17/2017	4/17/2017	
Strathmore	Repair potholes with Road Patcher	Road 224 south of Avenue 200	4/24/2017	4/24/2017	\$ 4,212.65
Three Rivers	Repair road surface by hand patching	Grouse Valley Road from South Fork Drive to End of Road	4/27/2017	4/27/2017	
Three Rivers	Repair road surface by hand patching	South Fork Drive from Grouse Valley Road to Mile Post 6.5	4/27/2017	4/27/2017	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 1 to Mile Post 3.5	5/2/2017	5/2/2017	
Three Rivers	Repair road surface by hand patching	North Fork Drive from Mile Post 0 to Mile Post 4	5/5/2017	5/5/2017	
Three Rivers	Repair road surface by hand patching	Blossom Drive South of South Fork Drive	5/17/2017	5/17/2017	
Three Rivers	Repair road surface by hand patching	South Fork Drive East of Blossom Drive	5/17/2017	5/17/2017	
Three Rivers	Repair road surface by hand patching	Hammond Drive from Mineral King Road to End of Road	5/24/2017	5/24/2017	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Sierra King Drive to Hammond Drive	5/24/2017	5/24/2017	
Three Rivers	Repair road surface by hand patching	Mineral King Road at State Highway 198	5/24/2017	5/24/2017	\$ 2,636.66

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Tonyville	Repair road surface by hand patching	Road 204 at Avenue 264	3/24/2017	3/24/2017	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 250	3/24/2017	3/24/2017	
Tonyville	Repair road surface by hand patching	Avenue 250 from Road 216 to Road 224	3/24/2017	3/24/2017	
Tonyville	Repair road surface by hand patching	Avenue 242 from Road 228 to Road 236	3/24/2017	3/24/2017	
Tonyville	Repair road surface by hand patching	Avenue 256 west of Road 204	3/27/2017	3/27/2017	
Tonyville	Repair road surface by hand patching	Avenue 256 from Road 196 to Road 204	3/31/2017	3/31/2017	
Tonyville	Repair road surface by hand patching	Avenue 252 at Diagonal 242	4/24/2017	4/24/2017	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 250	4/24/2017	4/24/2017	
Tonyville	Repair road surface by hand patching	Avenue 264 west of Road 216	4/25/2017	4/25/2017	\$ 1,412.32
Tooleville	Repair road surface by hand patching	Avenue 282 east of Road 204	3/30/2017	3/30/2017	
Tooleville	Repair road surface by hand patching	25764 Road 204	3/30/2017	3/30/2017	
Tooleville	Repair road surface by hand patching	Avenue 276 from Road 199* (Exeter City Limits) to Road 204	3/31/2017	3/31/2017	
Tooleville	Repair road surface by hand patching	Avenue 273 from Road 196 to Road 204	3/31/2017	3/31/2017	
Tooleville	Repair road surface by hand patching	Avenue 280 at Diagonal 208D	4/5/2017	4/5/2017	
Tooleville	Repair road surface by hand patching	Avenue 280 west of Mountain Road 296	4/10/2017	4/10/2017	
Tooleville	Repair road surface by hand patching	Avenue 268 from Road 192 to Road 196	4/10/2017	4/10/2017	
Tooleville	Repair road surface by hand patching	Avenue 288 from Road 196 to Road 204	4/10/2017	4/10/2017	
Tooleville	Repair road surface by hand patching	Avenue 268 from Road 204 to Road 216	4/11/2017	4/11/2017	
Tooleville	Repair road surface by hand patching	Avenue 268 at Road 192	5/4/2017	5/4/2017	\$ 1,753.62
Traver	Repair road surface by hand patching	Merritt Drive at Burke Drive	3/31/2017	3/31/2017	
Traver	Repair road surface by hand patching	Burke Drive at Avenue 360	3/31/2017	3/31/2017	
Traver	Repair road surface by hand patching	Burke Drive South of Merritt Drive	5/4/2017	5/4/2017	
Traver	Repair road surface by hand patching	Merritt Drive at Burke Drive	5/4/2017	5/4/2017	
Traver	Repair road surface by hand patching	Burker Drive North of Jacobs Drive	5/4/2017	5/4/2017	
Traver	Repair road surface by hand patching	Zante Drive from Bullard Drive to Kitchner Drive	5/4/2017	5/4/2017	
Traver	Repair road surface by hand patching	Baker Drive from Bullard Drive to Merritt Drive	5/4/2017	5/4/2017	
Traver	Repair road surface by hand patching	Road 36 from Avenue 368 to Avenue 384	6/19/2017	6/20/2017	\$ 1,402.23
Waukena	Measure R Reconstruction	Road 272 from Avenue 199 to Avenue 21	4/18/2017	4/18/2017	
Waukena	Re-lay, special project	Harmon Road from Avenue 199 to Leota Ave	4/18/2017	4/25/2017	\$ 27,723.42
West Exeter	Repair road surface by hand patching	Avenue 264 from Road 180 to Road 184	3/28/2017	3/28/2017	
West Exeter	Repair road surface by hand patching	Road 188 from Avenue 288 to End	3/29/2017	3/29/2017	
West Exeter	Repair road surface by hand patching	Road 188 north of Avenue 288	3/29/2017	3/29/2017	
West Exeter	Repair road surface by hand patching	Road 188 from Exeter City Limits to Avenue 288	3/30/2017	3/30/2017	
West Exeter	Repair road surface by hand patching	Road 180 north of Avenue 280	4/3/2017	4/3/2017	
West Exeter	Repair road surface by hand patching	Road 180 south of Avenue 180	5/4/2017	5/4/2017	\$ 786.17
Western Divide	Repair road surface by hand patching	Mountain Road 107 from Milepost 7 to Milepost 7.5	4/26/2017	4/26/2017	
Western Divide	Repair road surface by hand patching	Mountain Road 107 from Milepost 1 to Milepost 7	4/27/2017	4/27/2017	\$ 1,405.60
Yokohl	Repair road surface by hand patching	Avenue 300 west of Road 210	4/6/2017	4/6/2017	
Yokohl	Repair road surface by hand patching	Road 212 from Avenue 300 to Avenue 304	4/11/2017	4/11/2017	\$ 289.64

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads	Rural Roads	Repair road surface by hand patching	Avenue 181 from Road 238 to Diagonal 242	3/22/2017	3/22/2017	
	Rural Roads	Large area Patching with grader "Blade Patch"	Avenue 136 from Road 224 to Road 228	6/5/2017	6/14/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 228 from Road 228 to Road 236	3/23/2017	3/23/2017	
	Rural Roads	Repair potholes with Road Patcher	Road 228 from Avenue 228 to Avenue 232	3/24/2017	3/24/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 184 at Road 208	3/24/2017	3/24/2017	
	Rural Roads	Repair road surface by hand patching	Road 228 from Avenue 228 to Avenue 232	3/24/2017	3/24/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 184 at Friant Kern Canal	3/24/2017	3/24/2017	
	Rural Roads	Repair potholes with Road Patcher	Road 220 from Avenue 220 to Avenue 224	3/30/2017	3/30/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 220 from Road 196 to Road 224	3/30/2017	3/30/2017	
	Rural Roads	Repair road surface by hand patching	Road 220 from Avenue 220 to Avenue 224	3/30/2017	3/30/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 176 west of Road 192	3/30/2017	3/30/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 170 east of Road 232	3/30/2017	3/30/2017	
	Rural Roads	Repair road surface by hand patching	Road 201 from Avenue 228 to Avenue 232	4/3/2017	4/3/2017	
	Rural Roads	Repair road surface by hand patching	Road 205 from Avenue 220 to Avenue 224	4/3/2017	4/3/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 224 from Highway 65 to Road 244	4/3/2017	4/3/2017	
	Rural Roads	Repair road surface by hand patching	Road 272 west of Road 228	4/4/2017	4/4/2017	
	Rural Roads	Repair potholes with Road Patcher	Avenue 212 from Road 232 to Road 244	4/6/2017	4/6/2017	
	Rural Roads	Repair road surface by hand patching	Diagonal 234 at Road 236	4/6/2017	4/6/2017	
	Rural Roads	Repair road surface by hand patching	Road 252 north of Avenue 212	4/6/2017	4/6/2017	
	Rural Roads	Repair potholes with Road Patcher	Avenue 208 from Road 160 to Road 168	4/10/2017	4/10/2017	
	Rural Roads	Repair potholes with Road Patcher	Road 176 from Avenue 188 to Avenue 224	4/10/2017	4/10/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 280 from Road 160 to Road 168	4/10/2017	4/10/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 300 from Road 196 to Road 204	4/10/2017	4/10/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 256 at Road 192	4/11/2017	4/11/2017	
	Rural Roads	Repair potholes with Road Patcher	Avenue 300 from Road 196 to Road 204	4/13/2017	4/13/2017	
	Rural Roads	Repair potholes with Road Patcher	Road 204 at Avenue 172	4/18/2017	4/18/2017	
	Rural Roads	Repair road surface by hand patching	Road 228 south of Avenue 238	4/20/2017	4/20/2017	
	Rural Roads	Repair potholes with Road Patcher	Avenue 220 from Road 258 to Road 260	4/24/2017	4/24/2017	
	Rural Roads	Repair road surface by hand patching	Road 228 from Diagonal 242 to Avenue 238	4/24/2017	4/24/2017	
	Rural Roads	Repair road surface by hand patching	Road 188 south of Avenue 242	4/25/2017	4/25/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 184 at Road 180	4/27/2017	4/27/2017	
	Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 256 to Avenue 268	5/1/2017	5/1/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 238 from Diagonal 211B to Road 221	5/2/2017	5/2/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 178 from Road 232 to End	5/3/2017	5/3/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 170 east of Highway 65	5/3/2017	5/3/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 240 from Road 214 to Road 216	5/3/2017	5/3/2017	
	Rural Roads	Repair road surface by hand patching	Diagonal 246C east of Diagonal 246B	5/4/2017	5/4/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 176 from Road 320 to Mountain Road 171A	5/12/2017	5/12/2017	
	Rural Roads	Repair road surface by hand patching	Road 248 from Avenue 204 to Avenue 208	5/12/2017	5/12/2017	
	Rural Roads	Repair road surface by hand patching	Road 188 from Highway 137 to Avenue 248	5/12/2017	5/12/2017	
	Rural Roads	Large area Patching with grader "Blade Patch"	Avenue 136 from Road 226 to Road 232	6/5/2017	6/5/2017	
	Rural Roads	Large area Patching with grader "Blade Patch"	Road 208 at Avenue 56	6/5/2017	6/5/2017	
	Rural Roads	Large area Patching with grader "Blade Patch"	Avenue 136 Road 224 Road 232	6/5/2017	6/5/2017	
	Rural Roads	Large area Patching with grader "Blade Patch"	Road 208 at Avenue 56	6/5/2017	6/5/2017	
	Rural Roads	Move equipment from Blade Patch	Avenue 136 at Road 224	6/12/2017	6/12/2017	
	Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 0 to Avenue 24	4/3/2017	4/10/2017	
	Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 0 to Avenue 8	4/11/2017	4/12/2017	
	Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 32 to Avenue 40	4/11/2017	4/11/2017	
	Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 0 to Avenue 8	4/11/2017	4/11/2017	
	Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 144 to Avenue 152	4/11/2017	4/11/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 136 from Road 208 to West Street	4/11/2017	4/11/2017	
	Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 208 to Road 160	4/12/2017	4/12/2017	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 152 to Road 208	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 32 to Avenue 56	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 284 to Mile Post 4	4/19/2017	4/19/2017
Rural Roads	Repair road surface by hand patching	Road 204 from Avenue 96 to Avenue 108	4/20/2017	4/20/2017
Rural Roads	Repair road surface by hand patching	Road 264 from Avenue 116 to Avenue 120	4/24/2017	4/24/2017
Rural Roads	Repair road surface by hand patching	Road 268 from Avenue 120 to Avenue 128	4/24/2017	4/24/2017
Rural Roads	Repair road surface by hand patching	Road 264 from Avenue 96 to Avenue 108	4/24/2017	4/24/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 56 to Avenue 88	4/25/2017	4/25/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 56 to Avenue 80	4/26/2017	4/26/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 52 to Avenue 88	4/26/2017	4/26/2017
Rural Roads	Repair road surface by hand patching	Mountain 99 from Mountain 50 to Tulare County Line	4/27/2017	4/27/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 96 to Avenue 8	5/1/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Diagonal 205 from Avenue 32 to Avenue 56	5/1/2017	5/1/2017
Rural Roads	Repair road surface by hand patching	Mountain 10 from Mountain 3 to End	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Mountain 9 from Mountain 3 to Mile Post 5.72	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 88 from R248 to R236	5/4/2017	5/4/2017
Rural Roads	Repair road surface by hand patching	Road 236 at A88	5/4/2017	5/4/2017
Rural Roads	Repair road surface by hand patching	Road 268 from Avenue 88 to Avenue 78	5/5/2017	5/5/2017
Rural Roads	Repair road surface by hand patching	Avenue 78 from Road 268 to Road 267	5/5/2017	5/5/2017
Rural Roads	Repair road surface by hand patching	Road 267 from Avenue 78 to Avenue 70	5/5/2017	5/5/2017
Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 0 to Avenue 136	5/8/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Avenue 136 from Road 224 to Road 228	6/5/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 136 from West St to Friant Kern Canal	3/16/2017	3/20/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 8 to Avenue 32	3/16/2017	3/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 216 to Road 224	3/22/2017	3/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 0 from Road 144 to Road A200	3/24/2017	3/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 95 from Road 238 to Road 264	3/27/2017	3/27/2017
Rural Roads	Repair road surface by hand patching	Road 248 from Avenue 60 to Avenue 76	3/27/2017	3/27/2017
Rural Roads	Repair road surface by hand patching	Mountain 99 from Mile Post 1 to Mile Post 9	3/28/2017	3/28/2017
Rural Roads	Repair road surface by hand patching	Mountain 56 at Mile Post 9	3/29/2017	3/29/2017
Rural Roads	Repair road surface by hand patching	Grove Drive from Road 212 to Road 216	3/29/2017	3/29/2017
Rural Roads	Repair road surface by hand patching	Avenue 128 from Road 248 to Diagonal 238	3/29/2017	3/29/2017
Rural Roads	Repair road surface by hand patching	Avenue 128 from Newcomb to Road 208	3/29/2017	3/29/2017
Rural Roads	Repair road surface by hand patching	Avenue 128 from Newcomb to Road 216	3/31/2017	3/31/2017
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 432 to Avenue 440	3/20/2017	3/20/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 at Road 112	3/22/2017	3/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 112 to Road 124	3/22/2017	3/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 West of Road 132	3/22/2017	3/22/2017
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 352 to Avenue 368	3/22/2017	3/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 at Road 132	3/23/2017	3/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 West of Road 140	3/23/2017	3/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 104	3/27/2017	3/27/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 356 to Avenue 370	3/27/2017	3/27/2017
Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 136 to End of Road	3/28/2017	3/28/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 136 to End of Road	3/28/2017	3/28/2017
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 416	3/29/2017	3/29/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 at Road 172	3/29/2017	3/29/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 336 to Avenue 368	3/29/2017	3/29/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 at Road 168	3/30/2017	3/30/2017
Rural Roads	Repair road surface by hand patching	Road 114 from Avenue 416 to Avenue 424	3/30/2017	3/30/2017
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 400	3/30/2017	3/30/2017
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 312 to Avenue 328	3/30/2017	3/30/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from State Highway 63 to Road 152	3/30/2017	3/30/2017
Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 336	3/30/2017	3/30/2017
Rural Roads	Repair road surface by hand patching	Avenue 313 from Road 144 to Road 148	3/31/2017	3/31/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 336 East of Road 152	3/31/2017	3/31/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 124 to Road 320	3/31/2017	3/31/2017
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 312 to Avenue 320	3/31/2017	3/31/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 116 to Road 120	4/3/2017	4/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 152 to Road 168	4/3/2017	4/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 168 to Road 204	4/4/2017	4/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 112 to Road 124	4/4/2017	4/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 8 to Road 12	4/4/2017	4/4/2017
Rural Roads	Repair road surface by hand patching	Road 16 from Avenue 396 to Avenue 400	4/4/2017	4/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 West of Road 16	4/4/2017	4/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 400 at Road 144	4/5/2017	4/5/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 404 to Avenue 408	4/5/2017	4/5/2017
Rural Roads	Repair road surface by hand patching	Road 168 from El Rio Drive to State Highway 216	4/6/2017	4/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 456 from Road 120 to Road 144	4/12/2017	4/12/2017
Rural Roads	Repair road surface by hand patching	Avenue 448 from Road 120 to Road 124	4/12/2017	4/12/2017
Rural Roads	Repair road surface by hand patching	El Rio Drive from Road 160 to Road 168	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 328 to El Rio Drive	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Road 84 from Avenue 368 to Avenue 400	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Road 204 North of Avenue 336	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 392 at Road 104	4/13/2017	4/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 360 from Burke Drive to Road 80	4/17/2017	4/17/2017
Rural Roads	Repair road surface by hand patching	Road 44 from Avenue 360 to Avenue 368	4/17/2017	4/17/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 428 to Avenue 432	4/17/2017	4/17/2017
Rural Roads	Repair road surface by hand patching	Dry Creek Drive at Mile Post 5	4/19/2017	4/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 at Road 108	4/19/2017	4/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 at Road 108	4/19/2017	4/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 80 to State Highway 99	4/19/2017	4/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 at Road 100	4/19/2017	4/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 at Diagonal 27	4/20/2017	4/20/2017
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 352 to Avenue 360	4/24/2017	4/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 416 from Road 144 to Road 168	4/24/2017	4/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 East of State Highway 63	4/25/2017	4/25/2017
Rural Roads	Repair road surface by hand patching	Road 100 at Avenue 360	4/25/2017	4/25/2017
Rural Roads	Repair road surface by hand patching	Road 140 South of Avenue 352	4/25/2017	4/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 144	4/25/2017	4/25/2017
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 328 to Avenue 344	4/25/2017	4/25/2017
Rural Roads	Repair road surface by hand patching	Bermuda Street from Road 122 to State Highway 63	4/26/2017	4/26/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 132 to Road 140	4/26/2017	4/26/2017
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 344 to Avenue 352	4/26/2017	4/26/2017
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 104 to Road 114	5/2/2017	5/2/2017
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 404	5/2/2017	5/2/2017
Rural Roads	Repair road surface by hand patching	Road 33 from Avenue 396 to Avenue 400	5/2/2017	5/2/2017
Rural Roads	Repair road surface by hand patching	Road 32 from Avenue 400 to Jasper Drive	5/2/2017	5/2/2017
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 360 to Avenue 364	5/2/2017	5/2/2017
Rural Roads	Repair road surface by hand patching	Avenue 364 from Road 140 to Road 148	5/2/2017	5/2/2017
Rural Roads	Repair road surface by hand patching	Monson Drive from Road 108 to Avenue 384	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Road 40 from Avenue 408 to Avenue 416	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 428 from Road 128 to Road 144	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Road 136 from Avenue 428 to Avenue 432	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 136 to Road 144	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 56 to Road 64	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 84 to Road 88	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 East of State Highway 63	5/3/2017	5/3/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 344 to Avenue 352	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 384 to Avenue 388	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 388 to End of Road	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 352 to Avenue 368	5/3/2017	5/3/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 West of Road 100	5/4/2017	5/4/2017
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 368	5/4/2017	5/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 40 to Road 41	5/4/2017	5/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 North of Merritt Drive	5/4/2017	5/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 52 to Road 62	5/4/2017	5/4/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 172 to Road 188	5/5/2017	5/5/2017
Rural Roads	Repair road surface by hand patching	Road 126 from Ella Avenue to Avenue 414	5/8/2017	5/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 432 West of Road 132	5/8/2017	5/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 132 to Road 144	5/8/2017	5/8/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 416 to Avenue 424	5/8/2017	5/8/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 424 to Avenue 432	5/9/2017	5/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 24 to Road 32	5/9/2017	5/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Kingsburg City Limits to Road 20	5/9/2017	5/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 20 to Road 24	5/10/2017	5/10/2017
Rural Roads	Repair road surface by hand patching	Road 24 from Avenue 400 to Avenue 408	5/10/2017	5/10/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 from Road 80 to Road 120	5/10/2017	5/10/2017
Rural Roads	Repair road surface by hand patching	Road 124 South of Avenue 432	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Road 56 North of Avenue 416	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Avenue 468 from Road 120 to Road 128	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Avenue 364 from Road 140 to Road 148	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 360 to Avenue 364	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Charter Oak Drive from Road 180 to Road 188	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 from Road 80 to Road 120	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Road 108 from Visalia City Limits to Avenue 328	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 44 to Road 80	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 West of Road 80	5/11/2017	5/11/2017
Rural Roads	Repair road surface by hand patching	Avenue 398 from State Highway 245 to End of Road	5/12/2017	5/12/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 from Millwood Drive to State Highway 245	5/12/2017	5/12/2017
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 344 to Avenue 352	5/12/2017	5/12/2017
Rural Roads	Repair road surface by hand patching	Avenue 392 West of Road 74	5/12/2017	5/12/2017
Rural Roads	Repair road surface by hand patching	Avenue 392 West of Road 56	5/12/2017	5/12/2017
Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 384 to Avenue 392	5/12/2017	5/12/2017
Rural Roads	Repair road surface by hand patching	Road 72 from Avenue 430 to Avenue 432	5/15/2017	5/15/2017
Rural Roads	Repair road surface by hand patching	Cottonwood Drive from Avenue 352 to Road 188	5/16/2017	5/16/2017
Rural Roads	Repair road surface by hand patching	Road 188 at Cottonwood Drive	5/16/2017	5/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 444 from Road 120 to Road 128	5/16/2017	5/16/2017
Rural Roads	Repair road surface by hand patching	Road 124 at Avenue 448	5/16/2017	5/16/2017
Rural Roads	Repair road surface by hand patching	Avenue 452 at Road 124	5/16/2017	5/16/2017
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 456 to Avenue 460	5/16/2017	5/16/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 404 to Avenue 408	5/17/2017	5/17/2017
Rural Roads	Repair road surface by hand patching	Road 142 from Avenue 416 to Avenue 424	5/17/2017	5/17/2017
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 460 to Avenue 472	5/17/2017	5/17/2017
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 432 to Avenue 436	5/17/2017	5/17/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 44 to Road 80	5/18/2017	5/18/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 100 to Road 132	5/18/2017	5/18/2017
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 460 to Avenue 464	5/18/2017	5/18/2017
Rural Roads	Repair road surface by hand patching	Road 124 at Avenue 424	5/18/2017	5/18/2017
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 44 to Road 80	5/19/2017	5/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 80 to Road 132	5/19/2017	5/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 West of Road 140	5/19/2017	5/19/2017
Rural Roads	Repair road surface by hand patching	Avenue 352 East of Road 126	5/19/2017	5/19/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Rural Roads	Repair road surface by hand patching	Charter Oak Drive from Road 168 to Road 180	5/19/2017	5/19/2017
Rural Roads	Repair road surface by hand patching	Road 188 at Avenue 344	5/19/2017	5/19/2017
Rural Roads	Repair road surface by hand patching	Patching in Wilsonia, Ca	5/22/2017	5/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 404 from State Highway 63 to Mueller Road	5/22/2017	5/22/2017
Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 344 to Cottonwood Drive	5/22/2017	5/22/2017
Rural Roads	Repair road surface by hand patching	Road 16 from Avenue 396 to Avenue 400	5/22/2017	5/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 430 from Road 68 to Road 80	5/22/2017	5/22/2017
Rural Roads	Repair road surface by hand patching	Avenue 432 at Road 68	5/22/2017	5/22/2017
Rural Roads	Repair road surface by hand patching	Road 96 at Avenue 432	5/22/2017	5/22/2017
Rural Roads	Repair road surface by hand patching	Road 44 from Avenue 410 to Avenue 416	5/23/2017	5/23/2017
Rural Roads	Repair road surface by hand patching	Road 108 North of Avenue 388	5/23/2017	5/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 376 West of Road 76	5/23/2017	5/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 80 to Road 108	5/23/2017	5/23/2017
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 320 to Avenue 328	5/23/2017	5/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 West of Road 80	5/23/2017	5/23/2017
Rural Roads	Repair road surface by hand patching	Avenue 432 East of Road 132	5/24/2017	5/24/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Kingsburg City Limits to Road 16	5/24/2017	5/24/2017
Rural Roads	Large area patching with Grader- "Blade Patch"	Avenue 444 from Road 120 to Road 128	5/25/2017	5/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 8 to Road 16	5/25/2017	5/25/2017
Rural Roads	Repair road surface by hand patching	Avenue 404 from Road 96 to Road 104	5/25/2017	5/25/2017
Rural Roads	Repair road surface by hand patching	Road 88 South of Avenue 406	5/25/2017	5/25/2017
Rural Roads	Repair road surface by hand patching	Road 76 from Avenue 376 to Avenue 384	5/25/2017	5/25/2017
Rural Roads	Repair road surface by hand patching	Road 88 South of Avenue 406	5/26/2017	5/26/2017
Rural Roads	Repair road surface by hand patching	Avenue 384 from Road 80 to Road 96	5/26/2017	5/26/2017
Rural Roads	Repair road surface by hand patching	Road 136 from Avenue 420 to Avenue 424	5/30/2017	5/30/2017
Rural Roads	Repair road surface by hand patching	Road 108 from Avenue 368 to Avenue 376	5/30/2017	5/30/2017
Rural Roads	Repair road surface by hand patching	Avenue 376 West of Road 108	5/30/2017	5/30/2017
Rural Roads	Repair road surface by hand patching	Monson Drive from Avenue 384 to Avenue 388	5/30/2017	5/30/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 West of State Highway 63	5/30/2017	5/30/2017
Rural Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 3 to Mile Post 7	5/31/2017	5/31/2017
Rural Roads	Repair road surface by hand patching	Dry Creek Drive from Mile Post 7 to Mile Post 17	5/31/2017	5/31/2017
Rural Roads	Repair road surface by hand patching	Avenue 344 from Road 222 to State Highway 216	5/31/2017	5/31/2017
Rural Roads	Repair road surface by hand patching	Avenue 337 from Road 220 to Woodlake City Limits	5/31/2017	5/31/2017
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 376 to Avenue 380	5/31/2017	5/31/2017
Rural Roads	Repair road surface by hand patching	Road 124 at Avenue 384	5/31/2017	5/31/2017
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 352 to Avenue 384	5/31/2017	5/31/2017
Rural Roads	Repair road surface by hand patching	Negro Creek Drive from Road 152 to Mile Post 12	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Road 36 from Avenue 376 to Avenue 384	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Road 48 North of Avenue 384	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Road 40 from Avenue 384 to Avenue 390	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 92 to Road 96	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 420 from Road 92 to Dinuba City Limits	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Road 164 from Avenue 344 to Avenue 354	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 44 to Road 80	6/1/2017	6/1/2017
Rural Roads	Repair road surface by hand patching	Avenue 376 from Road 60 to Road 80	6/1/2017	6/1/2017
Rural Roads	Large area patching with Grader- "Blade Patch"	Avenue 136 from Road 224 to Road 228	6/5/2017	6/5/2017
Rural Roads	Large area patching with Grader- "Blade Patch"	Road 208 North of Avenue 56	6/5/2017	6/5/2017
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 68 to Road 80	6/5/2017	6/5/2017
Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 320 to End of Road	6/5/2017	6/5/2017
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 140 to Road 156	6/5/2017	6/5/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 432 to Johnson Drive	6/6/2017	6/6/2017
Rural Roads	Repair road surface by hand patching	Avenue 436 from Road 144 to Johnson Drive	6/6/2017	6/6/2017
Rural Roads	Repair road surface by hand patching	Road 84 at Avenue 384	6/6/2017	6/6/2017
Rural Roads	Repair road surface by hand patching	Road 84 at Avenue 400	6/6/2017	6/6/2017
Rural Roads	Repair road surface by hand patching	Road 140 South of Avenue 368	6/6/2017	6/6/2017

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 368 at Road 140	6/7/2017	6/7/2017
Rural Roads	Repair road surface by hand patching	Road 140 at Avenue 344	6/7/2017	6/7/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 428 to Avenue 432	6/7/2017	6/7/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 West of Road 80	6/7/2017	6/7/2017
Rural Roads	Repair road surface by hand patching	Road 164 South of Avenue 352	6/7/2017	6/7/2017
Rural Roads	Repair road surface by hand patching	Road 164 North of Avenue 344	6/7/2017	6/7/2017
Rural Roads	Repair road surface by hand patching	Road 68 at Avenue 400	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 64 to Road 68	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Road 44 from Avenue 360 to Avenue 368	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 104 to Road 124	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 384 to Avenue 392	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 416 at Road 152	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 412 to Avenue 416	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Avenue 388 from Road 88 to Monson Drive	6/8/2017	6/8/2017
Rural Roads	Repair road surface by hand patching	Orosi Drive from Railroad Drive to State Highway 63	6/9/2017	6/9/2017
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 384 to Avenue 392	6/9/2017	6/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 80 to State Highway 99	6/9/2017	6/9/2017
Rural Roads	Repair road surface by hand patching	Road 44 from Avenue 360 to Avenue 368	6/9/2017	6/9/2017
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 400	6/9/2017	6/9/2017
Rural Roads	Repair road surface by hand patching	Avenue 315 from Road 168 to Charter Oak Drive	6/12/2017	6/12/2017
Rural Roads	Repair road surface by hand patching	Avenue 376 from Road 76 to Road 80	6/12/2017	6/12/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 108 to Road 112	6/12/2017	6/12/2017
Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 124 to Road 132	6/12/2017	6/12/2017
Rural Roads	Repair road surface by hand patching	Monson Drive from Avenue 338 to Simpson Drive	6/12/2017	6/12/2017
Rural Roads	Repair road surface by hand patching	Eshom Valley Drive at Mile Post 1.5	6/12/2017	6/12/2017
Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 312 to Charter Oak Drive	6/13/2017	6/13/2017
Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 312 to Avenue 314	6/13/2017	6/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 188 to Road 196	6/13/2017	6/13/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from State Highway 63 to Road 188	6/13/2017	6/13/2017
Rural Roads	Repair road surface by hand patching	Sierra Avenue from Avenue 403 to Road 130	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 336 to Avenue 344	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 344 to Avenue 360	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 432 to Avenue 436	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 108 to Road 112	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 415 East of Road 128	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Road 136 from Avenue 420 to Avenue 428	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 420 East of Road 144	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Avenue 420 East of Lone Road	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 336 to Lort Drive	6/14/2017	6/14/2017
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 344 to Avenue 352	6/15/2017	6/15/2017
Rural Roads	Repair road surface by hand patching	Drive 60 at Avenue 360	6/15/2017	6/15/2017
Rural Roads	Repair road surface by hand patching	Lincoln Road from Avenue 324 to Avenue 328	6/16/2017	6/16/2017
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 352 to Avenue 384	6/21/2017	6/21/2017
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 336 to Avenue 384	6/21/2017	6/21/2017
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 120 to Road 172	6/21/2017	6/21/2017

Agency:

Tulare County Resource Management Agency

Quarter:

FY 2017 Quarter 4

Local Programs

Mountain Roads

Mountain Roads	Repair road surface by hand patching	Mountain Road 171A at Avenue 176	3/21/2017	3/21/2017
Mountain Roads	Repair road surface by hand patching	Road 320 from Avenue 176 to Mountain Road 194G	3/24/2017	3/24/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Highway 198 to Milepost 19.5	3/30/2017	3/30/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 19.5 to Mountain Road 276	3/31/2017	3/31/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 193A from Highway 190 to Mountain Road 195A	3/31/2017	3/31/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 239 from Highway 190 to Mountain Road 296	3/31/2017	3/31/2017
Mountain Roads	Repair road surface by hand patching	Road 320 from Avenue 176 to Mountain Road 194G	3/31/2017	3/31/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 195G from Road 309* Mountain 194G	3/31/2017	3/31/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 164D from Mountain Road 168D to Avenue 164*	4/3/2017	4/3/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 172A from Highway 190 to Highway 190	4/3/2017	4/3/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 159 from Mountain Road 164 to Road 328*	4/3/2017	4/3/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 168C from Mountain Road 161 to Mountain Road 168B	4/3/2017	4/3/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 158 from Mountain Road 161 to Mountain Road 164	4/3/2017	4/3/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 23 to Milepost 28	4/27/2017	4/27/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 from Milepost 8 to Milepost 9	5/2/2017	5/2/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 27 to Milepost 29	5/3/2017	5/3/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 247 from Mountain Road 296 to Milepost 1	5/3/2017	5/4/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 38 to Mountain Road 220	5/5/2017	5/5/2017
Mountain Roads	Repair road surface by hand patching	Mountain Road 208 from Milepost 0.5 to Milepost 4	5/9/2017	5/9/2017

\$ 193,571.67

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2017 Quarter 4

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720)		Preliminary Engineering	Avenue 280 County Line to State Route 99 Farm to Market	7/25/2016	ongoing	\$ 27,184.58
		Construction/Design	Road 148 Avenue 280 Visalia Road to Avenue 288 Marinette Avenue	7/18/2014	ongoing	\$ 1,690.56
		Construction/Design	Road 200 from Avenue 0 to Avenue 8	7/18/2014	ongoing	\$ 58.54
		Construction/Design	Avenue 432 Floral Avenue Road 128 to State Highway 63 to Road 136	7/18/2014	ongoing	\$ 2,020.59
		Preliminary Engineering/ Design	Community Road Surface Maintainance	1/15/2015	ongoing	\$ 232.60
		Preliminary Engineering/ Design	School Street to Park Drive	3/2/2016	ongoing	\$ 357,236.87
		Preliminary Engineering/ Design	Terra Bella Avenue to Court Avenue	3/2/2016	ongoing	\$ 1,924.31
		Preliminary Engineering/ Design	Road 38 at Avenue 54 to 650 South of Intersection	3/2/2016	ongoing	\$ 24,900.54
		Preliminary Engineering/ Design	Avenue 306 to Effie Drive	3/2/2016	ongoing	\$ 109,290.57
		Preliminary Engineering/ Design	Avenue 368 East of Canal Drive	3/2/2016	ongoing	\$ 94,560.28
		Preliminary Engineering/ Design	Zante Drive and Baker Drive	3/2/2016	ongoing	\$ 10,018.44
		Preliminary Engineering/ Design	Avenue 378	3/2/2016	ongoing	\$ 0.01
		Preliminary Engineering/ Design	Road 236 from Avenue 96 to Avenue 100	3/2/2016	ongoing	\$ 4,049.81
		Construction/Design	Strathmore Slurry Seal and Isolated Road Repair	3/2/2016	ongoing	\$ 1,535.09
		Preliminary Engineering/ Design	Sundale Union High School	2/21/2017	ongoing	\$ 5,135.87
		Preliminary Engineering/ Design	Pleasant View West	2/21/2017	ongoing	\$ 16,883.08
		Preliminary Engineering/ Design	Saucelito Elementary School	2/21/2017	ongoing	\$ 17,200.72
		Preliminary Engineering/ Design	Waukena Union Elementary	2/21/2017	ongoing	\$ 9,740.66
		Preliminary Engineering/ Design	Stone Corral Elementary	2/21/2017	ongoing	\$ 9,960.19
		Preliminary Engineering/ Design	Monson-Sultana School District	2/21/2017	ongoing	\$ 4,906.52
		Preliminary Engineering/ Design	Alta Vista Elementary School	2/21/2017	ongoing	\$ 10,470.88
		Preliminary Engineering/ Design	Outside Creek Elementary	2/21/2017	ongoing	\$ 19,563.83
		Preliminary Engineering/ Design	Columbine Elementary School	2/21/2017	ongoing	\$ 17,717.52
		Preliminary Engineering/ Design	Ivanhoe Road 159 and Azalea Improvements	2/21/2017	ongoing	\$ 2,985.77
		Preliminary Engineering/ Design	West Goshen Avenue 308	2/21/2017	ongoing	\$ 2,684.57
		Preliminary Engineering/ Design	Orosi Avenue 416 Crossing	2/21/2017	ongoing	\$ 54.73
		Preliminary Engineering/ Design	Poplar Crossing Road 192 and Avenue 146	2/21/2017	ongoing	\$ 42.29
		Preliminary Engineering/ Design	Strathmore Avenue 196 and Road 228 Intersection	2/21/2017	ongoing	\$ 758.14
		Preliminary Engineering/ Design	Allensworth Sidewalk & Crosswalk Improvements	2/21/2017	ongoing	\$ 410.43
		Preliminary Engineering/ Design	Alpaugh Center Street Improvements	2/21/2017	ongoing	\$ 1,646.41
		Preliminary Engineering/ Design	Terra Bella Road 243 at Avenue 95 and Avenue 92	2/21/2017	ongoing	\$ 1,717.08
		Preliminary Engineering/ Design	Earlimart Alila School ADA Ramp Construction	2/21/2017	ongoing	\$ 1,173.50
		Preliminary Engineering/ Design	Road 158 Rehabilitation	2/21/2017	ongoing	\$ 3,454.64
		Preliminary Engineering/ Design	Avenue 368 Rehabilitation	2/21/2017	ongoing	\$ 2,575.06
		Preliminary Engineering/ Design	Diagonal 205 Rehabilitation	2/21/2017	ongoing	\$ 3,234.21
		Preliminary Engineering/ Design	Road 192 Rehabilitation	2/21/2017	ongoing	\$ 3,105.70
						\$ 1,096,897.86