

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
17/18 Annual Advance \$4,199,499.00 Communities	Cameron Creek	Chip Seal Road	Avenue 296 from Road 152 to Road 168	8/18/2018	9/14/2018	\$ 17,913.02
	Cameron Creek	Chipseal Overlay of large area	Road 168 from Avenue 288 to Avenue 296	8/31/2018	9/14/2018	
	Cutler/Orosi	Repair road by hand patching	Avenue 424 West of Road 120	6/25/2018	6/26/2018	
	Cutler/Orosi	Repair road by hand patching	Avenue 424 from Road 120 to Road 124	6/29/2018	6/29/2018	
	Cutler/Orosi	Repair road by hand patching	Road 136 at Avenue 422	7/3/2018	7/3/2018	
	Cutler/Orosi	Repair road by hand patching	Road 136 from Avenue 424 to Avenue 428	7/3/2018	7/3/2018	
	Cutler/Orosi	Repair road by hand patching	Avenue 422 from State Highway 63 to Road 136	7/6/2018	7/6/2018	
	Cutler/Orosi	Repair road by hand patching	Avenue 428 from State Highway 63 to Road 130	7/6/2018	7/6/2018	
	Cutler/Orosi	Repair road by hand patching	Road 124 North of Avenue 416	7/18/2018	7/27/2018	
	Cutler/Orosi	Large area Patching with grader "Blade Patch"	Lincoln Road from First Drive to Amethyst Avenue	7/23/2018	8/9/2018	
	Cutler/Orosi	Large area Patching with grader "Blade Patch"	Road 130 from Avenue 416 to Avenue 419	7/23/2018	8/9/2018	
	Cutler/Orosi	Repair road by hand patching	Avenue 416 from Road 130 to Road 144	7/31/2018	7/31/2018	
	Cutler/Orosi	Repair road by hand patching	Road 124 from Avenue 416 to Avenue 432	7/31/2018	7/31/2018	
	Cutler/Orosi	Repair road by hand patching	Road 124 from Avenue 408 to Avenue 416	8/3/2018	8/6/2018	
	Cutler/Orosi	Repair road by hand patching	Road 124 from Avenue 424 to Avenue 432	8/3/2018	8/3/2018	
	Cutler/Orosi	Repair road by hand patching	Avenue 416 at State Highway 63	8/28/2018	8/28/2018	
	Cutler/Orosi	Repair road by hand patching	Road 130 South of Avenue 416	8/28/2018	8/28/2018	
	Cutler/Orosi	Repair road by hand patching	Avenue 415 at Road 128	9/4/2018	9/4/2018	\$ 12,740.46
	Cutler/Orosi	Repair road by hand patching	Avenue 416 from Road 120 to State Highway 63	9/6/2018	9/7/2018	
	Delft Colony	Repair road by hand patching	Avenue 404 at Road 64	6/26/2018	6/26/2018	
	Delft Colony	Repair road by hand patching	Avenue 392 from Road 56 to Road 64	7/10/2018	7/11/2018	
	Delft Colony	Repair road by hand patching	Avenue 392 from Road 48 to Road 56	7/11/2018	7/11/2018	
	Delft Colony	Repair road by hand patching	Avenue 396 from Road 64 to Road 74	7/11/2018	7/11/2018	
	Delft Colony	Repair road by hand patching	Road 56 from Avenue 400 to Avenue 416	9/4/2018	9/4/2018	
	Delft Colony	Repair road by hand patching	Avenue 408 from Road 56 to Dinuba City Limits	9/7/2018	9/7/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Baxley from Roby to Crabtree	7/12/2018	8/13/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Rocky Hill from Roby to Crabtree	7/12/2018	8/13/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Holcomb Street from Roby Avenue to Crabtree Avenue	7/30/2018	7/30/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Tulsa from Roby to Crabtree	7/30/2018	8/6/2018	
	Doyle Colony	Resurface road with Chip Rock	Avenue 150 from Road 260 to Road 272	8/8/2018	9/4/2018	
	Doyle Colony	Resurface road with Chip Rock	LA148B (Tyler Avenue) from LR261 (W Street) to Road 256	8/8/2018	9/4/2018	
	Doyle Colony	Resurface road with Chip Rock	Road 262 from D254A (Success Drive) to Avenue 150	8/8/2018	9/4/2018	
	Doyle Colony	Resurface road with Chip Rock	Road 264 from Avenue 148 to Avenue 150	8/8/2018	9/4/2018	
	Doyle Colony	Chip Seal Road	Avenue 148B from Road 261 to Road 265	8/24/2018	8/29/2018	
	Doyle Colony	Chip Seal Road	Road 260 from Avenue 150 to Avenue 152	8/24/2018	8/29/2018	
	Doyle Colony	Chipseal Overlay of large area	Tyler Avenue from W Street to Road 265	8/27/2018	8/29/2018	\$ 110,740.65
	Dutch Colony	Repair road by hand patching	Sentinel Drive from Avenue 360 to Avenue 364	7/2/2018	7/3/2018	\$ 143.62
	East Kingsburg	Repair road by hand patching	Jasper Drive at Road 32	6/26/2018	6/26/2018	
	East Kingsburg	Repair road by hand patching	Jasper Drive from Road 32 to Avenue 408	6/26/2018	6/26/2018	
	East Kingsburg	Repair road by hand patching	Road 33 from Avenue 396 to Avenue 400	6/26/2018	7/9/2018	
	East Kingsburg	Repair road by hand patching	Road 40 from Avenue 384 to Avenue 390	6/28/2018	6/28/2018	
	East Kingsburg	Repair road by hand patching	Road 34 from Avenue 384 to Avenue 396	6/29/2018	6/29/2018	
	East Kingsburg	Repair road by hand patching	Avenue 390 at Road 36	7/11/2018	7/11/2018	
	East Kingsburg	Repair road by hand patching	Avenue 404 from Road 40 to Road 48	8/21/2018	8/21/2018	
	East Kingsburg	Repair road by hand patching	Avenue 396 from Road 20 to Road 24	9/6/2018	9/10/2018	\$ 1,222.22

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

East Orosi	Repair road by hand patching	Avenue 432 from Road 132 to Road 144	6/29/2018	6/29/2018	
East Orosi	Repair road by hand patching	Road 144 from Avenue 416 to Avenue 432	7/2/2018	8/22/2018	
East Orosi	Repair road by hand patching	Road 140 from Avenue 428 to Avenue 432	7/3/2018	7/6/2018	
East Orosi	Repair road by hand patching	Avenue 416 from Road 144 to Road 154	7/31/2018	7/31/2018	
East Orosi	Repair road by hand patching	Avenue 428 from Road 144 to End	8/17/2018	8/17/2018	
East Orosi	Repair road by hand patching	Avenue 420 from Road 144 to Road 152	8/22/2018	8/28/2018	
East Orosi	Repair road by hand patching	Avenue 428 at Road 144	8/22/2018	8/22/2018	
East Orosi	Repair road by hand patching	Avenue 432 from Road 136 to Road 144	8/22/2018	8/22/2018	
East Orosi	Repair road by hand patching	Road 140 from Avenue 420 to Avenue 436	8/22/2018	8/22/2018	
East Orosi	Repair road by hand patching	Road 138 from Avenue 416 to Avenue 428	8/28/2018	8/28/2018	\$ 1,172.67
Goshen	Chip Seal Road	Road 76 from A305 to A308	8/14/2018	8/20/2018	\$ 6,856.82
Ivanhoe	Repair road by hand patching	Avenue 325 from Road 164 to Road 166	7/3/2018	7/3/2018	
Ivanhoe	Repair road by hand patching	Road 166 from Avenue 326 to Avenue 328	7/3/2018	7/3/2018	
Ivanhoe	Repair road by hand patching	Avenue 320 from Road 156 to Road 160	7/9/2018	7/9/2018	
Ivanhoe	Repair road by hand patching	Avenue 340 at Road 164	7/9/2018	7/9/2018	
Ivanhoe	Repair road by hand patching	Road 160 from Avenue 332 to Avenue 336	7/9/2018	7/9/2018	
Ivanhoe	Large area Patching with grader "Blade Patch"	Avenue 332 from Road 160 to Road 161	7/24/2018	8/6/2018	
Ivanhoe	Grind road for relay	Road 164 at Avenue 332	7/24/2018	7/24/2018	
Ivanhoe	Repair road by hand patching	Avenue 336 from Road 156 to Road 172	8/8/2018	8/8/2018	\$ 4,924.43
Lindcove	Resurface road with Chip Rock	LA316 (Boston Avenue) from Road 220 to LR224 (Blair Road)	8/14/2018	9/12/2018	
Lindcove	Resurface road with Chip Rock	LR224 (Blair Road) from Avenue 312 to LA313 (Avenue 313)	8/14/2018	9/12/2018	
Lindcove	Chip Seal Road	Avenue 316 from Road 220 to Road 224	9/5/2018	9/12/2018	
Lindcove	Chipseal Overlay of large area	Blair Road from Avenue 312 to Avenue 313	9/5/2018	9/6/2018	
Lindcove	Chip Seal Road	Road 224 from Avenue 312 to Avenue 313	9/5/2018	9/11/2018	
Lindcove	Chip Seal	Road 226 from Avenue 314 to End	9/5/2018	9/7/2018	\$ 8,289.80
London	Repair road by hand patching	Avenue 376 at Road 57	8/10/2018	8/10/2018	
London	Repair road by hand patching	Avenue 378 from Road 58 to Hunter Road	8/24/2018	8/24/2018	
London	Repair road by hand patching	Avenue 380 from Road 58 to Kate Road	8/24/2018	8/24/2018	
London	Repair road by hand patching	Denver Avenue at Road 60	8/24/2018	8/24/2018	
London	Repair road by hand patching	Hunter Road North of Avenue 376	8/24/2018	8/24/2018	
London	Repair road by hand patching	Kate Road from Avenue 376 to Avenue 380	8/24/2018	8/24/2018	
London	Repair road by hand patching	Road 58 at Avenue 377	8/24/2018	8/24/2018	
London	Chipseal Overlay of large area	Avenue 384 from Diagonal 27 to Road 68	8/28/2018	9/14/2018	
London	Loader at Chip Rock Pile	Pile #18	9/10/2018	9/12/2018	\$ 22,149.53
Monson	Repair road by hand patching	Avenue 388 at Road 96	7/20/2018	7/20/2018	
Monson	Repair road by hand patching	Avenue 392 from Road 120 to Road 124	7/27/2018	7/27/2018	
Monson	Repair road by hand patching	Road 104 at Monson Drive	8/16/2018	9/13/2018	
Monson	Repair road by hand patching	Avenue 384 at Road 104	8/28/2018	8/28/2018	
Monson	Repair road by hand patching	Avenue 388 at Road 96	8/28/2018	8/28/2018	
Monson	Repair road by hand patching	Avenue 384 East of Road 118	8/31/2018	8/31/2018	
Monson	Repair road by hand patching	Road 96 at Avenue 388	9/4/2018	9/5/2018	
Monson	Chip Seal Road	Road 104 from Diagona 108A to Avenue 400	9/6/2018	9/10/2018	
Monson	Repair road by hand patching	Road 108 from Avenue 368 to Avenue 376	9/12/2018	9/12/2018	\$ 11,322.66
Oak Ranch	Repair road by hand patching	Road 144 from Saint Johns River to Avenue 313	6/28/2018	6/28/2018	\$ 71.81
Patterson Tract	Repair road by hand patching	Avenue 328 from State Highway 63 to Road 132	8/7/2018	8/7/2018	
Patterson Tract	Repair road by hand patching	Lincoln Road from Avenue 325 to Avenue 328	8/7/2018	8/7/2018	
Patterson Tract	Repair road by hand patching	Avenue 336 at Road 132	8/23/2018	8/23/2018	
Patterson Tract	Repair road by hand patching	Road 138 from Avenue 320 to Avenue 328	8/28/2018	8/28/2018	
Patterson Tract	Repair road by hand patching	Avenue 322 from State Highway 63 to End	9/5/2018	9/5/2018	\$ 332.45
Pixley	Large area patched with grader "Blade Patch"	Market Street from Court to Orland	7/23/2018	7/25/2018	\$ 57,827.79
Plainview	Resurface road with Chip Rock	Road 204 from Avenue 192 to Avenue 196	8/13/2018	9/3/2018	\$ 7,422.82
Poplar	Chip Seal	Road 200 from Avenue 152 to Avenue 160	8/8/2018	9/15/2018	\$ 5,709.02

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

Strathmore	Large area Patching with grader "Blade Patch"	Avenue 197 at Road 230 to Road 231	7/2/2018	7/12/2018	
Strathmore	Large area Patching with grader "Blade Patch"	Avenue 198 from Diagonal 242 to Road 230	7/2/2018	7/12/2018	
Strathmore	Large area Patching with grader "Blade Patch"	Avenue 198 from Orange Belt Drive to Road 230	7/2/2018	7/12/2018	
Strathmore	Large area Patching with grader "Blade Patch"	Diagonal 230 Diagonal 232 to Diagonal 233A	7/2/2018	7/12/2018	
Strathmore	Grind road for relay	LR231A from Avenue 194 to Avenue 195	7/2/2018	7/11/2018	
Strathmore	Large area Patching with grader "Blade Patch"	Richardson Road from Avenue 194 to Avenue 195	7/2/2018	7/12/2018	
Strathmore	Large area Patching with grader "Blade Patch"	Road 232 Avenue 192 to Avenue 194	7/2/2018	7/12/2018	
Strathmore	Large area Patching with grader "Blade Patch"	LR 231A from Avenue 194 to Avenue 195	7/9/2018	7/9/2018	
Strathmore	Resurface road with Chip Rock	Avenue 204 from Road 222 to Drive 228A (Meridith Drive)	8/13/2018	9/10/2018	
Strathmore	Resurface road with Chip Rock	Road 216 from Avenue 192 to Avenue 196	8/13/2018	9/10/2018	
Strathmore	Resurface road with Chip Rock	Road 222 from Avenue 204 to Avenue 208	8/13/2018	9/10/2018	\$ 111,006.61
Sultana	Repair road by hand patching	Avenue 424 from Road 100 to Road 104	7/6/2018	7/26/2018	
Sultana	Repair road by hand patching	Road 100 from Avenue 416 to Avenue 424	7/31/2018	7/31/2018	
Sultana	Chipseal Overlay of large area	Road 92 from Avenue 416 to Avenue 424	8/27/2018	9/13/2018	
Sultana	Repair road by hand patching	Avenue 408 from Road 96 to Road 104	8/31/2018	8/31/2018	
Sultana	Repair road by hand patching	Avenue 416 from Road 92 to Road 104	8/31/2018	8/31/2018	
Sultana	Resurface road with Chip Rock	Road 96 from Avenue 416 to Avenue 424	9/6/2018	9/12/2018	
Sultana	Repair road by hand patching	Avenue 416 from Road 92 to Road 120	9/7/2018	9/7/2018	
Sultana	Repair road by hand patching	Avenue 424 from Road 88 to Road 104	9/7/2018	9/7/2018	
Sultana	Repair road by hand patching	Road 104 from Avenue 424 to Avenue 432	9/12/2018	9/12/2018	\$ 6,304.00
Terra Bella	Chip Seal	Road 234 from Avenue 80 to Avenue 88	8/7/2018	9/6/2018	
Terra Bella	Chip Seal	Avenue 100 from Road 240 to Road 248	8/8/2018	9/5/2018	
Terra Bella	Chip Seal	Avenue 88 from Road 236 to Road 256	8/8/2018	9/11/2018	\$ 21,873.79
Teviston	Chipseal Overlay of large area	Avenue 76 from Bishop Drive to Road 136	8/16/2018	8/22/2018	
Teviston	Chipseal Overlay of large area	Road 132 from Avenue 76 to Avenue 80	8/16/2018	8/22/2018	
Teviston	Resurface road with Chip Rock	Road 136 from Avenue 56 to Avenue 80	8/16/2018	8/22/2018	
Teviston	Chipseal Overlay of large area	Road 136 from Avenue 76 to Avenue 80	8/16/2018	8/22/2018	
Teviston	Chip Seal Road	Road 136 from Avenue 80 to Avenue 74	8/16/2018	8/22/2018	\$ 22,016.89
Three Rivers	Repair road by hand patching	Mineral King Road from Mile Post 2 to Mile Post 8	7/3/2018	7/3/2018	
Three Rivers	Repair road by hand patching	South Fork Drive North of Blossom Avenue	7/19/2018	7/19/2018	
Three Rivers	Repair road by hand patching	Mineral King Road from Mile Post 3 to Mile Post 7	7/23/2018	7/23/2018	
Three Rivers	Repair road by hand patching	Mynatt Drive from Eggers Drive to End	7/23/2018	7/23/2018	
Three Rivers	Repair road by hand patching	Pierce Drive North of State Highway 198	7/23/2018	7/23/2018	
Three Rivers	Repair road by hand patching	Old Three Rivers Drive from State Highway 198 to South Fork Drive	8/8/2018	8/9/2018	
Three Rivers	Repair road by hand patching	South Fork from Mile Post 1 to Mile Post 6.5	8/8/2018	8/9/2018	\$ 3,349.43
Tonyville	Resurface road with Chip Rock	Avenue 216 from Avenue 250 to Avenue 256	8/13/2018	9/9/2018	
Tonyville	Resurface road with Chip Rock	Avenue 248 from Road 224 to Drive 227 (Burr Drive)	8/13/2018	9/9/2018	
Tonyville	Resurface road with Chip Rock	Avenue 256 from Road 204 to Drive 227 (Burr Drive)	8/13/2018	9/9/2018	
Tonyville	Resurface road with Chip Rock	Drive 227 (Burr Drive) from Avenue 248 to Avenue 256	8/13/2018	9/9/2018	
Tonyville	Resurface road with Chip Rock	Road 212 from Avenue 248* to Avenue 256	8/13/2018	9/9/2018	
Tonyville	Chipseal Overlay of large area	Burr Drive from Avenue 248 to Avenue 256	8/30/2018	8/30/2018	
Tonyville	Chip Seal	Road 216 from Avenue 250 to Avenue 256	8/30/2018	9/4/2018	\$ 27,499.80

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

Traver	Repair road by hand patching	Burke Drive from Merritt Drive to Avenue 368	6/27/2018	6/27/2018	
Traver	Repair road by hand patching	Church Drive at Merritt Drive	6/27/2018	6/27/2018	
Traver	Repair road by hand patching	Merritt Drive at State Highway 99	6/27/2018	6/27/2018	
Traver	Repair road by hand patching	Drive 60 from Avenue 352 to Avenue 360	6/29/2018	6/29/2018	
Traver	Repair road by hand patching	Avenue 360 at Road 28	7/16/2018	7/16/2018	
Traver	Repair road by hand patching	Diagonal 39 South of Merritt Drive	7/17/2018	7/17/2018	
Traver	Repair road by hand patching	Drive 60 from Avenue 328 to Avenue 352	7/17/2018	7/17/2018	
Traver	Large area Patching with grader "Blade Patch"	Road 44 South of Avenue 368	8/2/2018	8/2/2018	
Traver	Repair road by hand patching	Drive 60 from Avenue 360 to Diagonal 56	8/7/2018	8/7/2018	
Traver	Repair road by hand patching	Road 44 from Avenue 360 to Avenue 368	8/9/2018	8/13/2018	
Traver	Repair road by hand patching	Road 44 at Avenue 376	8/17/2018	8/17/2018	
Traver	Repair road by hand patching	Avenue 368 from Road 44 to Road 52	8/20/2018	8/20/2018	
Traver	Repair road by hand patching	Avenue 360 from Road 44 to Road 52	8/21/2018	8/21/2018	
Traver	Repair road by hand patching	Burke Drive South of Merritt Drive	8/24/2018	8/24/2018	
Traver	Chipseal Overlay of large area	Road 44 from Avenue 368 to Avenue 376	8/28/2018	9/15/2018	
Traver	Repair road by hand patching	Drive 60 from Diagonal 56 to Avenue 360	8/31/2018	8/31/2018	
Traver	Repair road by hand patching	Avenue 360 from Burke Drive to Road 80	9/10/2018	9/10/2018	
Traver	Repair road by hand patching	Merritt Drive from Burke Drive to Road 80	9/10/2018	9/10/2018	
Traver	Loader at Chip Rock Pile	Pile #17	9/12/2018	9/12/2018	\$ 19,435.55
Union Edition	Chip Seal Road	Avenue 288 from Road 148 to Road 152	8/17/2018	9/7/2018	
Union Edition	Chip Seal Road	Road 148 from Avenue 280 to Avenue 288	8/17/2018	9/7/2018	
Union Edition	Chipseal Overlay of large area	Avenue 288 from Road 144 to Road 152	9/4/2018	9/6/2018	
Union Edition	Loader at Chip Rock Pile	Pile #18	9/12/2018	9/12/2018	\$ 10,941.56
Waukena	Chip Seal Road	Avenue 192 from Road 16 to Road 28	8/15/2018	8/20/2018	
Waukena	Chip Seal Road	Avenue 201 from Road 27 to Road 28	8/15/2018	8/20/2018	
Waukena	Chip Seal Road	Road 27 from Avenue 196 to Avenue 201	8/15/2018	8/20/2018	
Waukena	Chip Seal Road	Road 28 from Avenue 201 to Avenue 208	8/15/2018	8/20/2018	
Waukena	Resurface road with Chip Rock	Road 28 from Avenue 204 to Avenue 208	8/15/2018	8/17/2018	
Waukena	Chip Seal Road	Avenue 196 from Road 27 to Road 28	8/15/18	8/20/2018	\$ 19,165.01
West Exeter	Resurface road with Chip Rock	Road 184 from Avenue 284* (End) to Avenue 288	8/14/2018	9/10/2018	\$ 4,645.79
Woodville	Chip Seal Road	Road 252 from Avenue 70 to Avenue 84	8/23/2018	9/4/2018	\$ 189.32
Yetter	Large area Patching with grader "Blade Patch"	Avenue 392 East of Road 144	8/1/2018	8/2/2018	
Yetter	Chipseal Overlay of large area	Road 132 from Avenue 358 to Avenue 371	8/29/2018	9/15/2018	
Yetter	Chip Seal	Road 132 from Avenue 356 to Avenue 371	9/12/2018	9/19/2018	\$ 12,468.20
Yokohl	Resurface road with Chip Rock	Avenue 295 from Road 217 to LR218 (Eaton Road)	8/14/2018	9/12/2018	
Yokohl	Resurface road with Chip Rock	LR218 (Eaton Road) from Avenue 295 to Avenue 296 (State Highway 198)	8/14/2018	9/12/2018	
Yokohl	Resurface road with Chip Rock	Road 217 from Avenue 295 to Avenue 296 (State Highway 198)	8/14/2018	9/12/2018	
Yokohl	Chipseal Overlay of large area	Badger Hill Drive from Road 217 to Eaton Road	9/5/2018	9/7/2018	
Yokohl	Chip Seal Road	Road 218 from Avenue 295 to Avenue 296	9/5/2018	9/7/2018	\$ 10,857.34

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
	Rural Roads	Repair road by hand patching	Avenue 352 at Road 150	6/25/2018	6/25/2018	
	Rural Roads	Repair road by hand patching	Road 84 from Avenue 368 to Avenue 384	6/26/2018	7/2/2018	
	Rural Roads	Repair road by hand patching	Avenue 364 from Road 140 to Road 148	6/29/2018	6/29/2018	
	Rural Roads	Repair road by hand patching	Drive 60 from Avenue 328 to Avenue 352	6/29/2018	6/29/2018	
	Rural Roads	Repair road by hand patching	Road 108 from Avenue 320 to Avenue 328	6/29/2018	6/29/2018	
	Rural Roads	Repair road by hand patching	Avenue 432 from Road 136 to Road 144	7/2/2018	7/2/2018	
	Rural Roads	Repair road by hand patching	Road 144 at Avenue 400	7/2/2018	7/2/2018	
	Rural Roads	Repair road by hand patching	Avenue 360 from Road 148 to Road 150	7/3/2018	7/3/2018	
	Rural Roads	Repair road by hand patching	Avenue 337 at Road 222	7/5/2018	7/5/2018	
	Rural Roads	Repair road by hand patching	Road 222 from Avenue 344 to End	7/5/2018	7/5/2018	
	Rural Roads	Repair road by hand patching	Avenue 352 from Road 20 to Drive 60	7/6/2018	7/6/2018	
	Rural Roads	Repair road by hand patching	Avenue 432 from Road 120 to State Highway 63	7/6/2018	7/6/2018	
	Rural Roads	Repair road by hand patching	Avenue 436 from Road 136 to Road 140	7/6/2018	7/6/2018	
	Rural Roads	Repair road by hand patching	Avenue 392 at Road 124	7/9/2018	7/9/2018	
	Rural Roads	Repair road by hand patching	Road 36 from Avenue 376 to Avenue 384	7/9/2018	7/9/2018	
	Rural Roads	Repair road by hand patching	Road 48 North of Avenue 424	7/9/2018	7/9/2018	
	Rural Roads	Repair road by hand patching	Avenue 336 East of Road 216	7/12/2018	7/12/2018	
	Rural Roads	Repair road by hand patching	Avenue 448 from Road 120 to Road 128	7/12/2018	9/11/2018	
	Rural Roads	Repair road by hand patching	Avenue 456 from Road 128 to Road 136	7/12/2018	7/12/2018	
	Rural Roads	Repair road by hand patching	Charter Oak Drive from Road 180 to Road 188	7/12/2018	7/12/2018	
	Rural Roads	Repair road by hand patching	Road 136 from Avenue 456 to Avenue 460	7/12/2018	7/12/2018	
	Rural Roads	Repair road by hand patching	Road 172 from Avenue 352 to Avenue 376	7/12/2018	7/12/2018	
	Rural Roads	Repair road by hand patching	Avenue 328 from State Highway 99 to Road 80	7/13/2018	8/7/2018	
	Rural Roads	Repair road by hand patching	Road 140 from Avenue 344 to Avenue 352	7/13/2018	8/10/2018	
	Rural Roads	Repair road by hand patching	Road 180 from Avenue 336 to Avenue 352	7/13/2018	7/13/2018	
	Rural Roads	Repair road by hand patching	Avenue 352 at Road 140	7/16/2018	7/16/2018	
	Rural Roads	Repair road by hand patching	Avenue 368 at Road 124	7/16/2018	7/16/2018	
	Rural Roads	Repair road by hand patching	Road 140 at Avenue 344	7/16/2018	7/16/2018	
	Rural Roads	Repair road by hand patching	Avenue 328 from Road 76 to Road 80	7/17/2018	7/17/2018	
	Rural Roads	Repair road by hand patching	Road 140 from Avenue 360 to Avenue 368	7/17/2018	7/17/2018	
	Rural Roads	Repair road by hand patching	Road 108 from Avenue 320 to Avenue 328	7/18/2018	7/18/2018	
	Rural Roads	Repair road by hand patching	Road 112 at Avenue 328	7/18/2018	7/18/2018	
	Rural Roads	Repair road by hand patching	Road 128 from Avenue 460 to Avenue 472	7/18/2018	7/27/2018	
	Rural Roads	Repair road by hand patching	Avenue 352 from Road 100 to State Highway 63	7/19/2018	7/19/2018	
	Rural Roads	Repair road by hand patching	Avenue 352 from Road 132 to Road 140	7/19/2018	7/19/2018	
	Rural Roads	Repair road by hand patching	Avenue 368 West of State Highway 63	7/19/2018	7/19/2018	
	Rural Roads	Repair road by hand patching	Road 100 at Avenue 360	7/19/2018	7/19/2018	
	Rural Roads	Repair road by hand patching	Road 192 from Avenue 344 to Cottonwood Drive	7/19/2018	7/19/2018	
	Rural Roads	Repair road by hand patching	Avenue 344 from Road 164 to Road 172	7/20/2018	7/27/2018	
	Rural Roads	Repair road by hand patching	Avenue 392 from Road 120 to Road 124	7/23/2018	7/23/2018	
	Rural Roads	Repair road by hand patching	Dry Creek Drive from Mile Post 0 to Mile Post 11	7/25/2018	7/25/2018	
	Rural Roads	Repair road by hand patching	Avenue 432 from Road 80 to Road 88	7/26/2018	7/26/2018	
	Rural Roads	Repair road by hand patching	Avenue 352 from Road 152 to Road 156	7/27/2018	7/27/2018	
	Rural Roads	Repair road by hand patching	Road 132 North of Levee Drive	7/27/2018	7/27/2018	
	Rural Roads	Repair road by hand patching	Avenue 416 from Road 154 to Road 168	7/31/2018	7/31/2018	
	Rural Roads	Repair road by hand patching	Avenue 424 from Road 52 to Road 56	8/3/2018	8/8/2018	
	Rural Roads	Repair road by hand patching	Boyd Drive from Road 168 to State Highway 245	8/3/2018	8/3/2018	
	Rural Roads	Repair road by hand patching	Avenue 388 from Road 80 to Road 84	8/6/2018	8/6/2018	
	Rural Roads	Chip Seal	Avenue 32 from Diagonal 205 to Road 232	8/7/2018	9/6/2018	
	Rural Roads	Chip Seal	Avenue 56 from Road 148 to Road 156	8/7/2018	9/5/2018	
	Rural Roads	Chip Seal	Avenue 56 from Road 156 to Road 176	8/7/2018	9/7/2018	
	Rural Roads	Chip Seal	Avenue 84 from Road 252 to Road 256	8/7/2018	9/13/2018	
	Rural Roads	Chip Seal	Diagonal 205 from Avenue 16 to Avenue 32	8/7/2018	9/6/2018	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

Rural Roads	Repair road by hand patching	Road 108 from Avenue 320 to Avenue 328	8/7/2018	8/7/2018
Rural Roads	Repair road by hand patching	Road 144 from Avenue 400 to Avenue 408	8/7/2018	8/7/2018
Rural Roads	Chip Seal	Road 208 from Avenue 56 to Avenue 80	8/7/2018	9/8/2018
Rural Roads	Chip Seal	Road 252 from Avenue 70 to Avenue 84	8/7/2018	9/13/2018
Rural Roads	Repair road by hand patching	Road 48 from Avenue 408 to Avenue 416	8/7/2018	8/7/2018
Rural Roads	Repair road by hand patching	Road 52 North of Avenue 424	8/7/2018	8/7/2018
Rural Roads	Chip Seal	Avenue 108 from Mountain 109 to Road 270	8/8/2018	9/5/2018
Rural Roads	Repair road by hand patching	Avenue 336 from Road 172 to Road 196	8/8/2018	8/8/2018
Rural Roads	Repair road by hand patching	Avenue 336 from State Highway 63 to Road 152	8/9/2018	8/9/2018
Rural Roads	Repair road by hand patching	Avenue 320 from Road 190 to Road 196	8/10/2018	8/10/2018
Rural Roads	Repair road by hand patching	Dry Creek Drive from Mile Post 0 to Mile Post 14.5	8/10/2018	8/10/2018
Rural Roads	Water Chip Pile	23689 Camphor Ave at Road 237	8/13/2018	8/13/2018
Rural Roads	Resurface road with Chip Rock	Avenue 272 from Road 208 to Road 114* Visalia City Limits	8/13/2018	8/16/2018
Rural Roads	Repair road by hand patching	Avenue 360 from Road 52 to Road 76	8/13/2018	8/13/2018
Rural Roads	Water Chip Pile	Avenue 4 at Road 200	8/13/2018	8/13/2018
Rural Roads	Water Chip Pile	Avenue 56 at State Route 65	8/13/2018	8/13/2018
Rural Roads	Chipseal Overlay of large area	Road 100 from Diagonal 103 to Avenue 264	8/13/2018	8/16/2018
Rural Roads	Chip Seal Road	Avenue 272 from Road 114 to Visalia City	8/14/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 100 from Diagonal 103to Avenue 264	8/14/2018	8/21/2018
Rural Roads	Resurface road with Chip Rock	Avenue 216 from Road 36 (Highway 137) to Road 46*	8/14/2018	8/17/2018
Rural Roads	Loader at Chip Rock Pile	Lovers Lane (Road 140) at Avenue 256	8/14/2018	8/14/2018
Rural Roads	Chip Seal Road	Avenue 216 from SH137 to Road 46	8/15/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	Avenue 56 from Road 75* (Highway 43) to Road 96*	8/15/2018	8/20/2018
Rural Roads	Loader at Chip Rock Pile	Stanley at Dawkins Waukena	8/15/2018	8/15/2018
Rural Roads	Chip Seal Road	Avenue 56 from Road 75 to SH43	8/16/2018	9/13/2018
Rural Roads	Repair road by hand patching	Avenue 408 from Road 56 to Dinuba City Limits	8/16/2018	8/16/2018
Rural Roads	Loader at Chip Rock Pile	Exxon Pit	8/16/2018	8/20/2018
Rural Roads	Repair road by hand patching	Road 40 from Avenue 376 to Avenue 384	8/16/2018	8/16/2018
Rural Roads	Chip Seal Road	Avenue 56 from Road 148 to Road 156	8/17/2018	9/13/2018
Rural Roads	Repair road by hand patching	Avenue 376 from Road 76 to Road 80	8/17/2018	8/17/2018
Rural Roads	Repair road by hand patching	Road 140 from Avenue 352 to Avenue 368	8/17/2018	8/17/2018
Rural Roads	Chip Seal Road	Avenue 56 from Road 156 to Road 176	8/18/2018	9/13/2018
Rural Roads	Repair road by hand patching	Avenue 368 from Road 52 to Road 80	8/20/2018	8/20/2018
Rural Roads	Repair road by hand patching	Avenue 424 from Road 88 to State Highway 63	8/20/2018	8/20/2018
Rural Roads	Chipseal Overlay of large area	Avenue 56 from Road 148 to Road 160	8/20/2018	8/23/2018
Rural Roads	Repair road by hand patching	Road 8 from Avenue 384 to Avenue 392	8/20/2018	8/20/2018
Rural Roads	Chip Seal Road	Avenue 32 from Diagonal 205 to Road 232	8/21/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 208 from Avenue 56 to Avenue 80	8/21/2018	9/13/2018
Rural Roads	Repair road by hand patching	Avenue 352 from Road 206 to State Highway 216	8/21/2018	8/21/2018
Rural Roads	Repair road by hand patching	Avenue 360 from Road 52 to Road 80	8/21/2018	8/21/2018
Rural Roads	Loader at Chip Rock Pile	Ducor Pile 4	8/21/2018	8/21/2018
Rural Roads	Loader at Chip Rock Pile	Richgrove Pile 5	8/21/2018	8/21/2018
Rural Roads	Repair road by hand patching	Road 42 from Avenue 416 to Avenue 424	8/21/2018	8/21/2018
Rural Roads	Repair road by hand patching	Road 44 from Avenue 410 to Avenue 416	8/21/2018	8/21/2018
Rural Roads	Chip Seal Road	Diagonal 205 from Avenue 16 to Avenue 32	8/22/2018	9/13/2018
Rural Roads	Chipseal Overlay of large area	Avenue 108 from Old Stage Road to Road 270	8/22/2018	8/27/2018
Rural Roads	Chipseal Overlay of large area	Richgrove Drive from Avenue 16 to Avenue 32	8/22/2018	8/24/2018
Rural Roads	Chip Seal Road	Avenue 84 from Road 252 to Road 256	8/23/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 252 from Avenue 70 to Avenue 84	8/23/2018	8/28/2018
Rural Roads	Repair road by hand patching	Avenue 320 from Road 132 to Road 148	8/23/2018	8/23/2018
Rural Roads	Repair road by hand patching	Road 136 from Avenue 384 to Avenue 400	8/23/2018	8/23/2018
Rural Roads	Chip Seal Road	Avenue 108 from Mountain 109 to Road 270	8/24/2018	9/13/2018
Rural Roads	Repair road by hand patching	Dry Creek Drive from Mile Post 9 to Mile Post 17	8/24/2018	8/24/2018
Rural Roads	Resurface road with Chip Rock	Avenue 169 from Road 244 to Road 248	8/27/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	Avenue 169 from Road 250* (Porterville City Limtis) to Road 252	8/27/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	Avenue 171 from Road 244 to Road 248	8/27/2018	9/13/2018

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

Rural Roads	Loader at Chip Rock Pile	District 1 Pile 8	8/27/2018	8/28/2018
Rural Roads	Loader at Chip Rock Pile	District 5 Pile 6	8/27/2018	8/27/2018
Rural Roads	Resurface road with Chip Rock	Road 232 from Avenue 174 to Avenue 182	8/27/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	Road 244 from Avenue 169 to Avenue 171	8/27/2018	9/13/2018
Rural Roads	Chipseal Overlay of large area	Road 96 from Avenue 384 to Avenue 416	8/27/2018	9/14/2018
Rural Roads	Chip Seal Road	Avenue 169 from Road 244 to Road 248	8/28/2018	9/13/2018
Rural Roads	Chip Seal Road	Avenue 169 from Road 250 to Road 252	8/28/2018	9/13/2018
Rural Roads	Chip Seal Road	Avenue 171 from Road 244 to Road 248	8/28/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 232 from Avenue 174 to Avenue 182	8/28/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 244 from Avenue 169 to Avenue 171	8/28/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	Avenue 220 from Road 228 to Road 236	8/28/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	Avenue 237 from LR226D (Hall Avenue) to Road 227* (End)	8/28/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	LA237C (Bishop Street) from LR226D (Hall Avenue) to Road 227* (End)	8/28/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	LR226D (Hall Avenue) from Avenue 237 to Avenue 238	8/28/2018	9/13/2018
Rural Roads	Chipseal Overlay of large area	Newcomb Street from Avenue 178 to Avenue 182	8/28/2018	8/28/2018
Rural Roads	Loader at Chip Rock Pile	Pile #9	8/28/2018	8/30/2018
Rural Roads	Chipseal Overlay of large area	Road 56 from Avenue 400 to Avenue 432	8/28/2018	9/18/2018
Rural Roads	Repair road by hand patching	Road 96 South of Avenue 404	8/28/2018	8/28/2018
Rural Roads	Chip Seal Road	Avenue 220 from Road 228 to Road 236	8/29/2018	9/13/2018
Rural Roads	Chip Seal Road	Avenue 237 from Road 226D to Road 227	8/29/2018	9/13/2018
Rural Roads	Chip Seal Road	Avenue 237C from Road 226D to Road 227	8/29/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 226D from Avenue 237 to Avenue 238	8/29/2018	9/13/2018
Rural Roads	Chipseal Overlay of large area	Bishop Street from Hall Avenue to Road 227	8/29/2018	8/30/2018
Rural Roads	Chipseal Overlay of large area	Hall Avenue from Avenue 237 to Avenue 238	8/29/2018	8/30/2018
Rural Roads	Loader at Chip Rock Pile	Pile #10	8/29/2018	8/30/2018
Rural Roads	Loader at Chip Rock Pile	Pile #11	8/29/2018	8/29/2018
Rural Roads	Resurface road with Chip Rock	Road 132 from Avenue 200 to Avenue 208	8/30/2018	9/13/2018
Rural Roads	Resurface road with Chip Rock	Road 188 from Avenue 232 (State Highway 137) to Avenue 242	8/30/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 132 from Avenue 200 to Avenue 208	9/4/2018	9/13/2018
Rural Roads	Chip Seal Road	Road 188 from Avenue 232 to SH137	9/4/2018	9/13/2018
Rural Roads	Repair road by hand patching	Avenue 384 from State Highway 99 to Road 68	9/4/2018	9/4/2018
Rural Roads	Loader at Chip Rock Pile	Pile #14	9/4/2018	9/5/2018
Rural Roads	Repair road by hand patching	Road 132 from Avenue 352 to Avenue 368	9/4/2018	9/4/2018
Rural Roads	Repair road by hand patching	Road 56 from Avenue 416 to Avenue 432	9/4/2018	9/4/2018
Rural Roads	Repair road by hand patching	Road 92 from Avenue 416 to Avenue 424	9/4/2018	9/4/2018
Rural Roads	Repair road by hand patching	Avenue 360 from Road 80 to Road 112	9/5/2018	9/5/2018
Rural Roads	Repair road by hand patching	Avenue 388 from Road 176 to Road 184	9/5/2018	9/5/2018
Rural Roads	Repair road by hand patching	Avenue 390 from Road 172 to Road 176	9/5/2018	9/5/2018
Rural Roads	Repair road by hand patching	Avenue 394 from Road 172 to Road 176	9/5/2018	9/5/2018
Rural Roads	Loader at Chip Rock Pile	Pile #15	9/5/2018	9/5/2018
Rural Roads	Repair road by hand patching	Road 172 from Avenue 384 to Avenue 394	9/5/2018	9/5/2018
Rural Roads	Repair road by hand patching	Road 184 at Avenue 388	9/5/2018	9/5/2018
Rural Roads	Repair road by hand patching	Road 96 South of Avenue 400	9/5/2018	9/5/2018
Rural Roads	Chip Seal Road	Road 96 from Avenue 384 to Avenue 416	9/6/2018	9/13/2018
Rural Roads	Loader at Chip Rock Pile	Pile #16	9/6/2018	9/6/2018
Rural Roads	Chip Seal	Road 96 from Avenue 400 to Avenue 416	9/7/2018	9/10/2018
Rural Roads	Chip Seal Road	R56 from Avenue 400 to Avenue 432	9/11/2018	9/19/2018
Rural Roads	Repair road by hand patching	Avenue 432 from Road 104 to Road 108	9/11/2018	9/11/2018
Rural Roads	Chip Seal Road	Road 56 from Avenue 400 to Avenue 432	9/12/2018	9/13/2018
Rural Roads	Repair road by hand patching	Avenue 384 at Ward Drive	9/12/2018	9/12/2018
Rural Roads	Repair road by hand patching	Road 84 from Avenue 368 to Avenue 384	9/12/2018	9/12/2018
Rural Roads	Repair road by hand patching	Road 144 from Avenue 320 to Avenue 328	9/13/2018	9/13/2018
Rural Roads	Repair road by hand patching	Road 84 from Avenue 368 to Avenue 400	9/13/2018	9/13/2018
Mountain Roads	Mountain Roads	Mineral King Road from Mile Post 3 to Mile Post 6.5	7/19/2018	7/20/2018

\$ 237,947.41

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 1

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720)		Construction/design	Avenue 280 County Line to State Route 99 Farm to Market	6/26/2017	ongoing	
		Construction/Design	Court Ave - School Street to Park Drive	6/28/2017	ongoing	\$ 239.68
		Construction/Design	Road 68 - Ave 306 to Effie Drive	6/26/2017	ongoing	\$ 725.11
		Preliminary Engineering/ Design	ADA Ramp Improvements	3/3/2016	ongoing	\$ 184.69
		Preliminary Engineering/ Design	Ivanhoe R159 and Azalea Improvements	7/11/2017	ongoing	\$ 7,252.32
		Preliminary Engineering/ Design	West Goashen Ave 308	6/27/2017	ongoing	\$ 12,976.37
		Preliminary Engineering/ Design	Orosi A416 Crossing	7/12/2017	ongoing	\$ 8,926.45
		Preliminary Engineering/ Design	Poplar Crossing R192 and A146	8/1/2017	ongoing	\$ 2,787.58
		Preliminary Engineering/ Design	Strathmore A196 & R228 Intersection	8/1/2017	ongoing	\$ 2,978.67
		Preliminary Engineering/ Design	Allensworth Sidewalk & Crosswalk Improvements	8/2/2017	ongoing	\$ 2,149.53
		Preliminary Engineering/ Design	Alpaugh Center Street Improvements	8/2/2017	ongoing	\$ 2,339.31
		Preliminary Engineering/ Design	Earlimart Alila ADA Ramp Construction	8/8/2017	ongoing	\$ 1,006.43
		Preliminary Engineering/ Design	Sequoia Field - A368 Reahabilitation	6/26/2017	ongoing	\$ 8,244.75
						\$ 827,811.73

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
18/19 Annual Advance \$4,199,499.00 Communities	Alpaugh	Repair potholes with Road Patcher	Avenue 56 from Raod 120 to Road 96	11/1/2018	11/1/2018	\$ 574.94
	Alpaugh	Repair potholes with Road Patcher	Avenue 56 from State Highway 43 to Road 38	11/1/2018	11/1/2018	
	Alpaugh	Repair potholes with Road Patcher	Road 38 from, Avenue 56 to Avenue 38	11/1/2018	11/1/2018	
	Cutler/Orosi	Repair road surface by hand patching	George Road at Amethyst Avenue	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from State Highway 63 to Road 144	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 422 from State Highway 63 to Road 136	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	Road 126 from Avenue 419 to Avenue 424	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	School Avenue from State Highway 63 to Road 129	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	Ralph Road South of Avenue 403	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	Mueller Road at Avenue 404	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 407 at Road 124	9/18/2018	9/18/2018	
	Cutler/Orosi	Repair road surface by hand patching	Road 127 at Avenue 414	9/19/2018	9/19/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 413 from Road 124 to State Highway 63	9/19/2018	9/19/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from Road 120 to Road 144	9/21/2018	9/21/2018	
	Cutler/Orosi	Repair road surface by hand patching	Claude Road at Miller Avenue	9/24/2018	9/24/2018	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 from Avenue 416 to Avenue 432	10/5/2018	10/5/2018	
	Cutler/Orosi	Repair road surface by hand patching	Road 130 South of Avenue 416	10/8/2018	10/8/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 144	11/27/2018	11/27/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from Road 130 to Road 144	11/27/2018	11/27/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 413 from Road 1226 to State Highway 63	12/3/2018	12/3/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 424 at State Highway 63	12/6/2018	12/6/2018	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 412 from Road 136 to Road 144	12/11/2018	12/11/2018	\$ 1,648.39
	Delft Colony	Repair road surface by hand patching	Avenue 392 from Road 56 to Road 80	9/28/2018	9/28/2018	
	Delft Colony	Repair road surface by hand patching	Road 64 South of Avenue 408	10/12/2018	10/12/2018	\$ 492.34
	Delft Colony	Repair road surface by hand patching	Road 64 from Avenue 400 to Avenue 408	10/24/2018	10/24/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	River from Leggett to Ruth	10/1/2018	10/11/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Conner from Avenue 146 to Success Drive	10/1/2018	10/10/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Connor from Springville Drive to Success Dr.	10/1/2018	10/9/2008	
	Doyle Colony	Large area Patching with grader "Blade Patch"	River Drive from Leggett to Ruth	10/1/2018	10/9/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Crabtree Avenue from Holcomb Street to Rocky Hill Street	10/1/2018	10/2/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Conner Street from Springville Avenue to Success Drive	10/1/2018	10/9/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	River Avenue from Leggett Street to Ruth Street	10/1/2018	10/9/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	Crabtree from Holcomb to Rocky Hill	10/2/2018	10/11/2018	
	Doyle Colony	Resurface road with Chip Rock	Avenue 150 from Road 260 to Road 272	10/2/2018	10/2/2018	
	Doyle Colony	Large area Patching with grader "Blade Patch"	River from Leggett to Ruth	10/9/2018	10/9/2018	\$ 127,705.77
	Ducor	Repair road surface by hand patching	Road 232 from Avenue 80 to Avenue 56	12/10/2018	12/10/2018	
	Ducor	Repair road surface by hand patching	Road 236 from Avenue 88 to Avenue 60	12/19/2018	12/19/2018	\$ 349.15
	Earlimart	Repair potholes with Road Patcher	Church from Avenue 48 to Avenue 56	10/1/2018	10/1/2018	
	Earlimart	Repair potholes with Road Patcher	Avenue 48 from State Highway 99 to Road 144	10/1/2018	10/1/2018	
	Earlimart	Repair potholes with Road Patcher	Bobbi from Church to Molly	10/1/2018	10/1/2018	
	Earlimart	Repair potholes with Road Patcher	Quail at Spring	10/1/2018	10/1/2018	
	Earlimart	Repair potholes with Road Patcher	Church at Kovanovich	10/1/2018	10/1/2018	
	Earlimart	Repair potholes with Road Patcher	Lane at Cannon	10/1/2018	10/1/2018	
	Earlimart	Repair potholes with Road Patcher	Elm at Franklin	10/1/2018	10/1/2018	
	Earlimart	Repair potholes with Road Patcher	Spruce from Church to Lane	10/1/2018	10/1/2018	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Earlimart	Repair potholes with Road Patcher	School from State to Church	10/2/2018	10/2/2018	
Earlimart	Repair potholes with Road Patcher	State from Avenue 56 to Avenue 48	10/2/2018	10/2/2018	
Earlimart	Repair potholes with Road Patcher	East Tulare from Church to State	10/2/2018	10/2/2018	
Earlimart	Repair potholes with Road Patcher	Valente from Avenue 56 to Washington	10/2/2018	10/2/2018	
Earlimart	Repair potholes with Road Patcher	Front from Avenue 56 to State Highway 99	10/3/2018	10/3/2018	\$ 1,731.13
East Kingsburg	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 408	10/12/2018	10/12/2018	
East Kingsburg	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 416	10/18/2018	10/18/2018	
East Kingsburg	Large area Patching with grader "Blade Patch"	Road 8 South of Avenue 392	10/29/2018	10/29/2018	
East Kingsburg	Repair road surface by hand patching	Avenue 408 from Road 28 to Road 32	10/31/2018	10/31/2018	
East Kingsburg	Repair road surface by hand patching	Road 12 from Avenue 392 to Clarkson Drive	10/31/2018	10/31/2018	
East Kingsburg	Repair road surface by hand patching	Clarkson Drive from Avenue 392 to Road 12	10/31/2018	10/31/2018	
East Kingsburg	Repair road surface by hand patching	Road 20 from Avenue 392 to Avenue 396	10/31/2018	10/31/2018	
East Kingsburg	Repair road surface by hand patching	Ward Drive from Avenue 384 to Diagonal 23	10/31/2018	10/31/2018	
East Kingsburg	Repair road surface by hand patching	Ward Drive from Avenue 384 to Diagonal 23	12/5/2018	12/5/2018	\$ 3,628.06
East Orosi	Repair road surface by hand patching	Avenue 416 from Road 144 to Road 154	9/18/2018	9/21/2018	
East Orosi	Large area Patching with grader "Blade Patch"	Hollister Road from Idaho Avenue to Avenue 418	11/7/2018	11/7/2018	
East Orosi	Repair road surface by hand patching	Avenue 416 from Road 144 to Road 154	11/27/2018	11/27/2018	
East Orosi	Repair road surface by hand patching	Road 136 from Avenue 428 to Avenue 432	12/17/2018	12/17/2018	\$ 933.97
Elderwood	Repair road surface by hand patching	Road 204 from Avenue 380 to Avenue 384	9/17/2018	9/17/2018	
Elderwood	Repair road surface by hand patching	Road 206 from Avenue 384 to End	9/17/2018	9/17/2018	
Elderwood	Repair road surface by hand patching	Avenue 384 from Road 204 to Road 206	9/17/2018	9/17/2018	
Elderwood	Repair road surface by hand patching	Avenue 376 from State Highway 245 to Road 204	12/11/2018	12/11/2018	\$ 279.08
Goshen	Repair potholes with Road Patcher	Avenue 308 from Effie to Road 67	10/15/2018	10/15/2018	
Goshen	Repair potholes with Road Patcher	Harvest at Road 68	10/15/2018	10/15/2018	
Goshen	Repair potholes with Road Patcher	Effie from Road 68 to Goshen Avenue	10/15/2018	10/15/2018	
Goshen	Repair potholes with Road Patcher	Roy from Effie to Kane	10/15/2018	10/15/2018	
Goshen	Repair potholes with Road Patcher	Juniper from Elder to Harvest	10/15/2018	10/15/2018	
Goshen	Repair potholes with Road Patcher	Harvest at Road 72	10/15/2018	10/15/2018	
Goshen	Repair potholes with Road Patcher	Avenue 306 at Road 72	10/15/2018	10/15/2018	
Goshen	Repair potholes with Road Patcher	Avenue 310 at Road 69	10/17/2018	10/17/2018	
Goshen	Repair potholes with Road Patcher	Road 68 from Avenue 320 to Avenue 316	10/17/2018	10/17/2018	
Goshen	Repair potholes with Road Patcher	Avenue 320 from Road 76 to Road 68	10/17/2018	10/17/2018	
Goshen	Repair potholes with Road Patcher	Rasmussen from Road 76 to Road 72	10/17/2018	10/17/2018	
Goshen	Repair potholes with Road Patcher	Avenue 308 from Road 76 to Camp	10/17/2018	10/17/2018	
Goshen	Repair potholes with Road Patcher	Avenue 310 from Robinson to Commercial	10/17/2018	10/17/2018	
Goshen	Repair potholes with Road Patcher	Elder from Road 68 to Camp	10/17/2018	10/17/2018	\$ 1,035.72
Ivanhoe	Repair road surface by hand patching	Avenue 328 from Road 140 to Road 156	9/17/2018	9/17/2018	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 156 to Road 172	9/20/2018	9/20/2018	
Ivanhoe	Repair road surface by hand patching	Beechwood Avenue at Road 156	9/26/2018	9/26/2018	
Ivanhoe	Repair road surface by hand patching	Avenue 328 from Road 148 to Road 156	9/26/2018	9/26/2018	
Ivanhoe	Repair road surface by hand patching	Avenue 328 from Road 140 to Road 156	10/2/2018	10/2/2018	
Ivanhoe	Repair road surface by hand patching	Avenue 332 East of Road 159	10/17/2018	10/17/2018	
Ivanhoe	Repair road surface by hand patching	Road 164 from Avenue 320 to Avenue 325	10/17/2018	10/17/2018	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 152 to Road 172	10/26/2018	10/26/2018	
Ivanhoe	Repair road surface by hand patching	Road 157 from Avenue 327 to Avenue 328	10/30/2018	10/30/2018	
Ivanhoe	Repair road surface by hand patching	Fuchsia Avenue at Road 158	10/30/2018	10/30/2018	
Ivanhoe	Repair road surface by hand patching	Road 158 from Beechwood Avenue to Aspen Avenue	10/30/2018	10/30/2018	
Ivanhoe	Repair road surface by hand patching	Avenue 340 from Road 156 to Road 164	12/3/2018	12/3/2018	
Ivanhoe	Repair road surface by hand patching	Avenue 330 at Depot Drive	12/12/2018	12/12/2018	
Ivanhoe	Repair road surface by hand patching	Road 158 from Depot Drive to Road 159	12/12/2018	12/12/2018	
Ivanhoe	Repair road surface by hand patching	Road 158 at Avenue 332	12/12/2018	12/13/2018	
Ivanhoe	Repair road surface by hand patching	Lantana Avenue at Live Oak Drive	12/14/2018	12/14/2018	
Ivanhoe	Repair road surface by hand patching	Road 156 at Avenue 324	12/14/2018	12/14/2018	
Ivanhoe	Repair road surface by hand patching	Road 140 at Avenue 364	12/14/2018	12/14/2018	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Ivanhoe	Repair road surface by hand patching	Manzanita Road from Heather Avenue to Avenue 332	12/18/2018	12/18/2018	
Ivanhoe	Repair road surface by hand patching	Lantana Avenue from Road 159 to Road 160	12/18/2018	12/18/2018	
Ivanhoe	Repair road surface by hand patching	Road 159 from Avenue 328 to Depot Drive	12/18/2018	12/18/2018	
Ivanhoe	Repair road surface by hand patching	Hawthorne Road from Depot Drive to Avenue 328	12/18/2018	12/18/2018	\$ 2,119.04
Lindcove	Repair road surface by hand patching	Avenue 319 from Road 212 to Diagonal 219	11/19/2018	11/19/2018	\$ 239.22
London	Chipseal Overlay of large area	Avenue 384 from Road 60 to Road 64	9/18/2018	9/18/2018	
London	Chipseal Overlay of large area	Avenue 384 from Diagonal 27 to Road 64	9/20/2018	9/20/2018	
London	Repair road surface by hand patching	Kate Road at Avenue 380	10/4/2018	10/4/2018	
London	Repair road surface by hand patching	Avenue 378 at Road 57	10/4/2018	10/4/2018	
London	Repair road surface by hand patching	Avenue 377 at Road 57	10/4/2018	10/4/2018	
London	Repair road surface by hand patching	Road 57 from Avenue 376 to Avenue 378	10/4/2018	10/4/2018	
London	Repair road surface by hand patching	Avenue 376 from Road 60 to Road 80	12/12/2018	12/12/2018	\$ 2,024.99
Monson	Chipseal Overlay of large area	Road 104 from Monson Drive to Avenue 400	9/17/2018	9/17/2018	
Monson	Repair road surface by hand patching	Road 108 from Avenue 388 to Avenue 400	12/4/2018	12/4/2018	
Monson	Repair road surface by hand patching	Monson Drive from Simpson Drive to Avenue 388	12/4/2018	12/4/2018	
Monson	Repair road surface by hand patching	Avenue 384 from Road 96 to Road 114	12/17/2018	12/17/2018	\$ 525.71
Patterson Tract	Repair road surface by hand patching	Avenue 328 from State Highway 63 to Road 140	9/17/2018	9/17/2018	
Patterson Tract	Large area Patching with grader "Blade Patch"	Lincoln Road from Avenue 324 to Avenue 328	9/19/2018	9/25/2018	
Patterson Tract	Large area Patching with grader "Blade Patch"	Avenue 322 from Road 122 to Road 124	9/25/2018	9/25/2018	
Patterson Tract	Repair road surface by hand patching	Avenue 328 from Road 124 to Road 136	9/26/2018	9/26/2018	
Patterson Tract	Repair road surface by hand patching	Avenue 320 from Road 124 to Road 148	9/27/2018	9/27/2018	
Patterson Tract	Repair road surface by hand patching	Avenue 328 from State Highway 63 to Road 140	10/2/2018	10/2/2018	
Patterson Tract	Repair road surface by hand patching	Avenue 320 from Road 132 to Road 136	10/26/2018	10/26/2018	
Patterson Tract	Repair road surface by hand patching	Avenue 320 from Road 124 to Road 132	12/11/2018	12/11/2018	\$ 9,649.29
Pixley	Repair potholes with Road Patcher	Bradbury from Road 120 to Market	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Compton from Road 120 to Market	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Ellsworth from Ash to Market	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Ash from Court to Avenue 96	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Avenue 96 from Main Street to Cedar	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Howard from Elm to Park	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Pine from Compton to Howard	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Maple from Avenue 96 to Court	9/26/2018	9/26/2018	
Pixley	Repair potholes with Road Patcher	Dianna from Walnut to School	9/26/2018	9/26/2018	\$ 706.75
Plainview	Repair potholes with Road Patcher	Road 208 from Avenue 184 to Avenue 182	10/1/2018	10/1/2018	
Plainview	Repair road surface by hand patching	Avenue 192 at Road 180	10/26/2018	10/26/2018	
Plainview	Repair road surface by hand patching	Avenue 192 from Road 169 to Road 180	10/26/2018	10/26/2018	
Plainview	Repair road surface by hand patching	Road 208 from Avenue 196 to Avenue 204	10/29/2018	10/29/2018	
Plainview	Repair potholes with Road Patcher	Road 188 from Avenue 192 to Avenue 212	10/31/2018	10/31/2018	
Plainview	Repair potholes with Road Patcher	Road 188 from Avenue 212 to Highway 137	10/31/2018	10/31/2018	
Plainview	Repair road surface by hand patching	Avenue 208 west of Road 208	11/14/2018	11/14/2018	
Plainview	Repair road surface by hand patching	Avenue 200 from Road 180 to Road 196	11/27/2018	11/27/2018	
Plainview	Repair potholes with Road Patcher	Avenue 208 from Road 180 to Road 196	12/3/2018	12/3/2018	
Plainview	Repair road surface by hand patching	Avenue 192 from Road 168 to Road 208	12/10/2018	12/10/2018	
Plainview	Repair road surface by hand patching	Avenue 184 from Road 168 to Road 200	12/10/2018	12/10/2018	
Plainview	Repair road surface by hand patching	Avenue 192 from Road 200 to Road 212	12/11/2018	12/11/2018	\$ 1,650.83
Poplar/Cotton	Chip Seal	Road 200 from Avenue 152 to Avenue 160	9/16/2018	9/17/2018	\$ 69.99
Seville	Repair road surface by hand patching	Avenue 376 at Road 156	10/29/2018	10/29/2018	
Seville	Repair road surface by hand patching	Road 156 from Avenue 376 to Avenue 384	10/30/2018	10/30/2018	\$ 285.76
Springville	Repair road surface by hand patching	Pleasant Oak Drive at Globe Drive	12/7/2018	12/7/2018	\$ 286.22
Strathmore	Resurface road with Chip Rock	Road 216 from Avenue 250 to Avenue 256	8/13/2018	10/8/2018	
Strathmore	Repair potholes with Road Patcher	Road 212 from Avenue 196 to Avenue 204	9/17/2018	9/17/2018	
Strathmore	Repair road surface by hand patching	Avenue 184 west of Road 220	10/29/2018	10/29/2018	
Strathmore	Repair road surface by hand patching	Road 244 at Avenue 200	10/31/2018	10/31/2018	
Strathmore	Repair road surface by hand patching	Road 224 at Road 216	11/6/2018	11/6/2018	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Strathmore	Repair road surface by hand patching	Road 208 from Avenue 204 to Avenue 208	11/6/2018	11/6/2018	
Strathmore	Repair road surface by hand patching	Avenue 182 from Road 224 to Road 232	12/5/2018	12/5/2018	
Strathmore	Repair road surface by hand patching	Avenue 192 from Road 212 to Road 224	12/11/2018	12/11/2018	
Strathmore	Repair potholes with Road Patcher	Avenue 220 from Road 228 to End	12/19/2018	12/19/2018	
Strathmore	Repair road surface by hand patching	Road 216 from Avenue 188 to Avenue 192	12/21/2018	12/21/2018	\$ 1,700.37
Sultana	Chipseal Overlay of large area	Road 92 from Avenue 416 to Avenue 424	9/17/2018	9/17/2018	
Sultana	Repair road surface by hand patching	Avenue 416 from Road 92 to Road 120	9/21/2018	9/21/2018	
Sultana	Repair road surface by hand patching	Road 112 from Avenue 408 to Avenue 416	10/5/2018	10/5/2018	
Sultana	Repair road surface by hand patching	Avenue 424 from Road 104 to State Highway 63	10/8/2018	10/8/2018	
Sultana	Repair road surface by hand patching	Road 104 from Avenue 424 to Avenue 432	10/8/2018	10/8/2018	
Sultana	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	10/30/2018	10/30/2018	
Sultana	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 432	10/31/2018	10/31/2018	
Sultana	Repair road surface by hand patching	Avenue 416 West of Road 104	12/4/2018	12/4/2018	
Sultana	Repair road surface by hand patching	Avenue 424 West of Road 108	12/5/2018	12/5/2018	
Sultana	Repair road surface by hand patching	Road 114 from Avenue 416 to Avenue 424	12/17/2018	12/17/2018	\$ 1,021.36
Terra Bella	Large area Patching with grader "Blade Patch"	Road 240 from Avenue 80 to Avenue 92	9/24/2018	10/8/2018	
Terra Bella	Large area Patching with grader "Blade Patch"	Road 240 from Avenue 92 to Avenue 88	9/24/2018	10/8/2018	
Terra Bella	Large area Patching with grader "Blade Patch"	Avenue 84 from Road 238 to Road 240	9/24/2018	9/25/2018	
Terra Bella	Large area Patching with grader "Blade Patch"	Avenue 84 from Road 238 to Road 240	9/24/2018	9/25/2018	
Terra Bella	Large area Patching with grader "Blade Patch"	Road 240 from Avenue 80 to Avenue 92	9/24/2018	10/8/2018	
Terra Bella	Large area Patching with grader "Blade Patch"	Road 240 from Avenue 92 to Avenue 80	9/24/2018	10/11/2018	
Terra Bella	Large area Patching with grader "Blade Patch"	Avenue 84 from Road 238 to Road 240	9/24/2018	9/26/2018	
Terra Bella	Large area Patching with grader "Blade Patch"	Road 240 from Avenue 80 to Avenue 88	9/25/2018	9/25/2018	
Terra Bella	Repair potholes with Road Patcher	Road 192 from Avenue 80 to Avenue 88	9/26/2018	9/26/2018	
Terra Bella	Repair road surface by hand patching	Road 234 from Avenue 95 to Avenue 96	12/10/2018	12/10/2018	
Terra Bella	Repair road surface by hand patching	Avenue 88 from Road 192 to Road 232	12/10/2018	12/10/2018	
Terra Bella	Repair road surface by hand patching	Avenue 95 from Road 236 to Avenue 256	12/19/2018	12/20/2018	\$ 109,687.25
The Villa Tract	Repair potholes with Road Patcher	Various roads inside the tract	9/18/2018	9/18/2018	\$ 186.97
Three Rivers	Repair road surface by hand patching	South Fork Drive from Mile Post 5.5 to Mile Post 9	9/28/2018	10/1/2018	
Three Rivers	Repair road surface by hand patching	South Fork Drive at Blossom Drive	10/2/2018	10/2/2018	
Three Rivers	Repair road surface by hand patching	North Fork Drive from State Highway 198 to Mile Post 7.5	10/2/2018	10/4/2018	
Three Rivers	Repair road surface by hand patching	Mineral King Road from State Highway 198 to Mile Post 2	10/31/2018	10/31/2018	
Three Rivers	Repair road surface by hand patching	Old Three Rivers Road from State Highway 198 to South Fork Drive	10/31/2018	10/31/2018	
Three Rivers	Repair road surface by hand patching	South Fork Drive from Blossom Drive to Mile Post 6	10/31/2018	10/31/2018	
Three Rivers	Repair road surface by hand patching	Dineley Drive from State Highway 198 to End	12/18/2018	12/18/2018	
Three Rivers	Repair road surface by hand patching	Skyline Drive at State Highway 198	12/18/2018	12/19/2018	
Three Rivers	Repair road surface by hand patching	South Fork Drive from Mile Post 2 to Mile Post 6.5	12/18/2018	12/19/2018	\$ 3,994.54
Tipton	Repair potholes with Road Patcher	Callison from Avenue 144 to Avenue 152	10/4/2018	10/4/2018	
Tipton	Repair potholes with Road Patcher	Avenue 152 from Callison to Burnett	10/4/2018	10/4/2018	
Tipton	Repair potholes with Road Patcher	Newman from Avenue 152 to Cooper	10/4/2018	10/4/2018	
Tipton	Repair potholes with Road Patcher	Burnett from Avenue 152 to Avenue 144	10/4/2018	10/4/2018	
Tipton	Repair potholes with Road Patcher	Newman from Avenue 152 to Lerda	10/11/2018	10/11/2018	
Tipton	Repair potholes with Road Patcher	Smith at Olive	10/11/2018	10/11/2018	
Tipton	Repair potholes with Road Patcher	Evans from Avenue 152 to Avenue 144	10/11/2018	10/11/2018	
Tipton	Repair potholes with Road Patcher	Thompson from Avenue 152 to Klindera	10/11/2018	10/11/2018	
Tipton	Repair potholes with Road Patcher	Cooper from Evans to Thompson	10/11/2018	10/11/2018	
Tipton	Repair potholes with Road Patcher	Klindera at Adams	10/11/2018	10/11/2018	
Tipton	Repair potholes with Road Patcher	Jayne at Hamlin	10/11/2018	10/11/2018	
Tipton	Repair potholes with Road Patcher	Berry at Lipscomb	10/11/2018	10/11/2018	\$ 1,194.53
Tonyville	Resurface road with Chip Rock	Drive 227 (Burr Drive) from Avenue 248 to Avenue 256	8/13/2018	10/8/2018	
Tonyville	Resurface road with Chip Rock	Drive 227 (Burr Drive) from Avenue 248 to Avenue 256	8/13/2018	10/8/2018	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Tonyville	Resurface road with Chip Rock	Avenue 248 from Road 224 to Drive 227 (Burr Drive)	8/13/2018	10/8/2018	
Tonyville	Resurface road with Chip Rock	Avenue 256 from Road 204 to Drive 227 (Burr Drive)	8/13/2018	10/8/2018	
Tonyville	Resurface road with Chip Rock	Road 212 from Avenue 248* to Avenue 256	8/13/2018	10/8/2018	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 250	10/30/2018	10/30/2018	
Tonyville	Repair road surface by hand patching	Road 216 at Avenue 240	10/30/2018	10/30/2018	
Tonyville	Repair road surface by hand patching	Avenue 240 from Road 212 to Road 216	10/30/2018	10/30/2018	
Tonyville	Repair road surface by hand patching	Road 212 from Avenue 240 to Avenue 245	10/31/2018	10/31/2018	
Tonyville	Repair road surface by hand patching	Road 214 from Avenue 240 to Avenue 245	10/31/2018	10/31/2018	
Tonyville	Repair road surface by hand patching	Avenue 256 at Road 204	11/5/2018	11/5/2018	
Tonyville	Repair road surface by hand patching	Road 214 from Avenue 240 to Avenue 248	11/5/2018	11/5/2018	
Tonyville	Repair road surface by hand patching	Road 208 from Avenue 256 to Avenue 260	11/7/2018	11/7/2018	
Tonyville	Repair road surface by hand patching	Road 254 from Avenue 212 to Avenue 220	11/19/2018	11/19/2018	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 248	11/21/2018	11/21/2018	
Tonyville	Repair road surface by hand patching	Road 216 at Avenue 245	12/19/2018	12/19/2018	\$ 2,340.72
Tooleville	Repair road surface by hand patching	Road 216 north of Friant Kern Canal	11/5/2018	11/5/2018	
Tooleville	Repair road surface by hand patching	Road 208 from Avenue 256 to Avenue 260	11/6/2018	11/6/2018	\$ 269.74
Traver	Chipseal Overlay of large area	Road 44 from Avenue 368 to Avenue 376	9/17/2018	9/19/2018	
Traver	Repair road surface by hand patching	Drive 60 from Avenue 336 to Avenue 360	9/19/2018	9/19/2018	
Traver	Repair road surface by hand patching	Burke Drive South of Avenue 368	10/11/2018	10/11/2018	
Traver	Repair road surface by hand patching	Avenue 360 from Road 36 to Drive 60	10/24/2018	10/24/2018	
Traver	Repair road surface by hand patching	Road 44 from Avenue 360 to Avenue 368	10/29/2018	10/29/2018	
Traver	Repair road surface by hand patching	Burke Drive from Merritt Drive to Avenue 360	12/5/2018	12/5/2018	
Traver	Repair road surface by hand patching	Road 52 from Avenue 360 to Avenue 368	12/10/2018	12/10/2018	
Traver	Repair road surface by hand patching	Dinelev Drive from State Highway 198 to Mile Post 2	12/20/2018	12/20/2018	
Traver	Repair road surface by hand patching	Merritt Drive from Burke Drive to Road 44	12/20/2018	12/20/2018	\$ 2,981.31
West Exeter	Repair road surface by hand patching	1760 Belmont St	11/5/2018	11/5/2018	\$ 109.46
Woodville	Repair road surface by hand patching	Road 168 from Avenue 168 to Avenue 172	12/7/2018	12/7/2018	
Woodville	Repair road surface by hand patching	Road 168 north of Avenue 168	12/10/2018	12/10/2018	\$ 696.34
Yetttem	Chipseal Overlay of large area	Road 132 from Avenue 358 to Avenue 371	9/17/2018	9/24/2018	
Yetttem	Repair road surface by hand patching	Road 140 South of Avenue 376	10/18/2018	10/18/2018	
Yetttem	Repair road surface by hand patching	Road 144 from Avenue 364 to Avenue 388	11/9/2018	11/9/2018	
Yetttem	Repair road surface by hand patching	Road 136 from Avenue 384 to Avenue 400	11/9/2018	11/9/2018	
Yetttem	Repair road surface by hand patching	Road 136 from Avenue 384 to Avenue 400	11/1/2018	11/1/2018	\$ 1,933.84

Tulare County Association Of Governments
 Quarterly Reporting
 Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
	Rural Roads	Repair road surface by hand patching	Avenue 96 at Road 200	1/27/2018	11/27/2018	
	Rural Roads	Resurface road with Chip Rock	Road 232 from Avenue 174 to Avenue 182	8/27/2018	10/8/2018	
	Rural Roads	Resurface road with Chip Rock	Avenue 169 from Road 244 to Road 248	8/27/2018	10/8/2018	
	Rural Roads	Resurface road with Chip Rock	Avenue 169 from Road 250* (Porterville City Limits) to Road 252	8/27/2018	10/8/2018	
	Rural Roads	Resurface road with Chip Rock	Avenue 171 from Road 244 to Road 248	8/27/2018	10/8/2018	
	Rural Roads	Resurface road with Chip Rock	Avenue 220 from Road 228 to Road 236	8/28/2018	10/8/2018	
	Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 313 to Avenue 336	9/17/2018	9/17/2018	
	Rural Roads	Chipseal Overlay of large area	Road 96 from Avenue 384 to Avenue 416	9/17/2018	9/18/2018	
	Rural Roads	Chipseal Overlay of large area	Road 56 from Avenue 400 to Avenue 432	9/17/2018	9/20/2018	
	Rural Roads	Repair potholes with Road Patcher	Avenue 228 from Road 132 to Road 128	9/18/2018	9/18/2018	
	Rural Roads	Repair potholes with Road Patcher	Avenue 224 from Road 152 to Road 132	9/18/2018	9/18/2018	
	Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 408 to Avenue 416	9/18/2018	9/18/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 416 from Road 154 to Road 168	9/18/2018	9/21/2018	
	Rural Roads	Repair potholes with Road Patcher	Avenue 228 from Road 140 to Road 124	9/19/2018	9/19/2018	
	Rural Roads	Repair potholes with Road Patcher	Road 132 from SH137 to Avenue 208	9/19/2018	9/19/2018	
	Rural Roads	Repair potholes with Road Patcher	Avenue 200 from Road 140 to Road 124	9/19/2018	9/19/2018	
	Rural Roads	Repair potholes with Road Patcher	Road 132 from SH137 to Avenue 208	9/19/2018	9/19/2018	
	Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 336 to Avenue 344	9/19/2018	9/19/2018	
	Rural Roads	Repair road surface by hand patching	Road 74 from Avenue 384 to Avenue 392	9/19/2018	9/19/2018	
	Rural Roads	Repair potholes with Road Patcher	Road 164 from Avenue 256 to F'ville C.L.	9/20/2018	9/20/2018	
	Rural Roads	Repair potholes with Road Patcher	Road 168 from Avenue 296 to St. Johns River	9/20/2018	9/20/2018	
	Rural Roads	Repair potholes with Road Patcher	Avenue 280 from Road 148 to F'ville C.L.	9/20/2018	9/20/2018	
	Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 336 to Lort Drive	9/20/2018	9/20/2018	
	Rural Roads	Repair road surface by hand patching	Charter Oak Drive from Road 168 to Road 188	9/20/2018	9/20/2018	
	Rural Roads	Repair road surface by hand patching	Road 76 from Avenue 426 to Avenue 430	9/20/2018	9/20/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 172 to Millwood Drive	9/20/2018	9/20/2018	
	Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 360	9/21/2018	9/21/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 360 East of Road 34	9/21/2018	9/21/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 328 from State Highway 99 to Road 80	9/21/2018	9/21/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 412 at Road 96	9/21/2018	9/24/2018	
	Rural Roads	Repair potholes with Road Patcher	Road 156 from Avenue 256 to Avenue 296	9/24/2018	9/24/2018	
	Rural Roads	Repair potholes with Road Patcher	Road 128 from Avenue 96 to Avenue 72	9/24/2018	9/24/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 456 from Filer Road to Road 136	9/24/2018	9/24/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 452 at State Highway 63	9/24/2018	9/24/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 472 from Road 120 to End	9/24/2018	9/24/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 468 from Road 120 to Road 126	9/24/2018	9/24/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 456 from Road 120 to Road 128	9/24/2018	9/24/2018	
	Rural Roads	Repair road surface by hand patching	Filer Road from Avenue 450 to Avenue 456	9/24/2018	9/24/2018	
	Rural Roads	Repair road surface by hand patching	Road 74 from Avenue 384 to Avenue 392	9/25/2018	9/25/2018	
	Rural Roads	Repair road surface by hand patching	Road 40 from Avenue 376 to Avenue 384	9/26/2018	9/26/2018	
	Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 328 to Avenue 368	9/26/2018	9/26/2018	
	Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 313 to Avenue 344	9/27/2018	9/27/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 424 at Road 72	9/27/2018	9/27/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limits	9/27/2018	9/27/2018	
	Rural Roads	Repair potholes with Road Patcher	Road 208 from Avenue 160 to Avenue 184	10/1/2018	10/1/2018	
	Rural Roads	Repair potholes with Road Patcher	Avenue 170 east of Road 224	10/1/2018	10/1/2018	
	Rural Roads	Repair potholes with Road Patcher	Avenue 176 at Mountain Road 176B	10/1/2018	10/1/2018	
	Rural Roads	Repair potholes with Road Patcher	Mountain 171A from Avenue 176 to End	10/1/2018	10/1/2018	
	Rural Roads	Repair road surface by hand patching	Road 40 from Avenue 384 to Avenue 416	10/1/2018	10/1/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 424 West of Road 72	10/5/2018	10/5/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 104	10/5/2018	10/5/2018	
	Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 408	10/5/2018	10/5/2018	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 360 to Avenue 364	10/8/2018	10/8/2018
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 344 to Avenue 368	10/8/2018	10/8/2018
Rural Roads	Repair potholes with Road Patcher	Road 148 from Avenue 256 to Avenue 240	10/10/2018	10/10/2018
Rural Roads	Repair potholes with Road Patcher	Road 120 from Avenue 96 to Avenue 88	10/10/2018	10/10/2018
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 360	10/11/2018	10/11/2018
Rural Roads	Repair road surface by hand patching	Diagonal 56 from Diagonal 60 to Avenue 328	10/11/2018	10/11/2018
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limits	10/12/2018	10/12/2018
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 132 to Road 140	10/17/2018	10/17/2018
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 136 to Road 144	10/17/2018	10/17/2018
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 410 to Avenue 416	10/17/2018	10/17/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 96 from Road 120 to Road 96	10/18/2018	10/18/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 72 from Road 128 to Bishop	10/18/2018	10/18/2018
Rural Roads	Repair road surface by hand patching	Avenue 428 from Road 80 to Road 88	10/18/2018	10/18/2018
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 428 to Avenue 432	10/18/2018	10/18/2018
Rural Roads	Repair road surface by hand patching	Avenue 452 East of State Highway 63	10/19/2018	10/19/2018
Rural Roads	Haul Measure R Material for all road yards	Jaxon/Deer Creek plant to Ave 112 pit, Rankin pit and Ave 358 pit	10/22/2018	10/23/2018
Rural Roads	Repair potholes with Road Patcher	Road 120 from Avenue 96 to Avenue 88	10/22/2018	10/22/2018
Rural Roads	Hauling material to be used to Measure R patching	From Deer Creek Asphalt to Avenue 368 Pit. (to be stored until used)	10/22/2018	10/23/2018
Rural Roads	Repair potholes with Road Patcher	Road 120 from Avenue 96 to Avenue 56	10/23/2018	10/23/2018
Rural Roads	Repair road surface by hand patching	Road 8 South of Avenue 392	10/23/2018	10/23/2018
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 60 to Road 80	10/23/2018	10/23/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 88 to Road 72	10/24/2018	10/24/2018
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 352	10/24/2018	10/24/2018
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 96	10/25/2018	10/25/2018
Rural Roads	Repair road surface by hand patching	Road 192 from Avenue 56 to Avenue 120	10/25/2018	10/25/2018
Rural Roads	Repair road surface by hand patching	Avenue 168 from Road 216 to Road 224	10/26/2018	10/26/2018
Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 216 to Road 223	10/26/2018	10/26/2018
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 132 to Road 152	10/26/2018	10/26/2018
Rural Roads	Repair road surface by hand patching	Avenue 320 at Road 144	10/26/2018	10/26/2018
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 172 to Road 196	10/26/2018	10/26/2018
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 136 to Road 148	10/26/2018	10/26/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 176 from Road 192 to Road 208	10/29/2018	10/29/2018
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 109 to Mile Post 4.5	10/29/2018	10/29/2018
Rural Roads	Repair road surface by hand patching	Avenue 176 from Road 208 to Road 216	10/30/2018	10/30/2018
Rural Roads	Repair potholes with Road Patcher	Pine from Court to Howard	10/30/2018	10/30/2018
Rural Roads	Repair potholes with Road Patcher	Road 128 from Avenue 96 to Avenue 80	10/30/2018	10/30/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 56 from Road 136 to Road 88	10/30/2018	10/30/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 56 from Road 84 to Borchardt	10/30/2018	10/30/2018
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 360 to Avenue 376	10/30/2018	10/30/2018
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mile Post 4 to Mountain 50	10/30/2018	10/30/2018
Rural Roads	Repair road surface by hand patching	Avenue 168 at Road 224	10/31/2018	10/31/2018
Rural Roads	Repair road surface by hand patching	Avenue 238 from Road 224 to Road 228	10/31/2018	10/31/2018
Rural Roads	Repair road surface by hand patching	Avenue 218 at Road 196	10/31/2018	10/31/2018
Rural Roads	Repair potholes with Road Patcher	Road 224 from Avenue 112 to Avenue 120	10/31/2018	10/31/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 144 from Road 72 to SH43	10/31/2018	10/31/2018
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 64 to Road 96	10/31/2018	10/31/2018
Rural Roads	Repair road surface by hand patching	Avenue 160 west of Road 168	10/31/2018	10/31/2018
Rural Roads	Repair road surface by hand patching	Road 8 from Avenue 384 to Avenue 388	11/1/2018	11/1/2018
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 320 to Avenue 328	11/1/2018	11/1/2018
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 190 to Road 196	11/1/2018	11/1/2018
Rural Roads	Repair road surface by hand patching	Avenue 318 from Road 190 to Fisher Drive	11/1/2018	11/1/2018
Rural Roads	Repair road surface by hand patching	Avenue 136 from Road 160 to Road 162	11/1/2018	11/1/2018
Rural Roads	Repair road surface by hand patching	Road 176 north of Avenue 96	11/1/2018	11/1/2018
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 104 to Avenue 128	11/1/2018	11/5/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 144 to Road 72	11/2/2018	11/2/2018
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 144 to Avenue 152	11/2/2018	11/2/2018
Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to Mile Post 8.18	11/2/2018	11/2/2018

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Rural Roads	Repair road surface by hand patching	Mountain 109 from Avenue 88 to Avenue 56	11/2/2018	11/2/2018
Rural Roads	Resurface road with Chip Rock	Various locations supervised by Assistant Road Superintendent	11/5/2018	11/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 8 from Road 144 to Road 160	11/5/2018	11/5/2018
Rural Roads	Repair road surface by hand patching	Avenue 208 east of Road 208	11/6/2018	11/6/2018
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 8 to Avenue 56	11/6/2018	11/6/2018
Rural Roads	Repair potholes with Road Patcher	Road 128 from Avenue 56 to Avenue 0	11/7/2018	11/7/2018
Rural Roads	Repair road surface by hand patching	Avenue 320 from Road 190 to Road 196	11/8/2018	11/8/2018
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 312 to Avenue 320	11/8/2018	11/8/2018
Rural Roads	Repair potholes with Road Patcher	Road 128 from Avenue 56 to Avenue 0	11/8/2018	11/8/2018
Rural Roads	Repair potholes with Road Patcher	Avneue 16 from Road 128 to SH43	11/8/2018	11/8/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 west of Road 72	11/8/2018	11/8/2018
Rural Roads	Repair potholes with Road Patcher	Road 96 from Avenue 120 to Avenue 184	11/8/2018	11/8/2018
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 152 to Road 160	11/8/2018	11/8/2018
Rural Roads	Repair road surface by hand patching	Avenue 160 from Diagonal 208 to Road 152	11/8/2018	11/8/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 56 from Road 120 to Road 38	11/9/2018	11/9/2018
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 360 to Avenue 364	11/9/2018	11/9/2018
Rural Roads	Repair road surface by hand patching	Avenue 364 from Road 140 to Road 148	11/9/2018	11/9/2018
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 364 to Avenue 368	11/9/2018	11/9/2018
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 176 to Road 192	11/9/2018	11/9/2018
Rural Roads	Repair road surface by hand patching	Avenue 128 from Newcomb to Road 224	11/9/2018	11/9/2018
Rural Roads	Repair potholes with Road Patcher	Road 129 from Avenue 120 to Avenue 56	11/14/2018	11/14/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 56 from Front to Road 96	11/15/2018	11/15/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 48 from SH99 to Road 144	11/15/2018	11/15/2018
Rural Roads	Repair potholes with Road Patcher	Road 128 from Avenue 72 to Avenue 96	11/15/2018	11/15/2018
Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to Pot Hole Road	11/15/2018	11/15/2018
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 192 to Road 200	11/15/2018	11/15/2018
Rural Roads	Repair road surface by hand patching	Avenue 95 from Road 236 to Road 256	11/15/2018	11/15/2018
Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 208 to Avenue 216	11/16/2018	11/19/2018
Rural Roads	Repair road surface by hand patching	Avenue 208 east of Road 180	11/16/2018	11/16/2018
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 300 to Avenue 304	11/19/2018	11/19/2018
Rural Roads	Repair road surface by hand patching	Road 160 from Avenue 0 to Avenue 24	11/21/2018	11/26/2018
Rural Roads	Repair road surface by hand patching	Avenue 315 from Road 168 to Charter Oak Drive	11/26/2018	11/26/2018
Rural Roads	Repair road surface by hand patching	Road 52 South of Avenue 416	11/26/2018	11/26/2018
Rural Roads	Repair road surface by hand patching	Avenue 208 from Road 164 to Road 180	11/27/2018	12/3/2018
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 164 to Road 180	11/27/2018	11/27/2018
Rural Roads	Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limits	11/27/2018	11/27/2018
Rural Roads	Repair road surface by hand patching	Road 88 from Avenue 400 to Avenue 408	11/27/2018	11/27/2018
Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 408 to Avenue 416	11/27/2018	11/27/2018
Rural Roads	Repair road surface by hand patching	Avenue 416 from Road 154 to Road 168	11/27/2018	11/27/2018
Rural Roads	Repair road surface by hand patching	Avenue 32 from Road 168 to Road 152	11/27/2018	12/4/2018
Rural Roads	Repair road surface by hand patching	Avenue 128 from Road 192 to Road 152	11/29/2018	11/29/2018
Rural Roads	Repair road surface by hand patching	Mountain 137 @ Mile Post 7.5	11/29/2018	11/29/2018
Rural Roads	Repair road surface by hand patching	Mountain 137 @ Mile Post 6.5	11/29/2018	11/29/2018
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 238 to Road 248	12/3/2018	12/3/2018
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 344 to Avenue 352	12/3/2018	12/3/2018
Rural Roads	Repair road surface by hand patching	Road 120 South of Avenue 408	12/3/2018	12/3/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 71 to Road 96	12/4/2018	12/4/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 104 to Road 144	12/4/2018	12/4/2018
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 112 to State Highway 63	12/4/2018	12/4/2018
Rural Roads	Repair road surface by hand patching	Road 100 at Avenue 352	12/4/2018	12/4/2018
Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 80 to Road 108	12/4/2018	12/4/2018
Rural Roads	Repair road surface by hand patching	Road 232 from Avenue 68 to Avenue 80	12/4/2018	12/7/2018
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 208 to Road 224	12/5/2018	12/5/2018
Rural Roads	Repair road surface by hand patching	Avenue 216 west of Road 216	12/5/2018	12/5/2018
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 180 to Road 188	12/5/2018	12/5/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Park to Road 144	12/5/2018	12/5/2018
Rural Roads	Repair road surface by hand patching	Avenue 368 East of State Highway 63	12/5/2018	12/5/2018

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 376 at Road 32	12/5/2018	12/5/2018
Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 312 to End	12/5/2018	12/5/2018
Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 312 to End	12/5/2018	12/5/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 124 to Road 136	12/6/2018	12/6/2018
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 100 to Road 124	12/6/2018	12/6/2018
Rural Roads	Repair road surface by hand patching	Road 64 from Avenue 424 to Avenue 426	12/6/2018	12/6/2018
Rural Roads	Repair road surface by hand patching	Road 64 North of Avenue 426	12/6/2018	12/6/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 72 to Road 112	12/7/2018	12/7/2018
Rural Roads	Repair road surface by hand patching	Avenue 426 from Road 76 to Road 80	12/7/2018	12/7/2018
Rural Roads	Repair road surface by hand patching	Road 76 from Avenue 426 to Avenue 432	12/7/2018	12/7/2018
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 72 to Road 80	12/7/2018	12/7/2018
Rural Roads	Repair road surface by hand patching	Avenue 430 from Road 72 to Road 80	12/7/2018	12/7/2018
Rural Roads	Repair road surface by hand patching	Road 76 South of Avenue 428	12/7/2018	12/7/2018
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 172 to Avenue 192	12/10/2018	12/10/2018
Rural Roads	Repair road surface by hand patching	Avenue 404 from Road 68 to Road 74	12/10/2018	12/10/2018
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 80	12/10/2018	12/10/2018
Rural Roads	Repair road surface by hand patching	Road 76 from Avenue 368 to Avenue 376	12/10/2018	12/10/2018
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 384 to Avenue 400	12/10/2018	12/10/2018
Rural Roads	Repair road surface by hand patching	Road 256 from Avenue 95 to Avenue 56	12/10/2018	12/11/2018
Rural Roads	Repair road surface by hand patching	Road 228 from Avenue 212 to Avenue 232	12/11/2018	12/11/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 120 to Road 88	12/11/2018	12/11/2018
Rural Roads	Repair road surface by hand patching	Road 188 from Charter Oak Drive to Avenue 336	12/11/2018	12/11/2018
Rural Roads	Repair road surface by hand patching	Charter Oak Drive from Road 168 to Road 188	12/11/2018	12/11/2018
Rural Roads	Repair road surface by hand patching	Road 244 from Avenue 212 to Avenue 224	12/12/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 230 from Road 238 to Road 242	12/12/2018	12/13/2018
Rural Roads	Repair road surface by hand patching	Road 228 from Avenue 232 to Avenue 238	12/12/2018	12/12/2018
Rural Roads	Repair road surface by hand patching	Avenue 204 east of Road 248	12/12/2018	12/12/2018
Rural Roads	Repair road surface by hand patching	Rankin pit, haul patch material	12/12/2018	12/18/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 56 from Road 136 to Road 96	12/12/2018	12/12/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 120 to Road 72	12/12/2018	12/18/2018
Rural Roads	Repair potholes with Road Patcher	Road 120 from Avenue 120 to Avenue 96	12/12/2018	12/12/2018
Rural Roads	Repair road surface by hand patching	Avenue 396 from Road 88 to Road 92	12/12/2018	12/12/2018
Rural Roads	Repair road surface by hand patching	Road 108 from Avenue 320 to Avenue 328	12/12/2018	12/12/2018
Rural Roads	Hauling material to be used to Measure R patching	From Deer Creek Asphalt to Avenue 368 Pit. (to be stored until used)	12/12/2018	12/13/2018
Rural Roads	Haul Material for Measure R Patching	Haul Material Jaxon Baker to Avenue 368 Pit	12/12/2018	12/12/2018
Rural Roads	Haul Material for Measure R Patching	Haul Material Jaxon Baker to Rakin Pit	12/12/2018	12/12/2018
Rural Roads	Repair road surface by hand patching	Road 192 from Avenue 96 to Avenue 152	12/12/2018	12/12/2018
Rural Roads	Repair road surface by hand patching	Avenue 176 from Road 80 to Road 64	12/13/2018	12/13/2018
Rural Roads	Repair road surface by hand patching	Avenue 192 from Road 68 to Road 60	12/13/2018	12/13/2018
Rural Roads	Repair potholes with Road Patcher	Road 128 from Avenue 56 to Avenue 0	12/13/2018	12/13/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 16 from Road 128 to SH43	12/13/2018	12/13/2018
Rural Roads	Haul Material for Measure R Patching	Haul Material Jaxon Baker to Avenue 112 Pit	12/13/2018	12/13/2018
Rural Roads	Repair road surface by hand patching	Diagonal 205 south of Avenue 32	12/13/2018	12/13/2018
Rural Roads	Repair road surface by hand patching	Road 152 north of Avenue 0	12/13/2018	12/13/2018
Rural Roads	Repair road surface by hand patching	Road 192 from Avenue 95 to Avenue 152	12/13/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 240 to Road 244	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 228 from Road 224 to Friant Kern Canal	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Road 242 from Avenue 224 to Avenue 234	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 220 from Road 252 to Road 254	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 184 to Avenue 160	12/14/2018	12/14/2018
Rural Roads	Repair potholes with Road Patcher	Road 140 from Avenue 280 to SH137	12/14/2018	12/14/2018
Rural Roads	Repair potholes with Road Patcher	Road 152 from Avenue 144 to Avenue 96	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 104 to Avenue 88	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 88 from Road 96 to Road 84	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 423 from Road 136 to Road 144	12/14/2018	12/14/2018
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 168 to Road 224	12/17/2018	12/18/2018
Rural Roads	Repair road surface by hand patching	Avenue 88 from Road 96 to Road 84	12/17/2018	12/17/2018

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 109 to Avenue 88	12/17/2018	12/17/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 96 at Road 96	12/17/2018	12/17/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 112 from Park to Elm	12/17/2018	12/17/2018
Rural Roads	Repair road surface by hand patching	Avenue 404 at Road 104	12/17/2018	12/17/2018
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 432 to Avenue 440	12/17/2018	12/17/2018
Rural Roads	Repair road surface by hand patching	Avenue 384 from Road 114 to State Highway 63	12/17/2018	12/17/2018
Rural Roads	Repair road surface by hand patching	Road 132 West of Avenue 336	12/17/2018	12/17/2018
Rural Roads	Repair road surface by hand patching	Road 216 from Avenue 152 to Avenue 128	12/17/2018	12/19/2018
Rural Roads	Repair road surface by hand patching	Avenue 188 from Road 152 to Road 168	12/18/2018	12/19/2018
Rural Roads	Repair road surface by hand patching	Diagonal 184 at Avenue 176	12/18/2018	12/18/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 288 from VCL to FCL	12/18/2018	12/18/2018
Rural Roads	Repair potholes with Road Patcher	Road 156 from SH198 to Avenue 256	12/18/2018	12/18/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 256 from Road 152 to Road 140	12/18/2018	12/18/2018
Rural Roads	Repair road surface by hand patching	Avenue 240 at Road 60	12/18/2018	12/18/2018
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 260 to Avenue 248	12/18/2018	12/18/2018
Rural Roads	Repair road surface by hand patching	Road 84 from Avenue 260 to Avenue 248	12/18/2018	12/18/2018
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 132 to Road 140	12/18/2018	12/18/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 216 from Road 84 to Road 44	12/19/2018	12/19/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 184 from Road 96 to Road 44	12/19/2018	12/19/2018
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 160 to Avenue 144	12/19/2018	12/19/2018
Rural Roads	Repair road surface by hand patching	Avenue 120 from SH137 to Road 28	12/19/2018	12/19/2018
Rural Roads	Repair potholes with Road Patcher	Road 208 from Avenue 160 to Avenue 164	12/20/2018	12/20/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 184 from Road 96 to Road 28	12/20/2018	12/20/2018
Rural Roads	Repair road surface by hand patching	Avenue 180 from Road 136 to Road 128	12/20/2018	12/20/2018
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 144 to Avenue 120	12/20/2018	12/20/2018
Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 80 to Road 124	12/20/2018	12/20/2018
Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 56 to Avenue 40	12/20/2018	12/21/2018
Rural Roads	Repair road surface by hand patching	Avenue 188 at Road 168	12/21/2018	12/21/2018
Rural Roads	Repair potholes with Road Patcher	Avenue 120 from Road 144 to Road 72	12/21/2018	12/21/2018
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 194 to Avenue 160	12/21/2018	12/21/2018
Rural Roads	Repair road surface by hand patching	Avenue 168 from Road 152 to Road 136	12/21/2018	12/21/2018
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 144 to Avenue 120	12/21/2018	12/21/2018
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 152 to SH99	12/21/2018	12/21/2018
Mountain Roads	Large area Patching with grader "Blade Patch"	Eshom Valley Drive from Mile Post 8 to Mile Post 10.5	10/1/2018	10/1/2018
Mountain Roads	Repair road surface by hand patching	Whitaker Forest Drive from Mile Post 2 to Mile Post 5	10/23/2018	10/23/2018
Mountain Roads	Repair road surface by hand patching	Eshom Valley Drive at Mile Post 9	10/23/2018	10/23/2018
Mountain Roads	Repair road surface by hand patching	Whitaker Forest Drive from Mile Post 2 to Mile Post 7	10/24/2018	10/26/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 22 to Mountain Road 276	11/7/2018	11/7/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 13.5 to Milepost 22.5	11/8/2018	11/16/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 1 to Milepost 12	11/9/2018	11/13/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Mountain Road 239 to Milepost 19	11/9/2018	11/9/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 at Milepost 21	11/13/2018	11/13/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 at Milepost 19.5	11/13/2018	11/13/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 at Milepost 20.5	11/13/2018	11/13/2018
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 10 to Milepost 16	11/14/2018	11/14/2018
Mountain Roads	Repair road surface by hand patching	Road 276 at Avenue 176	11/28/2018	11/28/2018
Mountain Roads	Repair road surface by hand patching	Dry Creek Drive at Mile Post .5	12/3/2018	12/3/2018
Mountain Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to End	12/7/2018	12/7/2018
Mountain Roads	Repair potholes with Road Patcher	Globe Drive from Highway 190 to Highway 190	12/10/2018	12/11/2018
Mountain Roads	Repair road surface by hand patching	Eshom Valley Drive from Stagecoach Drive to Mile Post 10	12/12/2018	12/12/2018
Mountain Roads	Repair road surface by hand patching	Stagecoach Drive from Dry Creek Drive to Eshom Valley Drive	12/12/2018	12/12/2018
Mountain Roads	Repair road surface by hand patching	Dry Creek Drive from Mile Post 0 to Eshom Valley Drive	12/12/2018	12/12/2018

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Mountain Roads	Repair road surface by hand patching	Globe Drive south of Pleasant Oak Drive	12/13/2018	12/13/2018	
Mountain Roads	Repair road surface by hand patching	17578 Rio Vista Drive	12/13/2018	12/13/2018	
Mountain Roads	Repair road surface by hand patching	Pierce Valley Drive from Eshom Valley Drive to End	12/13/2018	12/13/2018	
Mountain Roads	Repair road surface by hand patching	Sand Creek Drive from Mile Post 0 to Mile Post 2.5	12/14/2018	12/14/2018	
Mountain Roads	Repair road surface by hand patching	Dry Creek Drive from State Highway 216 to State Highway 245	12/19/2018	12/19/2018	
Mountain Roads	Repair road surface by hand patching	Whitaker Forest Drive from State Highway 245 to Mile Post 6	12/19/2018	12/19/2018	
Mountain Roads	Repair road surface by hand patching	Pierce Valley Drive from Eshom Valley Drive to Mile Post 2	12/19/2018	12/19/2018	
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 at Milepost 5	12/20/2018	12/20/2018	
Mountain Roads	Repair road surface by hand patching	Mountain Road 239 from Highway 190 to Mountain Road 296	12/20/2018	12/20/2018	
Mountain Roads	Repair road surface by hand patching	Mountain 109 from Mountain 56 to 447Z	12/21/2018	12/21/2018	\$ 194,453.26

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 2

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720)		Preliminary Engineering/ Design	ADA Ramp Improvements	3/3/2016	ongoing	\$ 3,561.79
		Construction/Design	Pleasant View West - Fixed Asset Installation	6/26/2017	ongoing	\$ 317.45
		Construction/Design	Ivanhoe R159 and Azalea Improvements	7/11/2017	ongoing	\$ 118,048.58
		Construction/Design	West Goshen Ave 308	6/27/2017	ongoing	\$ 114,825.05
		Preliminary Engineering/ Design	Orosi A416 Crossing	7/12/2017	ongoing	\$ 5,492.21
		Preliminary Engineering/ Design	Poplar Crossing R192 and A146	8/1/2017	ongoing	\$ 5,987.86
		Preliminary Engineering/ Design	Strathmore A196 & R228 Intersection	8/1/2017	ongoing	\$ 8,380.94
		Preliminary Engineering/ Design	Allensworth Sidewalk & Crosswalk Improvements	8/2/2017	ongoing	\$ 3,819.73
		Preliminary Engineering/ Design	Alpaugh Center Street Improvements	8/2/2017	ongoing	\$ 2,137.49
		Preliminary Engineering/ Design	Terra Bella R243 at A95 & A92	6/26/2017	ongoing	\$ 207.78
		Preliminary Engineering/ Design	Earlimart Alila ADA Ramp Construction	8/8/2017	ongoing	\$ 15,263.29
		Preliminary Engineering/ Design	Richgrove - Diagonal 205 Rehabilitation	6/29/2017	ongoing	\$ 207.78
		Preliminary Engineering/ Design	Pepper Avenue ADA Improvements	6/28/2017	ongoing	\$ 681.85
		Preliminary Engineering/ Design	Pleasant View C-Walk Poplar	11/13/2018	ongoing	\$ 9,994.12
		Preliminary Engineering/ Design	Road 168 Overlay Project	11/1/2018	ongoing	\$ 2,803.00
						\$ 768,234.96

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
18/19 Annual Advance \$4,199,499.00 Communities	Alpaugh	Repair road surface by hand patching	Avenue 54 from Road 38 to Road 42	2/19/2019	2/19/2019	\$ 1,982.22
	Alpaugh	Repair road surface by hand patching	Road 132 from Avenue 200 to Avenue 220	2/19/2019	2/19/2019	
	Alpaugh	Repair road surface by hand patching	Avenue 56 from S.H. 43 to west of Borchardt	2/20/2019	2/20/2019	
	Alpaugh	Repair road surface by hand patching	Avenue 54 from Road 42 to Borchardt	2/27/2019	2/27/2019	
	Alpaugh	Repair road surface by hand patching	Road 96 south of Avenue 160	2/27/2019	2/27/2019	
	Alpaugh	Repair road surface by hand patching	Borchardt from Avenue 54 to Avenue 56	2/28/2019	2/28/2019	
	Alpaugh	Repair road surface by hand patching	Avenue 56 from Borchardt to Road 96	2/28/2019	2/28/2019	
	Cutler/Orosi	Repair road surface by hand patching	Railroad Drive from Road 124 to State Highway 63	1/18/2019	1/18/2019	
	Cutler/Orosi	Repair road surface by hand patching	Railroad Drive at Orosi Drive	1/18/2019	1/18/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 from Avenue 424 to Avenue 432	1/18/2019	1/18/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from Road 120 to Road 144	1/23/2019	1/23/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 424 West of Road 120	1/28/2019	1/28/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 424 West of Road 126	1/28/2019	1/28/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 126 at Avenue 424	1/28/2019	1/28/2019	
	Cutler/Orosi	Repair road surface by hand patching	Railroad Drive from Road 124 to State Highway 63	2/7/2019	2/7/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 424 from Road 120 to Road 124	2/7/2019	2/7/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 422 from State Highway 63 to Road 136	2/8/2019	2/8/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 from Avenue 424 to Avenue 432	2/11/2019	2/11/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 424 from Road 120 to State Highway 63	2/11/2019	2/11/2019	
	Cutler/Orosi	Repair road surface by hand patching	Amethyst Avenue at Road 127	2/12/2019	2/12/2019	
	Cutler/Orosi	Repair road surface by hand patching	Eddy Road North of Amethyst Avenue	2/12/2019	2/12/2019	
	Cutler/Orosi	Repair road surface by hand patching	Eddy Road at Avenue 407	2/12/2019	2/12/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 136 South of Avenue 416	2/14/2019	2/14/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 136 North of Avenue 416	2/14/2019	2/14/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from State Highway 63 to Road 136	2/15/2019	2/15/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 at Luxor Avenue	2/25/2019	2/25/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 from Avenue 413 to Avenue 416	2/25/2019	2/25/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 144 North of Avenue 416	3/4/2019	3/4/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 144 South of Avenue 416	3/4/2019	3/4/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 120 from Avenue 404 to Avenue 408	3/8/2019	3/8/2019	
	Cutler/Orosi	Repair road surface by hand patching	Road 124 from Avenue 404 to Avenue 408	3/11/2019	3/11/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 413 from Road 124 to Road 128	3/15/2019	3/15/2019	
	Cutler/Orosi	Repair road surface by hand patching	Avenue 403 from State Highway 63 to Ralph Road	3/15/2019	3/15/2019	
	Delft Colony	Repair road surface by hand patching	Avenue 408 at Road 64	2/20/2019	2/20/2019	
	Delft Colony	Repair road surface by hand patching	Road 64 at Avenue 404	2/20/2019	2/20/2019	
	Delft Colony	Repair road surface by hand patching	Avenue 408 from Road 56 to Dinuba City Limits	2/22/2019	2/22/2019	
	Delft Colony	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 408	2/26/2019	2/26/2019	
	Delft Colony	Repair road surface by hand patching	Road 64 from Avenue 400 to Avenue 404	3/12/2019	3/12/2019	
	Doyle Colony	Repair road surface by hand patching	Avenue 148 at LR269B	2/19/2019	2/19/2019	
	Doyle Colony	Repair road surface by hand patching	Avenue 146 west of Mountain Road 146	2/27/2019	2/27/2019	
	Ducor	Repair road surface by hand patching	Diagonal 205 from Avenue 56 to Avenue 32	3/7/2019	3/7/2019	
	Dutch Colony	Repair road surface by hand patching	Avenue 384 from Road 204 to Road 206	1/9/2019	1/9/2019	
	Dutch Colony	Repair road surface by hand patching	Road 196 from Avenue 364 to Avenue 368	2/27/2019	2/27/2019	
	Dutch Colony	Repair road surface by hand patching	Sentinel Drive from Avenue 360 to Avenue 364	3/5/2019	3/5/2019	
	Earlimart	Repair road surface by hand patching	Streets of Earlimart	1/25/2019	1/25/2019	
	Earlimart	Repair potholes with road patcher	Front from Avenue 56 to S.H.99	3/12/2019	3/12/2019	
	Earlimart	Repair potholes with road patcher	Front from Wilson to S.H.99	3/12/2019	3/12/2019	
						\$ 762.80
						\$ 319.21
						\$ 212.41
						\$ 518.96

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Earlimart	Repair potholes with road patcher	Bobbi from Church to Earlimart	3/11/2019	3/11/2019	
Earlimart	Repair potholes with road patcher	Andrea from Church to Earlimart	3/11/2019	3/11/2019	
Earlimart	Repair potholes with road patcher	Church from Armstrong to Washington	3/13/2019	3/13/2019	
Earlimart	Repair potholes with road patcher	State Street from Armstrong to Wilson	3/13/2019	3/13/2019	\$ 1,134.05
East Kingsburg	Repair road surface by hand patching	Road 24 from Avenue 396 to Avenue 400	1/3/2019	1/3/2019	
East Kingsburg	Repair road surface by hand patching	Avenue 396 from Road 12 to Road 24	1/3/2019	1/3/2019	
East Kingsburg	Repair road surface by hand patching	Avenue 384 at State Highway 99	2/12/2019	2/12/2019	
East Kingsburg	Repair road surface by hand patching	Clarkson Drive from Avenue 392 to Avenue 396	2/21/2019	2/21/2019	
East Kingsburg	Repair road surface by hand patching	Avenue 396 from Road 16 to Road 20	2/21/2019	2/21/2019	
East Kingsburg	Repair road surface by hand patching	Road 40 from Avenue 384 to Avenue 416	2/25/2019	2/25/2019	
East Kingsburg	Repair road surface by hand patching	Road 24 from Avenue 400 to Avenue 408	3/12/2019	3/12/2019	
East Kingsburg	Repair road surface by hand patching	Road 40 at Avenue 400	3/14/2019	3/14/2019	\$ 921.21
East Orosi	Repair road surface by hand patching	Avenue 428 from Road 142 to Road 144	1/9/2019	1/9/2019	
East Orosi	Repair road surface by hand patching	Avenue 416 from Road 144 to Road 152	1/23/2019	1/23/2019	\$ 217.46
Elderwood	Repair road surface by hand patching	Road 204 from Avenue 376 to Avenue 384	1/9/2019	1/9/2019	
Elderwood	Repair road surface by hand patching	Road 208 from Avenue 376 to Avenue 380	2/27/2019	2/27/2019	
Elderwood	Repair road surface by hand patching	Avenue 376 from Road 204 to Road 208	2/27/2019	2/27/2019	
Elderwood	Repair road surface by hand patching	Road 204 from State Highway 63 to End	2/27/2019	2/27/2019	\$ 500.65
Goshen	Repair road surface by hand patching	Road 48 from Avenue 280 to S.H. 198	12/27/2018	12/27/2018	
Goshen	Repair road surface by hand patching	Road 44 from S.H. 198 to Avenue 304	12/27/2018	12/27/2018	
Goshen	Repair road surface by hand patching	Road 52 from Avenue 309 to S.H. 198	12/27/2018	12/27/2018	
Goshen	Repair road surface by hand patching	Avenue 304 from Road 44 to Road 64	12/27/2018	12/27/2018	
Goshen	Repair road surface by hand patching	Avenue 308 from Road 60 to Road 48	3/1/2019	3/1/2019	
Goshen	Repair road surface by hand patching	Avenue 308 from Road 48 to Road 60	3/4/2019	3/4/2019	
Goshen	Repair road surface by hand patching	Avenue 304 from Road 44 to Road 64	3/4/2019	3/4/2019	
Goshen	Repair road surface by hand patching	Avenue 52 at Avenue 308	3/12/2019	3/12/2019	
Goshen	Repair road surface by hand patching	Avenue 52 at Avenue 309	3/12/2019	3/12/2019	
Goshen	Repair road surface by hand patching	Road 52 from Avenue 304 to S.H. 198	3/12/2019	3/12/2019	
Goshen	Repair road surface by hand patching	Road 64 at Avenue 304	3/12/2019	3/12/2019	
Goshen	Repair road surface by hand patching	Road 68 from Avenue 240 to Avenue 304	3/18/2019	3/18/2019	
Goshen	Repair road surface by hand patching	Avenue 304 from Road 44 to Road 64	3/18/2019	3/18/2019	
Goshen	Repair road surface by hand patching	Avenue 304 from Effie to Road 68	3/18/2019	3/18/2019	
Goshen	Repair road surface by hand patching	Effie from Avenue 308 to Avenue 304	3/19/2019	3/19/2019	
Goshen	Repair road surface by hand patching	Commercial from Avenue 308 to Avenue 310	3/19/2019	3/19/2019	
Goshen	Repair road surface by hand patching	Roy from Juniper to Avenue 308	3/19/2019	3/19/2019	
Goshen	Repair road surface by hand patching	Roy from Effie to 100 yards to the west	3/20/2019	3/20/2019	
Goshen	Repair road surface by hand patching	Commercial from Avenue 308 to Avenue 310	3/20/2019	3/20/2019	
Goshen	Repair road surface by hand patching	Juniper at Avenue 308	3/20/2019	3/20/2019	
Goshen	Repair road surface by hand patching	Avenue 200 from Road 140 to Road 132	3/20/2019	3/20/2019	\$ 2,438.51
Ivanhoe	Repair road surface by hand patching	Road 156 from Avenue 336 to Avenue 344	1/15/2019	1/15/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 152 to Road 156	2/1/2019	2/1/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 336 at Road 152	2/6/2019	2/6/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 332 from Road 152 to Road 156	2/7/2019	2/7/2019	
Ivanhoe	Repair road surface by hand patching	Road 160 South of Avenue 344	2/8/2019	2/8/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 144 to Road 172	2/8/2019	2/8/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 144 to Road 156	2/19/2019	2/19/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 156 to Road 164	2/20/2019	2/20/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 332 from Road 152 to Road 160	2/20/2019	2/20/2019	
Ivanhoe	Repair road surface by hand patching	Road 160 from Avenue 332 to Avenue 336	2/20/2019	2/20/2019	
Ivanhoe	Repair road surface by hand patching	Road 168 from Avenue 324 to Millwood Drive	3/5/2019	3/5/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 326 at Road 168	3/5/2019	3/5/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 328 at Road 168	3/5/2019	3/5/2019	\$ 1,301.12
Lemon Cove	Repair road surface by hand patching	Road 248 from Avenue 330 to Avenue 334	3/12/2019	3/12/2019	\$ 241.01
Lindcove	Repair road surface by hand patching	Avenue 328 at LR248	2/19/2019	2/19/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Lindcove	Repair road surface by hand patching	D246B from Avenue 307 to D246C	2/20/2019	2/20/2019	
Lindcove	Repair road surface by hand patching	D246B from Avenue 307 to LR228B	2/20/2019	2/20/2019	
Lindcove	Repair road surface by hand patching	Road 236 from Avenue 234 to D234	2/20/2019	2/20/2019	
Lindcove	Repair road surface by hand patching	D234 from Avenue 320 to Road 236	2/20/2019	2/20/2019	
Lindcove	Repair road surface by hand patching	D246B from Avenue 307 to Ave 307*	3/1/2019	3/1/2019	
Lindcove	Repair road surface by hand patching	LA315 east of LR224	3/4/2019	3/4/2019	\$ 585.64
London	Repair road surface by hand patching	Kate Road from Avenue 376 to Avenue 380	12/28/2018	12/28/2018	
London	Repair road surface by hand patching	Road 60 East of Avenue 376	2/15/2019	2/15/2019	\$ 203.15
Monson	Repair road surface by hand patching	Avenue 388 from Road 96 to Road 104	1/17/2019	1/17/2019	
Monson	Repair road surface by hand patching	Monson Drive from Road 104 to Avenue 384	2/1/2019	2/1/2019	
Monson	Repair road surface by hand patching	Monson Drive from Road 104 to Avenue 384	2/14/2019	2/14/2019	
Monson	Repair road surface by hand patching	Road 120 from Avenue 384 to Avenue 396	3/8/2019	3/8/2019	
Monson	Repair road surface by hand patching	Road 120 at Avenue 388	3/11/2019	3/11/2019	\$ 621.10
Patterson Tract	Repair road surface by hand patching	Road 132 from Avenue 310 to Avenue 328	1/15/2019	1/15/2019	
Patterson Tract	Repair road surface by hand patching	Road 127 from Avenue 328 to End	2/14/2019	2/14/2019	
Patterson Tract	Repair road surface by hand patching	Avenue 336 from State Highway 63 to Road 140	2/19/2019	2/19/2019	
Patterson Tract	Repair road surface by hand patching	Friden Avenue at State Highway 63	3/12/2019	3/12/2019	
Patterson Tract	Repair road surface by hand patching	Road 132 South of Avenue 320	3/13/2019	3/13/2019	
Patterson Tract	Repair road surface by hand patching	Avenue 320 from State Highway 63 to Road 144	3/15/2019	3/15/2019	\$ 840.52
Pixley	Repair road surface by hand patching	West side of town of Pixley	1/25/2019	1/25/2019	
Pixley	Repair potholes with road patcher	Elm from Avenue 96 to Avenue 72	2/19/2019	2/19/2019	
Pixley	Repair potholes with road patcher	Court from Road 136 to Park	2/26/2019	2/26/2019	
Pixley	Repair potholes with road patcher	Maple at Court	2/26/2019	2/26/2019	
Pixley	Repair potholes with road patcher	Avenue 72 from Road 136 to S.H. 99	3/4/2019	3/4/2019	
Pixley	Repair potholes with road patcher	Elm from Avenue 92 to Avenue 96	3/4/2019	3/4/2019	
Pixley	Repair potholes with road patcher	Franklin from Center to Main	3/4/2019	3/4/2019	
Pixley	Repair potholes with road patcher	Bradbury from Cedar to Ash	3/4/2019	3/4/2019	
Pixley	Repair potholes with road patcher	Avenue 96 from Maple to Main	3/4/2019	3/4/2019	
Pixley	Repair potholes with road patcher	Avenue 96 from Main Street to Road 120	3/7/2019	3/7/2019	
Pixley	Repair potholes with road patcher	Avenue 96 at Railroad trax	3/8/2019	3/8/2019	
Pixley	Repair potholes with road patcher	Avenue 96 from School to Main	3/8/2019	3/8/2019	
Pixley	Repair potholes with road patcher	Walnut from Terra Bella Avenue to Court	3/11/2019	3/11/2019	
Pixley	Repair potholes with road patcher	Howard from Elm to Park	3/11/2019	3/11/2019	
Pixley	Repair potholes with road patcher	Bobbi from Church to Earlimart Street	3/11/2019	3/11/2019	
Pixley	Repair potholes with road patcher	Andrea from Church to Earlimart	3/11/2019	3/11/2019	
Pixley	Repair potholes with road patcher	Walnut from Terra Bella Avenue to Court	3/11/2019	3/11/2019	
Pixley	Repair potholes with road patcher	Howard from Elm to Park	3/11/2019	3/11/2019	
Pixley	Repair potholes with road patcher	Park Street from Wright to 850 Park	3/25/2019	3/25/2019	
Pixley	Repair potholes with road patcher	Compton from Road 120 to South Market	3/25/2019	3/25/2019	
Pixley	Repair potholes with road patcher	Davis from Ash to Market	3/25/2019	3/25/2019	
Pixley	Repair potholes with road patcher	Ash from Court to Avenue 96	3/25/2019	3/25/2019	
Pixley	Repair potholes with road patcher	Bradbury from Road 120 to Cedar	3/25/2019	3/25/2019	
Pixley	Repair potholes with road patcher	Elm Street from Orrland to Court	3/26/2019	3/26/2019	
Pixley	Repair potholes with road patcher	Spani Way from Court to Ellsworth	3/26/2019	3/26/2019	
Pixley	Repair potholes with road patcher	Oaks Avenue from Cedar to Road 120	3/26/2019	3/26/2019	
Pixley	Repair potholes with road patcher	Cedar Street from Oaks Avenue to Stanford	3/26/2019	3/26/2019	
Pixley	Repair potholes with road patcher	Stanford from Road 120 to Cedar	3/26/2019	3/26/2019	
Pixley	Repair road surface by hand patching	Road 120 south of Avenue 96	3/27/2019	3/27/2019	\$ 2,834.83
Plainview	Repair road surface by hand patching	Road 196 from Avenue 192 to Avenue 195	1/7/2019	1/7/2019	
Plainview	Repair road surface by hand patching	Road 204 from Avenue 232 to Diagonal 205	2/25/2019	2/25/2019	\$ 1,417.98
Poplar	Repair road surface by hand patching	Road 192 at Avenue 150	3/12/2019	3/12/2019	\$ 180.60
Richgrove	Repair road surface by hand patching	Avenue 4 from Diagonal 205 to Road 200	2/25/2019	2/28/2019	
Richgrove	Repair road surface by hand patching	Avenue 2 from State Route 65 to Road 224	2/25/2019	2/25/2019	\$ 1,854.21
Seville	Repair road surface by hand patching	Road 156 from Avenue 376 to Avenue 384	1/15/2019	1/15/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Seville	Repair road surface by hand patching	Avenue 383 from Road 153 to Road 154	2/26/2019	2/26/2019	\$ 208.25

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Strathmore	Repair road surface by hand patching	Avenue 182 from Road 224 to Road 228	12/28/2018		
Strathmore	Repair road surface by hand patching	Road 234 from Avenue 194 to Avenue 196	12/31/2018		
Strathmore	Repair road surface by hand patching	Avenue 200 at Road 230	1/2/2019		
Strathmore	Repair road surface by hand patching	Road 204 at Avenue 228	2/19/2019		
Strathmore	Repair road surface by hand patching	Avenue 208 from Road 228 to Road 232	2/20/2019		
Strathmore	Repair road surface by hand patching	Avenue 204 at Road 196	2/26/2019		
Strathmore	Repair road surface by hand patching	Avenue 184 from Road 224 to Road 228	3/4/2019		
Strathmore	Repair road surface by hand patching	Avenue 174 from Diagonal 242 to Highway 65	3/4/2019		
Strathmore	Repair road surface by hand patching	Avenue 224 from Road 216 to	3/4/2019		\$ 3,384.40
Springville	Repair road surface by hand patching	Road 320 from Avenue 176 to M194G	2/26/2019		
Springville	Repair road surface by hand patching	Road 276 from Avenue 196 to Mountain Road 178	3/7/2019		
Springville	Repair road surface by hand patching	Avenue 176 from Mountain Road 178 to Road 284*	3/7/2019		\$ 702.96
Sultana	Repair road surface by hand patching	Avenue 416 from Road 92 to Road 120	1/23/2019	1/23/2019	
Sultana	Repair road surface by hand patching	Avenue 424 from Road 104 to Road 120	1/28/2019	1/28/2019	
Sultana	Repair road surface by hand patching	Avenue 408 from Road 96 to Road 104	2/6/2019	2/6/2019	
Sultana	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 432	2/11/2019	2/11/2019	
Sultana	Repair road surface by hand patching	Avenue 424 from Road 92 to Road 120	2/11/2019	2/11/2019	\$ 489.69
Terra Bella	Repair road surface by hand patching	Avenue 95 from Road 236 to Road 256	12/26/2018	2/20/2019	
Terra Bella	Repair road surface by hand patching	Road 248 from Avenue 95 to Avenue 128	12/26/2018	12/26/2018	
Terra Bella	Repair road surface by hand patching	Avenue 92 from Road 248 to Road 264	1/4/2019	1/4/2019	
Terra Bella	Repair road surface by hand patching	Avenue 88 from Road 256 to Mountain 109	1/4/2019	1/4/2019	
Terra Bella	Repair road surface by hand patching	Avenue 96 west of Mountain 109	2/5/2019	2/5/2019	
Terra Bella	Repair road surface by hand patching	Road 236 from Avenue 95 to Avenue 104	2/20/2019	2/20/2019	\$ 1,422.15
Teviston	Repair potholes with road patcher	Elm from Road 80 to Road 72	3/1/2019	3/1/2019	
Teviston	Repair potholes with road patcher	Road 132 from Avenue 84 to Avenue 72	3/1/2019	3/1/2019	
Teviston	Repair potholes with road patcher	Avenue 80 from Road 136 to S.H. 99	3/1/2019	3/1/2019	\$ 458.86
Three Rivers	Repair road surface by hand patching	Cherokee Oaks Drive from State Highway 198 to Grouse Drive	12/27/2018	12/27/2018	
Three Rivers	Repair road surface by hand patching	Grouse Drive from Oak Ridge Drive to End	12/27/2018	12/27/2018	
Three Rivers	Repair road surface by hand patching	Pierce Drive from State Highway 198 to Mile Post 1	12/27/2018	12/27/2018	
Three Rivers	Repair road surface by hand patching	North Fork Drive from State Highway 198 to Mile Post 7.5	12/28/2018	12/28/2018	
Three Rivers	Repair road surface by hand patching	North Fork Drive from Mile Post 0 to Mile Post 2	1/4/2019	1/4/2019	
Three Rivers	Repair road surface by hand patching	Eggers Drive South of Mynatt Drive	1/4/2019	1/4/2019	
Three Rivers	Repair road surface by hand patching	Skyline Drive at Oak Drive	1/4/2019	1/4/2019	
Three Rivers	Repair road surface by hand patching	Pierce Drive from State Highway 198 to Mile Post 1	1/4/2019	1/4/2019	
Three Rivers	Repair road surface by hand patching	Skyline Drive from State Highway 198 to Manzanita Drive	1/18/2019	1/18/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 6 to Mile Post 6.5	1/30/2019	1/30/2019	
Three Rivers	Repair road surface by hand patching	South Fork Drive at Mile Post 4.5	1/31/2019	1/31/2019	
Three Rivers	Repair road surface by hand patching	North Fork Drive at Mile Post 1.5	1/31/2019	1/31/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 7 to Mile Post 8.5	2/1/2019	2/1/2019	
Three Rivers	Repair road surface by hand patching	North Fork Drive from State Highway 198 to Mile Post 4	2/28/2019	2/28/2019	\$ 5,175.06
Tonyville	Repair potholes with Road Patcher	Road 224 from Avenue 220 to Avenue 226	2/1/2019	2/8/2019	
Tonyville	Repair road surface by hand patching	Avenue 245 at D208D	2/26/2019	2/26/2019	
Tonyville	Repair road surface by hand patching	Avenue 256 west of Road 204	3/5/2019	3/5/2019	
Tonyville	Repair road surface by hand patching	Road 240 at Avenue 212	3/5/2019	3/5/2019	\$ 1,103.42
Tooleville	Repair road surface by hand patching	Road 192 from Avenue 256 to Avenue 273	12/28/2018	12/28/2018	
Tooleville	Repair potholes with Road Patcher	Avenue 276 from Road 196 to Road 204	1/28/2019	1/28/2019	\$ 827.63
Traver	Repair road surface by hand patching	Avenue 352 from Road 36 to Diagonal 60	1/8/2019	1/8/2019	
Traver	Repair road surface by hand patching	Diagonal 60 from Avenue 352 to Avenue 360	1/8/2019	1/8/2019	
Traver	Repair road surface by hand patching	Avenue 368 from Burke Drive to Merritt Drive	1/8/2019	1/8/2019	
Traver	Repair road surface by hand patching	Merritt Drive from Road 36 to Diagonal 39	1/25/2019	1/25/2019	
Traver	Repair road surface by hand patching	Road 36 from Merritt Drive to Avenue 352	1/25/2019	1/25/2019	
Traver	Repair road surface by hand patching	Merritt Drive at Burke Drive	1/28/2019	1/29/2019	
Traver	Repair road surface by hand patching	Avenue 360 from Road 44 to Road 52	1/28/2019	1/29/2019	
Traver	Repair road surface by hand patching	Road 40 from Avenue 368 to Avenue 384	1/28/2019	1/29/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
	Traver	Repair road surface by hand patching	Road 44 from Avenue 360 to Avenue 368	2/13/2019	2/13/2019	
	Traver	Repair road surface by hand patching	Avenue 368 from State Highway 99 to Road 52	3/8/2019	3/8/2019	
	Traver	Repair road surface by hand patching	Burke Drive at Merritt Drive	3/8/2019	3/12/2019	
	Traver	Repair road surface by hand patching	Diagonal 39 at Merritt Drive	3/8/2019	3/12/2019	
	Traver	Repair road surface by hand patching	Avenue 360 at 4107	3/12/2019	3/12/2019	
	Traver	Repair road surface by hand patching	Burke Drive at Avenue 360	3/12/2019	3/12/2019	
	Traver	Repair road surface by hand patching	Burke Drive from Merritt Drive to Avenue 360	3/12/2019	3/12/2019	\$ 2,257.28
	Waukena	Repair road surface by hand patching	Avenue 184 from Road 64 to Road 128	1/14/2019	1/14/2019	\$ 219.44
	West Exeter	Repair road surface by hand patching	Avenue 288 from Road 180 to Road 188	12/28/2018	12/28/2018	
	West Exeter	Repair road surface by hand patching	Road 180 north of Avenue 280	12/28/2018	12/28/2018	
	West Exeter	Repair road surface by hand patching	Road 180 from Avenue 264 to Avenue 280	12/28/2018	12/28/2018	
	West Exeter	Repair road surface by hand patching	Avenue 288 from Road 180 to Road 188	12/28/2018	12/28/2018	
	West Exeter	Repair road surface by hand patching	Avenue 264 at Road 180	1/4/2019	1/4/2019	
	West Exeter	Repair road surface by hand patching	Avenue 280 west of Road 180	3/4/2019	3/4/2019	\$ 1,285.46
	Yettem	Repair road surface by hand patching	Avenue 388 from Road 124 to Road 136	3/12/2019	3/12/2019	\$ 185.90
	Yokohl	Repair road surface by hand patching	Avenue 300 from Road 196 to Road 204	12/28/2018	12/28/2018	\$ 232.80

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
Rural Roads	Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 88 to Avenue 95	3/15/2019	3/15/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 128 from Road 224 to Road 232	12/26/2018	1/3/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 128 from Diagonal 238 to Road 264	12/27/2018	12/27/2018	
	Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 112 to Avenue 152	12/31/2018	12/31/2018	
	Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 208 to Road 128	1/3/2019	1/3/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 24 from Diagonal 205 to Road 208	1/4/2019	1/4/2019	
	Rural Roads	Repair road surface by hand patching	Road 224 from Avenue 112 to Avenue 128	1/7/2019	1/7/2019	
	Rural Roads	Repair road surface by hand patching	Road 176 From Avenue 56 to Avenue 88	1/8/2019	1/28/2019	
	Rural Roads	Repair road surface by hand patching	Road 192 at White River	1/8/2019	1/8/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 24 from Road 192 to Road 208	1/8/2019	1/8/2019	
	Rural Roads	Repair road surface by hand patching	Road 208 from Avenue 128 to Avenue 152	1/8/2019	1/8/2019	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 96 to Avenue 104	1/8/2019	1/9/2018	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 104 to Avenue 128	1/23/2019	1/25/2019	
	Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to Mile Post 3.5	1/25/2019	2/19/2019	
	Rural Roads	Repair road surface by hand patching	Road 188 from Avenue 0 to Avenue 8	1/28/2019	1/28/2019	
	Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 8 to Avenue 48	1/28/2019	3/1/2019	
	Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 24 to Avenue 32	1/29/2019	2/1/2019	
	Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 88 to Avenue 96	1/29/2019	1/29/2019	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 120 to Avenue 128	1/29/2019	1/29/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 136 from Road 208 to West Street	1/29/2019	1/29/2019	
	Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 24 to Avenue 40	2/1/2019	2/1/2019	
	Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 24 to Avenue 40	2/5/2019	2/6/2019	
	Rural Roads	Haul Material for Measure R Patching	Haul Material from Jaxon Baker to Avenue 368 Pit	2/6/2019	2/6/2019	
	Rural Roads	Haul Material for Measure R Patching	Haul Material from Jaxon Baker to Rankin Pit	2/6/2019	2/6/2019	
	Rural Roads	Haul Material for Measure R Patching	Jaxon Baker to Avenue 112 Pit	2/7/2019	2/7/2019	
	Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 32 to Avenue 40	2/7/2019	2/7/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 136 from Road 208 to Road 216	2/7/2019	2/7/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 104 from Road 192 to West Street	2/19/2019	2/19/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 96 east of Road 192	2/20/2019	2/20/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 104 from Road 192 to Road 208	2/20/2019	2/20/2019	
	Rural Roads	Repair road surface by hand patching	Road 248 from Avenue 86 to Avenue 88	2/20/2019	2/20/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 76 from Road 48 to Road 252	2/22/2019	2/22/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 48 at Road 168	2/22/2019	2/22/2019	
	Rural Roads	Repair road surface by hand patching	Road 184 from Avenue 52 to Avenue 80	2/26/2019	2/26/2019	
	Rural Roads	Repair road surface by hand patching	Road 176 from Avenue 24 to Avenue 48	2/26/2019	2/26/2019	
	Rural Roads	Repair road surface by hand patching	Avenue 0 from Road 192 to Road 184	2/26/2019	2/26/2019	
	Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 0 to Avenue 8	2/26/2019	2/26/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 16 from Road 168 to Road 144	2/26/2019	2/26/2019
Rural Roads	Repair road surface by hand patching	Avenue 4 at Road 185	2/28/2019	2/28/2019
Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 32 to Avenue 8	3/11/2019	3/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 192 to Road 184	3/11/2019	3/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 128 from Road 238 to Road 248	3/12/2019	3/12/2019
Rural Roads	Repair road surface by hand patching	Road 152 from Avenue 96 to Avenue 152	2/28/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Mountain 109 from Mountain 56 to 447Z	1/16/2019	2/11/2019
Rural Roads	Repair road surface by hand patching	Mountain 137 from Mountain 160 to Mile Post 8	2/6/2019	2/6/2019
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 109 to Mountain 50	2/8/2019	2/11/2019
Rural Roads	Repair road surface by hand patching	Mountain 3 from Mountain 1 to Mile Post 6.50	2/12/2019	2/12/2019
Rural Roads	Repair road surface by hand patching	Tract 454 ~ Mountain 56 to Road 416	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 50 to End	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Mountain 56 from Mountain 109 to Mile Post 22.5	3/4/2019	3/4/2019
Rural Roads	Repair road surface by hand patching	Mountain 137 to End	3/6/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to End	3/12/2019	3/12/2019
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 52 to Road 56	12/27/2018	12/27/2018

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 428 from Road 42 to Road 48	12/27/2018	12/27/2018
Rural Roads	Repair road surface by hand patching	Road 64 from Avenue 424 to Avenue 432	12/27/2018	12/28/2018
Rural Roads	Repair road surface by hand patching	Avenue 432 from Road 64 to Road 96	12/28/2018	12/28/2018
Rural Roads	Repair road surface by hand patching	Avenue 426 from Road 56 to Road 64	12/31/2018	12/31/2018
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 42 to Road 56	12/31/2018	12/31/2018
Rural Roads	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 416	1/2/2019	1/2/2019
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 352 to Avenue 376	1/3/2019	1/3/2019
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 172 to Road 188	1/3/2019	1/3/2019
Rural Roads	Repair road surface by hand patching	Road 188 from Cottonwood Drive to Avenue 344	1/3/2019	1/3/2019
Rural Roads	Repair road surface by hand patching	Cottonwood Drive West of Road 188	1/3/2019	1/3/2019
Rural Roads	Repair road surface by hand patching	Avenue 324 from Road 196 to Road 204	1/4/2019	1/4/2019
Rural Roads	Repair road surface by hand patching	Avenue 328 from Road 204 to State Highway 245	1/10/2019	1/10/2019
Rural Roads	Repair road surface by hand patching	Road 204 from Avenue 322 to Avenue 328	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Road 74 from Avenue 384 to Avenue 396	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Road 80 South of Avenue 360	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Road 80 North of Avenue 400	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Road 108 South of Avenue 328	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 337 from State Highway 245 to Road 222	1/14/2019	1/14/2019
Rural Roads	Repair road surface by hand patching	Avenue 344 from Road 180 to Road 182	1/14/2019	1/14/2019
Rural Roads	Repair road surface by hand patching	Avenue 352 West of Road 172	1/14/2019	1/14/2019
Rural Roads	Repair road surface by hand patching	Road 80 North of Avenue 400	1/14/2019	1/14/2019
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 344 to Avenue 376	1/15/2019	1/15/2019
Rural Roads	Repair road surface by hand patching	Avenue 368 West of State Highway 63	1/15/2019	1/15/2019
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 315 to El Rio Drive	1/16/2019	1/16/2019
Rural Roads	Repair road surface by hand patching	Avenue 315 from Road 168 to Charter Oak Drive	1/16/2019	1/16/2019
Rural Roads	Repair road surface by hand patching	Avenue 344 West of Road 180	1/16/2019	1/16/2019
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 328 to Avenue 344	1/18/2019	1/18/2019
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 432 to Avenue 440	1/18/2019	1/18/2019
Rural Roads	Repair road surface by hand patching	Avenue 440 from Road 120 to State Highway 63	1/22/2019	1/22/2019
Rural Roads	Repair road surface by hand patching	Road 164 at Avenue 362	1/22/2019	1/22/2019
Rural Roads	Repair road surface by hand patching	Road 188 at Charter Oak Drive	1/22/2019	1/22/2019
Rural Roads	Repair road surface by hand patching	Avenue 416 from Road 152 to End	1/23/2019	1/23/2019
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 416 to Boyd Drive	1/23/2019	1/23/2019
Rural Roads	Repair road surface by hand patching	Boyd Drive from Road 168 to State Highway 245	1/23/2019	1/23/2019
Rural Roads	Repair road surface by hand patching	Avenue 392 from Road 74 to Road 80	1/24/2019	1/24/2019
Rural Roads	Repair road surface by hand patching	Road 74 at Avenue 392	1/24/2019	1/24/2019
Rural Roads	Repair road surface by hand patching	Road 168 from Saint Johns River to State Highway 216	1/24/2019	1/24/2019
Rural Roads	Repair road surface by hand patching	Road 72 at Avenue 424	1/24/2019	1/24/2019
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Road 36 to Avenue 328	1/25/2019	1/25/2019
Rural Roads	Repair road surface by hand patching	Avenue 328 from Diagonal 60 to Road 80	1/25/2019	1/25/2019
Rural Roads	Repair road surface by hand patching	Avenue 392 West of Road 12	1/28/2019	1/28/2019
Rural Roads	Repair road surface by hand patching	Road 140 South of Avenue 352	1/28/2019	1/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 80	1/28/2019	1/28/2019
Rural Roads	Repair road surface by hand patching	Road 84 from Avenue 384 to Avenue 400	1/30/2019	1/30/2019
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 336 to Avenue 368	2/1/2019	2/1/2019
Rural Roads	Repair road surface by hand patching	Avenue 384 from Road 28 to State Highway 99	2/1/2019	2/1/2019
Rural Roads	Repair road surface by hand patching	Road 64 from Avenue 424 to Avenue 432	2/5/2019	2/5/2019
Rural Roads	Repair road surface by hand patching	Avenue 388 West of Road 8	2/6/2019	2/6/2019
Rural Roads	Repair road surface by hand patching	Avenue 456 from State Highway 63 to Road 144	2/6/2019	2/6/2019
Rural Roads	Repair road surface by hand patching	Road 132 North of Avenue 456	2/6/2019	2/6/2019
Rural Roads	Repair road surface by hand patching	Avenue 320 East of Road 144	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 320 West of Road 144	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 313 from Road 144 to Road 148	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Road 160 North of Avenue 344	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Road 196 South of State Highway 216	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Road 196 from Avenue 320 to Avenue 344	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 172 to Road 196	2/8/2019	2/8/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 336 from State Highway 63 to Road 144	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 92	2/11/2019	2/11/2019
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 432 to Avenue 440	2/11/2019	2/11/2019
Rural Roads	Repair road surface by hand patching	Road 172 North of Avenue 344	2/12/2019	2/12/2019
Rural Roads	Repair road surface by hand patching	Road 64 from Avenue 424 to Avenue 432	2/12/2019	2/12/2019
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 332 to Avenue 356	2/12/2019	2/12/2019
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 80	2/13/2019	2/13/2019
Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 364	2/13/2019	2/13/2019
Rural Roads	Repair road surface by hand patching	Road 144 at Avenue 313	2/14/2019	2/14/2019
Rural Roads	Repair road surface by hand patching	Road 112 South of Avenue 368	2/14/2019	2/14/2019
Rural Roads	Repair road surface by hand patching	Charter Oak Drive from Road 168 to Road 188	2/15/2019	2/15/2019
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 376 to Avenue 384	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 140 to Road 144	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Road 64 North of Avenue 424	2/20/2019	2/20/2019
Rural Roads	Repair road surface by hand patching	Avenue 424 at Road 108	2/21/2019	2/21/2019
Rural Roads	Repair road surface by hand patching	Avenue 320 at Road 108	2/21/2019	2/21/2019
Rural Roads	Repair road surface by hand patching	Road 108 from Visalia City Limit to Avenue 328	2/21/2019	2/21/2019
Rural Roads	Repair road surface by hand patching	Road 16 from Diagonal 16 to Avenue 384	2/21/2019	2/21/2019
Rural Roads	Repair road surface by hand patching	Avenue 368 West of State Highway 63	2/21/2019	2/21/2019
Rural Roads	Repair road surface by hand patching	Road 72 North of Avenue 424	2/22/2019	2/22/2019
Rural Roads	Repair road surface by hand patching	Road 84 from Avenue 388 to Avenue 396	2/22/2019	2/22/2019
Rural Roads	Repair road surface by hand patching	Road 76 South of Avenue 368	2/22/2019	2/22/2019
Rural Roads	Repair road surface by hand patching	Road 42 from Avenue 416 to Avenue 424	2/25/2019	2/25/2019
Rural Roads	Repair road surface by hand patching	Avenue 308 from State Highway 245 to End	2/26/2019	2/28/2019
Rural Roads	Repair road surface by hand patching	Road 80 South of Avenue 360	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Road 88 North of Avenue 400	3/4/2019	3/5/2019
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 328 to El Rio Drive	3/6/2019	3/6/2019
Rural Roads	Repair road surface by hand patching	Avenue 360 from State Highway 245 to Avenue 352	3/6/2019	3/6/2019
Rural Roads	Repair road surface by hand patching	Avenue 360 from Road 212 to Road 220	3/6/2019	3/6/2019
Rural Roads	Repair road surface by hand patching	Road 140 South of Avenue 364	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Road 140 South of Avenue 360	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Road 120 from Avenue 396 to Avenue 404	3/8/2019	3/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 52 to Road 80	3/8/2019	3/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 352 from Road 206 to Road 212	3/8/2019	3/8/2019
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 336 to Dairy Road	3/11/2019	3/11/2019
Rural Roads	Repair road surface by hand patching	Road 8 from Avenue 384 to Kingsburg City Limit	3/11/2019	3/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 384 at Road 8	3/11/2019	3/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 388 from Road 120 to Road 124	3/12/2019	3/12/2019
Rural Roads	Repair road surface by hand patching	Road 204 at 34767	3/13/2019	3/13/2019
Rural Roads	Repair road surface by hand patching	Avenue 384 at State Highway 99	3/13/2019	3/13/2019
Rural Roads	Repair road surface by hand patching	Avenue 336 from Road 196 to Road 200	3/13/2019	3/13/2019
Rural Roads	Repair road surface by hand patching	Avenue 384 at Road 172	3/14/2019	3/14/2019
Rural Roads	Repair road surface by hand patching	Avenue 344 at Road 188	3/14/2019	3/14/2019
Rural Roads	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	3/15/2019	3/15/2019
Rural Roads	Repair road surface by hand patching	Diagonal 60 from Avenue 344 to Avenue 360	3/15/2019	3/15/2019
Rural Roads	Repair road surface by hand patching	Avenue 16 from Road 128 to S.H. 43	12/27/2018	12/27/2018
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 0 to Avenue 56	12/27/2018	12/27/2018
Rural Roads	Repair road surface by hand patching	Road 144 from Avenue 0 to Avenue 56	12/27/2018	12/27/2018
Rural Roads	Repair potholes with road patcher	Avenue 168 from Road 152 to Road 128	12/27/2018	12/27/2018
Rural Roads	Repair potholes with road patcher	Avenue 160 from Road 152 to Diagonal 116	12/27/2018	12/27/2018
Rural Roads	Repair road surface by hand patching	Diagonal 112 from Avenue 184 to Road 112	1/7/2019	1/7/2019
Rural Roads	Repair road surface by hand patching	Road 112 from Diagonal 112 to Avenue 160	1/7/2019	1/7/2019
Rural Roads	Repair potholes with road patcher	Avenue 56 from SH43 to Road 36	1/8/2019	1/8/2019
Rural Roads	Repair road surface by hand patching	Road 32 from Avenue 184 to Avenue 178	1/8/2019	1/8/2019
Rural Roads	Repair road surface by hand patching	Diagonal 112 from Avenue 184 to Road 112	1/8/2019	1/8/2019
Rural Roads	Repair road surface by hand patching	Road 112 from Diagonal 112 to Avenue 128	1/8/2019	1/8/2019
Rural Roads	Repair road surface by hand patching	Diagonal 112 from Avenue 184 to Road 112	1/9/2019	1/9/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Road 112 from Diagonal 112 to Avenue 120	1/9/2019	1/9/2019
Rural Roads	Repair road surface by hand patching	Avenue 184 at railroad tracks	1/9/2019	1/9/2019
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 28 to Road 48	1/9/2019	1/9/2019
Rural Roads	Repair road surface by hand patching	Road 112 from Avenue 184 to Avenue 120	1/10/2019	1/10/2019
Rural Roads	Repair potholes with road patcher	Avenue 56 from Road 46 to Road 36	1/10/2019	1/10/2019
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 48 to Road 56	1/10/2019	1/10/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 144 to Road 136	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 248 to Avenue 232	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 260 from Road 64 to Road 52	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 56 to Road 64	1/11/2019	1/11/2019
Rural Roads	Repair road surface by hand patching	Road 20 from Avenue 192 to Avenue 200	1/14/2019	1/14/2019
Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 92 to Road 48	1/15/2019	1/15/2019
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 28 to Road 20	1/15/2019	1/15/2019
Rural Roads	Repair road surface by hand patching	Road 44 from Avenue 216 to Avenue 192	1/15/2019	1/15/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 136 to Road 135	1/16/2019	1/16/2019
Rural Roads	Repair road surface by hand patching	I Street from Avenue 200 to Addie Road	1/16/2019	1/16/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 140 to Elk Bayou Park	1/18/2019	1/18/2019
Rural Roads	Repair road surface by hand patching	I Street from Avenue 200 to south of Addie	1/22/2019	1/22/2019
Rural Roads	Repair road surface by hand patching	Avenue 280 from Road 140 to F'ville C.L.	1/22/2019	1/22/2019
Rural Roads	Repair road surface by hand patching	Avenue 280 from F'ville C.L. to Road 180	1/22/2019	1/22/2019
Rural Roads	Repair potholes with road patcher	Avenue 240 from Road 156 to Road 168	1/22/2019	1/22/2019
Rural Roads	Repair road surface by hand patching	Avenue 240 from Road 152 to Road 168	1/23/2019	1/23/2019
Rural Roads	Repair road surface by hand patching	Elm from Avenue 96 to Avenue 76	1/25/2019	1/25/2019
Rural Roads	Repair road surface by hand patching	R56 from Avenue 280 to Avenue 304	1/25/2019	1/25/2019
Rural Roads	Repair road surface by hand patching	R48 from Avenue 280 to Avenue 304	1/25/2019	1/25/2019
Rural Roads	Repair road surface by hand patching	R52 north of Avenue 304	1/25/2019	1/25/2019
Rural Roads	Repair potholes with road patcher	Avenue 96 from Road 152 to Road 136	1/25/2019	1/25/2019
Rural Roads	Repair potholes with road patcher	Road 136 from Avenue 96 to Avenue 104	1/25/2019	1/25/2019
Rural Roads	Repair potholes with road patcher	Avenue 104 from Road 136 to Road 124	1/25/2019	1/25/2019
Rural Roads	Repair potholes with road patcher	Road 124 from Avenue 104 to Avenue 120	1/25/2019	1/25/2019
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 260 to Avenue 248	1/28/2019	1/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 96 to Road 68	1/28/2019	1/28/2019
Rural Roads	Repair potholes with road patcher	Road 124 from Avenue 116 to Avenue 118	1/28/2019	1/28/2019
Rural Roads	Repair potholes with road patcher	Avenue 112 from Road 124 to Road 128	1/28/2019	1/28/2019
Rural Roads	Repair potholes with road patcher	Avenue 108 from Road 124 to Road 126	1/28/2019	1/28/2019
Rural Roads	Repair potholes with road patcher	Road 128 from Avenue 108 to Avenue 100	1/28/2019	1/28/2019
Rural Roads	Repair potholes with road patcher	Avenue 104 from Road 136 to Road 128	1/28/2019	1/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 92 to Road 36	1/29/2019	1/29/2019
Rural Roads	Repair potholes with road patcher	Road 152 from Avenue 256 to Avenue 208	1/29/2019	1/29/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 120 to Avenue 144	1/30/2019	1/30/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 120 to Road 96	1/31/2019	1/31/2019
Rural Roads	Repair potholes with road patcher	Road 152 from Avenue 208 to Avenue 192	1/31/2019	1/31/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 96 to Road 112	2/1/2019	2/1/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 144 to Avenue 184	2/1/2019	2/1/2019
Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 68 to Road 28	2/1/2019	2/1/2019
Rural Roads	Repair road surface by hand patching	Avenue 256 from Road 52 to Road 44	2/1/2019	2/1/2019
Rural Roads	Repair road surface by hand patching	Spacer Drive from Avenue 200 to Avenue 212	2/5/2019	2/5/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Spacer Drive to Park	2/5/2019	2/5/2019
Rural Roads	Repair road surface by hand patching	I Street from Addie to Avenue 200	2/5/2019	2/5/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 120 to Road 72	2/5/2019	2/5/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 112 to Road 104	2/6/2019	2/6/2019
Rural Roads	Repair road surface by hand patching	Road 112 from Avenue 184 to Diagonal 116	2/6/2019	2/6/2019
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 212 to Avenue 224	2/6/2019	2/6/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 104 to Road 112	2/7/2019	2/7/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 96 to Road 72	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Spacer Drive to Elk Bayou Park	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 296 to St. Johns Bridge	2/7/2019	2/7/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 296 from Road 168 to the end	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 288 from Farmersville C.L. to Visalia C.L.	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 288 to S.H. 198	2/7/2019	2/7/2019
Rural Roads	Repair potholes with road patcher	Avenue 120 from Road 112 to Road 104	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Road 112 north of Avenue 184	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 192 to Elk Bayou Park	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 310 at Farr Road	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 112 to Road 64	2/11/2019	2/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Spacer Drive to Road 124	2/11/2019	2/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 56 from State to Front	2/12/2019	2/12/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 west of Spacer Drive	2/12/2019	2/12/2019
Rural Roads	Repair road surface by hand patching	Avenue 240 east of Road 128	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 128 to Road 96	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 84 to Road 52	2/19/2019	2/19/2019
Rural Roads	Repair potholes with road patcher	Road 156 from Avenue 256 to Avenue 264	2/19/2019	2/19/2019
Rural Roads	Repair potholes with road patcher	Road 156 from Avenue 264 to Avenue 272	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 128 to Road 64	2/20/2019	2/20/2019
Rural Roads	Repair road surface by hand patching	Avenue 216 from Road 52 to Road 28	2/20/2019	2/20/2019
Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 228 to Avenue 216	2/20/2019	2/20/2019
Rural Roads	Repair road surface by hand patching	Avenue 56 west of Borchardt	2/22/2019	2/22/2019
Rural Roads	Repair road surface by hand patching	Road 96 south of Avenue 184	2/22/2019	2/22/2019
Rural Roads	Repair road surface by hand patching	Avenue 184 from Road 64 to Road 28	2/22/2019	2/22/2019
Rural Roads	Repair potholes with road patcher	Road 64 from Avenue 304 to Avenue 308	2/22/2019	2/22/2019
Rural Roads	Repair potholes with road patcher	Avenue 308 from Road 64 to Road 50	2/22/2019	2/22/2019
Rural Roads	Repair road surface by hand patching	Avenue 54 from Road 40 to east of Road 46	2/25/2019	2/25/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 208 to Avenue 184	2/25/2019	2/25/2019
Rural Roads	Repair road surface by hand patching	Road 112 from Avenue 152 to south of Avenue 144	2/26/2019	2/26/2019
Rural Roads	Repair road surface by hand patching	Avenue 152 at Road 140	2/26/2019	2/26/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 184 to Avenue 144	2/26/2019	2/26/2019
Rural Roads	Repair road surface by hand patching	Road 156 at Avenue 288	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Road 156 at Avenue 296	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Road 126 at Avenue 232	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Avenue 280 at Road 156	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Avenue 248 east of Road 124	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Avenue 312 from Road 88 to Road 92	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 248 to Avenue 240	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Road 96 south of Avenue 160	2/28/2019	2/28/2019
Rural Roads	Repair road surface by hand patching	Road 124 from Avenue 248 to Avenue 240	2/28/2019	2/28/2019
Rural Roads	Repair road surface by hand patching	Road 126 at Avenue 232	2/28/2019	2/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 132 to Road 152	2/28/2019	2/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 56 from Road 96 to Road 136	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Avenue 248 from West to Enterprise	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 240 to Avenue 248	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Avenue 224 from Road 140 to Road 152	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 68 to Road 52	3/4/2019	3/4/2019
Rural Roads	Repair road surface by hand patching	Pacific Avenue from Road 104 to Tulare C.L.	3/5/2019	3/5/2019
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 256 to Avenue 240	3/6/2019	3/6/2019
Rural Roads	Repair road surface by hand patching	Noble Avenue east of Road 156	3/6/2019	3/6/2019
Rural Roads	Repair road surface by hand patching	Avenue 272 from Road 132 to Road 178	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Road 128 from Avenue 272 to Avenue 271	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 271 from Road 128 to Road 122	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	451 Park Street	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Road 156 from Avenue 256 to Avenue 296	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Road 156 at Noble Avenue	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 296 from Road 156 to Road 164	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 296 to Avenue 310	3/7/2019	3/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 288 from Farmersville C.L. to Visalia C.L.	3/7/2019	3/7/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 152 to Road 140	3/8/2019	3/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 272 from Road 132 to Road 140	3/8/2019	3/8/2019
Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 192 to Avenue 200	3/8/2019	3/8/2019
Rural Roads	Repair road surface by hand patching	Avenue 152 from Road 152 to Road 96	3/11/2019	3/11/2019
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 96 to Road 64	3/11/2019	3/11/2019
Rural Roads	Repair potholes with road patcher	Road 164 from Avenue 256 to Farmersville C.L.	3/12/2019	3/12/2019
Rural Roads	Repair potholes with road patcher	Avenue 264 from Road 176 to Road 140	3/12/2019	3/12/2019
Rural Roads	Repair potholes with road patcher	Road 176 from Avenue 264 to Avenue 280	3/12/2019	3/12/2019
Rural Roads	Repair road surface by hand patching	Avenue 24 at Road 128	3/13/2019	3/13/2019
Rural Roads	Repair road surface by hand patching	Road 132 from Avenue 208 to Avenue 224	3/13/2019	3/13/2019
Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 200 to Avenue 216	3/13/2019	3/14/2019
Rural Roads	Repair road surface by hand patching	Avenue 264 from Road 108 to Road 92	3/14/2019	3/14/2019
Rural Roads	Repair road surface by hand patching	Road 100 at Avenue 276	3/14/2019	3/14/2019
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 272 to Avenue 280	3/14/2019	3/14/2019
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 264 to Zumwalt	3/14/2019	3/14/2019
Rural Roads	Repair road surface by hand patching	Avenue 272 from Road 68 to S.H. 99	3/14/2019	3/15/2019
Rural Roads	Repair road surface by hand patching	Avenue 272 from S.H.99 to Road 62	3/15/2019	3/15/2019
Rural Roads	Repair road surface by hand patching	Road 52 from Avenue 208 to Avenue 216	3/15/2019	3/15/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 52 to Road 60	3/15/2019	3/15/2019
Rural Roads	Repair road surface by hand patching	Road 140 from Avenue 192 to Avenue 190	3/15/2019	3/15/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 west of Road 136	3/16/2019	3/16/2019
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 96 to west of Road 80	3/16/2019	3/16/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 136 to Road 128	3/18/2019	3/18/2019
Rural Roads	Repair road surface by hand patching	Avenue 280 from Road 156 to Farmersville C.L.	3/18/2019	3/18/2019
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 256 to Avenue 224	3/18/2019	3/18/2019
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 60 to Road 64	3/19/2019	3/19/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 136 to Road 120	3/19/2019	3/19/2019
Rural Roads	Repair road surface by hand patching	Avenue 160 from Road 72 to Road 64	3/20/2019	3/20/2019
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 144 to Avenue 152	3/20/2019	3/20/2019
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 184 to Avenue 176	3/20/2019	3/20/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 125 to Road 126	3/20/2019	3/20/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 136 to Road 123	3/21/2019	3/21/2019
Rural Roads	Haul plant run for patching	Deer Creek to Avenue 112 Pit	3/21/2019	3/21/2019
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 196 to Avenue 192	3/21/2019	3/21/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 68 to Road 52	3/21/2019	3/21/2019
Rural Roads	Repair road surface by hand patching	Avenue 68 from Avenue 192 to Avenue 210	3/21/2019	3/21/2019
Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 208 to Avenue 228	3/22/2019	3/22/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 124 to Road 112	3/22/2019	3/22/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 120 to Avenue 88	3/23/2019	3/23/2019
Rural Roads	Repair road surface by hand patching	Road 96 at Avenue 104	3/23/2019	3/23/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 120 to Avenue 104	3/25/2019	3/25/2019
Rural Roads	Repair road surface by hand patching	Road 120 to the alignment of Avenue 134	3/25/2019	3/25/2019
Rural Roads	Repair road surface by hand patching	Road 68 from Avenue 228 to Avenue 248	3/25/2019	3/25/2019
Rural Roads	Repair road surface by hand patching	Avenue 248 from Road 68 to Road 92	3/25/2019	3/25/2019
Rural Roads	Repair road surface by hand patching	Road 92 from Zumwalt to Avenue 248	3/25/2019	3/25/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 128	3/25/2019	3/25/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 104 to Avenue 97	3/26/2019	3/26/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 134 to Road 124	3/26/2019	3/26/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 128 to Road 116	3/26/2019	3/26/2019
Rural Roads	Repair road surface by hand patching	Road 92 from Avenue 248 to Avenue 260	3/26/2019	3/26/2019
Rural Roads	Repair road surface by hand patching	Avenue 256 from Road 92 to Road 84	3/26/2019	3/26/2019
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 232 to Avenue 244	3/27/2019	3/27/2019
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 264 to Avenue 248	3/27/2019	3/27/2019
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 120 to Road 112	3/28/2019	3/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 120 to Road 112	3/28/2019	3/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 200 from Spacer Drive to Road 120	3/28/2019	3/28/2019
Rural Roads	Repair road surface by hand patching	Road 168 from Avenue 296 to St. Johns Bridge	3/28/2019	3/28/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Rural Roads	Repair road surface by hand patching	Avenue 296 from Road 168 to the east	3/28/2019	3/28/2019
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 240 to Avenue 248	3/28/2019	3/28/2019
Rural Roads	Repair potholes with road patcher	Road 120 from Avenue 96 to Avenue 88	3/28/2019	3/28/2019
Rural Roads	Repair road surface by hand patching	Avenue 96 from Road 120 to Road 112	3/29/2019	3/29/2019
Rural Roads	Repair road surface by hand patching	Road 96 from Avenue 97 to Avenue 88	3/29/2019	3/29/2019
Rural Roads	Repair road surface by hand patching	Road 148 from Avenue 240 to Avenue 248	3/29/2019	3/29/2019
Rural Roads	Repair road surface by hand patching	Road 148 at Avenue 248	3/29/2019	3/29/2019
Rural Roads	Repair road surface by hand patching	Road 80 from Avenue 184 to Avenue 152	3/29/2019	3/29/2019
Rural Roads	Repair road surface by hand patching	Avenue 120 from Road 117 to Road 104	3/29/2019	3/29/2019
Rural Roads	Repair road surface by hand patching	Road 120 at Avenue 116	3/29/2019	3/29/2019
Rural Roads	Repair road surface by hand patching	Road 88 from Avenue 120 to south of Avenue 128	3/30/2019	3/30/2019
Rural Roads	Repair road surface by hand patching	Avenue 170 at Friant Kern Canal	12/28/2018	12/28/2018
Rural Roads	Repair road surface by hand patching	Diagonal 211 from Avenue 268 to Road 228	12/28/2018	12/28/2018
Rural Roads	Repair road surface by hand patching	Road 212 at Avenue 192	12/28/2018	12/28/2018
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 176 to Road 188	12/31/2018	12/31/2018
Rural Roads	Repair road surface by hand patching	Road 172 from Avenue 200 to Avenue 208	12/31/2018	12/31/2018
Rural Roads	Repair road surface by hand patching	Avenue 200 from Road 172 to Road 180	1/2/2019	1/2/2019
Rural Roads	Repair road surface by hand patching	Avenue 208 from Road 152 to Road 188	1/2/2019	1/2/2019
Rural Roads	Repair road surface by hand patching	Road 220 from Diagonal 242 to Avenue 224	1/4/2019	1/4/2019
Rural Roads	Repair road surface by hand patching	Avenue 220 at Road 240	1/4/2019	1/4/2019
Rural Roads	Repair potholes with Road Patcher	Avenue 178 from Road 238 to Diagonal 242	1/11/2019	2/27/2019
Rural Roads	Repair potholes with Road Patcher	Road 238 from Avenue 178 to Avenue 181	1/11/2019	1/11/2019
Rural Roads	Repair potholes with Road Patcher	Fill Road Patcher with oil at Cain Trucking	1/28/2019	1/28/2019
Rural Roads	Repair road surface by hand patching	Haul Measure R Patch Material from plant to District locations	2/6/2019	2/6/2019
Rural Roads	Repair road surface by hand patching	Haul Measure R Patch Material from plant to District locations	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Diagonal 242 at Avenue 178	2/7/2019	2/7/2019
Rural Roads	Repair road surface by hand patching	Avenue 212 from Road 226* to Road 228	2/8/2019	2/8/2019
Rural Roads	Repair road surface by hand patching	Road 254 at Avenue 164	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Road 252 south of Avenue 169	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Road 284 at M146	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Road 256 from Avenue 196 to Avenue 212	2/19/2019	2/19/2019
Rural Roads	Repair road surface by hand patching	Road 196 from D184B to Avenue 328*	2/20/2019	2/20/2019
Rural Roads	Repair road surface by hand patching	Road 180 at D180A	2/20/2019	2/20/2019
Rural Roads	Repair road surface by hand patching	Avenue 178 from Road 232 to Road 234*	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Road 238 from Avenue 178 to Avenue 184	2/27/2019	2/27/2019
Rural Roads	Repair road surface by hand patching	Road 224 at Avenue 238	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Road 224 at Avenue 224	3/1/2019	3/1/2019
Rural Roads	Repair road surface by hand patching	Avenue 174 at Road 224	3/4/2019	3/4/2019
Rural Roads	Repair road surface by hand patching	Avenue 192 east of Road 268	3/4/2019	3/4/2019
Rural Roads	Repair road surface by hand patching	Road 188 at Avenue 232	3/4/2019	3/4/2019
Rural Roads	Repair road surface by hand patching	Road 180 from Avenue 224 to Avenue 232	3/4/2019	3/4/2019
Rural Roads	Repair road surface by hand patching	Road 32 from Avenue 192 to Avenue 184	1/7/2019	12/27/2018
Rural Roads	Repair road surface by hand patching	Haul Measure R Patch Material from Avenue 112 Pit to Yard 1	3/7/2019	3/7/2019
Mountain Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 2.5 to Whitaker Forest Drive	1/2/2019	1/2/2019
Mountain Roads	Repair road surface by hand patching	Dry Creek Drive from Mile Post 3.5 to Stage Coach Drive	1/2/2019	1/2/2019
Mountain Roads	Repair road surface by hand patching	Whitaker Forest Drive at Mile Post 2	1/11/2019	1/11/2019

\$ 165,968.79

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 3

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720)		Construction/Design	Road 68 - Ave 306 to Effie Drive	6/26/2017	ongoing	\$ 682.33
		Preliminary Engineering/ Design	ADA Ramp Improvements	3/3/2016	ongoing	\$ 3,327.39
		Construction/Design	Ivanhoe R159 and Azalea Improvements	7/11/2017	ongoing	\$ 46,427.72
		Construction/Design	West Goshen Ave 308	6/27/2017	ongoing	\$ 290,720.85
		Preliminary Engineering/ Design	Orosi A416 Crossing	7/12/2017	ongoing	\$ 11,336.55
		Preliminary Engineering/ Design	Poplar Crossing R192 and A146	8/1/2017	ongoing	\$ 5,608.43
		Preliminary Engineering/ Design	Strathmore A196 & R228 Intersection	8/1/2017	ongoing	\$ 14,017.12
		Preliminary Engineering/ Design	Allensworth Sidewalk & Crosswalk Improvements	8/2/2017	ongoing	\$ 1,718.35
		Preliminary Engineering/ Design	Terra Bella R243 at A95 &A92	6/26/2017	ongoing	\$ 2,620.00
		Preliminary Engineering/ Design	Earlimart Alila ADA Ramp Construction	8/8/2017	ongoing	\$ 5,196.88
		Preliminary Engineering/ Design	Sequoia Field - A368 Reahabilitation	6/26/2017	ongoing	\$ 3,000.00
		Preliminary Engineering/ Design	Richgrove - Diagonal 205 Rehabilitation	6/29/2017	ongoing	\$ 1,310.00
					Total	\$ 591,526.50
			Repair potholes with Road Patcher			

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
18/19 Annual Advance \$4,199,499.00 Communities	Alpaugh	Repair road surface by hand patching	All of Knox and all of Lake	4/4/19	4/4/19	1,728.18
	Alpaugh	Repair road surface by hand patching	Avenue 56 from Borchardt to Road 16	5/21/19	5/21/19	
	Earlimart	Repair road surface by hand patching	Carmella at Mariposa	4/4/19	4/4/19	
	Earlimart	Repair potholes with Road Patcher	Valente from Washington to Sierra	4/16/19	4/16/19	
	Earlimart	Repair potholes with Road Patcher	Washington from Howard to Valente	4/16/19	4/16/19	
	Earlimart	Repair potholes with Road Patcher	Market from Kelly to Washington	4/16/19	4/16/19	
	Earlimart	Repair potholes with Road Patcher	Clay from Front to Center	4/16/19	4/16/19	
	Earlimart	Repair potholes with Road Patcher	Alila at Kovacovich	4/16/19	4/16/19	
	Earlimart	Repair potholes with Road Patcher	Sutter from State to Church	4/16/19	4/16/19	
	Earlimart	Repair potholes with Road Patcher	Sierra from Front to Earlimart Street	4/18/19	4/18/19	
	Earlimart	Repair potholes with Road Patcher	Andrea from Diane to Road 136	4/18/19	4/18/19	
	Earlimart	Repair potholes with Road Patcher	Vinyard at Cardinal	4/18/19	4/18/19	
	Earlimart	Repair potholes with Road Patcher	Sutter at Mariposa	4/18/19	4/18/19	
	Earlimart	Repair potholes with Road Patcher	Market from Clay to Franklin	4/18/19	4/18/19	
	Earlimart	Repair potholes with Road Patcher	Market from Armstrong to Franklin	4/30/19	4/30/19	
	Earlimart	Repair potholes with Road Patcher	Valente at Center	4/30/19	4/30/19	4,135.42
	Earlimart	Repair potholes with Road Patcher	Front from S.H.99 to Armstrong	4/30/19	4/30/19	
	Earlimart	Repair road surface by hand patching	Elm Street from School to Spruce	5/9/19	5/9/19	
	Earlimart	Repair road surface by hand patching	Armstrong from Road 138 to Road 136	5/9/19	5/9/19	
	Earlimart	Repair road surface by hand patching	Diagonal 136A from Washington to Armstrong	5/9/19	5/9/19	
	Earlimart	Repair road surface by hand patching	Valente from Washington to Armstrong	5/9/19	5/9/19	
	Earlimart	Repair road surface by hand patching	Marin from Molly to Road 136	5/9/19	5/9/19	
	Earlimart	Repair road surface by hand patching	Road 134 from Avenue 56 to Marin	5/9/19	5/9/19	
	Earlimart	Repair road surface by hand patching	Market from Washington to Avenue 133	5/9/19	5/9/19	
	Earlimart	Repair potholes with Road Patcher	Washington from Howard to Dietz	5/20/19	5/20/19	
	Earlimart	Repair potholes with Road Patcher	State from Church to Franklin	5/20/19	5/20/19	
	Earlimart	Repair potholes with Road Patcher	School from Wilson to Tulare	5/20/19	5/20/19	
	Earlimart	Repair potholes with Road Patcher	Kern at Armstrong	5/20/19	5/20/19	3,044.69
	Goshen	Repair potholes with Road Patcher	Road 70 from Avenue 308 to Avenue 310	5/14/19	5/14/19	
	Goshen	Repair potholes with Road Patcher	Road 70 from Avenue 308 to Wills	5/14/19	5/14/19	2,742.22
	Pixley	Repair potholes with Road Patcher	Palm from Terra Bella Avenue to Orriand Ave	4/15/19	4/15/19	
	Pixley	Repair potholes with Road Patcher	Walnut to Terra Bella Avenue	4/15/19	4/15/19	
	Pixley	Repair potholes with Road Patcher	Terra Bella Avenue east of School	4/15/19	4/15/19	
	Pixley	Repair potholes with Road Patcher	Road 120 south of Avenue 96	4/15/19	4/15/19	
	Pixley	Repair potholes with Road Patcher	Road 140 north of Avenue 96	4/15/19	4/15/19	
	Pixley	Repair potholes with Road Patcher	Compton at Road 120	4/16/19	4/16/19	
	Pixley	Repair potholes with Road Patcher	Avenue 96 from Road 104 to Road 96	4/18/19	4/18/19	
	Pixley	Repair potholes with Road Patcher	Park North of Avenue 96	4/18/19	4/18/19	
	Pixley	Repair potholes with Road Patcher	Wright from Road 120 to Elm	5/21/19	5/21/19	
	Tipton	Repair potholes with Road Patcher	Evans from Avenue 144 to Avenue 152	4/25/19	4/25/19	2,083.90
	Matheny Tract	Repair road surface by hand patching	Road 96 west of I Street	5/28/19	5/28/19	
	Matheny Tract	Repair road surface by hand patching	Wade from Road 96 to I Street	5/28/19	5/28/19	
	Matheny Tract	Repair road surface by hand patching	Wade from Pratt to Casa	5/28/19	5/28/19	
	Matheny Tract	Repair road surface by hand patching	Casa from Wade to Addie	5/28/19	5/28/19	
	Matheny Tract	Repair road surface by hand patching	Beacon from I Street to Casa	5/28/19	5/28/19	
	Matheny Tract	Repair road surface by hand patching	Addie at Pratt	5/28/19	5/28/19	
	Matheny Tract	Repair road surface by hand patching	Luton from Addie to Wade	5/28/19	5/28/19	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Matheny Tract	Repair road surface by hand patching	Canal from Addle to Wade	5/28/19	5/28/19	
Matheny Tract	Repair road surface by hand patching	Beacon from Canal to Luton	5/28/19	5/28/19	1,853.85
Coy Flat Road	Repair road surface by hand patching	Coy Flat Road from Nelson Drive to End	6/4/2019	6/4/2019	2,027.17
Doyle Cololny	Repair road surface by hand patching	Road 270 at LA147D (Richard Avenue)	3/19/2019	3/19/2019	
Doyle Cololny	Repair road surface by hand patching	LR269 from Avenue 146 to Avenue 148	4/10/2019	4/10/2019	
Doyle Cololny	Repair road surface by hand patching	LR261 from Avenue 148 to Avenue 150	4/10/2019	4/10/2019	
Doyle Cololny	Repair road surface by hand patching	Avenue 150 from Road 272 to End	5/29/2019	5/29/2019	
Doyle Cololny	Repair road surface by hand patching	Bennet Street from Cleo Avenue to Springville Drive	5/31/2019	5/31/2019	
Doyle Cololny	Repair road surface by hand patching	Bennet Street from Cleo Avenue to Springville Drive	6/4/2019	6/4/2019	
Doyle Cololny	Repair road surface by hand patching	Ruth Street from Orange Avenue to Roby Avenue	6/19/2019	6/19/2019	1,704.23
Lindcove	Repair road surface by hand patching	Carson Avenue at Road 228	4/9/2019	4/9/2019	
Lindcove	Repair road surface by hand patching	Carson Avenue at Road 220	4/9/2019	4/9/2019	
Lindcove	Repair road surface by hand patching	Road 228 at Avenue 320	4/9/2019	4/9/2019	
Lindcove	Repair road surface by hand patching	Mehrten Drive from Avenue 307 to Avenue 307* (End)	4/9/2019	4/9/2019	358.08
Plainview	Repair road surface by hand patching	Avenue 204 from Road 192 to Road 196	3/25/2019	3/25/2019	
Plainview	Repair road surface by hand patching	Avenue 208 from Road 208 to Highway 65	4/18/2019	4/18/2019	
Plainview	Repair road surface by hand patching	Avenue 192 from Road 208 to Road 212	4/26/2019	4/26/2019	
Plainview	Repair road surface by hand patching	Avenue 192 east of Road 208	5/1/2019	5/1/2019	
Plainview	Repair road surface by hand patching	Road 196 from Avenue 184 to Avenue 192	5/10/2019	5/10/2019	
Plainview	Repair road surface by hand patching	Road 208 from Avenue 176 to Avenue 208	5/14/2019	5/14/2019	
Plainview	Repair road surface by hand patching	Road 204 from Avenue 184 to Avenue 208	5/14/2019	5/14/2019	
Plainview	Repair road surface by hand patching	Road 180 from Avenue 192 to Avenue 194	5/15/2019	5/15/2019	
Plainview	Repair road surface by hand patching	Avenue 184 at Road 180	6/5/2019	6/7/2019	2,212.03
Springville	Repair road surface by hand patching	Mountain Road 176B at Mountain Road 171A	4/9/2019	4/9/2019	
Springville	Repair road surface by hand patching	32679 Maverick Drive	4/15/2019	4/15/2019	
Springville	Repair road surface by hand patching	Road 320 from Avenue 176 to Mountain Road 194G	4/24/2019	4/24/2019	
Springville	Repair road surface by hand patching	Mountain Road 194G from Road 320 to Mountain Road 195G	4/24/2019	4/24/2019	
Springville	Repair road surface by hand patching	Mountain Road 195G from Road 309* to Mountain Road 194G	4/24/2019	4/24/2019	
Springville	Repair road surface by hand patching	Pleasant Oak Drive from Goat Ranch Drive to Mustang Drive	6/3/2019	6/3/2019	
Springville	Repair road surface by hand patching	Mountain Road 176 at Mountain Road 171A	6/4/2019	6/4/2019	
Springville	Repair road surface by hand patching	Avenue 175 from Road 292 to Road 296	6/5/2019	6/5/2019	
Springville	Repair road surface by hand patching	Mountain Road 176B west of Avenue 176	6/13/2019	6/13/2019	
Springville	Repair road surface by hand patching	Avenue 176 at Road 320	6/14/2019	6/19/2019	
Springville	Repair road surface by hand patching	Road 320 from Avenue 176 to Mountain Road 194G	6/14/2019	6/14/2019	
Strathmore	Repair road surface by hand patching	Avenue 194 from Diagonal 242 to Raod 234	3/18/2019	3/18/2019	
Strathmore	Repair road surface by hand patching	Road 234 at Avenue 192	3/18/2019	3/18/2019	
Strathmore	Repair road surface by hand patching	Road 236 at Avenue 184	3/18/2019	3/18/2019	
Strathmore	Repair potholes with Road Patcher	Avenue 188 west of Diagonal 242	3/18/2019	3/18/2019	
Strathmore	Repair potholes with Road Patcher	Avenue 244 at Road 204	3/18/2019	3/18/2019	
Strathmore	Repair road surface by hand patching	Road 220 at Avenue 208	3/26/2019	3/26/2019	
Strathmore	Repair road surface by hand patching	Avenue 200 at Road 228	4/2/2019	4/2/2019	
Strathmore	Repair potholes with Road Patcher	Avenue 184 from Road 224 to Road 243	4/4/2019	4/4/2019	
Strathmore	Repair road surface by hand patching	Avenue 208 from Friant Kern Canal to Road 244	4/5/2019	4/5/2019	
Strathmore	Repair potholes with Road Patcher	Road 216 from Avenue 184 to Avenue 196	4/8/2019	4/8/2019	
Strathmore	Repair road surface by hand patching	Larson at Strathmore Post Office	4/18/2019	4/18/2019	
Strathmore	Repair road surface by hand patching	Avenue 192 west of Road 220	4/23/2019	4/23/2019	
Strathmore	Repair road surface by hand patching	19729 Road 232	4/25/2019	4/25/2019	
Strathmore	Repair road surface by hand patching	Avenue 196 west of Road 216	5/8/2019	5/8/2019	
Strathmore	Repair road surface by hand patching	Road 220 from Avenue 196 to Avenue 220	5/9/2019	5/9/2019	
Strathmore	Repair road surface by hand patching	Road 224 from Avenue 196 to Avenue 200	5/10/2019	5/10/2019	
Strathmore	Repair road surface by hand patching	Avenue 196 from Road 228 to Diagonal 242	5/28/2019	5/28/2019	
Strathmore	Repair road surface by hand patching	Avenue 196 at Strathmore High School	6/4/2019	6/4/2019	
Strathmore	Repair road surface by hand patching	Avenue 200 from Road 230 to Road 232	6/5/2019	6/5/2019	
Strathmore	Repair road surface by hand patching	Avenue 200 from Diagonal 242 to Road 236	6/5/2019	6/5/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Strathmore	Repair road surface by hand patching	Road 216 from Avenue 196 to Avenue 208	6/7/2019	6/7/2019	
Strathmore	Repair road surface by hand patching	Avenue 182 from Road 232 to Diagonal 242	6/19/2019	6/19/2019	
Strathmore	Repair road surface by hand patching	Road 212 from Avenue 212 to Avenue 216	6/19/2019	6/19/2019	6,301.39
Tonyville	Repair potholes with Road Patcher	Avenue 212 from Road 228 to Road 232	3/18/2019	3/29/2019	
Tonyville	Repair road surface by hand patching	Road 228 south of Avenue 238	3/19/2019	3/19/2019	
Tonyville	Repair road surface by hand patching	Avenue 230 west of Road 248	3/20/2019	3/20/2019	
Tonyville	Repair road surface by hand patching	Avenue 250 at Road 216	3/26/2019	3/26/2019	
Tonyville	Repair road surface by hand patching	D208D from Avenue 244 to Avenue 245	3/27/2019	3/27/2019	
Tonyville	Repair road surface by hand patching	21030 Avenue 245	3/27/2019	3/27/2019	
Tonyville	Repair road surface by hand patching	Avenue 212 from Road 236 to Road 256	3/27/2019	3/29/2019	
Tonyville	Repair road surface by hand patching	Road 214 at Avenue 240	4/2/2019	4/2/2019	
Tonyville	Repair road surface by hand patching	Avenue 240 from Road 212 to Road 216	4/3/2019	4/3/2019	
Tonyville	Repair road surface by hand patching	Avenue 245 from Road 212 to Road 216	4/3/2019	4/3/2019	
Tonyville	Repair road surface by hand patching	Avenue 240 east of Road 212	4/8/2019	4/8/2019	
Tonyville	Repair road surface by hand patching	Avenue 250 from Road 216 to Road 224	4/16/2019	4/16/2019	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 248 to Avenue 250	4/16/2019	4/16/2019	
Tonyville	Repair road surface by hand patching	Avenue 240 from Road 212 to Road 214	4/18/2019	4/18/2019	
Tonyville	Repair road surface by hand patching	Avenue 268 from Road 212 to Road 216	4/18/2019	4/18/2019	
Tonyville	Repair road surface by hand patching	Avenue 264 at Road 216	4/18/2019	4/18/2019	
Tonyville	Repair road surface by hand patching	Road 204 at Avenue 244	4/25/2019	4/25/2019	
Tonyville	Repair road surface by hand patching	Avenue 280 from Road 216 to Road 224	5/28/2019	5/28/2019	
Tonyville	Repair road surface by hand patching	Road 224 from Avenue 238 to Avenue 248	5/28/2019	5/28/2019	
Tonyville	Repair road surface by hand patching	Road 216 at Avenue 245	6/10/2019	6/10/2019	4,266.92
Tooleville	Repair road surface by hand patching	LA274B from Road 204 to End	4/16/2019	4/16/2019	
Tooleville	Repair road surface by hand patching	LA274C from Road 204 to End	4/16/2019	4/16/2019	
Tooleville	Repair road surface by hand patching	Road 204 from Avenue 208 to Highway 198	5/28/2019	5/28/2019	
Tooleville	Repair road surface by hand patching	Avenue 288 from Road 196 to Road 204	5/28/2019	5/31/2019	
Tooleville	Repair road surface by hand patching	Bennet Street from Springville Drive to Crabtree Street	6/4/2019	6/4/2019	
Tooleville	Repair road surface by hand patching	Avenue 280 east of Road 204	6/7/2019	6/7/2019	2,248.79
West Exeter	Repair road surface by hand patching	Road 192 north of Avenue 256	4/18/2019	4/18/2019	
West Exeter	Repair road surface by hand patching	Avenue 268 west of Road 256	4/18/2019	4/18/2019	
West Exeter	Repair road surface by hand patching	Avenue 278 at Road 176	5/14/2019	5/14/2019	
West Exeter	Repair road surface by hand patching	Avenue 288 from Road 180 to Road 184	5/28/2019	5/31/2019	543.23
Yokohl	Repair road surface by hand patching	Road 220 south of Avenue 300	4/15/2019	4/15/2019	323.40
Cutler/Orosi	Repair road surface by hand patching	Avenue 416 at State Highway 63	3/18/2019	3/18/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 130 from Ledbetter Drive to Ella Avenue	3/18/2019	3/18/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 126 from Ella Avenue to Avenue 414	3/18/2019	3/18/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 404 at Robert Road	3/20/2019	3/20/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 403 from State Highway 63 to Cannon Avenue	3/20/2019	3/20/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 140 from Avenue 428 to Avenue 432	3/26/2019	3/26/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 416 from Road 120 to Road 144	3/29/2019	3/29/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 404 West of Road 140	4/15/2019	4/15/2019	
Cutler/Orosi	Repair road surface by hand patching	Paradise Court at 41706	4/22/2019	4/22/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 124 at Avenue 416	4/22/2019	4/22/2019	
Cutler/Orosi	Repair road surface by hand patching	Miller Avenue from Road 126 to State Highway 63	4/22/2019	4/22/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 412 from State Highway 63 to Road 130	4/30/2019	4/30/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 130 from Avenue 412 to Avenue 414	4/30/2019	4/30/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 130 at Avenue 404	5/1/2019	5/1/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 415 at State Highway 63	5/1/2019	5/1/2019	
Cutler/Orosi	Repair road surface by hand patching	Ralph Road from Avenue 416 to Miller Avenue	5/9/2019	5/9/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 424 West of Road 120	5/9/2019	5/9/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 424 from Road 120 to State Highway 63	5/17/2019	5/17/2019	
Cutler/Orosi	Repair road surface by hand patching	Second Drive from George Road to Cutler Drive	5/23/2019	5/23/2019	
Cutler/Orosi	Repair road surface by hand patching	George Road from Second Drive to Avenue 406	5/23/2019	5/23/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Cutler/Orosi	Repair road surface by hand patching	Avenue 412 from Road 136 to Road 144	5/24/2019	5/24/2019	23,847.32
Cutler/Orosi	Repair road surface by hand patching	Road 126 from Avenue 419 to Avenue 424	5/24/2019	5/24/2019	
Cutler/Orosi	Repair road surface by hand patching	Eddy Road from Avenue 416 to Miller Avenue 06/07	6/7/2019	6/7/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 126 at Avenue 419	6/7/2019	6/7/2019	
Cutler/Orosi	Repair road surface by hand patching	Road 124 at Avenue 413	6/7/2019	6/7/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 407 from Road 124 to Eddy Road	6/12/2019	6/12/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 404 from State Highway 63 to Road 140	6/12/2019	6/12/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 415 from State Highway 63 to Road 130	6/12/2019	6/12/2019	
Cutler/Orosi	Repair road surface by hand patching	Avenue 414 at Road 130	6/12/2019	6/12/2019	
Cutler/Orosi	Repair road surface by hand patching	George Road from Second Drive to Avenue 407	6/12/2019	6/12/2019	
Cutler/Orosi	Sidewalk repair, cement repair	Road 124 at Avenue 413	6/6/2019	6/19/2019	
Delft Colony	Repair road surface by hand patching	Road 64 at Avenue 392	4/5/2019	4/5/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Delft Colony	Repair road surface by hand patching	Road 56 at 39160	4/22/2019	4/22/2019	1,227.26
Delft Colony	Repair road surface by hand patching	Road 56 South of Avenue 392	4/22/2019	4/22/2019	
Delft Colony	Repair road surface by hand patching	Avenue 408 from Dinuba City Limit to Road 56	4/26/2019	4/26/2019	
Delft Colony	Repair road surface by hand patching	Avenue 392 from Road 48 to Road 56	5/31/2019	5/31/2019	
Delft Colony	Repair road surface by hand patching	Road 48 from Avenue 384 to Avenue 410	6/11/2019	6/11/2019	
East Orosi	Repair road surface by hand patching	Avenue 416 from Road 144 to Road 154	3/29/2019	3/29/2019	2,915.31
East Orosi	Repair road surface by hand patching	Road 136 at Avenue 416	4/1/2019	4/1/2019	
East Orosi	Repair road surface by hand patching	Road 152 North of Avenue 424	4/5/2019	4/5/2019	
East Orosi	Repair road surface by hand patching	Road 142 from Avenue 416 to Avenue 420	4/5/2019	4/5/2019	
East Orosi	Repair road surface by hand patching	Road 142 from Avenue 416 to Avenue 432	4/15/2019	4/15/2019	
East Orosi	Repair road surface by hand patching	Avenue 424 from Road 140 to Road 142	4/15/2019	4/15/2019	
East Orosi	Repair road surface by hand patching	Road 144 from Avenue 424 to Avenue 432	4/16/2019	4/16/2019	
East Orosi	Repair road surface by hand patching	Road 144 from Avenue 416 to Avenue 424	4/17/2019	4/17/2019	
East Orosi	Repair road surface by hand patching	Road 152 from Avenue 412 to Avenue 416	5/10/2019	5/10/2019	
East Orosi	Repair road surface by hand patching	Road 144 from Avenue 416 to Avenue 420	5/10/2019	5/10/2019	
East Orosi	Repair road surface by hand patching	Avenue 432 from State Highway 63 to Road 144	5/10/2019	5/10/2019	
East Orosi	Repair road surface by hand patching	Avenue 428 from Road 140 to Road 142	5/24/2019	5/24/2019	
Ivanhoe	Repair road surface by hand patching	Road 156 North of Avenue 324	4/2/2019	4/2/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 160 to Road 168	4/8/2019	4/8/2019	
Ivanhoe	Repair road surface by hand patching	Road 160 from Avenue 332 to Avenue 344	4/8/2019	4/8/2019	4,133.31
Ivanhoe	Repair road surface by hand patching	Avenue 324 West of Road 156	4/8/2019	4/8/2019	
Ivanhoe	Repair road surface by hand patching	Road 156 from Avenue 328 to Jasmine Avenue	4/8/2019	4/8/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 336 from Road 172 to State Highway 216	4/9/2019	4/9/2019	
Ivanhoe	Repair road surface by hand patching	Road 159 at 33125	4/24/2019	4/24/2019	
Ivanhoe	Repair road surface by hand patching	Road 168 South of Avenue 328	5/1/2019	5/1/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 332 at Road 164	5/2/2019	5/2/2019	
Ivanhoe	Repair road surface by hand patching	Depot Drive from Avenue 328 to Road 158	5/21/2019	5/21/2019	
Ivanhoe	Repair road surface by hand patching	Manzanita Road from Heather Avenue to Avenue 332	5/21/2019	5/21/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 328 at Road 157	5/28/2019	5/28/2019	
Ivanhoe	Repair road surface by hand patching	Road 160 from Azalea Avenue to Heather Avenue	5/28/2019	5/28/2019	
Ivanhoe	Repair road surface by hand patching	Road 158 at Avenue 327	5/28/2019	5/28/2019	
Ivanhoe	Repair road surface by hand patching	Rosaline Road at Road 157	5/28/2019	5/28/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 327 at 15844	5/28/2019	5/28/2019	
Ivanhoe	Repair road surface by hand patching	Road 168 from Avenue 336 to Avenue 344	5/31/2019	5/31/2019	
Ivanhoe	Repair road surface by hand patching	Road 148 from Avenue 328 to Avenue 336	6/6/2019	6/6/2019	
Ivanhoe	Repair road surface by hand patching	Road 158 from Beechwood Avenue to Aspen Avenue	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Jasmine Avenue from Road 156 to Road 160	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Road 156 from Avenue 324 to Avenue 328	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Live Oak Drive from Lantana Avenue to Avenue 330	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Manzanita Road from Avenue 328 to Fuchsia Avenue	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Heather Avenue from Buckeye Road to Road 160	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Road 161 at Heather Avenue	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 340 from Road 164 to Road 168	6/13/2019	6/13/2019	
Ivanhoe	Repair road surface by hand patching	Avenue 344 from Road 156 to Road 164	6/21/2019	6/21/2019	
Ivanhoe	Repair road surface by hand patching	Road 168 from State Highway 216 to Avenue 315	6/21/2019	6/21/2019	
London	Repair road surface by hand patching	Avenue 376 at Road 57	4/22/2019	4/22/2019	1,684.45
London	Repair road surface by hand patching	Avenue 377 at Kate Road	4/22/2019	4/22/2019	
London	Repair road surface by hand patching	Clay Road from Avenue 377 to Avenue 378	4/22/2019	4/22/2019	
London	Repair road surface by hand patching	Avenue 376 East of Road 44	4/22/2019	4/22/2019	
London	Repair road surface by hand patching	Road 60 at Denver Avenue	4/23/2019	4/23/2019	
London	Repair road surface by hand patching	Avenue 377 from Road 52 to end	4/23/2019	4/23/2019	
London	Repair road surface by hand patching	Avenue 376 at Kate Road	5/14/2019	5/14/2019	
London	Repair road surface by hand patching	Road 58 at Avenue 380	5/14/2019	5/14/2019	
London	Repair road surface by hand patching	Hunter Road at 37714	5/14/2019	5/14/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Monson	Repair road surface by hand patching	Monson Drive South of Simpson Road	4/17/2019	4/17/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Monson	Repair road surface by hand patching	Avenue 388 at Road 96	4/17/2019	4/17/2019	
Monson	Repair road surface by hand patching	Avenue 384 West of Road 120	4/25/2019	4/25/2019	
Monson	Repair road surface by hand patching	Avenue 384 at Road 108	4/25/2019	4/25/2019	
Monson	Repair road surface by hand patching	Monson Drive at Avenue 388	5/10/2019	5/10/2019	1,658.14
Seville	Repair road surface by hand patching	Road 156 from Avenue 362 to Avenue 384	4/11/2019	4/11/2019	177.83
Sultana	Repair road surface by hand patching	Avenue 416 from Road 92 to Road 120	3/29/2019	3/29/2019	
Sultana	Repair road surface by hand patching	Avenue 424 from Road 96 to Road 100	4/1/2019	4/1/2019	
Sultana	Repair road surface by hand patching	Road 96 from Avenue 416 to Avenue 424	5/9/2019	5/9/2019	
Sultana	Repair road surface by hand patching	Avenue 424 from Road 104 to Road 120	5/17/2019	5/17/2019	
Sultana	Repair road surface by hand patching	Avenue 412 from Road 104 to Road 112	5/24/2019	5/24/2019	
Sultana	Repair road surface by hand patching	Road 112 from Avenue 408 to Avenue 416	5/24/2019	5/24/2019	
Sultana	Repair road surface by hand patching	Road 112 from Avenue 400 to Avenue 408	5/24/2019	5/24/2019	1,860.77
Three Rivers	Repair road surface by hand patching	Grouse Valley Road from South Fork Drive to end	4/2/2019	4/3/2019	
Three Rivers	Repair road surface by hand patching	South Fork Drive from Mile Post 1 to Mile Post 6	4/2/2019	4/4/2019	
Three Rivers	Repair road surface by hand patching	Oak Grove Drive at Hammond Drive	4/11/2019	4/11/2019	
Three Rivers	Repair road surface by hand patching	Hammond Drive from Oak Grove Drive to Sierra King Drive	4/11/2019	4/11/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road at Milk Ranch Road	4/11/2019	4/11/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 7.5 to Mile Post 10	4/15/2019	4/19/2019	
Three Rivers	Large area Patching with grader "Blade Patch"	Mineral King Road at Mile Post 7.5	4/17/2019	4/23/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 4.5 to Mile Post 8	4/23/2019	4/23/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from State Highway 198 to Mile Post 1.5	4/25/2019	4/25/2019	
Three Rivers	Repair road surface by hand patching	North Fork Drive from Mile Post 0 to Mile Post 7	5/1/2019	5/1/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 0 to Mile Post 2.5	5/1/2019	5/1/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 2.5 to Mile Post 4	5/3/2019	5/3/2019	
Three Rivers	Repair road surface by hand patching	Old Three Rivers Road at 40676	5/7/2019	5/7/2019	
Three Rivers	Repair road surface by hand patching	Mineral King Road from Mile Post 3 to Mile Post 8	5/6/2019	5/8/2019	
Three Rivers	Repair road surface by hand patching	Hammond Drive at 45451	5/17/2019	5/17/2019	
Three Rivers	Repair road surface by hand patching	South Fork Drive from Mile Post 0 to Mile Post 7	5/17/2019	5/17/2019	
Three Rivers	Repair road surface by hand patching	South Fork Drive from Mile Post 6.5 to Mile Post 8.5	5/21/2019	5/21/2019	
Three Rivers	Repair road surface by hand patching	North Fork Drive from State Highway 198 to Mile Post 2	5/21/2019	5/21/2019	
Three Rivers	Repair road surface by hand patching	Ferndale Drive from Grouse Drive to End	5/22/2019	5/22/2019	
Three Rivers	Repair road surface by hand patching	Grouse Drive West of Ferndale Drive	5/22/2019	5/22/2019	
Three Rivers	Repair road surface by hand patching	Oakridge Drive from Grouse Drive to End	5/22/2019	5/22/2019	
Three Rivers	Repair road surface by hand patching	North Fork Drive from Mile Post 6.5 to Mile Post 7.5	5/22/2019	5/22/2019	
Three Rivers	Repair road surface by hand patching	Skyline Drive from State Highway 198 to End	5/31/2019	5/31/2019	
Three Rivers	Repair road surface by hand patching	Craig Drive from Skyline Drive to End	5/31/2019	5/31/2019	
Three Rivers	Repair road surface by hand patching	Manzanita Drive from Skyline Drive to End	5/31/2019	5/31/2019	
Three Rivers	Repair road surface by hand patching	Dinely Drive from State Highway 198 to End	5/31/2019	5/31/2019	
Three Rivers	Repair road surface by hand patching	Dinely Drive from Mile Post 0 to Mile Post 2	6/7/2019	6/7/2019	14,892.66
Traver	Repair road surface by hand patching	Diagonal 60 from Avenue 352 to Avenue 360	3/28/2019	3/28/2019	
Traver	Repair road surface by hand patching	Merritt Drive West of Burke Drive	4/19/2019	4/19/2019	
Traver	Repair road surface by hand patching	Avenue 368 from State Highway 99 to Road 52	4/23/2019	4/23/2019	
Traver	Repair road surface by hand patching	Avenue 368 from State Highway 99 to Road 60	6/11/2019	6/11/2019	
Traver	Repair road surface by hand patching	Road 52 from Avenue 368 to End	6/11/2019	6/11/2019	757.14
East Kingsburg	Repair road surface by hand patching	Road 28 from Avenue 386 to Avenue 392	3/19/2019	3/19/2019	
East Kingsburg	Repair road surface by hand patching	Road 34 from Avenue 384 to Avenue 393	3/19/2019	3/19/2019	
East Kingsburg	Repair road surface by hand patching	Avenue 384 at Diagonal 23	3/19/2019	3/19/2019	
East Kingsburg	Repair road surface by hand patching	Road 36 North of Avenue 400	3/20/2019	3/20/2019	
East Kingsburg	Repair road surface by hand patching	Road 32 at Avenue 408	4/1/2019	4/1/2019	
East Kingsburg	Repair road surface by hand patching	Road 34 from Avenue 384 to Avenue 390	4/1/2019	4/1/2019	
East Kingsburg	Repair road surface by hand patching	Road 48 from Avenue 400 to Avenue 408	4/3/2019	4/3/2019	
East Kingsburg	Repair road surface by hand patching	Road 34 from Avenue 393 to Avenue 396	4/3/2019	4/3/2019	
East Kingsburg	Repair road surface by hand patching	Road 28 from Avenue 400 to end	4/10/2019	4/10/2019	
East Kingsburg	Repair road surface by hand patching	Road 24 from Avenue 396 to Avenue 400	4/10/2019	4/10/2019	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

East Kingsburg	Repair road surface by hand patching	Avenue 408 from Road 24 to Road 32	4/11/2019	4/11/2019	
East Kingsburg	Repair road surface by hand patching	Avenue 404 from Road 24 to Kingsburg City Limit	4/11/2019	4/11/2019	
East Kingsburg	Repair road surface by hand patching	Road 36 North of Avenue 400	4/11/2019	4/11/2019	
East Kingsburg	Repair road surface by hand patching	Avenue 404 from Road 40 to Road 48	5/17/2019	5/17/2019	
East Kingsburg	Repair road surface by hand patching	Avenue 390 from Road 28 to Road 34	5/17/2019	5/17/2019	2,431.70
Elderwood	Repair road surface by hand patching	Road 206 from Avenue 384 to Avenue 388	6/21/2019	6/21/2019	179.51
Patterson Tract	Repair road surface by hand patching	Avenue 328 from Road 132 to Road 140	4/3/2019	4/3/2019	
Patterson Tract	Repair road surface by hand patching	Avenue 328 from Road 128 to Road 132	5/9/2019	5/10/2019	
Patterson Tract	Repair road surface by hand patching	Avenue 328 from Road 132 to Road 140	5/21/2019	5/21/2019	
Patterson Tract	Repair road surface by hand patching	Avenue 320 from State Highway 63 to Road 132	6/4/2019	6/4/2019	
Patterson Tract	Repair road surface by hand patching	Bermuda Street from Road 122 to Road 124	6/4/2019	6/4/2019	
Patterson Tract	Large area Patching with grader "Blade Patch"	Road 121 from Avenue 322 to End	6/4/2019	6/5/2019	
Patterson Tract	Large area Patching with grader "Blade Patch"	Avenue 320 from State Highway 63 to Road 132	6/4/2019	6/5/2019	
Patterson Tract	Repair road surface by hand patching	Avenue 328 from Road 127 to Road 132	6/13/2019	6/13/2019	
Patterson Tract	Repair road surface by hand patching	Avenue 328 from Road 124 to Road 132	6/21/2019	6/21/2019	7,391.86
Yetttem	Repair road surface by hand patching	Avenue 376 at Road 144	3/20/2019	3/20/2019	
Yetttem	Repair road surface by hand patching	Road 140 from Avenue 384 to Avenue 392	3/25/2019	3/25/2019	
Yetttem	Repair road surface by hand patching	Avenue 392 from Road 136 to Road 144	3/25/2019	3/25/2019	
Yetttem	Repair road surface by hand patching	Road 136 from Avenue 384 to Avenue 400	3/26/2019	3/26/2019	
Yetttem	Repair road surface by hand patching	Road 140 South of Avenue 384	5/9/2019	5/9/2019	
Yetttem	Repair road surface by hand patching	Avenue 376 from Road 144 to Road 156	6/6/2019	6/6/2019	1,473.95
Richgrove	Repair road surface by hand patching	Grove Drive from Diagonal 205 to Road 210	3/25/2019	3/29/2019	
Richgrove	Repair road surface by hand patching	Road 192 from Avenue 0 to Avnuue 8	4/12/2019	4/12/2019	587.52
Terra Bella	Repair road surface by hand patching	Avenue 14 from Diagonal 238 to Highway 65	3/18/2019	3/18/2019	
Terra Bella	Repair road surface by hand patching	Road 248 from Avenue 88 to Avenue 92	3/25/2019	3/25/2019	
Terra Bella	Repair road surface by hand patching	Avenue 88 from Road 234 State Route 65	4/5/2019	4/5/2019	
Terra Bella	Repair road surface by hand patching	Road 234 from Avenue 95 to Avenue 88	4/5/2019	4/5/2019	
Terra Bella	Repair road surface by hand patching	Avenue 96 from Road 240 to Road 248	4/11/2019	4/11/2019	
Terra Bella	Repair road surface by hand patching	Avenue 96 from Road 236 to Road 256	4/18/2019	4/18/2019	
Terra Bella	Repair road surface by hand patching	Avenue 100 from Road 236 to Road 248	4/30/2019	4/30/2019	
Terra Bella	Repair road surface by hand patching	Camphor Avenue from Road 237 to road 238	5/15/2019	5/15/2019	3,160.96
Porterville	Repair road surface by hand patching	Road 192 from Avenue 144 to Avenue 152	3/18/2019	3/28/2019	
Porterville	Repair road surface by hand patching	Avenue 152 from Road 212 to Magnolia/Cedar	5/15/2019	5/15/2019	2,301.20
Camp Nelson	Repair road surface by hand patching	Mountain Road 197C at End	4/1/2019	4/1/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 196C at Highway 190	4/1/2019	4/1/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Highway 190 to Mountain Road 191C	4/1/2019	4/1/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 191C at End	4/1/2019	4/1/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 191C at Mountain Road 205A	4/1/2019	4/1/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 195F from End to Highway 190	5/13/2019	5/13/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 190A to Mountain Road 197	5/30/2019	5/30/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 192A from End to Mountain Road 193A	6/4/2019	6/4/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Highway 190 to Mountain Road 195A	6/4/2019	6/4/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 195A to Mountain Road 200	6/11/2019	6/11/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 191C from Mountain Road 193A to Mountain Road 187	6/11/2019	6/11/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 201 from Mountain Road 199A to Mountain Road 200A	6/11/2019	6/11/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 200A from Mountain Road 201 to Mountain Road 193A	6/11/2019	6/18/2019	
Camp Nelson	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 200A to Mountain Road 188	6/18/2019	6/18/2019	7,394.69
Pierpoint	Repair road surface by hand patching	Mountain Road 192C from Highway 190 to End	5/29/2019	5/29/2019	
Pierpoint	Repair road surface by hand patching	Mountain Road 193C from Mountain Road 192C to End	5/29/2019	5/29/2019	
Pierpoint	Repair road surface by hand patching	Mountain Road 194F from Mountain Road 192C to End	5/29/2019	5/29/2019	1,152.30
Cedar Slope	Repair road surface by hand patching	Mountain Road 216 from Circle Way to Redwood Drive	4/25/2019	4/25/2019	518.20
Western Divide	Repair road surface by hand patching	Mountain Road 107 from Milepost 2 to Milepost 8	4/25/2019	4/25/2019	
Western Divide	Repair road surface by hand patching	Mountain Road 107 from Highway 190 to Mountain Road 50	6/20/2019	6/20/2019	3,721.33
M216	Repair road surface by hand patching	Avenue 238 west of Road 224	6/10/2019	6/10/2019	165.97

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs						
	Belknap	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 191C to Mountain Road 197	4/10/2019	4/10/2019	460.03
Measure R Expenditure Allocation						Amount Spent this Quarter
Rural Roads						
	Rural	Repair road surface by hand patching	Avenue 120 from Road 112 to Road 104	4/1/19	4/2/19	
	Rural	Repair road surface by hand patching	Road 96 from Avenue 97 to Avenue 88	4/2/19	4/2/19	
	Rural	Repair road surface by hand patching	Road 88 from Avenue 120 to Avenue 128	4/2/19	4/2/19	
	Rural	Repair road surface by hand patching	Avenue 120 form Road 104 to Road 97	4/3/19	4/3/19	
	Rural	Repair road surface by hand patching	Avenue 240 from Road 212 to Road 216	4/3/19	4/3/19	
	Rural	Repair road surface by hand patching	Avenue 245 from Road 2112 to Road 216	4/3/19	4/3/19	
	Rural	Repair road surface by hand patching	Avenue 128 from Road 80 to Road 112	4/3/19	4/3/19	
	Rural	Repair road surface by hand patching	Road 36 from Avenue 236 to Avenue 228	4/4/19	4/4/19	
	Rural	Repair road surface by hand patching	Avenue 120 from Road 97 to Road 92	4/4/19	4/4/19	
	Rural	Repair road surface by hand patching	Avenue 128 from Road 88 to Road 104	4/4/19	4/4/19	
	Rural	Repair road surface by hand patching	Road 96 from Avenue 120 to Avenue 128	4/5/19	4/5/19	
	Rural	Repair road surface by hand patching	Road 96 from Avenue 128 to Avenue 132	4/5/19	4/5/19	
	Rural	Repair road surface by hand patching	Avenue 128 from Road 112 to Road 104	4/8/19	4/8/19	
	Rural	Repair road surface by hand patching	Road 104 south of Avenue 128	4/8/19	4/8/19	
	Rural	Repair road surface by hand patching	Avenue 120 from Road 96 to Road 90	4/8/19	4/8/19	
	Rural	Repair road surface by hand patching	Road 80 from Avenue 176 to Avenue 160	4/9/19	4/9/19	
	Rural	Repair road surface by hand patching	Avenue 176 from Road 80 to the west	4/9/19	4/9/19	
	Rural	Repair road surface by hand patching	Avenue 120 from Road 96 to Road 88	4/9/19	4/9/19	
	Rural	Repair road surface by hand patching	Avenue 176 from Road 80 to Road 57	4/10/19	4/10/19	
	Rural	Repair road surface by hand patching	Road 52 from Avenue 200 to Avenue 208	4/10/19	4/10/19	
	Rural	Repair road surface by hand patching	Avenue 120 from Road 88 to the west	4/10/19	4/10/19	
	Rural	Repair road surface by hand patching	Road 128 at Avenue 180	4/10/19	4/10/19	
	Rural	Repair road surface by hand patching	Avenue 176 from Road 56 to Road 51	4/11/19	4/11/19	
	Rural	Repair road surface by hand patching	Avenue 304 at Road 52	4/11/19	4/11/19	
	Rural	Repair road surface by hand patching	Zumwalt from West to Enterprise	4/11/19	4/11/19	
	Rural	Repair road surface by hand patching	Avenue 280 east of Road 148	4/11/19	4/11/19	
	Rural	Repair road surface by hand patching	Avenue 216 from Road 84 to Road 44	4/12/19	4/12/19	
	Rural	Repair road surface by hand patching	Avenue 216 from Road 84 to Road 44	4/15/19	4/15/19	
	Rural	Repair road surface by hand patching	Avenue 176 from Road 51 east of Road 32	4/15/19	4/15/19	
	Rural	Repair road surface by hand patching	Avenue 120 from Road 88 to Road 72	4/15/19	4/15/19	
	Rural	Repair road surface by hand patching	Avenue 200 from Spacer to Elk Bayou	4/15/19	4/15/19	
	Rural	Repair road surface by hand patching	Avenue 120 from Road 88 to Road 72	4/16/19	4/16/19	
	Rural	Repair road surface by hand patching	A368 pit, Rankin, A112 pit, haul matl	4/16/19	4/16/19	
	Rural	Repair road surface by hand patching	Road 48 from Avenue 184 to Avenue 192	4/16/19	4/16/19	
	Rural	Repair road surface by hand patching	Avenue 176 from Road 51 to Road 29	4/16/19	4/16/19	
	Rural	Repair road surface by hand patching	Avenue 256 from Road 63 to Road 108	4/16/19	4/16/19	
	Rural	Repair road surface by hand patching	Road 96 at Addie	4/16/19	4/16/19	
	Rural	Repair road surface by hand patching	Avenue 216 from Road 88 to Road80	4/16/19	4/16/19	
	Rural	Repair road surface by hand patching	Avenue 216 from Road 80 to Road 52	4/17/19	4/17/19	
	Rural	Repair road surface by hand patching	Diagonal 122 from Avenue 120 to Avenue 118	4/17/19	4/17/19	
	Rural	Repair road surface by hand patching	Avenue 120 from Road 80 to Road 72	4/17/19	4/17/19	
	Rural	Repair road surface by hand patching	Road 80 from Avenue 144 to Avenue 96	4/18/19	4/18/19	
	Rural	Repair road surface by hand patching	Road 96 south of Avenue 152	4/18/19	4/18/19	
	Rural	Repair road surface by hand patching	Avenue 184 from Road 112 to Road 80	4/19/19	4/19/19	
	Rural	Repair road surface by hand patching	Avenue 128 from Road 80 to Road 96	4/22/19	4/22/19	
	Rural	Repair road surface by hand patching	Road 80 from Avenue 128 to Avenue 104	4/22/19	4/22/19	
	Rural	Repair road surface by hand patching	Road 80 from Avenue 120 to Avenue 96	4/22/19	4/22/19	
	Rural	Repair road surface by hand patching	Avenue 96 from Road 80 to Road 76	4/22/19	4/22/19	
	Rural	Repair road surface by hand patching	Avenue 96 from Road 80 to Road 96	4/24/19	4/24/19	
	Rural	Repair road surface by hand patching	Avenue 88 from Road 96 to Road 88	4/24/19	4/24/19	

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Avenue 200 from Spacer to Road 124	4/24/19	4/24/19
Rural	Repair road surface by hand patching	Spacer Drive north of Avenue 200	4/24/19	4/24/19

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Avenue 88 from Road 96 to Road 84	4/25/19	4/25/19
Rural	Repair road surface by hand patching	Road 84 from Avenue 88 to Avenue 84	4/25/19	4/25/19
Rural	Repair potholes with Road Patcher	Road 152 from S.R. 216 to S.R. 198	4/25/19	4/25/19
Rural	Repair potholes with Road Patcher	Road 156 from S.R. 198 to Avenue 256	4/25/19	4/25/19
Rural	Repair potholes with Road Patcher	Road 164 from Avenue 256 to F.C.L.	4/25/19	4/25/19
Rural	Repair road surface by hand patching	Road 96 from Avenue 204 to Avenue 160	4/25/19	4/25/19
Rural	Repair road surface by hand patching	Bailey at 7505	4/29/19	4/29/19
Rural	Repair road surface by hand patching	Road 96 from Avenue 153 to Avenue 144	4/29/19	4/29/19
Rural	Repair road surface by hand patching	Avenue 216 from Road 84 to Road 44	4/30/19	4/30/19
Rural	Repair road surface by hand patching	Road 44 from Avenue 216 to Avenue 208	4/30/19	4/30/19
Rural	Repair potholes with Road Patcher	Avenue 288 from V.C.L. to F.C.L.	4/30/19	4/30/19
Rural	Repair potholes with Road Patcher	Avenue 272 from Road 140 to Road 132	4/30/19	4/30/19
Rural	Repair road surface by hand patching	Avenue 104 from Road 152 to Road 136	5/1/19	5/1/19
Rural	Repair road surface by hand patching	Road 140 from Avenue 140 to Avenue 96	5/1/19	5/1/19
Rural	Repair road surface by hand patching	Avenue 208 east of Road 140	5/2/19	5/2/19
Rural	Repair road surface by hand patching	Avenue 228 from Road 130 to Road 124	5/2/19	5/2/19
Rural	Repair road surface by hand patching	Avenue 112 from Road 124 to Road 136	5/2/19	5/2/19
Rural	Repair road surface by hand patching	Road 136 from Avenue 192 to Avenue 190	5/2/19	5/2/19
Rural	Repair road surface by hand patching	Road 44 from Avenue 216 to Avenue 192	5/3/19	5/3/19
Rural	Repair road surface by hand patching	Road 124 south of Avenue 271	5/3/19	5/3/19
Rural	Repair road surface by hand patching	Avenue 304 at Road 64	5/3/19	5/3/19
Rural	Repair road surface by hand patching	Road 44 from Avenue 248 to south of Avenue 264	5/3/19	5/3/19
Rural	Repair road surface by hand patching	Road 140 from Avenue 104 to Avenue 96	5/8/19	5/8/19
Rural	Repair road surface by hand patching	Avenue 112 from Road 136 to Road 124	5/8/19	5/8/19
Rural	Repair road surface by hand patching	Road 44 from Avenue 264 to Avenue 248	5/8/19	5/8/19
Rural	Repair road surface by hand patching	Road 56 from Avenue 272 to Avenue 280	5/8/19	5/8/19
Rural	Repair road surface by hand patching	Avenue 144 from Road 96 to S.R. 43	5/10/19	5/10/19
Rural	Repair road surface by hand patching	Road 136 from Spacer to Avenue 192	5/10/19	5/10/19
Rural	Repair road surface by hand patching	Road 152 from Avenue 196 to Avenue 256	5/13/19	5/13/19
Rural	Repair road surface by hand patching	Road 136 from Avenue 192 to the south	5/13/19	5/13/19
Rural	Repair road surface by hand patching	Avenue 144 from Road 96 to S.R. 43	5/13/19	5/13/19
Rural	Repair road surface by hand patching	Road 48 from Avenue 264 to Avenue 272	5/13/19	5/13/19
Rural	Repair road surface by hand patching	Road 56 from Avenue 280 to Avenue 284	5/13/19	5/13/19
Rural	Repair potholes with Road Patcher	Road 168 from Avenue 296 to St. Johns Br.	5/13/19	5/13/19
Rural	Repair potholes with Road Patcher	Road 60 from Avenue 308 to Avenue 320	5/13/19	5/13/19
Rural	Repair potholes with Road Patcher	Road 70 from Avenue 308 to Avenue 310	5/13/19	5/13/19
Rural	Repair road surface by hand patching	Avenue 228 at Road 140	5/14/19	5/14/19
Rural	Repair road surface by hand patching	Road 136 from Avenue 192 to Avenue 160	5/14/19	5/14/19
Rural	Repair road surface by hand patching	Road 56 from Avenue 284 to S.R. 198	5/14/19	5/14/19
Rural	Repair road surface by hand patching	Avenue 224 from Road 100 to Road 52	5/14/19	5/14/19
Rural	Repair road surface by hand patching	Road 20 from Avenue 192 to Avenue 199	5/15/19	5/15/19
Rural	Large area patching with Grader, blade patch	Avenue 228 from Road 140 east to end	5/15/19	5/15/19
Rural	Repair road surface by hand patching	Road 136 from Avenue 176 to Avenue 160	5/16/19	5/16/19
Rural	Repair road surface by hand patching	Avenue 240 from Road 140 to Road 152	5/16/19	5/16/19
Rural	Repair road surface by hand patching	Mooney at Pratt	5/16/19	5/16/19
Rural	Repair road surface by hand patching	Avenue 56 from Road 120 to S.H. 43	5/17/19	5/17/19
Rural	Repair road surface by hand patching	Avenue 56 from S.H. 43 to Borchardt	5/20/19	5/20/19
Rural	Repair road surface by hand patching	Avenue 264 from Road 52 to Road 28	5/21/19	5/21/19
Rural	Repair road surface by hand patching	Road 28 from Avenue 232 to Avenue 248	5/21/19	5/21/19
Rural	Repair road surface by hand patching	Road 28 from Avenue 232 to Avenue 248	5/22/19	5/22/19
Rural	Repair road surface by hand patching	Road 28 from Avenue 248 to Avenue 264	5/22/19	5/22/19
Rural	Repair road surface by hand patching	Avenue 54 from Road 56 to Road 38	5/23/19	5/23/19
Rural	Repair road surface by hand patching	Avenue 200 from Spacer to Road 120	5/23/19	5/23/19
Rural	Repair road surface by hand patching	Avenue 152 from Road 112 to Road 104	5/23/19	5/23/19
Rural	Repair road surface by hand patching	Road 28 from Avenue 248 to Avenue 256	5/23/19	5/23/19
Rural	Repair road surface by hand patching	Road 28 from Avenue 256 to Avenue 264	5/23/19	5/23/19
Rural	Repair road surface by hand patching	Road 28 from Avenue 248 to Avenue 256	5/23/19	5/23/19

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Avenue 264 from Road 36 to Road 44	5/23/19	5/23/19
Rural	Repair road surface by hand patching	Avenue 272 west of Road 108	5/24/19	5/24/19
Rural	Repair road surface by hand patching	Avenue 200 from Spacer to Road 124	5/24/19	5/24/19
Rural	Repair road surface by hand patching	Avenue 200 from Avenue 124 to Laspina	5/24/19	5/24/19
Rural	Repair road surface by hand patching	Avenue 160 from Road 96 to Road 112	5/24/19	5/24/19
Rural	Repair road surface by hand patching	Avenue 184 from Road 96 to Road 80	5/24/19	5/24/19
Rural	Repair road surface by hand patching	Avenue 200 from Spacer to Elk Bayou	5/28/19	5/28/19
Rural	Repair potholes with Road Patcher	Road 128 from Avenue 72 to Avenue 76	5/28/19	5/28/19
Rural	Repair road surface by hand patching	Beacon from Canal to Pratt	5/30/19	5/30/19
Rural	Repair road surface by hand patching	Avenue 120 from S.H. 99 to Road 124	5/30/19	5/30/19
Rural	Repair road surface by hand patching	Avenue 248 from Road 124 to Road 130	5/30/19	5/30/19
Rural	Repair road surface by hand patching	Avenue 120 from Road 124 to Road 144	5/31/19	5/31/19
Rural	Repair potholes with Road Patcher	Avenue 16 from S.H.99 to Road 112	6/5/19	6/5/19
Rural	Repair potholes with Road Patcher	Avenue 24 from Road 144 to Road 128	6/5/19	6/5/19
Rural	Repair potholes with Road Patcher	Avenue 24 from Road 144 to Road 128	6/6/19	6/6/18
Rural	Repair potholes with Road Patcher	Avenue 16 from S.H. 99 to S.H. 43	6/6/19	6/6/19
Rural	Repair potholes with Road Patcher	Avenue 16 from S.H. 43 to S.H. 99	6/10/19	6/10/19
Rural	Repair potholes with Road Patcher	Road 128 from Avenue 16 to Avenue 0	6/10/19	6/10/19
Rural	Repair potholes with Road Patcher	Road 128 from Avenue 0 to Avenue 40	6/11/19	6/11/19
Rural	Repair potholes with Road Patcher	Road 168 from Avenue 296 to Avenue 310	6/24/19	6/24/19
Rural	Repair potholes with Road Patcher	Road 156 from S.H. 198 to Avenue 288	6/24/19	6/24/19
Rural	Repair potholes with Road Patcher	Avenue 288 from Road 168 to Road 176	6/24/19	6/24/19
Rural	Repair road surface by hand patching	Road 192 from Avenue 218 to Avenue 220*	3/18/2019	3/18/2019
Rural	Repair potholes with Road Patcher	Avenue 170 east of Road 224	3/18/2019	3/18/2019
Rural	Repair road surface by hand patching	Road 248 from Avenue 196 to Avenue 208	3/19/2019	3/19/2019
Rural	Repair road surface by hand patching	Avenue 226 at Road 236	3/19/2019	3/19/2019
Rural	Haul Measure R Material	Plant to Avenue 368 Pit and Rankin pit	3/20/2019	3/20/2019
Rural	Haul Measure R Material	Plant to Avenue 112 Pit	3/21/2019	3/21/2019
Rural	Repair potholes with Road Patcher	Road 208 from Avenue 160 to Avenue 176	3/25/2019	3/25/2019
Rural	Repair potholes with Road Patcher	Avenue 176 from Road 208 to Road 224	3/25/2019	3/25/2019
Rural	Repair road surface by hand patching	Avenue 230 west of Road 242	3/25/2019	3/25/2019
Rural	Repair road surface by hand patching	Avenue 230 from Road 204 to Road 209*	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Road 204 from Avenue 164 to Avenue 172	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Avenue 220 from Road 248 to Road 254	4/2/2019	4/2/2019
Rural	Repair potholes with Road Patcher	Road 216 from Avenue 184 to Avenue 188	4/2/2019	4/2/2019
Rural	Repair road surface by hand patching	Avenue 178 at Diagonal 242	4/4/2019	4/4/2019
Rural	Repair road surface by hand patching	Avenue 228 from Road 196 to Highway 65	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Avenue 208 from Road 244 to Road 252	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Road 252 from Avenue 208 to Avenue 220	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Avenue 272 from Diagonal 211 to Road 228	4/8/2019	4/8/2019
Rural	Repair road surface by hand patching	Road 276 from Avenue 166 to Mountain Road 178	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 176 from Road 276 to Road 292	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 176 from Mountain Road 176B to Mountain Road 171A	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 304 from Road 180 to Diagonal 184B	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Road 254 from Avenue 204 to Avenue 208	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 224 from Road 240 to Road 244	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Diagonal 252 from Road 254 to Road 256	4/10/2019	4/10/2019
Rural	Repair road surface by hand patching	Road 256 from Diagonal 252 to Avenue 196	4/10/2019	4/10/2019
Rural	Repair road surface by hand patching	Avenue 169 at Road 254	4/10/2019	4/10/2019
Rural	Haul Measure R Material	Avenue 112 Pit to Camp Nelson Road Yard	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Avenue 242 from Road 188 to Road 196	4/12/2019	4/12/2019
Rural	Repair road surface by hand patching	Road 196 from Highway 198 to Avenue 300	4/16/2019	4/16/2019
Rural	Repair road surface by hand patching	Road 224 from Avenue 224 to Avenue 228	4/16/2019	4/16/2019
Rural	Haul Measure R Material	Deer Creek Plant to Avenue 112 Pit, Avenue 368 Pit, and Rankin Pit	4/16/2019	4/16/2019
Rural	Repair road surface by hand patching	Reid at Plano	4/17/2019	4/17/2019
Rural	Repair road surface by hand patching	Plano north and south of Reid	4/17/2019	4/17/2019
Rural	Repair road surface by hand patching	Avenue 230 at Road 224	4/17/2019	4/17/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Avenue 212 east of Road 232	4/17/2019	4/17/2019
Rural	Repair road surface by hand patching	Avenue 170 at Road 224	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Avenue 176 at Road 224	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Avenue 176 from Road 208 to Road 216	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Avenue 176 east of Road 202	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Avenue 176 west of Road 192	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Road 284 from Mountain Road 146 to Drive 254B	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Road 224 south of Avenue 188	4/23/2019	4/23/2019
Rural	Repair road surface by hand patching	Road 196 south of Avenue 232	4/23/2019	4/23/2019
Rural	Repair road surface by hand patching	Avenue 170 at Friant Kern Canal	4/23/2019	4/23/2019
Rural	Repair road surface by hand patching	Avenue 212 from Road 228 to Road 232	4/24/2019	4/26/2019
Rural	Repair road surface by hand patching	Avenue 160 at Friant Kern Canal	4/30/2019	5/6/2019
Rural	Repair road surface by hand patching	25866 Road 180	5/1/2019	5/1/2019
Rural	Repair road surface by hand patching	Road 220 from Diagonal 242 to Avenue 224	5/9/2019	5/9/2019
Rural	Repair road surface by hand patching	Avenue 300 from Road 192 to Road 192	5/10/2019	5/10/2019
Rural	Repair road surface by hand patching	Avenue 304 from Road 192 to Road 196	5/10/2019	5/10/2019
Rural	Repair road surface by hand patching	Road 188 from Avenue 192 to Avenue 216	5/10/2019	5/10/2019
Rural	Repair road surface by hand patching	Road 188 from Avenue 242 to Avenue 256	5/10/2019	5/10/2019
Rural	Repair road surface by hand patching	Road 192 from Avenue 300 to Avenue 304	5/10/2019	5/10/2019
Rural	Repair road surface by hand patching	Avenue 178 from Road 224 to Friant Kern Canal	5/10/2019	5/10/2019
Rural	Repair road surface by hand patching	Avenue 160 at Road 212	5/14/2019	5/14/2019
Rural	Repair road surface by hand patching	Avenue 188 at Road 224	5/15/2019	5/15/2019
Rural	Repair road surface by hand patching	Avenue 208 west of Road 172	5/15/2019	5/15/2019
Rural	Repair road surface by hand patching	Avenue 242 from Road 188 to Road 196	5/17/2019	5/17/2019
Rural	Repair road surface by hand patching	Avenue 256 at Tule River	5/21/2019	5/21/2019
Rural	Repair road surface by hand patching	Road 168 south of Avenue 184	5/21/2019	5/21/2019
Rural	Repair road surface by hand patching	Road 228 from Avenue 200 to Avenue 232	5/21/2019	5/21/2019
Rural	Repair road surface by hand patching	Road 228 at Avenue 238	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Avenue 216 from Road 228 to Road 242	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Road 236 north of Avenue 216	5/28/2019	5/28/2019
Rural	Repair road surface by hand patching	Avenue 220 at Road 236	5/28/2019	6/3/2019
Rural	Repair road surface by hand patching	Road 216 north of Avenue 168	6/5/2019	6/5/2019
Rural	Haul Measure R Material	Deer Creek Plant to Avenue 368 Pit	6/5/2019	6/6/2019
Rural	Repair road surface by hand patching	Diagonal 242 at Bruce Drive	6/7/2019	6/7/2019
Rural	Repair road surface by hand patching	Avenue 238 west of Road 224	6/10/2019	6/10/2019
Rural	Repair road surface by hand patching	Avenue 228 at Friant Kern Canal	6/14/2019	6/14/2019
Rural	Repair road surface by hand patching	Road 256 from Avenue 196 to Avenue 200	6/14/2019	6/14/2019
Rural	Repair road surface by hand patching	Avenue 220 west of Road 254	6/14/2019	6/14/2019
Rural	Repair road surface by hand patching	Avenue 171 at Friant Kern Canal	6/21/2019	6/21/2019
Rural	Repair road surface by hand patching	Road 228 from Avenue 220 to Avenue 228	6/21/2019	6/21/2019
Rural	Repair road surface by hand patching	Road 72 at Avenue 424	3/18/2019	3/18/2019
Rural	Repair road surface by hand patching	Avenue 368 from Road 64 to Road 80	3/19/2019	3/19/2019
Rural	Haul material for future Blade Patch projects	Haul to Avenue 368 Pit for storage	3/20/2019	3/21/2019
Rural	Repair road surface by hand patching	Road 64 South of Avenue 424	3/20/2019	3/20/2019
Rural	Repair road surface by hand patching	Road 150 at Avenue 352	3/21/2019	3/21/2019
Rural	Repair road surface by hand patching	Road 20 from Avenue 360 to Ward Drive	3/21/2019	3/21/2019
Rural	Repair road surface by hand patching	Avenue 328 East of State Highway 99	3/21/2019	3/21/2019
Rural	Repair road surface by hand patching	Road 158 at Avenue 344	3/21/2019	3/21/2019
Rural	Repair road surface by hand patching	Avenue 344 at Road 156	3/21/2019	3/21/2019
Rural	Repair road surface by hand patching	Road 60 South of Avenue 360	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Road 156 at Avenue 344	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Road 32 South of Avenue 416	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Avenue 328 West of Road 80	3/27/2019	3/27/2019
Rural	Repair road surface by hand patching	Road 172 from Avenue 344 to Avenue 384	3/27/2019	3/27/2019
Rural	Repair road surface by hand patching	Avenue 328 from Road 204 to Road 212	3/28/2019	3/28/2019
Rural	Repair road surface by hand patching	Avenue 352 from Road 20 to Diagonal 60	3/28/2019	3/28/2019
Rural	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 352	3/28/2019	3/28/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Road 114 from Avenue 416 to Avenue 424	3/28/2019	3/28/2019
Rural	Repair road surface by hand patching	Road 88 from Avenue 424 to Avenue 432	3/29/2019	3/29/2019
Rural	Repair road surface by hand patching	Avenue 416 from Road 154 to Road 168	3/29/2019	3/29/2019
Rural	Repair road surface by hand patching	Millwood Drive at 34850	4/1/2019	4/1/2019
Rural	Repair road surface by hand patching	Avenue 384 East of Road 12	4/1/2019	4/1/2019
Rural	Repair road surface by hand patching	Avenue 432 from Road 80 to Road 88	4/3/2019	4/3/2019
Rural	Repair road surface by hand patching	Avenue 328 from Road 140 to Road 152	4/3/2019	4/3/2019
Rural	Repair road surface by hand patching	Avenue 404 from Road 88 to Road 96	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Road 88 from Avenue 404 to Avenue 406	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Road 44 at Avenue 428	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Avenue 328 at Road 76	4/8/2019	4/8/2019
Rural	Repair road surface by hand patching	Avenue 320 East of Road 156	4/8/2019	4/8/2019
Rural	Repair road surface by hand patching	Road 160 from Avenue 344 to Avenue 360	4/8/2019	4/8/2019
Rural	Repair road surface by hand patching	Road 140 from Avenue 336 to Avenue 352	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 336 from Road 172 to State Highway 216	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 328 from State Highway 99 to Road 76	4/10/2019	4/10/2019
Rural	Repair road surface by hand patching	Road 108 from Avenue 320 to Avenue 328	4/10/2019	4/10/2019
Rural	Repair road surface by hand patching	Avenue 352 at Road 176	4/10/2019	4/10/2019
Rural	Repair road surface by hand patching	Avenue 356 from Road 172 to Road 176	4/10/2019	4/10/2019
Rural	Repair road surface by hand patching	Avenue 352 at Road 152	4/10/2019	4/10/2019
Rural	Repair road surface by hand patching	Avenue 352 from Road 148 to Road 156	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Avenue 352 West of Road 148	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Road 156 at Avenue 344	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Road 144 from Visalia City Limit to Avenue 328	4/15/2019	4/15/2019
Rural	Repair road surface by hand patching	Road 132 North of Avenue 352	4/15/2019	4/15/2019
Rural	Repair road surface by hand patching	Avenue 428 at Road 88	4/15/2019	4/15/2019
Rural	Repair road surface by hand patching	Road 144 South of Avenue 408	4/17/2019	4/17/2019
Rural	Repair road surface by hand patching	Avenue 400 at Road 140	4/18/2019	4/18/2019
Rural	Repair road surface by hand patching	Road 144 from Avenue 432 to Avenue 436	4/18/2019	4/18/2019
Rural	Repair road surface by hand patching	Road 140 from Avenue 352 to Avenue 360	4/18/2019	4/18/2019
Rural	Repair road surface by hand patching	Road 192 at Avenue 344	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Road 188 from Avenue 336 to Avenue 344	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Road 152 from Avenue 344 to Avenue 352	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Avenue 360 from Road 100 to Road 112	4/19/2019	4/19/2019
Rural	Repair road surface by hand patching	Road 84 from Avenue 384 to Avenue 400	4/22/2019	4/22/2019
Rural	Large area Patching with grader "Blade Patch"	Worth Drive from Road 278 to Road 284	4/22/2019	4/23/2019
Rural	Repair road surface by hand patching	Avenue 368 from Road 52 to Road 80	4/23/2019	4/23/2019
Rural	Repair road surface by hand patching	Avenue 328 from State Highway 99 to Road 80	4/24/2019	4/24/2019
Rural	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 360	4/24/2019	4/24/2019
Rural	Repair road surface by hand patching	Road 192 at Avenue 344	4/24/2019	4/24/2019
Rural	Repair road surface by hand patching	Avenue 336 at State Highway 216	4/24/2019	4/24/2019
Rural	Repair road surface by hand patching	Avenue 336 at 14222	4/25/2019	4/25/2019
Rural	Repair road surface by hand patching	Avenue 336 from State Highway 216 to Road 204	4/26/2019	4/26/2019
Rural	Repair road surface by hand patching	Road 80 at Avenue 368	4/26/2019	4/26/2019
Rural	Repair road surface by hand patching	Avenue 368 from Road 112 to Road 124	4/26/2019	4/26/2019
Rural	Repair road surface by hand patching	Avenue 448 from Road 120 to Road 124	4/26/2019	4/26/2019
Rural	Repair road surface by hand patching	Avenue 426 at Road 64	4/26/2019	4/26/2019
Rural	Repair road surface by hand patching	Avenue 432 from Road 120 to Road 128	4/29/2019	4/29/2019
Rural	Repair road surface by hand patching	Fisher Drive from Road 180 to Road 196	4/29/2019	4/30/2019
Rural	Repair road surface by hand patching	Road 80 from Avenue 320 to Avenue 400	4/30/2019	4/30/2019
Rural	Repair road surface by hand patching	Road 188 from Charter Oak Drive to Avenue 336	4/30/2019	4/30/2019
Rural	Repair road surface by hand patching	Road 124 from Avenue 384 to Avenue 388	5/1/2019	5/1/2019
Rural	Repair road surface by hand patching	Avenue 432 from Road 120 to Road 128	5/1/2019	5/1/2019
Rural	Repair road surface by hand patching	Road 140 from Avenue 352 to Avenue 368	5/1/2019	5/1/2019
Rural	Repair road surface by hand patching	Avenue 424 from Road 88 to Road 96	5/1/2019	5/1/2019
Rural	Repair road surface by hand patching	Road 64 at Avenue 432	5/1/2019	5/1/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Avenue 432 at State Highway 63	5/2/2019	5/2/2019
Rural	Repair road surface by hand patching	Diagonal 60 from Avenue 328 to Avenue 352	5/2/2019	5/2/2019
Rural	Repair road surface by hand patching	Road 124 from Avenue 464 to Avenue 468	5/2/2019	5/2/2019
Rural	Repair road surface by hand patching	Avenue 460 at Road 124	5/2/2019	5/2/2019
Rural	Repair road surface by hand patching	Avenue 404 from Road 96 Road 104	5/3/2019	5/3/2019
Rural	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 80	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Road 42 from Avenue 416 to Avenue 424	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Avenue 320 from Road 140 to Road 148	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Road 76 from Avenue 360 to Avenue 376	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Avenue 392 West of Road 12	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Avenue 392 from Road 8 to Road 12	5/7/2019	5/7/2019
Rural	Repair road surface by hand patching	Road 16 South of Avenue 400	5/7/2019	5/7/2019
Rural	Repair road surface by hand patching	Avenue 360 from Road 52 to Road 80	5/8/2019	5/8/2019
Rural	Repair road surface by hand patching	Road 16 North of Avenue 396	5/8/2019	5/8/2019
Rural	Repair road surface by hand patching	Avenue 396 from Fresno County Line to Road 16	5/9/2019	5/9/2019
Rural	Repair road surface by hand patching	Road 104 at Avenue 432	5/10/2019	5/10/2019
Rural	Repair road surface by hand patching	Avenue 376 from Road 36 to Road 40	5/15/2019	5/15/2019
Rural	Repair road surface by hand patching	Avenue 452 East of Road 120	5/17/2019	5/17/2019
Rural	Repair road surface by hand patching	Road 144 at St. Johns Bridge	5/17/2019	5/17/2019
Rural	Repair road surface by hand patching	Road 144 at Avenue 313	5/17/2019	5/17/2019
Rural	Repair road surface by hand patching	Road 36 at Avenue 376 to Avenue 384	5/17/2019	5/17/2019
Rural	Repair road surface by hand patching	Avenue 456 from Road 120 to Road 124	5/17/2019	5/17/2019
Rural	Repair road surface by hand patching	Avenue 328 from Road 140 to Road 156	5/17/2019	5/17/2019
Rural	Repair road surface by hand patching	Avenue 360 West of Road 80	5/21/2019	5/22/2019
Rural	Repair road surface by hand patching	Avenue 315 from Road 168 to Charter Oak Drive	5/22/2019	5/22/2019
Rural	Repair road surface by hand patching	El Rio Drive from Road 160 to Road 168	5/22/2019	5/22/2019
Rural	Repair road surface by hand patching	Avenue 320 from Road 190 to Road 196	5/22/2019	5/22/2019
Rural	Repair road surface by hand patching	Fisher Drive from Avenue 318 to Road 180	5/22/2019	5/22/2019
Rural	Repair road surface by hand patching	Avenue 318 from Fisher Drive to Road 190	5/22/2019	5/22/2019
Rural	Repair road surface by hand patching	Avenue 430 at Road 68	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Avenue 432 from Road 80 to Road 90	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Avenue 364 from Road 140 to Road 144	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Road 190 from Avenue 318 to Avenue 320	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Road 188 North of Charter Oak Drive	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Charter Oak Drive from Road 168 to Road 188	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Road 124 at Avenue 336	5/23/2019	5/23/2019
Rural	Repair road surface by hand patching	Road 196 North of Lort Drive	5/31/2019	5/31/2019
Rural	Repair road surface by hand patching	Road 74 from Avenue 384 to Avenue 400	5/31/2019	5/31/2019
Rural	Repair road surface by hand patching	Road 52 from Avenue 408 to Avenue 416	6/5/2019	6/5/2019
Rural	Repair road surface by hand patching	Road 52 North of Avenue 424	6/5/2019	6/5/2019
Rural	Repair road surface by hand patching	Avenue 376 from Road 76 to Road 80	6/5/2019	6/5/2019
Rural	Haul material for future Blade Patch projects	Haul to Avenue 368 Pit for storage	6/5/2019	6/6/2019
Rural	Repair road surface by hand patching	Avenue 320 from Road 144 to Road 148	6/6/2019	6/6/2019
Rural	Repair road surface by hand patching	Avenue 368 from Road 132 to Road 140	6/6/2019	6/6/2019
Rural	Repair road surface by hand patching	Road 52 from Avenue 408 to Avenue 416	6/6/2019	6/6/2019
Rural	Repair road surface by hand patching	Road 52 North of Avenue 424	6/6/2019	6/6/2019
Rural	Repair road surface by hand patching	Avenue 376 from Road 76 to Road 80	6/6/2019	6/6/2019
Rural	Repair road surface by hand patching	Avenue 320 from Road 138 to Road 148	6/7/2019	6/7/2019
Rural	Repair road surface by hand patching	Avenue 315 from Road 168 to Charter Oak Drive	6/7/2019	6/7/2019
Rural	Repair road surface by hand patching	Road 132 from Avenue 352 to Avenue 368	6/7/2019	6/7/2019
Rural	Repair road surface by hand patching	Road 156 from Avenue 376 to Cottonwood Creek	6/7/2019	6/7/2019
Rural	Repair road surface by hand patching	Road 52 from Avenue 416 to Avenue 432	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	Avenue 432 from Road 52 to Road 56	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	Avenue 426 from Road 56 to Road 64	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	Avenue 432 at Road 96	6/11/2019	6/11/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Avenue 368 from Road 60 to Road 80	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	Road 48 from Avenue 410 to Avenue 416	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	Avenue 432 from Road 68 to Road 96	6/12/2019	6/12/2019
Rural	Repair road surface by hand patching	Avenue 360 from Road 148 to Road 156	6/13/2019	6/13/2019
Rural	Repair road surface by hand patching	Road 108 from Visalia City Limit to Avenue 328	6/13/2019	6/13/2019
Rural	Repair road surface by hand patching	Avenue 328 East of Road 112	6/13/2019	6/13/2019
Rural	Repair road surface by hand patching	Road 8 South of Avenue 360	6/17/2019	6/17/2019
Rural	Repair road surface by hand patching	Avenue 352 from Road 20 to Diagonal 60	6/21/2019	6/21/2019
Rural	Repair road surface by hand patching	Avenue 344 from Road 164 to State Highway 216	6/21/2019	6/21/2019
Rural	Repair road surface by hand patching	Road 168 from Avenue 308 to Avenue 315	6/21/2019	6/21/2019
Rural	Side walk repair, cement work	Avenue 422 at Road 126	4/10/2019	4/18/2019
Rural	Repair road surface by hand patching	Road 208 rom Avenue 96 to Avenue 88	3/18/2019	3/18/2019
Rural	Repair road surface by hand patching	Indiana from Avenue 128 to Hemlock	3/18/2019	3/18/2019
Rural	Repair road surface by hand patching	Avenue 128 from Newcomb to Road 224	3/18/2019	3/18/2019
Rural	Repair road surface by hand patching	Avenue 32 from Diagonal 205 to Road 208	3/20/2019	3/26/2019
Rural	Haul Material for Measure R	Jaxon Baker to Avenue 368 Pit	3/20/2019	3/20/2019
Rural	Haul Material for Measure R	Jaxon Baker to Rankin Pit	3/20/2019	3/20/2019
Rural	Haul Material for Measure R	Jaxon Baker to Avenue 112 Pit	3/21/2019	3/21/2019
Rural	Repair road surface by hand patching	Avenue 128 from Diagonal 238 to Road 252	3/25/2019	3/25/2019
Rural	Repair road surface by hand patching	Avenue 0 from Diagonal 205 to Road 224	3/25/2019	3/26/2019
Rural	Repair road surface by hand patching	Road 248 at Deer Creek	3/25/2019	3/25/2019
Rural	Repair road surface by hand patching	Gibbons from Plano to Porterville City Limits	3/25/2019	3/25/2019
Rural	Repair road surface by hand patching	Plano from Porterville City Limits to Avenue 128	3/25/2019	3/25/2019
Rural	Repair road surface by hand patching	Avenue 96 from Road 200 to Road 208	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Diagonal 205 from Road 56 to Road 32	3/26/2019	5/14/2019
Rural	Repair road surface by hand patching	Avenue 40 from Road 200 to Road 192	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Road 176 at Avenue 68	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Road 192 at Avenue 88	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Avenue 4 from Road 200 to Diagonal 205	3/26/2019	3/26/2019
Rural	Repair road surface by hand patching	Avenue 40 from Road 200 to Road 144	3/27/2019	3/27/2019
Rural	Repair road surface by hand patching	Road 160 from Avenue 56 to Avenue 0	3/27/2019	3/27/2019
Rural	Repair road surface by hand patching	Road 160 from Avenue 56 to Avenue 88	3/28/2019	3/28/2019
Rural	Repair road surface by hand patching	Road 160 from Avenue 16 to Avenue 0	3/28/2019	3/28/2019
Rural	Repair road surface by hand patching	Road 152 from Avenue 44 to Avenue 48	3/29/2019	3/29/2019
Rural	Repair road surface by hand patching	Road 168 from Avenue 8 to Avenue 16	3/29/2019	3/29/2019
Rural	Repair road surface by hand patching	Avenue 40 from Road 192 to Road 144	3/28/2019	3/28/2019
Rural	Repair road surface by hand patching	Avenue 120 from Road 192 to Road 84	3/29/2019	3/29/2019
Rural	Repair road surface by hand patching	Avenue 120 from Road 192 to Road 144	4/2/2019	4/2/2019
Rural	Large area Patching with grader "Blade Patch"	Avenue 138 west of Road 284	4/3/2019	4/3/2019
Rural	Repair road surface by hand patching	Road 208 from Avenue 128 to Avenue 152	4/5/2019	4/5/2019
Rural	Repair road surface by hand patching	Road 244 at Avenue 124	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 120 from Road 236 to Road 244	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 136 from Road 152 to Road 184	4/9/2019	4/9/2019
Rural	Repair road surface by hand patching	Avenue 136 from Road 232 to Road 236	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Road 232 from Avenue 126 to State Route 190	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Road 208 at Deer Creek	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Road 192 from Avenue 0 to Avenue 8	4/11/2019	4/11/2019
Rural	Repair road surface by hand patching	Avenue 0 from Road 176 to Road 192	4/12/2019	4/15/2019
Rural	Repair road surface by hand patching	Avenue 136 from Road 168 to West Street	4/12/2019	4/12/2019
Rural	Repair road surface by hand patching	Avenue 128 from Road 192 to Road 144	4/17/2019	4/17/2019
Rural	Repair road surface by hand patching	Road 264 from Mountain 109 to Avenue 95	4/18/2019	4/18/2019
Rural	Repair road surface by hand patching	Road 208 from Avenue 96 to Avenue 88	4/18/2019	4/18/2019
Rural	Repair road surface by hand patching	Road 164 from Avenue 96 to Avenue 88	4/18/2019	4/18/2019
Rural	Repair road surface by hand patching	Avenue 16 from Road 168 to Road 160	4/22/2019	4/22/2019
Rural	Repair road surface by hand patching	Avenue 70 from Road 256 to Road 267	4/22/2019	4/22/2019
Rural	Repair road surface by hand patching	Road 267 from Avenue 70 to Avenue 80	4/22/2019	4/22/2019
Rural	Repair road surface by hand patching	Avenue 136 west of Friant Kern Canal	4/29/2019	4/29/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Rural	Repair road surface by hand patching	Avenue 96 west of Road 208	4/30/2019	4/30/2019
Rural	Repair road surface by hand patching	Avenue 56 from Roadk 236 to Road 240	4/30/2019	4/30/2019
Rural	Repair road surface by hand patching	Road 248 from Avenue 60 to Avenue 80	4/30/2019	4/30/2019
Rural	Large area Patching with grader "Blade Patch"	Avenue 136 west of Friant Kern Canal	5/1/2019	5/1/2019
Rural	Large area Patching with grader "Blade Patch"	Road 208 south of Avenue 112	5/1/2019	5/1/2019
Rural	Large area Patching with grader "Blade Patch"	Avenue 96 west of Road 208	5/1/2019	5/1/2019
Rural	Large area Patching with grader "Blade Patch"	Avenue 104 from Road 152 to Road 160	5/2/2019	5/2/2019
Rural	Repair road surface by hand patching	Road 192 from Avenue 96 to Avenue 168	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Avenue 64 from Rad 208 to Road 224	5/6/2019	5/6/2019
Rural	Repair road surface by hand patching	Road 192 from Avenue 95 to Avenue 104	5/7/2019	5/7/2019
Rural	Repair road surface by hand patching	Avenue 8 from Road 144 to Road 192	5/8/2019	5/8/2019
Rural	Repair road surface by hand patching	Avenue 8 from Road 192 to Road 208	5/9/2019	5/9/2019
Rural	Repair road surface by hand patching	Avenue 128 from Road 208 to Road 236	5/9/2019	5/9/2019
Rural	Large area Patching with grader "Blade Patch"	Road 136 west of Highway 65	5/9/2019	5/9/2019
Rural	Repair road surface by hand patching	Road 224 from Avenue 112 to Avenue 128	5/13/2019	5/13/2019
Rural	Repair road surface by hand patching	Road 192 from Avenue 96 to Avenue 8	5/13/2019	5/13/2019
Rural	Repair road surface by hand patching	Avenue 0 at Ames	5/13/2019	5/13/2019
Rural	Repair road surface by hand patching	Road 208 from Avenue 8 to Avenue 32	5/14/2019	5/14/2019
Rural	Repair road surface by hand patching	Road 248 from Avenue 86 to Avenue 84	5/28/2019	5/28/2019
Rural	Repair road surface by hand patching	Road 208 from Avenue 190 to Avenue 152	5/29/2019	5/29/2019
Rural	Repair road surface by hand patching	Road 208 from Avenue 144 to Avenue 24	5/30/2019	5/30/2019
Rural	Repair road surface by hand patching	23791 Avenue 93	6/10/2019	6/10/2019
Rural	Repair road surface by hand patching	Avenue 40 from Road 144 to Road 200	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	Avenue 24 from Road 144 to State Hwy 99	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	Avenue 16 from Road 144 to Road 168	6/11/2019	6/11/2019
Rural	Repair road surface by hand patching	North Grand at FKC District 1	6/18/2019	6/21/2019
Rural	Repair road surface by hand patching	Road 228 from Avenue 220 to Avenue 228	6/21/2019	6/21/2019
Rural	Repair road surface by hand patching	Road 184 North of Avenue 112	6/3/2019	6/4/2019
Rural	Repair road surface by hand patching	Road 164 from Avenue 96 to Avenue 104	6/4/2019	6/4/2019
Rural	Repair road surface by hand patching	Road 168 at Avenue 104	6/4/2019	6/4/2019
Rural	Haul Material for Measure R	Deer Creek to Avenue 368 Pit	6/5/2019	6/6/2019
Rural	Repair road surface by hand patching	Avenue 96 from State Highway 65 to Road 216	6/5/2019	6/5/2019

Mountain Roads

Mountain Roads	Repair road surface by hand patching	Mountain Road 239 at Milepost 0	3/20/2019	3/20/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 at Milepost 23.5	3/20/2019	3/20/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Avenue 280 to Milepost 2	4/8/2019	4/8/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Milepost 3 to Milepost 12	4/8/2019	4/8/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 176A from Road 292 to Mountain Road 171A	4/9/2019	4/9/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 176B from Avenue 176 to Highway 190	4/9/2019	4/9/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 276 from Mountain Road 296 to Milepost 2	4/10/2019	4/12/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 from Mountain Road 239 to Milepost 7	4/15/2019	4/15/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 296 from Mountain Road 239 to Milepost 13.5	4/15/2019	4/18/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 146 west of Avenue 146	4/16/2019	4/16/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 107 from Milepost 2 to Milepost 8	4/25/2019	4/25/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 276 from Milepost 1.75 to Milepost 2.25	5/6/2019	5/6/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 from Mountain Road 239 to Mountain Road 220	5/8/2019	5/9/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 from Mountain Road 296 to Milepost 16	5/9/2019	5/9/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 146 west of Avenue 146	5/14/2019	5/14/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 216 at Milepost 5	6/10/2019	6/10/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 from Mountain Road 247 to Milepost 15.5	6/10/2019	6/10/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 195A to Mountain Road 200	6/11/2019	6/11/2019

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Mountain Roads	Repair road surface by hand patching	Mountain Road 191C from Mountain Road 193A to Mountain Road 187	6/11/2019	6/11/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 201 from Mountain Road 199A to Mountain Road 200A	6/11/2019	6/11/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 200A from Mountain Road 201 to Mountain Road 193A	6/11/2019	6/18/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 192A from Mountain Road 192B to Mountain Road 193	6/18/2019	6/18/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 220 from Milepost 3.5 to Milepost 7.5	6/17/2019	6/17/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 276 from Milepost 3 to Milepost 3.5	6/17/2019	6/17/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 193A from Mountain Road 200A to Mountain Road 188	6/18/2019	6/18/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 107 from Highway 190 to Mountain Road 50	6/20/2019	6/20/2019
Mountain Roads	Repair road surface by hand patching	Mountain Road 231 from Mountain Road 239 to Avenue 240*	6/21/2019	6/21/2019
Mountain Roads	Repair road surface by hand patching	Sand Creek Drive from Mile Post 2.5 to Mile Post 8.5	4/9/2019	4/9/2019
Mountain Roads	Repair road surface by hand patching	Dry Creek Drive from Mile Post 8.5 to Mile Post 12.5	4/10/2019	4/10/2019
Mountain Roads	Repair road surface by hand patching	Dry Creek Drive at Mile Post 2	4/12/2019	4/12/2019
Mountain Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 4 to Mile Post 9	4/12/2019	4/12/2019
Mountain Roads	Repair road surface by hand patching	Stagecoach Drive from Dry Creek Drive to Eshom Valley Drive	4/30/2019	4/30/2019
Mountain Roads	Repair road surface by hand patching	Eshom valley Drive from Mile Post 1 to Mile Post 3	4/30/2019	4/30/2019
Mountain Roads	Repair road surface by hand patching	Whitaker Forest Drive from Mile Post 2 to Mile Post 3	5/2/2019	5/2/2019
Mountain Roads	Repair road surface by hand patching	Whitaker Forest Drive from Mile Post 2 to Eshom Valley Drive	5/6/2019	5/8/2019
Mountain Roads	Repair road surface by hand patching	Dry Creek Drive from Mile Post 4.5 to Mile Post 14.5	5/14/2019	5/15/2019
Mountain Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 2.5 to Mile Post 3.5	6/4/2019	6/4/2019
Mountain Roads	Repair road surface by hand patching	Eshom Valley Drive from Mile Post 4 to Mile Post 8	6/6/2019	6/6/2019
Mountain Roads	Repair road surface by hand patching	Mountain 137 from Road 296 to Mile Post 8	3/25/2019	5/16/2019
Mountain Roads	Repair road surface by hand patching	Mountain 56 East of Mountain 112	3/27/2019	3/27/2019
Mountain Roads	Repair road surface by hand patching	Mountain 56 from Mountain 109 to Mile Post 11.5	4/1/2019	4/1/2019
Mountain Roads	Repair road surface by hand patching	Mountain 109 from Avenue 72 to Avenue 56	4/1/2019	4/1/2019
Mountain Roads	Repair road surface by hand patching	Mountain 56 from Mountain 109 to Mountain 50	4/2/2019	4/3/2019
Mountain Roads	Repair road surface by hand patching	Mountain 43 from Mountain 56 to End	4/4/2019	4/4/2019
Mountain Roads	Repair road surface by hand patching	Mountain 152 from Mile Post 10 to Mile Post 27.0	4/8/2019	4/10/2019
Mountain Roads	Repair road surface by hand patching	Pine Flat at Rocking K	4/8/2019	4/8/2019
Mountain Roads	Repair road surface by hand patching	Mountain 50 from Mountain 56 to Mountain 107	4/8/2019	4/25/2019
Mountain Roads	Repair road surface by hand patching	Mountain 50 from Mountain 56 to Mile Post 7.5	4/16/2019	4/16/2019
Mountain Roads	Repair road surface by hand patching	Mountain 137 from Road 284 to Mile Post 8.18	4/23/2019	4/24/2019
Mountain Roads	Repair road surface by hand patching	Mountain 99 from county line to Mountain 50	4/25/2019	4/29/2019
Mountain Roads	Repair road surface by hand patching	Mountain 9 from Mountain 3 to Mile Post 5.72	4/29/2019	4/29/2019
Mountain Roads	Repair road surface by hand patching	Mountain 109 from Avenue 88 to Avenue 56	4/30/2019	4/30/2019
Mountain Roads	Large area Patching with grader "Blade Patch"	Mountain 45 at Mountain 43	5/1/2019	5/1/2019
Mountain Roads	Large area Patching with grader "Blade Patch"	Mountain 56 at Road 416 (Tract 454) Pine Mountain	5/6/2019	5/23/2019
Mountain Roads	Large area Patching with grader "Blade Patch"	Mountain 9 from Mountain 3 to Mountain 14	5/6/2019	5/7/2019
Mountain Roads	Large area Patching with grader "Blade Patch"	Mountain 9 from Mountain 3 to Mile Post 5.72	5/8/2019	6/10/2019
Mountain Roads	Repair road surface by hand patching	Mountain 3 from Mountain 109 to Mountain 11	5/10/2019	5/10/2019
Mountain Roads	Repair road surface by hand patching	Mountain 11 from Mountain 3 to Mountain 14	5/10/2019	5/10/2019
Mountain Roads	Repair road surface by hand patching	Mountain 109 from Avenue 56 to Mountain 1	5/28/2019	6/10/2019
Mountain Roads	Repair road surface by hand patching	Mountain 137 from Road 284 to End	5/30/2019	5/30/2019
Mountain Roads	Repair road surface by hand patching	Mountain 231 from Mountain 9 to Avenue 240*End	6/21/2019	6/21/2019
Mountain Roads	Repair road surface by hand patching	Mountain 9 from Mountain 3 to MP 5.72	6/4/2019	6/10/2019

375,981.21

Tulare County Association Of Governments
Quarterly Reporting
Measure R Programs

Agency: Tulare County Resource Management Agency

Quarter: FY 2019 Quarter 4

Local Programs

Measure R Expenditure Allocation	Project	Description	Limits	Start Date	Completion Date	Amount Spent this Quarter
AC Sidewalk MR (AB 720)		Construction/design	Avenue 280 County Line to State Route 99 Farm to Market	6/26/2017	ongoing	
		Preliminary Engineering/ Design	Harvest Avenue Project Road 64 to Road 68	5/5/2017	ongoing	352.13
		Construction/Design	Strathmore Slurry Seal and Isolated Road Repair	7/17/2017	ongoing	1,427.88
		Preliminary Engineering/ Design	ADA Ramp Improvements	3/3/2016	ongoing	196.40
		Construction/Design	Ivanhoe R159 and Azalea Improvements	7/11/2017	ongoing	3,262.70
		Construction/Design	West Goshen Ave 308	6/27/2017	ongoing	3,622.61
		Preliminary Engineering/ Design	Orosi A416 Crossing	7/12/2017	ongoing	4,339.33
		Preliminary Engineering/ Design	Poplar Crossing R192 and A146	8/1/2017	ongoing	6,805.41
		Preliminary Engineering/ Design	Strathmore A196 & R228 Intersection	8/1/2017	ongoing	9,296.91
		Preliminary Engineering/ Design	Allensworth Sidewalk & Crosswalk Improvements	8/2/2017	ongoing	3,712.99
		Preliminary Engineering/ Design	Alpaugh Center Street Improvements	8/2/2017	ongoing	8,534.67
			Repair potholes with Road Patcher		Total	\$ 540,701.70